

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Fassifern Public School (1904)</b>
<b>Region:</b>	<b>Hunter/Central Coast AMU</b>
<b>State Electorate:</b>	<b>Lake Macquarie</b>
<b>Local Government Area:</b>	<b>Lake Macquarie</b>

<b>Last Reviewed By:</b>	<b>AECOM 17-JUN-2016</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

1904 - Fassifern Public School  
Site Plan (13063)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/General Learning - 1926 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00A - R0001 - Clerical Office - 10.55 m2</b>							
No Asbestos							
<b>B00A - R0002 - Home Base - 47.15 m2</b>							
No Asbestos							
<b>B00A - R0003 - Movement - 22.55 m2</b>							
No Asbestos							
<b>B00A - R0004 - Home Base - 49.86 m2</b>							
No Asbestos							
<b>B00A - R0005 - Interview - 7.85 m2</b>							
No Asbestos							
<b>B00A - R0008 - Staff Toilet - 3.08 m2</b>							
No Asbestos							
<b>B00A - R0009 - Staff Toilet - 3.06 m2</b>							
No Asbestos							
<b>B00A - R0012 - Movement - 9.5 m2</b>							
No Asbestos							
<b>B00A - R0013 - Sick Bay - 8.07 m2</b>							
No Asbestos							
<b>B00A - R0014 - Principal - 12.89 m2</b>							
No Asbestos							
<b>B00A - R0015 - Clerical Office - 18.14 m2</b>							
No Asbestos							
<b>B00B - Communal Facilities/Building Services - 1926 - Timber</b>							
<b>Exterior</b>							
Underfloor Voids	Packing	16	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
<b>Interior</b>							
<b>B00B - R0001 - External Movement - 10.27 m2</b>							
No Asbestos							
<b>B00B - R0002 - Other-Community Use - 10.1 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0003 - External Movement - 19.76 m2</b>							
No Asbestos							
<b>B00B - R0004 - Cleaning Distributed Store - 5.11 m2</b>							
No Asbestos							
<b>B00B - R0005 - Sports Store - 9.76 m2</b>							
No Asbestos							

<b>B00B - R0006 - General Storeroom - 5.04 m2</b>							
No Asbestos							
<b>B00C - Pupil Facilities - 1926 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00C - R0001 - Toilets - Girls - 17.93 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0002 - Toilets - Boys - 18.07 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - Library - 1999 - Timber</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Reading Area - 66.67 m2</b>							
No Asbestos							
<b>B00D - R0002 - K.L.A. Store - 4.97 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0003 - External Movement - 13.43 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
<b>B00E - Staff Facilities - 1999 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Flat AC Sheeting	4.06	South west corner of building under ER003.	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00E - R0001 - Staff Room - 37.34 m2</b>							
No Asbestos							
<b>B00E - R0002 - Security Store - 4.25 m2</b>							
No Asbestos							
<b>B00E - R0003 - Staff Toilet - 4.16 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00E - R0004 - External Movement - 13.38 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						

## B00F - Library - 2011 - Fibre Cement Clad

### Exterior

Underfloor Voids	No Asbestos Found
------------------	-------------------

Ceiling Voids	No Asbestos Found
---------------	-------------------

### Interior

#### B00F - R0001 - External Movement - 31.19 m2

No Asbestos
-------------

#### B00F - R0002 - Reading Area - 91.95 m2

No Asbestos
-------------

#### B00F - R0003 - Library Office/Workroom - 20.47 m2

No Asbestos
-------------

#### B00F - R0004 - Communications Room - 8.4 m2

No Asbestos
-------------

#### B00F - R0005 - K.L.A. Store - 9.89 m2

No Asbestos
-------------

**Demountables**

**NS 100 10837 - Learning Unit - Single Primary/PAA - Placement Date : 16-JAN-2007**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**NS 300 11867 - FSU /Bulk Store/Toilet - Placement Date : 09-JAN-2004**

No Asbestos Found