

30m

Crack damage to the kerb and gutter.





40m

General views of the road surface, kerb and gutter.





40m

General views of the road surface, kerb and gutter.







40m

Crack damage to the kerb, layback and gutter.







40m

Crack damage to the kerb, layback and gutter.



50m

General views of the road surface, kerb and gutter.







50m

General views of the road surface, kerb and gutter.



50m

Crack damage throughout the kerb and gutter.





50m

Crack damage throughout the kerb and gutter.







60m

General views of the road surface, kerb and gutter.





60m

General views of the road surface, kerb and gutter.





60m


Crack damage throughout the layback, gutter and kerb.





60m

Crack damage throughout the layback, gutter and kerb.





70m

General views of the road surface, kerb and gutter.





70m

General views of the road surface, kerb and gutter.



70m

Crack damage throughout the kerb and gutter.





70m

Crack damage throughout the kerb and gutter.





80m

General views of the road surface, kerb and gutter.





80m

General views of the road surface, kerb and gutter.





80m

Crack damage throughout the kerb and gutter.







80m

Crack damage throughout the kerb and gutter.





90m

General views of the road surface, kerb and gutter.





90m

General views of the road surface, kerb and gutter.







90m

Crack damage to the kerb, gutter and layback.







90m

Crack damage to the kerb, gutter and layback.





100m

General views of the road surface, kerb and gutter.





100m

General views of the road surface, kerb and gutter.





100m

Crack damage to the kerb and gutter.







100m

Crack damage to the kerb and gutter.







### Notable Items – Section 3

#### Intersection of Sunlea Place and Allambie Road:

The following inspection is of the public infrastructure at the intersection of Sunlea Place and Allambie Road, Allambie Heights.



General view of the intersection of Sunlea Place and Allambie Road looking south.





General views of the footpath and inspection lid at the north side of Sunlea Place.







General views of the footpath and inspection lid at the north side of Sunlea Place.





General views of the kerb and gutter showing crack damage at the north side of Sunlea Place.





General views of the kerb and gutter showing crack damage at the north side of Sunlea Place.





Views of the road surface of Sunlea Place.





Views of the road surface of Sunlea Place.





Views of the road surface of Sunlea Place.





Views of the road surface of Sunlea Place.





Views to the road surface of Allambie Road at Sunlea Place, Allambie Heights.

