



90m

Crack damage to the kerb and gutter.





90m

Crack damage to the kerb and gutter.



100m

General views of the road surface, kerb and gutter.



100m


General views of the road surface, kerb and gutter.





100m

Crack damage to the road surface.





100m

Crack damage to the road surface.



100m

Various cracks to the kerb and gutter.





100m

Various cracks to the kerb and gutter.





110m

General views of the road surface, kerb and gutter.



110m

General views of the road surface, kerb and gutter.





110m

Crack damage to the road surface.



110m

Crack damage to the kerb and gutter.



120m

General views of the road surface, kerb and gutter.



120m

General views of the road surface, kerb and gutter.



120m

General views of the road surface, kerb and gutter.





120m

Various cracks to the road surface.





120m

Various cracks to the road surface.



120m

Various cracks to the kerb and gutter.





120m

Various cracks to the kerb and gutter.



130m

General views of the road surface, kerb and gutter.



130m

General views of the road surface, kerb and gutter.



130m

General views of the road surface, kerb and gutter.





130m

Crack damage and subsidence to the road surface and gutter.





130m

Crack damage and subsidence to the road surface and gutter.



140m

General views of the road surface, kerb and gutter.



140m

General views of the road surface, kerb and gutter.



140m	<p>Gouges to the road surface.</p> 
140m	<p>Crack damage to the kerb and gutter.</p> 

150m

General views of the road surface, kerb and gutter.



150m

General views of the road surface, kerb and gutter.



150m

Crack damage to the kerb and gutter.





150m

Crack damage to the kerb and gutter.



160m

General views of the road surface, kerb and gutter.



160m

General views of the road surface, kerb and gutter.



170m

General views of the road surface, kerb and gutter.



170m

General views of the road surface, kerb and gutter.





170m

Crack damage to the road surface.



180m

General views of the road surface, kerb and gutter.



180m

General views of the road surface, kerb and gutter.





180m	<p>General views of the road surface, kerb and gutter.</p>  A photograph showing a general view of a road surface, kerb, and gutter. The road is paved with asphalt and has a green-painted section. The kerb is made of concrete and is bordered by a grassy area. The gutter is visible on the right side of the road. The background shows trees and a clear blue sky.
180m	<p>Crack damage to the road surface.</p>  A close-up photograph of a crack in the road surface. The crack runs diagonally across the asphalt. A green-painted section is visible above the crack. The road surface is dark grey asphalt.



180m

Crack damage to the kerb and gutter.

