
Crack damage throughout the kerb and gutter.





150m General views of the footpath, kerb and gutter.





150m General views of the footpath, kerb and gutter.



Crack damage throughout the kerb and gutter.

Crack damage throughout the kerb and gutter.

General views of the footpath, kerb and gutter at the end point.






General views of the footpath, kerb and gutter at the end point.

General views of the footpath, kerb and gutter at the end point.

Crack damage throughout the kerb and gutter at the end point.





Views of the street signs at the intersection of Aquatic Drive and Allambie Road.





The following inspection is of the road surface to the south side of Allambie Road starting at the intersection of Aquatic Drive and Allambie Road at the roundabout, heading in a westerly direction and finishing at the driveway entrance to Arranounbai School.



General views of the road surface at the start point.




5m Views of the median strip and street sign.






Views of the median strip and street sign.





General views of the road surface.














General views of the road surface.






























General views of the road surface.