



100m

Crack damage to the kerb and gutter.



100m

Crocodile cracking to the road surface.





100m

Crocodile cracking to the road surface.





100m

Crocodile cracking to the road surface.





Crack damage throughout the driveway crossover, layback and gutter servicing number 2 Aquatic Drive.





Crack damage throughout the driveway crossover, layback and gutter servicing number 2 Aquatic Drive.





Crack damage throughout the driveway crossover, layback and gutter servicing number 2 Aquatic Drive.





110m

Crack damage to the road surface.





110m

Crack damage to the road surface.





110m

Crack damage to the road surface.



120m

Views of the tree.



120m

General views of the kerb, gutter and road surface.



120m

General views of the kerb, gutter and road surface.



120m

General views of the kerb, gutter and road surface.



130m

General views of the kerb, gutter and road surface.



130m

General views of the kerb, gutter and road surface.



130m

General views of the kerb, gutter and road surface.



130m	<p>General views of the kerb, gutter and road surface.</p> 
130m	<p>Crack damage to the road surface.</p> 




140m

General views of the kerb, gutter, road surface and kerb ramp.




140m

General views of the kerb, gutter, road surface and kerb ramp.



140m

General views of the kerb, gutter, road surface and kerb ramp.



140m

General views of the kerb, gutter, road surface and kerb ramp.





General views of the northern side of the roundabout at the intersection of Aquatic Drive and Allambie Road.



General views of the northern side of the roundabout at the intersection of Aquatic Drive and Allambie Road.



Crack damage throughout the road surface at the roundabout.



Crack damage to the kerb and gutter at the north side of the roundabout.



Crack damage to the kerb and gutter at the north side of the roundabout.



Crack damage to the footpath at the roundabout.



Views of the inspection lids to the footpath at the northern side of Aquatic Drive.





Views of the inspection lids to the footpath at the northern side of Aquatic Drive.





Crack damage to the footpath at the roundabout.



Repaired section noted to the footpath.



Views of the inspection lids to the footpath at the eastern side of the driveway servicing number 2 Aquatic Drive.





Notable Items – Section 5

Arranounbai School:


The following inspection is of the driveway and footpath leading from Aquatic Drive through to the Arranounbai School.



General views of the brick wall and sign to the left side of the driveway to the Arranounbai School.



General views of the brick wall and sign to the left side of the driveway to the Arranounbai School.



Cracks to the brickwork at the left side of the brick wall.



General views of the electronic sign and brickwork wall at the right side of the driveway.



General views of the electronic sign and brickwork wall at the right side of the driveway.



Crack damage to the middle of the brickwork wall.





The following inspection is of the footpath to the eastern side of the driveway starting from Aquatic Drive and heading towards Arranounbai School in a southerly direction.



0m	<p>General view of the fencing and footpath at the start point.</p>  A photograph showing a concrete footpath leading through a metal mesh fence. The fence is supported by metal posts. The path is surrounded by dry grass and some green foliage in the background.
5m	<p>View of the footpath looking at the expansion joint.</p>  A close-up photograph of the concrete footpath, showing a joint in the pavement. The path is bordered by a metal mesh fence on both sides. Dry grass and some debris are visible along the edges of the path.

7m

General views of the fencing and footpath.

