

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Fairfield Public School (1895)
Region:	South Western Sydney AMU
State Electorate:	Fairfield
Local Government Area:	Fairfield

Last Reviewed By:	WSP 28-DEC-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

1895 - Fairfield Public School
Site Plan (12512)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B001 - General Learning - 1997 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	No Asbestos Found						
Interior							
B001 - R0002 - Practical Activities - 1hb - 19.85 m2							
No Asbestos							
B001 - R0003 - Personal Effects Storage - 6.73 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B001 - R0004 - Home Base Store - 7.17 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0005 - Personal Effects Storage - 2.38 m2							
No Asbestos							
B001 - R0006 - Home Base - 55.04 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0007 - Withdrawal Space - 1hb - 6.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B001 - R0008 - Practical Activities - 1hb - 15.65 m2							
No Asbestos							
B001 - R0009 - Home Base - 56.18 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0010 - Home Base Store - 6.45 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0011 - Withdrawal Space - 1hb - 6.53 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0012 - Withdrawal Space - 1hb - 6.5 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0013 - Home Base - 49.42 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0014 - Practical Activities - 1hb - 20.04 m2							
No Asbestos							
B001 - R0015 - Home Base Store - 8.15 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B001 - R0017 - Movement - 2.41 m2							
No Asbestos							
B001 - R0018 - Stairs - 5.27 m2							
No Asbestos							
B001 - R0019 - Stairs - 6.07 m2							

No Asbestos		
B001 - R0020 - External Movement - 93.68 m2		
No Asbestos		
B001 - R1001 - General Storeroom - 7.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1002 - Distribution Board - 1.07 m2		
Note: No inspection of live electrical installation		
No Asbestos		
B001 - R1003 - Movement - 29.73 m2		
No Asbestos		
B001 - R1004 - Home Base - 56.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1005 - Practical Activities - 1hb - 31.78 m2		
No Asbestos		
B001 - R1006 - Home Base Store - 6.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1007 - Withdrawal Space - 1hb - 17.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1008 - Withdrawal Space - 1hb - 16.89 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1009 - Movement - 31.39 m2		
No Asbestos		
B001 - R1010 - Home Base - 56.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1011 - Home Base Store - 6.84 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B001 - R1012 - Plant - 8.49 m2		
Wall Linings Internal	Flat AC Sheeting	
B001 - R1013 - Stairs - 6.14 m2		
No Asbestos		
B001 - R1014 - Stairs - 6.08 m2		
No Asbestos		
B002 - General Learning - 1888 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B002 - R0001 - Cleaning Distributed Store - 3.05 m2		
No Asbestos		
B002 - R0002 - Garden Store - 14.56 m2		
No Asbestos		
B002 - R0003 - General Assistant/Bulk Store - 10.63 m2		
No Asbestos		
B002 - R0004 - External Movement - 5.87 m2		
No Asbestos		
B002 - R0005 - Staff Toilet - 4.73 m2		
No Asbestos		

B002 - R0006 - Cleaning Distributed Store - 4.79 m2							
No Asbestos							
B002 - R0007 - Staff Toilet - 4.77 m2							
No Asbestos							
B002 - R0008 - Kiln Room - 9.91 m2							
No Asbestos							
B002 - R0009 - Craft Store - 8.86 m2							
No Asbestos							
B002 - R0010 - Practical Activities - 1hb - 47.61 m2							
No Asbestos							
B002 - R0011 - Practical Activities - 1hb - 47.61 m2							
No Asbestos							
B002 - R0012 - Movement - 43.36 m2							
No Asbestos							
B002 - R0013 - Special Programs Room - 20.23 m2							
No Asbestos							
B002 - R0014 - Staff Room Annexe - 15.26 m2							
No Asbestos							
B002 - R0015 - Community Clinic - 24.82 m2							
No Asbestos							
B002 - R0016 - Withdrawal Space - 1hb - 21.21 m2							
No Asbestos							
B002 - R0017 - Home Base - 43.44 m2							
No Asbestos							
B002 - R0018 - Home Base - 45.03 m2							
No Asbestos							
B002 - R0019 - Home Base - 43.98 m2							
No Asbestos							
B002 - R0020 - Home Base - 47.41 m2							
No Asbestos							
B002 - R0021 - Home Base - 46.37 m2							
No Asbestos							
B002 - R0023 - Movement - 11.35 m2							
No Asbestos							
B002 - R0024 - Distribution Board - .48 m2							
No Asbestos							
B002 - R0025 - Personal Effects Storage - 14.04 m2							
No Asbestos							
B002 - R0026 - Home Base - 46.89 m2							
No Asbestos							
B002 - R0027 - External Movement - 146.73 m2							
No Asbestos							
B002 - R0028 - External Movement - 28.76 m2							
No Asbestos							
B002 - R0029 - General Storeroom - 16.57 m2							
No Asbestos							
B008 - General Learning - 1949 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	120m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Wall Linings Internal - Infill	Flat AC Sheeting							
Wall Linings Internal - Infill	Flat AC Sheeting	5	Above Windows, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found							
Interior								
B008 - R0003 - Home Base Store - 6.09 m2								
No Asbestos								
B008 - R0009 - Music Store - 6.07 m2								
No Asbestos								
B008 - R0020 - Home Base Store - 6.04 m2								
No Asbestos								
B008 - R0027 - Home Base Store - 6.18 m2								
No Asbestos								
B008 - R0038 - Toilets - Boys/Girls - 3.42 m2								
No Asbestos								
B008 - R0039 - Home Base - 59.09 m2								
No Asbestos								
B008 - R0040 - Practical Activities - 1hb - 15.88 m2								
No Asbestos								
B008 - R0041 - Practical Activities - 1hb - 13.85 m2								
No Asbestos								
B008 - R0042 - Home Base - 51.52 m2								
No Asbestos								
B008 - R0043 - Home Base Store - 3.47 m2								
No Asbestos								
B008 - R0044 - Movement - 2.92 m2								
No Asbestos								
B008 - R0045 - Movement - 5.31 m2								
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B008 - R0046 - Movement - 178.27 m2								
Ceiling Structures/Linings	Flat AC Sheeting	179m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal - Infill	Flat AC Sheeting							
Floor Coverings Res/Textile	Vinyl Sheet							
B008 - R0047 - Movement - 4.7 m2								
No Asbestos								
B008 - R0048 - Home Base Store - 5.1 m2								
No Asbestos								
B008 - R0049 - Movement - 2.87 m2								
No Asbestos								
B008 - R0050 - Home Base Store - 4.08 m2								
No Asbestos								
B008 - R0051 - Home Base - 50.61 m2								
No Asbestos								
B008 - R0052 - Practical Activities - 1hb - 13.46 m2								
No Asbestos								
B008 - R0053 - Practical Activities - 1hb - 15.74 m2								
No Asbestos								
B008 - R0054 - Home Base - 60.19 m2								

No Asbestos							
B008 - R0055 - Toilets - Boys/Girls - 3.36 m2							
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B008 - R0056 - Home Base Store - 5.15 m2							
No Asbestos							
B008 - R0057 - Movement - 4.62 m2							
No Asbestos							
B008 - R0058 - Movement - 3.66 m2							
No Asbestos							
B008 - R0059 - Home Base Store - 3.31 m2							
No Asbestos							
B008 - R0060 - Home Base - 61.62 m2							
No Asbestos							
B008 - R0061 - Practical Activities - 1hb - 19.51 m2							
No Asbestos							
B008 - R0062 - Special Programs Room - 32.69 m2							
No Asbestos							
B008 - R0063 - General Assistant/Bulk Store - 6.42 m2							
No Asbestos							
B008 - R0064 - Staff Toilet - 7.58 m2							
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B008 - R0065 - Movement - 2.82 m2							
No Asbestos							
B008 - R0066 - Home Base Store - 4.21 m2							
No Asbestos							
B008 - R0067 - Movement - 4.84 m2							
No Asbestos							
B008 - R0068 - Home Base - 51.28 m2							
No Asbestos							
B008 - R0069 - Practical Activities - 1hb - 13.42 m2							
No Asbestos							
B008 - R0070 - Practical Activities - 1hb - 15.89 m2							
No Asbestos							
B008 - R0071 - Home Base - 60.32 m2							
No Asbestos							
B008 - R0072 - Toilets - Boys/Girls - 3.36 m2							
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B008 - R0073 - Practical Activities - 1hb - 5 m2							
No Asbestos							
B008 - R0074 - Cleaning Distributed Store - 2.76 m2							
No Asbestos							
B008 - R0075 - Main Switch Board - 7.61 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Wall Linings Internal	Flat AC Sheeting						
B008 - R0076 - External Movement - 42.38 m2							
No Asbestos							
B009 - General Learning - 1920 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						

Underfloor Voids	No Asbestos Found	
Ceiling Voids	Non Accessible Area	
Interior		
B009 - R0001 - Home Base - 53.98 m2		
No Asbestos		
B009 - R0002 - Home Base - 46.9 m2		
No Asbestos		
B009 - R0003 - Home Base - 47.08 m2		
No Asbestos		
B009 - R0004 - Home Base - 47.66 m2		
No Asbestos		
B009 - R0005 - Movement - 18.4 m2		
No Asbestos		
B009 - R0008 - Home Base Store - 5.96 m2		
No Asbestos		
B009 - R0009 - Practical Activities - 1hb - 17.07 m2		
No Asbestos		
B009 - R0010 - Withdrawal Space - 1hb - 7.02 m2		
No Asbestos		
B009 - R0011 - Withdrawal Space - 1hb - 7.07 m2		
No Asbestos		
B009 - R0012 - Practical Activities - 1hb - 16.91 m2		
No Asbestos		
B009 - R0013 - Home Base Store - 5.68 m2		
No Asbestos		
B009 - R0014 - Personal Effects Storage - 73.42 m2		
No Asbestos		
B009 - R0015 - Withdrawal Space - 1hb - 12.11 m2		
No Asbestos		
B009 - R0016 - Plant - 6.95 m2		
No Asbestos		
B009 - R0017 - External Movement - 1.15 m2		
No Asbestos		
B009 - R0018 - External Movement - 36.31 m2		
No Asbestos		
B00A - Administration/Staff Facilities - 1949 - Brick/Block		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00A - R0001 - Staff Room Annexe - 29.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0002 - Staff Room - 68.66 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0003 - Deputy Principal - 12.57 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0004 - Deputy Principal - 13.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00A - R0005 - Principal - 15.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0006 - Sick Bay - Shower/Toilet - 7.24 m2		
No Asbestos		
B00A - R0007 - Movement - 1.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0008 - Sick Bay - 8.4 m2		
No Asbestos		
B00A - R0009 - Duplicating Workroom - 17.64 m2		
No Asbestos		
B00A - R0010 - Entry Vestibule - 17.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0011 - External Movement - 7.36 m2		
No Asbestos		
B00A - R0012 - Clerical Office - 32.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0013 - Interview - 13.7 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0014 - Security Store - 17.89 m2		
No Asbestos		
B00A - R0015 - Staff Toilet - 4.83 m2		
No Asbestos		
B00A - R0016 - Staff Toilet - 4.83 m2		
No Asbestos		
B00A - R0017 - Staff Toilet - 4.83 m2		
No Asbestos		
B00A - R0018 - Cleaning Distributed Store - 5.38 m2		
No Asbestos		
B00A - R0019 - Movement - 38.1 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0020 - Main Switch Board - 2.25 m2		
No Asbestos		
B00A - R0021 - External Movement - 30.39 m2		
No Asbestos		
B00A - R0022 - External Movement - 87.9 m2		
No Asbestos		
B00C - Pre-School Facilities - 2002 - Steel		
Exterior		
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00C - R0001 - No Access - 94.09 m2		
No Asbestos		
B00H - Communal Facilities/Pupil Facilities - 1888 - Brick/Block		
Exterior		

Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00H - R0001 - Plant - .63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0002 - P.E Store - 16.42 m2		
No Asbestos		
B00H - R0003 - Hall Chair Store - 10.4 m2		
No Asbestos		
B00H - R0004 - Toilets - Girls - 5.46 m2		
No Asbestos		
B00H - R0005 - Shower/Change - 2.5 m2		
No Asbestos		
B00H - R0006 - Movement - 1.21 m2		
No Asbestos		
B00H - R0007 - General Storeroom - 8.81 m2		
No Asbestos		
B00H - R0008 - Movement - 10.15 m2		
No Asbestos		
B00H - R0009 - Raised Platform - 48.05 m2		
No Asbestos		
B00H - R0010 - Movement - 9.95 m2		
No Asbestos		
B00H - R0011 - General Storeroom - 9.7 m2		
No Asbestos		
B00H - R0012 - Movement - 1.17 m2		
No Asbestos		
B00H - R0013 - Shower/Change - 2.44 m2		
No Asbestos		
B00H - R0014 - Toilets - Boys - 5.57 m2		
No Asbestos		
B00H - R0015 - Communal Space - 202.13 m2		
No Asbestos		
B00H - R0016 - Cleaning Distributed Store - 3.1 m2		
No Asbestos		
B00H - R0017 - Disabled Toilet - 6.33 m2		
No Asbestos		
B00H - R0018 - Sports Store - 15.75 m2		
No Asbestos		
B00H - R0019 - Distribution Board - .54 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0020 - General Storeroom - 12.36 m2		
No Asbestos		
B00H - R0021 - Garden Store - 15.6 m2		
No Asbestos		
B00H - R0022 - External Movement - 86.51 m2		
No Asbestos		
B00H - R0023 - Canteen - 46.58 m2		
No Asbestos		
B00H - R0024 - Canteen Office/Store - 10.59 m2		

No Asbestos		
B00H - R0025 - External Movement - 1.56 m2		
No Asbestos		
B00H - R0026 - External Movement - 1.56 m2		
No Asbestos		
B00H - R0027 - External Movement - 223.69 m2		
No Asbestos		
B00H - R0028 - Plant - .29 m2		
No Asbestos		
B00L - Library/General Learning - 1970 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - External Movement - 21.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0002 - Special Programs Room - 41.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0003 - Special Programs Store - 1.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0004 - Plant - 3.89 m2		
No Asbestos		
B00L - R0005 - Cleaning Distributed Store - 3.96 m2		
No Asbestos		
B00L - R0006 - Distribution Board - .71 m2		
No Asbestos		Note: No inspection of live electrical installation
B00L - R0007 - Communications Room - 12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0008 - Library Office/Workroom - 26.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0009 - Reading Area - 229.33 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0010 - External Movement - 6.5 m2		
No Asbestos		
B00L - R0011 - Home Base Store - 5.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0012 - Withdrawal Space - 1hb - 5.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0013 - Home Base - 50.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0014 - Practical Activities - 1hb - 27.39 m2		
No Asbestos		
B00L - R0015 - Home Base - 49.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00L - R0016 - Practical Activities - 1hb - 25.92 m2		
No Asbestos		
B00L - R0017 - Distribution Board - .55 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0018 - Home Base Store - 5.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0019 - Withdrawal Space - 1hb - 5.63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0020 - External Movement - 158.16 m2		
No Asbestos		
B00L - R0021 - External Movement - 35.64 m2		
No Asbestos		
B00M - Communal Facilities - 2006 - Steel		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	Flat AC Sheeting	
Interior		
B00M - R0001 - Other-Community Use - 47.89 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0002 - Toilets-Unisex - 3.48 m2		
No Asbestos		
B00M - R0003 - Other-Community Use - 11.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0004 - External Movement - 1.5 m2		
No Asbestos		
B00N - General Learning - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00N - R0001 - Practical Activities - 19.21 m2		
No Asbestos		
B00N - R0002 - Home Base - 60.81 m2		
No Asbestos		
B00N - R0003 - Home Base Store - 6.27 m2		
No Asbestos		
B00N - R0004 - Withdrawal Space - 1hb - 11.78 m2		
No Asbestos		
B00N - R0005 - Practical Activities - 17.99 m2		
No Asbestos		
B00N - R0006 - Home Base - 60.74 m2		
No Asbestos		
B00N - R0007 - Home Base Store - 6.27 m2		
No Asbestos		
B00N - R0008 - External Movement - 58.48 m2		
No Asbestos		
B00N - R0009 - Distribution Board - .39 m2		Note: No inspection of live electrical installation
No Asbestos		

B00N - R0010 - External Stairs - 16 m2							
No Asbestos							
B00N - R1001 - Practical Activities - 19.21 m2							
No Asbestos							
B00N - R1002 - Home Base - 60.69 m2							
No Asbestos							
B00N - R1003 - Home Base Store - 6.27 m2							
No Asbestos							
B00N - R1004 - Withdrawal Space - 2hb - 11.78 m2							
No Asbestos							
B00N - R1005 - Practical Activities - 19.21 m2							
No Asbestos							
B00N - R1006 - Home Base - 60.69 m2							
No Asbestos							
B00N - R1007 - Home Base Store - 6.27 m2							
No Asbestos							
B00N - R1008 - External Movement - 64.22 m2							
No Asbestos							
B00N - R1009 - External Stairs - 16 m2							
No Asbestos							
B011 - General Learning - 1997 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B011 - R0001 - External Movement - 29.44 m2							
No Asbestos							
B011 - R0002 - Home Base Store - 7.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0003 - Home Base - 52.15 m2							
No Asbestos							
B011 - R0004 - Home Base - 52.22 m2							
No Asbestos							
B012 - General Learning - 1997 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B012 - R0001 - External Movement - 12.53 m2							
No Asbestos							
B012 - R0002 - Home Base - 46.74 m2							
No Asbestos							
B014 - Pupil Facilities - 1948 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	AC Fragments/Debris	1	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Interior							

B014 - R0001 - Toilets - Boys - 54.3 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B014 - R0002 - Cleaning Distributed Store - 1.6 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B014 - R0003 - Toilets - Girls - 78.7 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B014 - R0004 - Cleaning Distributed Store - 1.85 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B014 - R0005 - External Movement - 158.11 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B015 - General Learning - 2004 - Fibre Cement Clad		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B015 - R0001 - External Movement - 39.33 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0002 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B015 - R0003 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0004 - Home Base - 59.23 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0005 - Withdrawal Space - 2hb - 11.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0006 - Home Base - 59.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0007 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B015 - R0008 - Practical Activities - 1hb - 19.42 m2		
No Asbestos		
B016 - Storage - 2017 - Metal Shed		
Exterior		
Require Inspection		
Interior		
B016 - R0001 - Chair Storeroom - 23.26 m2		
Require Inspection		

Demountables

OS 602 14981 - Learning Unit - Standard With P.A.A. - Placement Date : 25-FEB-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found