

Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1941 - Brick/Block							
Exterior							
Ceiling Voids	Requires Inspection						
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	10	South East side abow windows	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	14m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00A - R0001 - Home Base - 57.05 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00A - R0002 - Home Base Store - 3.73 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0003 - Distribution Board - .48 m2							
Note: No inspection of live electrical installation							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	0.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	0.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0004 - Personal Effects Storage - 19.08 m2							
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0005 - Home Base Store - 3.77 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3.77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0006 - Home Base - 57.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57.01m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00A - R0007 - Toilets - Boys - 35.97 m2							
Partition Walls (Cubides)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0008 - Movement - 42.5 m2							
Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	10m2	South East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0009 - Movement - 87.98 m2							
No Asbestos							
B00B - Pupil Facilities/Support Unit - 1975 - Brick/Block							
Exterior							
Ceiling Voids	Requires Inspection						
Wall Linings Internal - Infill	Compressed AC Sheet	16	Northwest & Southeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Interior							
B00B - R0001 - Hydrotherapy - Pool - 13.29 m2							
No Asbestos							
B00B - R0002 - Home Base - M - 41.32 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	41.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00B - R0003 - Practical Activities - 1hb - 15.57 m2							
No Asbestos							
B00B - R0004 - Laundry - Type 2 - 19.58 m2							
No Asbestos							
B00B - R0005 - Distribution Board - .52 m2							
Note: No inspection of live electrical installation							
Ceiling Structures/Linings	Flat AC Sheeting	0.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Electrical - Mounting Board	Fibrous Membrane	1	South East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00B - R0006 - Movement - 7.29 m2							
No Asbestos							
B00B - R0007 - Home Base - M - 56.8 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	56.77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00B - R0008 - Toilets - Girls - 36.1 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00B - R0009 - Movement - 64.54 m2							
Ceiling Structures/Linings	Flat AC Sheeting	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - General Learning/Support Unit - 1942 - Brick/Block							
Exterior							
Ceiling Voids	Requires Inspection						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Window	Mastic						
Interior							
B00C - R0001 - Staff Toilet - 6.43 m2							
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - R0002 - General Storeroom - 2.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00C - R0003 - Cleaning Distributed Store - 3.24 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00C - R0004 - Movement - 4.82 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4.82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0005 - Withdrawal Space - 1hb - 20.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0006 - Movement - 4.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0007 - Personal Effects Storage - 6.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0008 - Home Base Store - 5.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0009 - Home Base - 71.97 m2							

Ceiling Structures/Linings	Flat AC Sheeting	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0010 - Main Switch Board - 1.02 m2							
Electrical - Mounting Board	Resinous Membrane	1	North East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - R0011 - Withdrawal Space - 1hb - 21.72 m2							
No Asbestos							
B00C - R0012 - Staff Toilet - 4.96 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0013 - Cleaning Distributed Store - .24 m2							
No Asbestos							
B00C - R0014 - Staff Room Annexe - 18.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0015 - Home Base - 72.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0016 - Practical Activities - 1hb - 10.96 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0017 - Movement - 26.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0018 - General Storeroom - 8.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0019 - Staff Room Annexe - 14.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B00C - R0020 - Movement - 2.55 m2							

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - General Learning - 1969 - Brick/Veneer							
Exterior							
Ceiling Voids	Requires Inspection						
Underfloor Voids	Non Accessible Area						
Window	Mastic						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Interior							
B00D - R0001 - Toilets - Boys/Girls - 6.42 m2							
No Asbestos							
B00D - R0002 - Home Base Store - 13.01 m2							
No Asbestos							
B00D - R0003 - Home Base - 83.55 m2							
No Asbestos							
B00D - R0004 - Distribution Board - .57 m2							
						Note: No inspection of live electrical installation	
Electrical - Mounting Board	Fibrous Membrane	1	North East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00D - R0005 - Personal Effects Storage - 11.5 m2							
No Asbestos							
B00D - R0006 - Movement - 1.2 m2							
No Asbestos							
B00D - R0007 - Toilets - Boys/Girls - 4.62 m2							
No Asbestos							
B00D - R0008 - Home Base - 79.08 m2							
No Asbestos							
B00D - R0009 - Withdrawal Space - 1hb - 29.77 m2							
No Asbestos							
B00E - Library - 1962 - Brick/Veneer							
Exterior							
Ceiling Voids	Requires Inspection						
Wall Linings Internal - Infill	Compressed AC Sheet	20	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Wall Cladding	Flat AC Sheeting						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00E - R0001 - Reading Area - 143.73 m2							
No Asbestos							
B00E - R0002 - K.L.A. Store - 10.88 m2							
No Asbestos							
B00E - R0003 - Library Office/Workroom - 28.64 m2							
No Asbestos							
B00E - R0004 - Cleaning Supplies - .77 m2							
Wall Linings Internal	Flat AC Sheeting						
B00E - R0005 - Movement - 15.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting						

B00E - R0006 - Distribution Board - .76 m2

Note: No inspection of live electrical installation

No Asbestos

B00F - General Learning/Tiered Learning - 1941 - Brick/Block**Exterior**

Ceiling Voids	Requires Inspection						
Eaves Linings	Flat AC Sheeting	16m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found						
Window	Mastic						
Ceiling Voids - Pitched Roof	No Asbestos Found						

Interior**B00F - R0001 - Special Programs Room - 42.12 m2**

No Asbestos

B00F - R0002 - Special Programs Store - 2.45 m2

No Asbestos

B00F - R0003 - Movement - 2.31 m2

Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						

B00F - R0004 - Home Base - 59.6 m2

No Asbestos

B00F - R0005 - Home Base - 57.48 m2

No Asbestos

B00F - R0006 - Home Base Store - 6.04 m2

No Asbestos

B00F - R0007 - Personal Effects Storage - 14.29 m2

Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						

B00F - R0008 - Home Base Store - 6.05 m2

No Asbestos

B00F - R0009 - Home Base - 57.07 m2

No Asbestos

B00F - R0010 - Home Base - 57.31 m2

No Asbestos

B00F - R0011 - Home Base Store - 6.01 m2

No Asbestos

B00F - R0012 - Personal Effects Storage - 3.59 m2

Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						

B00F - R0013 - Cleaning Distributed Store - 1.95 m2

Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						

B00F - R0014 - Movement - 14.71 m2

Floor Coverings Res/Textile	Vinyl Sheet						
-----------------------------	-------------	--	--	--	--	--	--

Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00F - R0015 - General Storeroom - 2.29 m2							
No Asbestos							
B00F - R0016 - General Storeroom - 1.91 m2							
No Asbestos							
B00F - R0017 - Staff Study - 16.68 m2							
No Asbestos							
B00F - R0018 - Movement - 93.06 m2							
Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00G - General Learning - 1941 - Brick/Block							
Exterior							
Ceiling Voids	Requires Inspection						
Ceiling Voids - Pitched Roof	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Window	Mastic						
Interior							
B00G - R0001 - Home Base - 46.57 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	45.66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive	46.55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G - R0002 - Cleaning Distributed Store - 1.89 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00G - R0003 - Home Base - 46.67 m2							
No Asbestos							
B00G - R0004 - Home Base - 46.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive	46.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G - R0005 - Home Base Store - 5.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	5.04m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G - R0006 - Staff Toilet - 5.04 m2							
No Asbestos							
B00G - R0007 - Home Base - 55.67 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00G - R0008 - Home Base Store - 3.77 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	3.76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G - R0009 - Home Base - 46.6 m2							

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G- R0010 - Special Programs Room - 46.69 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G- R0011 - Handwashing Facilities - 2.57 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00G- R0012 - Movement - 99.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet						
B00G- R0013 - Movement - 1.43 m2							
No Asbestos							
B00G- R0014 - Movement - 1.47 m2							
No Asbestos							
B00G- R0015 - Movement - 1.93 m2							
No Asbestos							
B00G- R0016 - Darkroom Space - 9.09 m2							
No Asbestos							
B00G- R0017 - Home Base - 58.14 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58.11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G- R0018 - Practical Activities - 1hb - 16.84 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00G- R0019 - Staff Room Annexe - 9.28 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9.27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00G- R0020 - Interview - 9 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8.99m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00H - Administration - 1969 - Brick/Block							
Exterior							
Underfloor Voids	Requires Inspection						
Ceiling Voids	Requires Inspection						
Wall Linings Internal - Infill	Compressed AC Sheet	16	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab On Ground	No Asbestos Found						
Ceiling Voids - Pitched Roof	No Asbestos Found						

Interior							
B00H - R0001 - Movement - 40.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Interview - 14.84 m2							
No Asbestos							
B00H - R0003 - Sick Bay - 10.15 m2							
No Asbestos							
B00H - R0004 - Movement - 27.83 m2							
No Asbestos							
B00H - R0005 - Principal - 21.04 m2							
No Asbestos							
B00H - R0006 - Staff Toilet - 3.29 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0007 - Staff Toilet - 5.68 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0008 - Cleaning Distributed Store - 1.61 m2							
No Asbestos							
B00H - R0009 - Distribution Board - .86 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00H - R0010 - Clerical Office - 14.04 m2							
No Asbestos							
B00H - R0011 - General Storeroom - 10.8 m2							
No Asbestos							
B00H - R0012 - Clerical Office/Workroom - 12.19 m2							
No Asbestos							
B00H - R0013 - Staff Study - 49.65 m2							
No Asbestos							
B00H - R0014 - Movement - 40.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - Pupil Facilities/General Learning - 1969 - Brick/Block							
Exterior							
Wall Cladding	Flat AC Sheeting						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	Requires Inspection						
Wall Linings Internal - Infill	Compressed AC Sheet						
Ceiling Voids - Pitched Roof	No Asbestos Found						
Interior							
B00I - R0001 - Toilets - Girls - 31.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00I - R0002 - General Storeroom - 3.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00I - R0003 - Toilets - Boys - 29.56 m2							

Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00I - R0004 - General Storeroom - 3.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00I - R0005 - Home Base - 50.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00I - R0006 - General Storeroom - 14.34 m2							
No Asbestos							
B00I - R0007 - Staff Toilet - 3.93 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00I - R0008 - General Storeroom - 17.81 m2							
No Asbestos							
B00I - R0009 - General Storeroom - 2.84 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00I - R0010 - General Storeroom - 3.36 m2							
Electrical - Mounting Board	Fibrous Membrane	1	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00J - Pupil Facilities - 1975 - Brick/Block							
Exterior							
Wall Cladding	Flat AC Sheeting						
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	East, West	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Interior							
B00J - R0001 - Toilets - Girls - 38.76 m2							
Wall Linings Internal	Flat AC Sheeting	6m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0002 - Cleaning Distributed Store - 4.57 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0003 - Toilets - Boys - 28.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00J - R0004 - General Storeroom - 4.09 m2							
Ceiling Structures/Linings	Fibre Cement Pipe	4.09m2	Throughout	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00J - R0005 - General Assistant/Bulk Store - 43.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0006 - General Assistant/Bulk Store - 15.49 m2							
No Asbestos							
B00J - R0007 - Sports Store - 15.51 m2							
No Asbestos							
B00L - Shed - 1969 - Metal Shed							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00L - R0001 - General Storeroom - 19.92 m2							
No Asbestos							
B00M - Shed - 1969 - Metal Shed							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00M - R0001 - General Storeroom - 42.62 m2							
No Asbestos							
B00N - Other-Community Use - 1965 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Wall Cladding	Flat AC Sheeting						
Interior							
B00N - R0001 - Other-Community Use - 3.96 m2							
No Asbestos							
B00N - R0002 - Other-Community Use - 3.65 m2							
No Asbestos							
B00N - R0003 - Other-Community Use - 8.31 m2							
No Asbestos							
B00N - R0004 - Other-Community Use - 8.6 m2							
No Asbestos							
B00N - R0005 - Other-Community Use - 23.03 m2							
No Asbestos							
B00N - R0006 - Other-Community Use - 3.67 m2							
No Asbestos							
B00N - R0007 - Other-Community Use - 11.34 m2							
No Asbestos							
B00P - Shed - 1999 - Metal Shed							
Exterior							

Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00P - R0001 - Sports Store - 24.37 m2		
No Asbestos		
B00R - Communal Facilities - 2011 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00R - R0001 - No Access - 7.4 m2		
No Asbestos		
B00R - R0002 - Distribution Board - 3.29 m2		Note: No inspection of live electrical installation
No Asbestos		
B00R - R0003 - Cleaning Distributed Store - 3.46 m2		
No Asbestos		
B00R - R0004 - Plant - 1.6 m2		
No Asbestos		
B00R - R0005 - Movement - 3.45 m2		
No Asbestos		
B00R - R0006 - Toilets - Boys - 5.62 m2		
No Asbestos		
B00R - R0007 - Sound Cupboard - 2.16 m2		
No Asbestos		
B00R - R0008 - Movement - 2.48 m2		
No Asbestos		
B00R - R0009 - Toilets - Girls - 7.2 m2		
No Asbestos		
B00R - R0010 - P.E Store - 16.25 m2		
No Asbestos		
B00R - R0011 - Communal/Performance Store - 10.33 m2		
No Asbestos		
B00R - R0012 - No Access - 11.81 m2		
No Asbestos		
B00R - R0013 - Communal Space - 295.18 m2		
No Asbestos		
B00R - R0014 - External Movement - 65.2 m2		
No Asbestos		
B00R - R0015 - External Movement - 7.13 m2		
No Asbestos		

Demountables

OS 520 10752 - Staff Study - Placement Date : 26-SEP-1996

Exterior

Eaves Linings	Flat AC Sheeting	8.64m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Staff Room

End Wall Panel	Flat AC Sheeting	50m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

OS 810 13049 - FSU/Shelter/Stores - Placement Date : 14-DEC-1995

Exterior

Eaves Linings	Flat AC Sheeting	25.92m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Canteen

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Assumed Asbestos

R2- Covered Area

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	109m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Assumed Asbestos
----------------------------	------------------	-----	------------------

R4- Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R5- Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
----------------------------	------------------	-----	------------------

R6- Change Room

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos
----------------------------	------------------	-----	------------------

R7- Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Assumed Asbestos
----------------------------	------------------	-----	------------------