

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Frederickton Public School (1943)
Region:	North Coast AMU
State Electorate:	Oxley
Local Government Area:	Kempsey

Last Reviewed By:	Greencap 14-APR-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B001 - General Learning - 1880 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B001 - R0003 - General Storeroom - 1.77 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B001 - R0004 - Cleaning Supplies - .92 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B001 - R0007 - Movement - 21.17 m2							
No Asbestos							
B001 - R0011 - Movement - 16.22 m2							
No Asbestos							
B001 - R0012 - Reading Area - 108.78 m2							
No Asbestos							
B001 - R0013 - Staff Toilet - 2.68 m2							
No Asbestos							
B001 - R0014 - External Movement - 4.27 m2							
No Asbestos							
B001 - R0015 - Special Programs Room - 25.86 m2							
No Asbestos							
B001 - R0016 - K.L.A. Store - 14.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet						
B001 - R0017 - Movement - 23.09 m2							
No Asbestos							
B002 - Pupil Facilities - 1975 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting						
Interior							
B002 - R0001 - Toilets - Boys - 11.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B002 - R0002 - Toilets - Boys - 1.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B002 - R0003 - Toilets - Girls - 1.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B002 - R0004 - Toilets - Girls - 7.44 m2							

Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Plant / Equipment - Flue	Fibre Cement Moulded	4	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B002 - R0005 - External Movement - 26.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B003 - General Learning - 1877 - Timber							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B003 - R0001 - Movement - 80.49 m2							
No Asbestos							
B003 - R0002 - General Storeroom - 8.09 m2							
No Asbestos							
B003 - R0003 - P.E Store - 4.7 m2							
No Asbestos							
B005 - Administration - 1880 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Plumbing / Pipework	Fibre Cement Pipe	4	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Interior							
B005 - R0001 - Movement - 9.14 m2							
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B005 - R0002 - Entry Vestibule - 6.62 m2							
No Asbestos							
B005 - R0003 - Clerical Office - 14.28 m2							
No Asbestos							
B005 - R0006 - General Storeroom - 3.5 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet						
B005 - R0007 - Staff Shower/Change - 5.88 m2							
No Asbestos							
B005 - R0008 - Cleaning Supplies - 12.18 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting						

B005 - R0010 - Sick Bay - 10.71 m2		
No Asbestos		
B005 - R0011 - Staff Toilet - 3.04 m2		
No Asbestos		
B005 - R0012 - Duplicating Workroom - 16.92 m2		
No Asbestos		
B005 - R0014 - Interview - 15.55 m2		
No Asbestos		
B005 - R0015 - Principal - 19.91 m2		
No Asbestos		
B005 - R0016 - Sick Bay - 7.46 m2		
Floor Coverings Res/Textile	Vinyl Sheet	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	
B005 - R0017 - Movement - 5.66 m2		
No Asbestos		
B005 - R0018 - Clerical Office - 13.94 m2		
No Asbestos		
B005 - R0019 - Movement - 5.53 m2		
No Asbestos		
B005 - R0020 - Toilet - Lobby - 5.72 m2		
No Asbestos		
B006 - Building Services - 1984 - Timber Shed		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
Interior		
B006 - R0001 - Cleaning Distributed Store - 20.13 m2		
No Asbestos		
B00C - Staff Facilities/Administration - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00C - R0001 - Distribution Board Cupboard - 3.36 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0002 - Staff Toilet - 4.07 m2		
No Asbestos		
B00C - R0003 - Staff Toilet - 4.04 m2		
No Asbestos		
B00C - R0004 - Security Store - 15.59 m2		
No Asbestos		
B00C - R0005 - Deputy Principal - 17.95 m2		
No Asbestos		
B00C - R0006 - Movement - 19.39 m2		
No Asbestos		

B00C - R0008 - Staff Room Annexe - 26.23 m2		
No Asbestos		
B00C - R0009 - External Movement - 4.37 m2		
No Asbestos		
B00C - R0010 - External Movement - 51.65 m2		
No Asbestos		
B00C - R0011 - Staff Kitchen - 6.84 m2		
No Asbestos		
B00C - R0012 - Staff Room - 44.77 m2		
No Asbestos		
B00D - General Learning - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0001 - Practical Activities - 1hb - 16.2 m2		
No Asbestos		
B00D - R0002 - Movement - 3.99 m2		
No Asbestos		
B00D - R0003 - Home Base Store - 6.27 m2		
No Asbestos		
B00D - R0004 - Home Base - 63.36 m2		
No Asbestos		
B00D - R0005 - Withdrawal Space - 2hb - 11.19 m2		
No Asbestos		
B00D - R0006 - Movement - 3.95 m2		
No Asbestos		
B00D - R0007 - Practical Activities - 1hb - 15.65 m2		
No Asbestos		
B00D - R0008 - Home Base - 63.13 m2		
No Asbestos		
B00D - R0009 - Home Base Store - 6.3 m2		
No Asbestos		
B00D - R0010 - Practical Activities - 1hb - 15.66 m2		
No Asbestos		
B00D - R0011 - Movement - 3.99 m2		
No Asbestos		
B00D - R0012 - Home Base Store - 6.27 m2		
No Asbestos		
B00D - R0013 - Home Base - 62.93 m2		
No Asbestos		
B00D - R0014 - Withdrawal Space - 2hb - 9.81 m2		
No Asbestos		
B00D - R0015 - Movement - 3.99 m2		
No Asbestos		
B00D - R0016 - Practical Activities - 1hb - 16.21 m2		
No Asbestos		
B00D - R0017 - Home Base - 63.14 m2		
No Asbestos		
B00D - R0018 - Home Base Store - 6.28 m2		

No Asbestos		
B00D - R0019 - Distribution Board Cupboard - .63 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0020 - External Movement - 143.24 m2		
No Asbestos		
B00E - General Learning - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00E - R0001 - Practical Activities - 1hb - 15.78 m2		
No Asbestos		
B00E - R0002 - Movement - 4.01 m2		
No Asbestos		
B00E - R0003 - Home Base Store - 6.21 m2		
No Asbestos		
B00E - R0004 - Home Base - 62.65 m2		
No Asbestos		
B00E - R0005 - Withdrawal Space - 2hb - 11.21 m2		
No Asbestos		
B00E - R0006 - Movement - 3.99 m2		
No Asbestos		
B00E - R0007 - Practical Activities - 1hb - 15.83 m2		
No Asbestos		
B00E - R0008 - Home Base - 62.58 m2		
No Asbestos		
B00E - R0009 - Home Base Store - 5.93 m2		
No Asbestos		
B00E - R0010 - Distribution Board Cupboard - .66 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0011 - Special Programs Store - 9.09 m2		
No Asbestos		
B00E - R0012 - Special Programs Room - 40.11 m2		
No Asbestos		
B00E - R0013 - Practical Activities - 1hb - 15.73 m2		
No Asbestos		
B00E - R0014 - Movement - 3.99 m2		
No Asbestos		
B00E - R0015 - Home Base Store - 6.22 m2		
No Asbestos		
B00E - R0016 - Home Base - 62.72 m2		
No Asbestos		
B00E - R0017 - Withdrawal Space - 2hb - 11.25 m2		
No Asbestos		
B00E - R0018 - Movement - 3.99 m2		
No Asbestos		
B00E - R0019 - Practical Activities - 1hb - 15.86 m2		
No Asbestos		
B00E - R0020 - Home Base - 62.64 m2		
No Asbestos		

B00E - R0021 - Home Base Store - 6.26 m2		
No Asbestos		
B00E - R0022 - Movement - 96.21 m2		
No Asbestos		
B00F - Multi Purpose Facilities/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Canteen - 32.17 m2		
No Asbestos		
B00F - R0002 - Canteen Office/Store - 8.93 m2		
No Asbestos		
B00F - R0003 - Maintenance Bulk Store - 14.4 m2		
No Asbestos		
B00F - R0004 - Chair Store - 10.1 m2		
No Asbestos		
B00F - R0005 - Raised Platform - 51.15 m2		
No Asbestos		
B00F - R0006 - Communal Space - 146.72 m2		
No Asbestos		
B00F - R0007 - Performance Store - 9.07 m2		
No Asbestos		
B00F - R0008 - Cleaning Distributed Store - 2.58 m2		
No Asbestos		
B00F - R0009 - Cleaning Distributed Store - 6.56 m2		
No Asbestos		
B00F - R0010 - P.E Store - 12.91 m2		
No Asbestos		
B00F - R0011 - Toilets - Girls - 31.58 m2		
No Asbestos		
B00F - R0012 - Servery Covered Area - 18.96 m2		
No Asbestos		
B00F - R0013 - Movement - 13.3 m2		
No Asbestos		
B00F - R0014 - Toilets - Boys - 23.01 m2		
No Asbestos		
B00F - R0015 - Communications Cupboard - 2.28 m2		
No Asbestos		
B00F - R0016 - Toilets-Disabled - 5.68 m2		
No Asbestos		
B00F - R0017 - Main Switch Board - 1.51 m2		
No Asbestos		
B00F - R0018 - Canteen Covered Area - 148.54 m2		
No Asbestos		
B00F - R0019 - Movement - 40.72 m2		
No Asbestos		
B00F - R0020 - Movement - 6.48 m2		
No Asbestos		
B00F - R0021 - Movement - 74.7 m2		

No Asbestos	
-------------	--

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020