

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Figtree Public School (3964)
Region:	Southern NSW AMU
State Electorate:	Keira
Local Government Area:	Wollongong

Last Reviewed By:	AECOM 18-JUN-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

3964 - Figtree Public School
Site Plan (13344)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Support Unit - 1979 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0002 - Community Clinic - 21.68 m2							
No Asbestos							
B00A - R0005 - External Movement - 17.66 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0006 - External Movement - 37.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0007 - External Movement - 21.18 m2							
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0008 - Covered Outdoor Learning Area - P - 18.34 m2							
No Asbestos							
B00A - R0009 - Staff Room - 51.62 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0010 - Staff Toilet - 6.34 m2							
No Asbestos							
B00A - R0011 - Movement - 5.23 m2							
No Asbestos							
B00A - R0012 - General Assistant/Bulk Store - 25.74 m2							
No Asbestos							
B00A - R0013 - Duplicating Workroom - 22.47 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0014 - Movement - 33.61 m2							
No Asbestos							
B00A - R0015 - Distribution Board - .71 m2							
No Asbestos							
B00A - R0016 - Staff Toilet - 6.3 m2							
No Asbestos							
B00A - R0017 - Sick Bay - 8.55 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0018 - Interview - 12.85 m2							
No Asbestos							
B00A - R0019 - Deputy Principal - 12.92 m2							
No Asbestos							
B00A - R0020 - Cleaning Distributed Store - 3.29 m2							
No Asbestos							
B00A - R0021 - Principal - 21.76 m2							
No Asbestos							
B00A - R0022 - Entry Vestibule - 13.3 m2							
No Asbestos							

Note: No inspection of live electrical installation

B00A - R0023 - Clerical Office - 14.27 m2							
No Asbestos							
B00A - R0024 - External Movement - 19.89 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0025 - Special Programs Room - 29.44 m2							
No Asbestos							
B00B - General Learning/Support Unit - 1979 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00B - R0001 - External Movement - 55.71 m2							
Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0002 - Toilets - Boys - 8.88 m2							
No Asbestos							
B00B - R0003 - Toilets - Girls - 9.27 m2							
No Asbestos							
B00B - R0004 - Home Base - 90.72 m2							
No Asbestos							
B00B - R0005 - Practical Activities - 1hb - 18.02 m2							
No Asbestos							
B00B - R0006 - General Storeroom - 14.47 m2							
No Asbestos							
B00B - R0007 - Movement - 92.16 m2							
No Asbestos							
B00B - R0008 - Security Store - 12.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0009 - Security Store - 12.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0010 - Movement - 5.88 m2							
No Asbestos							
B00B - R0011 - Laundry - P - 5.22 m2							
No Asbestos							
B00B - R0012 - Toilet - P - 9.12 m2							
No Asbestos							
B00B - R0013 - Distribution Board - .62 m2							
No Asbestos							
B00B - R0014 - Toilet - P - 16.39 m2							
No Asbestos							
B00B - R0015 - Toilet - P - 15.32 m2							
No Asbestos							
B00B - R0016 - Cleaning Distributed Store - 3.57 m2							
No Asbestos							
B00B - R0017 - Toilet - P - 15.11 m2							
No Asbestos							

Note: No inspection of live electrical installation

No Asbestos							
B00B - R0018 - Toilet - P - 16.23 m2							
No Asbestos							
B00B - R0019 - Therapy - 107.19 m2							
No Asbestos							
B00B - R0020 - Wheelchair Store - 18.36 m2							
No Asbestos							
B00B - R0021 - Practical Activities - 1hb - 33.71 m2							
No Asbestos							
B00B - R0022 - Teachers Aide Special Ed - 13.25 m2							
No Asbestos							
B00B - R0023 - Movement - 28.43 m2							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0024 - Movement - 3.34 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0025 - External Movement - 71.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0026 - External Movement - 29.92 m2							
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0027 - External Movement - 16.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0028 - External Movement - 16.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0029 - Home Base - 70.67 m2							
No Asbestos							
B00B - R0030 - Practical Activities - 1hb - 17.97 m2							
No Asbestos							
B00B - R0031 - Withdrawal Space - 1hb - 9.18 m2							
No Asbestos							
B00B - R0032 - Practical Activities - 1hb - 17.91 m2							
No Asbestos							
B00B - R0033 - Staff Room Annexe - 5.43 m2							
No Asbestos							
B00B - R0034 - Home Base - 74.38 m2							
No Asbestos							
B00B - R0035 - External Movement - 26.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0036 - Covered Vehicle Area/Porte Cochere - 36.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - Communal Facilities - 1979 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids - Raked Ceiling	Non Accessible Area						

Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00C - R0001 - External Movement - 44.57 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0002 - Communal Space - 157.44 m2							
No Asbestos							
B00C - R0003 - Hall Chair Store - 9.53 m2							
No Asbestos							
B00C - R0004 - Distribution Board - .75 m2							
No Asbestos							
B00C - R0005 - Sports Store - 28.8 m2							
No Asbestos							
B00C - R0006 - Raised Platform - 42.36 m2							
No Asbestos							
B00C - R0007 - Movement - 27.58 m2							
No Asbestos							
B00C - R0008 - Canteen - 29.15 m2							
No Asbestos							
B00C - R0009 - Canteen Office/Store - 5.52 m2							
No Asbestos							
B00C - R0010 - Staff Toilet - 4.37 m2							
No Asbestos							
B00C - R0011 - Canteen Office/Store - 2.87 m2							
No Asbestos							
B00C - R0012 - Cleaning Supplies - 8.81 m2							
No Asbestos							
B00C - R0013 - General Assistant/Bulk Store - 7.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0014 - Main Switch Board - 7.29 m2							
Electrical - Mounting Board	Resinous Board	1	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - R0015 - Garden Store - 12.02 m2							
No Asbestos							
B00C - R0016 - Movement - 2.02 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00C - R0017 - Toilets - Boys - 16.07 m2							
No Asbestos							
B00C - R0018 - Toilets - Girls - 12.73 m2							
No Asbestos							
B00C - R0019 - No Access - 3.15 m2							
No Asbestos							
B00C - R0020 - External Movement - 66.01 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00E - General Learning - 1956 - Timber							
Exterior							
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Eaves Linings	Flat AC Sheeting	50m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Requires Inspection						
Interior							
B00E - R0001 - Security Store - 7.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0002 - Movement - 32.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	15m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0003 - Practical Activities - 1hb - 9.33 m2							
No Asbestos							
B00E - R0004 - Practical Activities - 1hb - 12.72 m2							
No Asbestos							
B00E - R0005 - Home Base - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Wall Heater	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0006 - Home Base - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Wall Heater	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0007 - Movement - 8.64 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0008 - Practical Activities - 1hb - 22.11 m2							
No Asbestos							
B00E - R0009 - Home Base - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Wall Heater	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0010 - Movement - 40.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Electrical - Backing Board	Resinous Board	1	Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Electrical - Backing Board	Flat AC Sheeting	2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	15m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0011 - Home Base - 53.58 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Wall Heater	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0012 - Practical Activities - 1hb - 9.3 m2							
No Asbestos							
B00E - R0013 - General Storeroom - 12.81 m2							
No Asbestos							
B00F - General Learning - 1979 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						

Interior						
B00F - R0001 - External Movement - 18.14 m2						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R0002 - Toilets - Boys - 13.8 m2						
No Asbestos						
B00F - R0003 - Toilets - Girls - 12.77 m2						
No Asbestos						
B00F - R0004 - Cleaning Distributed Store - 2.61 m2						
No Asbestos						
B00F - R0005 - Personal Effects Storage - 10.4 m2						
No Asbestos						
B00F - R0006 - Withdrawal Space - 1hb - 16.28 m2						
No Asbestos						
B00F - R0007 - Home Base - 63.75 m2						
No Asbestos						
B00F - R0008 - Home Base Store - 5.85 m2						
Floor Coverings Res/Textile	Vinyl Tiles					
B00F - R0010 - General Storeroom - 12.42 m2						
No Asbestos						
B00F - R0011 - Distribution Board - 1.01 m2						Note: No inspection of live electrical installation
No Asbestos						
B00F - R0012 - Practical Activities - 1hb - 10.5 m2						
No Asbestos						
B00F - R0013 - Kiln Room - 3.03 m2						
No Asbestos						
B00F - R0014 - Home Base - 61.4 m2						
No Asbestos						
B00F - R0015 - Practical Activities - 1hb - 23.03 m2						
No Asbestos						
B00F - R0016 - Personal Effects Storage - 4.23 m2						
No Asbestos						
B00F - R0017 - Movement - 57.58 m2						
No Asbestos						
B00F - R0018 - Practical Activities - 1hb - 4.61 m2						
No Asbestos						
B00F - R0019 - Home Base Store - 5.92 m2						
Floor Coverings Res/Textile	Vinyl Tiles					
B00F - R0020 - Personal Effects Storage - 19.37 m2						
No Asbestos						
B00F - R0021 - Home Base - 64.32 m2						
No Asbestos						
B00F - R0023 - Home Base Store - 5.91 m2						
Floor Coverings Res/Textile	Vinyl Tiles					
B00F - R0024 - Withdrawal Space - 1hb - 13.42 m2						
No Asbestos						
B00F - R0025 - Home Base - 64.4 m2						
No Asbestos						
B00F - R0026 - Home Base Store - 5.69 m2						

Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0028 - Toilet - P - 2.62 m2							
No Asbestos							
B00F - R0029 - Toilet - P - 2.6 m2							
No Asbestos							
B00F - R0030 - General Storeroom - 5.93 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0031 - External Movement - 66.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0032 - Deputy Principal - 13.5 m2							
No Asbestos							
B00F - R0033 - Outdoor Learning Area - 45.16 m2							
Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0034 - External Movement - 126.64 m2							
Ceiling Structures/Linings	Flat AC Sheeting	125m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - General Learning - 1945 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - Home Base - 46.84 m2							
No Asbestos							
B00G - R0002 - Home Base Store - 5.48 m2							
No Asbestos							
B00G - R0003 - External Movement - 7.45 m2							
No Asbestos							
B00G - R0004 - Covered Outdoor Learning Area - 12.74 m2							
No Asbestos							
B00H - General Learning/Building Services - 2010 - Brick/Veneer							
Exterior							
No Asbestos							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00H - R0001 - External Movement - 116.71 m2							
No Asbestos							
B00H - R0002 - Practical Activities/Movement - 1hb - 19.16 m2							
No Asbestos							
B00H - R0003 - Home Base Store - 6.28 m2							
No Asbestos							
B00H - R0004 - Home Base - 60.54 m2							
No Asbestos							
B00H - R0005 - Withdrawal Space - 2hb - 11.71 m2							
No Asbestos							
B00H - R0006 - Home Base - 61.08 m2							

No Asbestos		
B00H - R0007 - Home Base Store - 6.28 m2		
No Asbestos		
B00H - R0008 - Practical Activities/Movement - 1hb - 19.42 m2		
No Asbestos		
B00H - R0009 - Practical Activities/Movement - 1hb - 19.44 m2		
No Asbestos		
B00H - R0010 - Home Base Store - 6.31 m2		
No Asbestos		
B00H - R0011 - Home Base - 61.37 m2		
No Asbestos		
B00H - R0012 - Withdrawal Space - 2hb - 11.73 m2		
No Asbestos		
B00H - R0013 - Home Base - 60.39 m2		
No Asbestos		
B00H - R0014 - Home Base Store - 6.29 m2		
No Asbestos		
B00H - R0015 - Practical Activities/Movement - 1hb - 19.15 m2		
No Asbestos		
B00H - R0016 - Withdrawal Space - 1hb - 8.77 m2		
No Asbestos		
B00H - R0017 - Home Base Store - 5.59 m2		
No Asbestos		
B00H - R0018 - Home Base - 59.05 m2		
No Asbestos		
B00H - R0019 - Practical Activities/Movement - 1hb - 19.26 m2		
No Asbestos		
B00H - R0020 - Garden Store - 12.84 m2		
No Asbestos		
B00H - R0021 - General Assistant/Bulk Store - 15.84 m2		
No Asbestos		
B00H - R0022 - No Access - 12.81 m2		
No Asbestos		
B00L - Library - 2011 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
No Asbestos		
Interior		
B00L - R0001 - Reading Area - 167.98 m2		
No Asbestos		
B00L - R0002 - Library Office/Workroom - 24.11 m2		
No Asbestos		
B00L - R0003 - Communications Room - 8.1 m2		
No Asbestos		
B00L - R0004 - K.L.A. Store - 14.84 m2		
No Asbestos		
B00L - R0005 - Movement - 2.47 m2		
No Asbestos		
B00L - R0006 - Cleaning Distributed Store - 3.69 m2		

No Asbestos	
B00L - R0007 - Staff Toilet - 4.79 m2	
No Asbestos	
B00L - R0008 - Distribution Board - .61 m2	Note: No inspection of live electrical installation
No Asbestos	
B00L - R0009 - External Movement - 47.43 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020