

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Figtree High School (8449)
Region:	Southern NSW AMU
State Electorate:	Keira
Local Government Area:	Wollongong

Last Reviewed By:	WSP 25-JUL-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1969 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00A - R0001 - Deputy Principal Office - 16.33 m2							
No Asbestos							
B00A - R0002 - Staff Study - 12.39 m2							
No Asbestos							
B00A - R0003 - Staff Study - 13.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles	13.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0004 - Staff - Toilet - 3.33 m2							
No Asbestos							
B00A - R0005 - General Storeroom - 3.15 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0006 - Principal Office - 16.18 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0012 - Interview/Office - Type 1 - 13.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles	13.79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0013 - Clinic - Boys - 13.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0014 - Clinic - Boys - 13.94 m2							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0015 - Staff - Toilet - 9.64 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0016 - Staff - Toilet - 1.91 m2							
No Asbestos							
B00A - R0017 - Staff - Toilet - 8.02 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0020 - Staff Study - 13.74 m2							
No Asbestos							
B00A - R0021 - Pupil Entry - 27.23 m2							
No Asbestos							
B00A - R0025 - Administration - Clerical - 55.02 m2							
No Asbestos							
B00A - R0026 - Interview/Meeting - 17.03 m2							
No Asbestos							
B00A - R0027 - Public Reception - 20.63 m2							
No Asbestos							
B00A - R0028 - Movement - 80.49 m2							

No Asbestos								
B00A - R0029 - External Movement - 13.46 m2								
No Asbestos								
B00B - Art - 1968 - Timber								
Exterior								
Underfloor Voids	Flat AC Sheeting							
Ceiling Voids	Non Accessible Area							
Interior								
B00B - R0001 - Art Learning Space - 94.89 m2								
Wall Linings Internal - Infill	Compressed AC Sheet	3m2	North-east	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00B - R0002 - Bulk Store - 13.3 m2								
No Asbestos								
B00B - R0003 - Movement - 13.31 m2								
No Asbestos								
B00D - Music/Art - 1969 - Brick/Block								
Exterior								
Underfloor Voids - Slab on Ground	Non Accessible Area							
Ceiling Voids	Non Accessible Area							
Interior								
B00D - R0001 - Food Technology L.S. - 87.7 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)							
B00D - R0002 - Movement - 87.19 m2								
Floor Coverings Res/Textile	Vinyl Tiles	88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0007 - Plant - .67 m2								
No Asbestos								
B00D - R0009 - Staff Study - 4.74 m2								
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00D - R0010 - Cleaning Store - Distributed - 4.71 m2								
No Asbestos								
B00D - R0011 - General Storeroom - 9.56 m2								
No Asbestos								
B00D - R0013 - Cleaning Store - Distributed - 8.57 m2								
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0014 - Staff Study - 32.66 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
B00D - R0016 - Toilets-Girls - 65.73 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Wall Linings Internal	Flat AC Sheeting							
Partition Walls (Cubides)	Compressed AC Sheet	35m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0017 - Distribution Board Cupboard - 1.58 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00D - R0020 - Stairs - 2.49 m2								
No Asbestos								

B00D - R0021 - Movement - 7.74 m2							
No Asbestos							
B00D - R0022 - General Storeroom - 5.24 m2							
No Asbestos							
B00D - R0023 - Movement - 63.42 m2							
No Asbestos							
B00D - R0024 - Stairs - 9.34 m2							
No Asbestos							
B00D - R0025 - Movement - 24.37 m2							
No Asbestos							
B00D - R0026 - Movement - 19.13 m2							
No Asbestos							
B00D - R0027 - Movement - 1.67 m2							
No Asbestos							
B00D - R0028 - Store - 2.69 m2							
No Asbestos							
B00D - R0029 - Store - 19.51 m2							
No Asbestos							
B00D - R0030 - Kitchen - Type 1 - 80.38 m2							
No Asbestos							
B00D - R0031 - Pantry - 12.57 m2							
No Asbestos							
B00D - R0032 - Preparation - 18.46 m2							
No Asbestos							
B00D - R0033 - Store - 6.15 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R0034 - Practical Activities - 65.29 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00D - R0035 - Practical Activities - 12.47 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	12.47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0036 - Kitchen - Type 2 - 9.14 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00D - R1001 - Music Learning Space - 65.07 m2							
No Asbestos							
B00D - R1002 - General Storeroom - 10.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1003 - Design L.S. - 65.66 m2							
No Asbestos							
B00D - R1004 - Staff Study - 31.97 m2							
No Asbestos							
B00D - R1005 - Movement - .71 m2							
No Asbestos							
B00D - R1006 - Practice/Seminar - 65.29 m2							
No Asbestos							
B00D - R1007 - Music Learning Space - 65.47 m2							
No Asbestos							
B00D - R1008 - Art Learning Space - 65.41 m2							

Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R1009 - Resources Store - 14.29 m2								
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R1010 - Design L.S. - 65.31 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00D - R1011 - Distribution Board Cupboard - 1.24 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00D - R1012 - Cleaning Store - Distributed - .89 m2								
No Asbestos								
B00D - R1014 - Materials Store - 4.39 m2								
No Asbestos								
B00D - R1015 - Movement - 61.13 m2								
Floor Coverings Res/Textile	Vinyl Tiles	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R1016 - Movement - 31.11 m2								
No Asbestos								
B00D - R1017 - Stairs - 6.48 m2								
No Asbestos								
B00D - R1018 - Movement - 54.4 m2								
No Asbestos								
B00D - R1019 - Stairs - 13.99 m2								
No Asbestos								
B00D - R1020 - General Storeroom - .77 m2								
No Asbestos								
B00D - R1021 - General Storeroom - 1.63 m2								
No Asbestos								
B00D - R1022 - Visual Arts Store - 1.17 m2								
No Asbestos								
B00E - Multi Purpose Facilities - 2007 - Brick/Veneer								
Exterior								
Underfloor Voids - Slab on Ground	Non Accessible Area							
Ceiling Voids	Non Accessible Area							
Interior								
B00E - R0001 - Gymnasium - 623.33 m2								
No Asbestos								
B00E - R0002 - Large Equipment Store - 25.4 m2								
No Asbestos								
B00E - R0003 - Chair Store - 34.44 m2								
No Asbestos								
B00E - R0004 - Stairs - 2.47 m2								
No Asbestos								
B00E - R0005 - Stage - 86.41 m2								
No Asbestos								
B00E - R0006 - Stairs - 2.77 m2								
No Asbestos								
B00E - R0007 - Lift - 3.34 m2								
No Asbestos								
B00E - R0008 - Movement - 14.65 m2								
No Asbestos								

B00E - R0009 - Change - 27.67 m2		
No Asbestos		
B00E - R0010 - Change - 27.81 m2		
No Asbestos		
B00E - R0011 - Cleaning Store - Distributed - 6.98 m2		
No Asbestos		
B00E - R0012 - Movement - 3.07 m2		
No Asbestos		
B00E - R0013 - Access Student Shower/Toilet - Type 2 - 5.43 m2		
No Asbestos		
B00E - R0014 - Toilets-Boys - 20.77 m2		
No Asbestos		
B00E - R0015 - Control Room - 15.09 m2		
No Asbestos		
B00E - R0016 - Distribution Board Cupboard - .74 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0017 - Movement - 18.74 m2		
No Asbestos		
B00E - R0018 - Toilets-Girls - 26.52 m2		
No Asbestos		
B00E - R0019 - External Movement - 146.88 m2		
No Asbestos		
B00E - R0020 - External Movement - 3.19 m2		
No Asbestos		
B00E - R0021 - External Movement - 3.11 m2		
No Asbestos		
B00E - R0022 - External Movement - 3.15 m2		
No Asbestos		
B00E - R0023 - External Movement - 3.15 m2		
No Asbestos		
B00F - Building Services - 2007 - Steel		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
Interior		
B00F - R0001 - General Assistants - 34.13 m2		
No Asbestos		
B00F - R0002 - General Assistants - 6.28 m2		
No Asbestos		
B00F - R0003 - General Storeroom - 5.45 m2		
No Asbestos		
B00F - R0004 - General Storeroom - 5.45 m2		
No Asbestos		
B00M - Technological & Applied Studies - 1969 - Brick/Block		
Exterior		
Ceiling Voids	Non Accessible Area	
Interior		
B00M - R0001 - Materials Technology L.S. - 81.9 m2		
No Asbestos		
B00M - R0002 - Distribution Board Cupboard - 2.7 m2		Note: No inspection of live electrical installation

No Asbestos							
B00M - R0003 - Cleaning Store - Distributed - 1.66 m2							
No Asbestos							
B00M - R0004 - No Access - 67.28 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
Wall Linings Internal	Flat AC Sheeting						
B00M - R0005 - Movement - 37.84 m2							
Floor Coverings Res/Textile	Vinyl Tiles	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00M - R0006 - Kiln Space - 79.3 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Floor Coverings Res/Textile	Vinyl Tiles	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R0007 - Resources Store - 4.88 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R0012 - Resources Store - .81 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R0013 - General Storeroom - 5.18 m2							
No Asbestos							
B00M - R0014 - Movement - 63.9 m2							
No Asbestos							
B00M - R0015 - Stairs - 9.26 m2							
No Asbestos							
B00M - R0016 - Metal Technology Bay - 102.39 m2							
No Asbestos							
B00M - R0017 - Project Store - Type 1 - 10.39 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00M - R0018 - Store - 6.6 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00M - R0019 - Welding Area - 4.37 m2							
No Asbestos							
B00M - R0020 - Welding Area - 4.38 m2							
No Asbestos							
B00M - R0021 - Welding Area - 4.4 m2							
No Asbestos							
B00M - R0022 - Covered Area - 83.02 m2							
No Asbestos							
B00M - R0023 - Store - 18.37 m2							
No Asbestos							
B00M - R1001 - Workshop Area - 82.73 m2							
No Asbestos							
B00M - R1002 - General Storeroom - 12.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R1003 - Materials Technology L.S. - 52.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles						

B00M - R1004 - Movement - 53.41 m2							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R1005 - Staff Study - 25.88 m2							
No Asbestos							
B00M - R1006 - Computer Learning Space - 47.34 m2							
No Asbestos							
B00M - R1007 - Materials Store - 12.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R1008 - Materials Technology L.S. - 82.64 m2							
No Asbestos							
B00M - R1009 - Materials Store - 21.39 m2							
No Asbestos							
B00M - R1011 - Cleaning Store - Distributed - .64 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00M - R1012 - Distribution Board Cupboard - .8 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00M - R1013 - Computer Store - 5.01 m2							
No Asbestos							
B00M - R1015 - Dust Extraction Space - 9.8 m2							
No Asbestos							
B00M - R1016 - Movement - 54.26 m2							
No Asbestos							
B00M - R1017 - Stairs - 13.97 m2							
No Asbestos							
B00S - Pupil Facilities/Physical Education - 1969 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00S - R0001 - Gymnasium - 308.68 m2							
No Asbestos							
B00S - R0002 - Student Canteen - 79.16 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00S - R0003 - Sport Equipment Store - 15.97 m2							
No Asbestos							
B00S - R0004 - Office/Store - 16.97 m2							
No Asbestos							
B00S - R0005 - Office/Store - 6.52 m2							
No Asbestos							
B00S - R0006 - Main Switchroom - 9.92 m2							
No Asbestos							
B00S - R0007 - Student Canteen - 48.24 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00S - R0008 - Staff - Toilet - 3.4 m2							
No Asbestos							
B00S - R0009 - Cleaning Supplies Store - 6.15 m2							
No Asbestos							

B00S - R0010 - Sport Equipment Store - 16.74 m2								
No Asbestos								
B00S - R0011 - Staff - Toilet - 3.21 m2								
No Asbestos								
B00S - R0012 - Chair Store - 19.3 m2								
No Asbestos								
B00S - R0013 - Distribution Board Cupboard - .56 m2						Note: No inspection of live electrical installation		
No Asbestos								
B00S - R0014 - Cleaning Store - Distributed - .95 m2								
No Asbestos								
B00S - R0015 - Covered Area - 228.43 m2								
No Asbestos								
B00S - R1001 - Main Switchroom - 3.42 m2								
No Asbestos								
B00S - R1002 - Movement - 63.85 m2								
No Asbestos								
B00S - R1003 - Cleaning Store - Distributed - 3.38 m2								
No Asbestos								
B00S - R1004 - Staff Study - 10.65 m2								
No Asbestos								
B00S - R1005 - Staff - Toilet - 7.45 m2								
Partition Walls (Cubides)	Compressed AC Sheet	5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00S - R1006 - Shower/Change - 62.18 m2								
Wall Linings Internal	Flat AC Sheeting							
Partition Walls (Cubides)	Compressed AC Sheet	40m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00S - R1007 - Shower/Change - 62.03 m2								
Wall Linings Internal	Flat AC Sheeting							
Partition Walls (Cubides)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00S - R1008 - Staff - Toilet - 7.24 m2								
Partition Walls (Cubides)	Compressed AC Sheet	5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00S - R1009 - Staff Study - 10.64 m2								
No Asbestos								
B0C1 - Pupil Facilities/General Learning - 1969 - Brick/Block								
Exterior								
Underfloor Voids - Slab on Ground	Non Accessible Area							
Ceiling Voids	Non Accessible Area							
Interior								
B0C1 - R0001 - Administration - Clerical - 7.97 m2								
No Asbestos								
B0C1 - R0002 - Administration - Clerical - 8.03 m2								
No Asbestos								
B0C1 - R0004 - Toilets-Disabled - 3.91 m2								
No Asbestos								
B0C1 - R0005 - Toilets-Disabled - 3.91 m2								
No Asbestos								
B0C1 - R0006 - Cleaning Store - Distributed - 4.46 m2								
No Asbestos								
B0C1 - R0007 - Toilets-Disabled - 48.22 m2								

No Asbestos							
B0C1 - R0008 - General Storeroom - 5.04 m2							
No Asbestos							
B0C1 - R0009 - Clinic-Waiting - 5.85 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B0C1 - R0010 - Staff Study - 26.03 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0C1 - R0014 - General Learning Space - 53.07 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B0C1 - R0015 - General Storeroom - 4.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R0016 - Staff - Toilet - 5.05 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B0C1 - R0017 - Staff - Toilet - 7.05 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R0018 - Darkroom Space - 31.88 m2							
Floor Coverings Res/Textile	Vinyl Tiles	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R0019 - Distribution Board Cupboard - .99 m2 Note: No inspection of live electrical installation							
No Asbestos							
B0C1 - R0020 - Ancillary Staff - 10.99 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0C1 - R0021 - Cleaning Store - Distributed - 2.61 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R0023 - General Storeroom - 8.67 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R0025 - General Storeroom - 17.33 m2							
No Asbestos							
B0C1 - R0027 - Home Base - S - 56.16 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B0C1 - R0028 - Staff Study - 53.37 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B0C1 - R0029 - Stairs - 6.15 m2							
No Asbestos							
B0C1 - R0030 - Movement - 78.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B0C1 - R0031 - General Storeroom - 6.4 m2							
No Asbestos							
B0C1 - R0032 - Covered Vehicle Area/Porte Cochere - 98.85 m2							
No Asbestos							

B0C1 - R0033 - Movement - 8.29 m2							
No Asbestos							
B0C1 - R0034 - Movement - 77.39 m2							
No Asbestos							
B0C1 - R0035 - Stairs - 12.59 m2							
No Asbestos							
B0C1 - R0036 - Commonroom - 104.83 m2							
No Asbestos							
B0C1 - R0037 - Staff Kitchen - 14.66 m2							
No Asbestos							
B0C1 - R0038 - General Learning Space - 39.63 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0C1 - R0039 - Store - 8.15 m2							
No Asbestos							
B0C1 - R1001 - General Learning Space - 53.8 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1002 - Computer Learning Space - 53.59 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1003 - Computer Store - 18.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	18.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1004 - General Learning Space - 53.07 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.06m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.06m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1005 - General Learning Space - 53.28 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1006 - General Storeroom - 18.31 m2							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1008 - General Learning Space - 53.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1009 - Staff Study - 39.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	39.47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	39.47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1010 - Leading Teacher - 11.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	11.08m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11.08m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1012 - Distribution Board Cupboard - 1.23 m2				Note: No inspection of live electrical installation			
No Asbestos							
B0C1 - R1013 - General Learning Space - 53.44 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1014 - General Learning Space - 53.15 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	83.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1015 - Movement - 18.52 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	18.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1016 - Stairs - 15.16 m2							
No Asbestos							
B0C1 - R1017 - Cleaning Distributed Store - 6.17 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1018 - Movement - 26.41 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	26.41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	26.41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C1 - R1019 - Movement - 46.84 m2							
No Asbestos							
B0C1 - R1020 - Stairs - 19.14 m2							
No Asbestos							
B0C2 - General Learning - 1969 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B0C2 - R0001 - General Learning Space - 53.44 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R0002 - General Learning Space - 52.2 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	52.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R0003 - General Storeroom - 11.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R0004 - Performance Workspace - 49.21 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	49.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0008 - Distribution Board Cupboard - .82 m2				Note: No inspection of live electrical installation				
No Asbestos								
B0C2 - R0009 - Toilets-Girls - 6.93 m2								
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B0C2 - R0010 - Staff - Toilet - 5.05 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B0C2 - R0011 - General Storeroom - 4.91 m2								
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0012 - General Learning Space - 53.08 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0013 - General Learning Space - 52.2 m2								
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	52.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B0C2 - R0014 - Duplicating Workroom - 39.33 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	39.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	39.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0015 - General Learning Space - 52.92 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	52.92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0016 - General Storeroom - 31.7 m2								
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	31.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	31.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C2 - R0017 - Movement - 87.27 m2								
Floor Coverings Res/Textile	Vinyl Tiles	88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)							
B0C2 - R0018 - Stairs - 5.24 m2								
No Asbestos								

B0C2 - R0019 - Staff Study - 16.8 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	16.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R0020 - General Storeroom - 6.37 m2							
No Asbestos							
B0C2 - R0021 - Movement - 55.19 m2							
No Asbestos							
B0C2 - R0022 - Stairs - 12.47 m2							
No Asbestos							
B0C2 - R1001 - General Learning Space - 53.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1002 - General Learning Space - 53.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1003 - General Learning Space - 53.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1004 - Movement - 17.39 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	17.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17.39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1005 - General Learning Space - 53.22 m2							
No Asbestos							
B0C2 - R1006 - Distribution Board Cupboard - 1.26 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B0C2 - R1007 - Movement - 27.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	27.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	27.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1008 - Cleaning Store - Distributed - 4.03 m2							
No Asbestos							
B0C2 - R1009 - General Storeroom - 11.05 m2							
No Asbestos							
B0C2 - R1010 - Staff Study - 39.56 m2							
No Asbestos							
B0C2 - R1011 - General Learning Space - 53.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1012 - General Storeroom - 19.15 m2							
No Asbestos							
B0C2 - R1013 - General Learning Space - 53.22 m2							

Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1014 - General Learning Space - 53.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1015 - Staff Study - 19.15 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	19.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C2 - R1016 - Stairs - 15.35 m2							
No Asbestos							
B0C2 - R1017 - Movement - 46.42 m2							
No Asbestos							
B0C2 - R1018 - Stairs - 19.27 m2							
No Asbestos							
B0C3 - General Learning/Library - 1969 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B0C3 - R0003 - Seminar - 53.79 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B0C3 - R0004 - Audio Visual Workroom - 26.07 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0C3 - R0007 - Seminar - 5.64 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B0C3 - R0008 - General Storeroom - 18.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R0009 - Cleaning Store - Distributed - .47 m2							
No Asbestos							
B0C3 - R0010 - Distribution Board Cupboard - .56 m2							
No Asbestos							
B0C3 - R0011 - Toilets-Girls - 14.08 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Wall Linings Internal	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R0012 - General Storeroom - 4.07 m2							
No Asbestos							
B0C3 - R0013 - Cleaning Store - Distributed - 1.26 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R0014 - Toilets-Boys - 11.82 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						

Wall Linings Internal	Flat AC Sheeting							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R0015 - Senior Study - 6.52 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B0C3 - R0016 - Senior Seminar - 6.55 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B0C3 - R0017 - Senior Study - 6.47 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B0C3 - R0018 - Movement - 70.18 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)							
B0C3 - R0019 - General Storeroom - 3.98 m2								
No Asbestos								
B0C3 - R0020 - Interview - 26.28 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
B0C3 - R0021 - Main Area - 269.28 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (> 250 m2) - (X25)							
B0C3 - R0022 - Stairs - 2.26 m2								
No Asbestos								
B0C3 - R0023 - General Storeroom - 5.58 m2								
No Asbestos								
B0C3 - R0024 - Movement - 66.59 m2								
No Asbestos								
B0C3 - R0025 - Stairs - 13.97 m2								
No Asbestos								
B0C3 - R1001 - General Learning Space - 53.58 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1002 - Computer Learning Space - 53.66 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1003 - Computer Store - 18.64 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1004 - General Storeroom - 6.46 m2								
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1005 - Cleaning Store - Distributed - 3.38 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	3.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1006 - Movement - 19.87 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1007 - General Learning Space - 59.69 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0C3 - R1008 - General Learning Space - 59.92 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	

B0C3 - R1009 - General Learning Space - 53.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1010 - Staff Study - 39.94 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	39.93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1012 - Distribution Board Cupboard - .83 m2							
Note: No inspection of live electrical installation							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1013 - Stairs - 10.7 m2							
No Asbestos							
B0C3 - R1014 - Computer Resource - 17.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15.2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1015 - General Learning Space - 52.99 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.99m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1016 - General Learning Space - 53.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1017 - Movement - 19.75 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19.75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0C3 - R1018 - Movement - 61.74 m2							
No Asbestos							
B0C3 - R1019 - Stairs - 20.79 m2							
No Asbestos							
B0L1 - Science Learning - 1969 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B0L1 - R0001 - Computer Learning Space - 91.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	South-west	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B0L1 - R0002 - Apparatus Store - 30.73 m2							
Floor Coverings Res/Textile	Vinyl Tiles	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0L1 - R0003 - Laboratory L.S. - 91.22 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B0L1 - R0004 - Preparation - 13.05 m2							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B0L1 - R0005 - Chemical Store - 3.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0L1 - R0006 - Lift - .25 m2							
No Asbestos							
B0L1 - R0007 - Cleaning Store - Distributed - .67 m2							

No Asbestos							
B0L1 - R0008 - Distribution Board Cupboard - .67 m2							Note: No inspection of live electrical installation
No Asbestos							
B0L1 - R0009 - Movement - 67.17 m2							
No Asbestos							
B0L1 - R1001 - Laboratory L.S. - 91.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0L1 - R1002 - Apparatus Store - 30.73 m2							
No Asbestos							
B0L1 - R1003 - Laboratory L.S. - 91.23 m2							
No Asbestos							
B0L1 - R1004 - Apparatus Store - 13.05 m2							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0L1 - R1005 - Apparatus Store - 3.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0L1 - R1006 - Lift - .25 m2							
No Asbestos							
B0L1 - R1007 - Lift - .67 m2							
No Asbestos							
B0L1 - R1008 - Distribution Board Cupboard - .67 m2							Note: No inspection of live electrical installation
No Asbestos							
B0L1 - R1009 - Movement - 64.55 m2							
No Asbestos							
B0L2 - Science Learning - 1969 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B0L2 - R0001 - Laboratory L.S. - 91.42 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B0L2 - R0005 - Laboratory L.S. - 91.42 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B0L2 - R0006 - Lift - .27 m2							
No Asbestos							
B0L2 - R0007 - Distribution Board Cupboard - .67 m2							Note: No inspection of live electrical installation
No Asbestos							
B0L2 - R0008 - Distribution Board Cupboard - .67 m2							Note: No inspection of live electrical installation
No Asbestos							
B0L2 - R0009 - Cleaning Supplies Store - 10.75 m2							
No Asbestos							
B0L2 - R0010 - Chair Store - 8.26 m2							
No Asbestos							
B0L2 - R0011 - Movement - 1.49 m2							
No Asbestos							
B0L2 - R0012 - Movement - 65.67 m2							
No Asbestos							
B0L2 - R0014 - Movement - 26.51 m2							

No Asbestos								
B0L2 - R0015 - Preparation - Science - 41.98 m2								
Ceiling Structures/Linings	Non Accessible Area	m2						
B0L2 - R0016 - Lift - 1.57 m2								
No Asbestos								
B0L2 - R1001 - Laboratory L.S. - 91.41 m2								
No Asbestos								
B0L2 - R1002 - Staff Study - 48.39 m2								
Floor Coverings Res/Textile	Vinyl Tiles	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0L2 - R1003 - Laboratory L.S. - 91.41 m2								
No Asbestos								
B0L2 - R1004 - Distribution Board Cupboard - .67 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B0L2 - R1005 - Plant - .67 m2								
No Asbestos								
B0L2 - R1006 - Lift - .27 m2								
No Asbestos								
B0L2 - R1009 - Movement - 65.62 m2								
No Asbestos								
B0L2 - R1010 - Movement - 24.36 m2								
No Asbestos								

Demountables

OS 601 12265 - Learning Unit - Standard/Withdrawal - Placement Date : 23-FEB-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

NS 200 12311 - Art Learning Space/Workshop/Bulk Store - Placement Date : 02-FEB-2008

No Asbestos Found

OS 600 12340 - Learning Unit - Small - Placement Date : 02-MAR-2016

No Asbestos Found

NS 110 13424 - Learning Unit - Single Secondary/Secure - Placement Date : 02-FEB-2008

No Asbestos Found

OS 600 16813 - Learning Unit - Small - Placement Date : 17-APR-2012

Exterior

Eaves Linings	Flat AC Sheeting	8.64m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1 - General Learning Space

End Wall Panel	Flat AC Sheeting	50m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos