

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Hammondville Public School (2128)</b>
<b>Region:</b>	<b>South Western Sydney AMU</b>
<b>State Electorate:</b>	<b>Holsworthy</b>
<b>Local Government Area:</b>	<b>Liverpool</b>

<b>Last Reviewed By:</b>	<b>WSP 28-AUG-2015</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

2128 - Hammondville Public School  
Site Plan (12616)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Library - 1958 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Toilets - Girls - 3.11 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0002 - Movement - 1.38 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	Above Door	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0003 - Distribution Board - .75 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	Below Switchboard	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
Door - Lining	Flat AC Sheeting	4	Throughout	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
Material - Stored / Debris Material	Flat AC Sheeting	2	On floor	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)	Chrysotile (white asbestos)
Electrical - Backing Board	Resinous Board	1	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00A - R0004 - Cleaning Distributed Store - 1.87 m2</b>							
No Asbestos							
<b>B00A - R0005 - Toilets - Boys - 3.1 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0006 - Movement - 1.38 m2</b>							
No Asbestos							
<b>B00A - R0007 - Communications Room - 12.6 m2</b>							
No Asbestos							
<b>B00A - R0008 - Communications Room - 12.6 m2</b>							
No Asbestos							
<b>B00A - R0009 - Reading Area - 212.65 m2</b>							
No Asbestos							
<b>B00A - R0010 - Library Office/Workroom - 6.07 m2</b>							
No Asbestos							
<b>B00A - R0011 - Library Office/Workroom - 19.35 m2</b>							
No Asbestos							
<b>B00A - R0012 - Communications Room - 52.5 m2</b>							
No Asbestos							
<b>B00A - R0014 - External Movement - 162.08 m2</b>							
No Asbestos							
<b>B00B - Administration/General Learning - 1995 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
New XYZ	AC Fragments/Debris	1	West	Poor Condition - Extensive Damage (4)	Medium (2)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior							
<b>B00B - R0001 - Toilets - Boys/Girls - 2.29 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00B - R0002 - General Storeroom - 2.36 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00B - R0003 - Clerical Office - 18.63 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0004 - Duplicating Workroom - 14.74 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0005 - Sick Bay - 9.58 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0006 - Staff Toilet - 5.45 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00B - R0007 - Staff Toilet - 3.58 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00B - R0008 - Movement - 10.59 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0009 - Principal - 37.21 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0010 - General Storeroom - 7.67 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0011 - Entry Vestibule - 19.9 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0012 - Clerical Office/Workroom - 4.57 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00B - R0013 - General Storeroom - 6.62 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0014 - Deputy Principal - 15.96 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0015 - Security Store - 19.03 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R0016 - Toilets - Girls - 15.19 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Partition Walls (Cubides)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0017 - Toilets - Boys - 15.7 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Partition Walls (Cubides)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0018 - Movement - 99.17 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00B - R0019 - Distribution Board - .8 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Electrical - Backing Board	Resinous Board	1	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Door - Lining	Flat AC Sheeting	3	Throughout	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	Below Switchboard	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
Material - Stored / Debris Material	Flat AC Sheeting	1	On floor	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)	Chrysotile (white asbestos)
<b>B00B - R0020 - Cleaning Distributed Store - 7.29 m2</b>							
No Asbestos							
<b>B00B - R0021 - External Movement - 153.2 m2</b>							
No Asbestos							
<b>B00B - R0022 - External Stairs - 10.73 m2</b>							
No Asbestos							
<b>B00B - R0023 - External Stairs - 9.19 m2</b>							
No Asbestos							
<b>B00B - R1001 - Home Base - 66.89 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	1m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1002 - Home Base - 67.76 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	1m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1003 - Movement - 50.52 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00B - R1004 - External Movement - 46 m2</b>							
No Asbestos							
<b>B00B - R1005 - Home Base - 67.15 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	1m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1006 - Home Base - 66.89 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	1m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1007 - Cleaning Distributed Store - 1.74 m2</b>							
No Asbestos							
<b>B00B - R1009 - External Stairs - 18.02 m2</b>							
No Asbestos							
<b>B00B - R1010 - Movement - 8.28 m2</b>							
No Asbestos							

<b>B00B - R1011 - External Stairs - 8.17 m2</b>							
No Asbestos							
<b>B00C - General Learning - 1953 - Brick/Veneer</b>							
<b>Exterior</b>							
External Wall Structure - Awnings	Flat AC Sheeting	48	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0001 - Personal Effects Storage - 6.66 m2</b>							
No Asbestos							
<b>B00C - R0002 - Home Base Store - 3.91 m2</b>							
No Asbestos							
<b>B00C - R0003 - Toilets - Boys/Girls - 3.06 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00C - R0004 - Home Base - 84.55 m2</b>							
No Asbestos							
<b>B00C - R0005 - Staff Room - 60.96 m2</b>							
No Asbestos							
<b>B00C - R0010 - Distribution Board - 1.51 m2</b>							
No Asbestos							
<b>B00C - R0011 - No Access - .81 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Electrical - Backing Board	Resinous Board						
<b>B00C - R0012 - Staff Toilet - 4.32 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
Wall Linings Internal	Flat AC Sheeting						
<b>B00C - R0013 - Staff Toilet - 4.41 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
Wall Linings Internal	Flat AC Sheeting						
<b>B00C - R0014 - Movement - 4.85 m2</b>							
No Asbestos							
<b>B00C - R0015 - External Movement - 40.26 m2</b>							
No Asbestos							
<b>B00C - R0016 - External Movement - 54.57 m2</b>							
No Asbestos							
<b>B00D - Pupil Facilities - 1972 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Canteen Office/Store - 1.89 m2</b>							
No Asbestos							
<b>B00D - R0002 - Staff Toilet - 1.89 m2</b>							
No Asbestos							
<b>B00D - R0003 - Canteen Office/Store - 2.78 m2</b>							

No Asbestos							
<b>B00D - R0004 - Canteen - 20.83 m2</b>							
Electrical - Backing Board	Resinous Board	1	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00D - R0006 - External Movement - 12.21 m2</b>							
Wall Linings Internal	Flat AC Sheeting	3m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - General Learning - 1958 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	16m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	AC Fragments/Debris	1	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Flat AC Sheeting						
<b>Interior</b>							
<b>B00E - R0001 - Personal Effects Storage - 9.5 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00E - R0002 - Distribution Board - .1 m2</b>						<b>Note: No inspection of live electrical installation</b>	
Electrical - Backing Board	Resinous Board	1	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0003 - Home Base Store - 4.19 m2</b>							
No Asbestos							
<b>B00E - R0004 - Home Base - 85.02 m2</b>							
No Asbestos							
<b>B00E - R0005 - Home Base - 56.16 m2</b>							
No Asbestos							
<b>B00E - R0006 - Home Base Store - 4.19 m2</b>							
No Asbestos							
<b>B00E - R0007 - Personal Effects Storage - 9.63 m2</b>							
No Asbestos							
<b>B00E - R0008 - External Movement - 4.6 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	Above Door	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0009 - External Movement - 54.81 m2</b>							
No Asbestos							
<b>B00E - R9001 - Garden Store - 54.21 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	1	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00F - General Learning/Administration - 1958 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	24m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						

Underfloor Voids	AC Fragments/Debris	1	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>Interior</b>							
<b>B00F - R0001 - Movement - 5.49 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0002 - Sick Bay - 7.68 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0004 - General Storeroom - 6.48 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0005 - Duplicating Workroom - 21.23 m2</b>							
No Asbestos							
<b>B00F - R0006 - External Movement - 14.39 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	Above Door	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0007 - Entry Vestibule - 28.68 m2</b>							
No Asbestos							
<b>B00F - R0008 - Deputy Principal - 17.27 m2</b>							
No Asbestos							
<b>B00F - R0009 - General Storeroom - .39 m2</b>							
No Asbestos							
<b>B00F - R0010 - General Storeroom - .77 m2</b>							
No Asbestos							
<b>B00F - R0011 - Cleaning Distributed Store - 2.52 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0012 - Home Base - 56.73 m2</b>							
No Asbestos							
<b>B00F - R0013 - Home Base Store - 4.55 m2</b>							
No Asbestos							
<b>B00F - R0014 - Personal Effects Storage - 11.39 m2</b>							
No Asbestos							
<b>B00F - R0015 - Movement - 6.03 m2</b>							
No Asbestos							
<b>B00F - R0016 - External Movement - 4.71 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	Above Door	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0017 - Home Base Store - 4.55 m2</b>							
No Asbestos							
<b>B00F - R0018 - Home Base - 56.73 m2</b>							
No Asbestos							
<b>B00F - R0019 - Home Base - 85.49 m2</b>							
No Asbestos							
<b>B00F - R0020 - Toilets - Boys/Girls - 3.42 m2</b>							
Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0021 - Home Base Store - 3.24 m2</b>							
No Asbestos							



<b>B00F - R0022 - Personal Effects Storage - 5.49 m2</b>							
Electrical - Backing Board	Resinous Board	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00F - R0024 - External Movement - 138.1 m2</b>							
No Asbestos							
<b>B00F - R0025 - Toilet - Lobby - 1.86 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Wall Linings Internal	Flat AC Sheeting	6m2	South & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0026 - Toilets-Unisex - 1.75 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	6m2	South & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R9001 - General Storeroom - 5.85 m2</b>							
No Asbestos							
<b>B00F - R9002 - External Movement - 6.55 m2</b>							
No Asbestos							
<b>B00F - R9003 - General Storeroom - 49.83 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R9004 - Cleaning Supplies - 27.02 m2</b>							
No Asbestos							
<b>B00G - Communal Facilities - 1958 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Flat AC Sheeting	1	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00G - R0001 - Special Programs Room - 95.13 m2</b>							
No Asbestos							
<b>B00J - Pupil Facilities - 1958 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00J - R0001 - Toilets - Boys - 59.02 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0002 - Sports Store - 4.73 m2</b>							
No Asbestos							
<b>B00J - R0003 - General Storeroom - 4.73 m2</b>							
No Asbestos							
<b>B00J - R0004 - Toilets - Girls - 54.93 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00K - Pupil Facilities - 2002 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							

<b>B00K - R0001 - Communal Space - 186.43 m2</b>							
No Asbestos							
<b>B00K - R0002 - Toilets - Girls - 16.68 m2</b>							
No Asbestos							
<b>B00K - R0003 - Staff Kitchen - 13.36 m2</b>							
No Asbestos							
<b>B00K - R0004 - Communal/Performance Store - 14.44 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00K - R0005 - Communal/Performance Store - 14.47 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00K - R0006 - Communal/Performance Store - 6.3 m2</b>							
No Asbestos							
<b>B00K - R0007 - Communal/Performance Store - 6.8 m2</b>							
No Asbestos							
<b>B00K - R0008 - Movement - 29.13 m2</b>							
No Asbestos							
<b>B00K - R0009 - Raised Platform - 48.24 m2</b>							
No Asbestos							
<b>B00K - R0010 - Movement - 12.42 m2</b>							
No Asbestos							
<b>B00K - R0011 - Clerical Office - 16.92 m2</b>							
No Asbestos							
<b>B00K - R0012 - P.E. Store - 16.98 m2</b>							
No Asbestos							
<b>B00K - R0013 - Hall Chair Store - 10.17 m2</b>							
No Asbestos							
<b>B00K - R0014 - Cleaning Distributed Store - 2.84 m2</b>							
No Asbestos							
<b>B00K - R0015 - Toilets - Boys - 16.2 m2</b>							
No Asbestos							
<b>B00K - R0016 - Distribution Board - 1.68 m2</b>							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00K - R0017 - Disabled Toilet - 5.26 m2</b>							
No Asbestos							
<b>B00K - R0018 - Communal/Performance Store - 1.1 m2</b>							
No Asbestos							
<b>B00K - R0019 - Covered Outdoor Learning Area - 195.87 m2</b>							
No Asbestos							
<b>B00M - General Learning - 1958 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Flat AC Sheeting						
<b>Interior</b>							
<b>B00M - R0001 - Seminar/Study - 19.33 m2</b>							
No Asbestos							
<b>B00M - R0002 - General Storeroom - 6.3 m2</b>							
No Asbestos							

<b>B00M - R0003 - External Movement - 4.78 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0004 - Movement - 10.36 m2</b>							
No Asbestos							
<b>B00M - R0005 - Personal Effects Storage - 3.53 m2</b>							
No Asbestos							
<b>B00M - R0006 - Home Base Store - 7.83 m2</b>							
No Asbestos							
<b>B00M - R0007 - Home Base - 65.75 m2</b>							
No Asbestos							
<b>B00M - R0008 - Home Base - 65.74 m2</b>							
No Asbestos							
<b>B00M - R0009 - Home Base Store - 7.83 m2</b>							
No Asbestos							
<b>B00M - R0010 - Personal Effects Storage - 3.53 m2</b>							
No Asbestos							
<b>B00M - R0011 - External Movement - 9.19 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0012 - Movement - 16.46 m2</b>							
No Asbestos							
<b>B00M - R0013 - Sports Store - 1.78 m2</b>							
No Asbestos							
<b>B00M - R0015 - Personal Effects Storage - 4.09 m2</b>							
Electrical - Backing Board	Resinous Board	2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00M - R0016 - Staff Room Annexe - 17.25 m2</b>							
No Asbestos							
<b>B00M - R0017 - Cleaning Distributed Store - 3.6 m2</b>							
No Asbestos							
<b>B00M - R0018 - Home Base Store - 7.83 m2</b>							
No Asbestos							
<b>B00M - R0019 - Home Base - 66.11 m2</b>							
No Asbestos							
<b>B00M - R0022 - Other-Community Use - 3.55 m2</b>							
No Asbestos							
<b>B00M - R0024 - Other-Community Use - 3.1 m2</b>							
No Asbestos							
<b>B00M - R0025 - Other-Community Use - 15.05 m2</b>							
No Asbestos							
<b>B00M - R0028 - External Movement - 4.66 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0029 - No Access - 6.46 m2</b>							
No Asbestos							
<b>B00M - R0030 - Other-Community Use - 10.59 m2</b>							
No Asbestos							
<b>B00M - R0031 - Other-Community Use - 2.75 m2</b>							
No Asbestos							
<b>B00M - R0032 - Other-Community Use - 5.11 m2</b>							
No Asbestos							
<b>B00M - R0033 - Other-Community Use - 22.96 m2</b>							

No Asbestos							
<b>B00M - R0034 - Other-Community Use - 42.93 m2</b>							
No Asbestos							
<b>B00M - R0035 - Ramp - 5.96 m2</b>							
No Asbestos							
<b>B00M - R0036 - Other-Community Use - 8.82 m2</b>							
No Asbestos							
<b>B00N - General Learning - 1997 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting						
Underfloor Voids	Encapsulated Asbestos material within unit	9	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids	Flat AC Sheeting						
<b>Interior</b>							
<b>B00N - R0001 - Home Base Store - 5.8 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00N - R0002 - Outdoor Learning Area - 14.31 m2</b>							
No Asbestos							
<b>B00N - R0003 - Withdrawal Space - 1hb - 11.93 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00N - R0004 - Outdoor Learning Area - 14.23 m2</b>							
No Asbestos							
<b>B00N - R0005 - Home Base Store - 5.82 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00N - R0006 - Home Base - 64.9 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00N - R0007 - Home Base - 64.75 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00N - R0008 - Practical Activities - 1hb - 13.07 m2</b>							
No Asbestos							
<b>B00N - R0009 - Practical Activities - 1hb - 13.02 m2</b>							
No Asbestos							
<b>B00N - R0010 - External Movement - 35.57 m2</b>							
No Asbestos							
<b>B00N - R9001 - General Storeroom - 253.48 m2</b>							
No Asbestos							
<b>B00P - Pre-School Facilities - 2007 - Metal Shed</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00P - R0001 - No Access - 35.36 m2</b>							
No Asbestos							
<b>B00Q - General Learning - 2010 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00Q - R0001 - Practical Activities - 1hb - 19.97 m2</b>		
No Asbestos		
<b>B00Q - R0002 - Home Base - 58.72 m2</b>		
No Asbestos		
<b>B00Q - R0003 - Home Base Store - 6.05 m2</b>		
No Asbestos		
<b>B00Q - R0004 - Withdrawal Space - 1hb - 7.66 m2</b>		
No Asbestos		
<b>B00Q - R0005 - Practical Activities - 1hb - 19.31 m2</b>		
No Asbestos		
<b>B00Q - R0006 - Home Base - 60.4 m2</b>		
No Asbestos		
<b>B00Q - R0007 - Home Base Store - 6.05 m2</b>		
No Asbestos		
<b>B00Q - R0008 - Withdrawal Space - 2hb - 11.74 m2</b>		
No Asbestos		
<b>B00Q - R0009 - Practical Activities - 1hb - 19.83 m2</b>		
No Asbestos		
<b>B00Q - R0010 - Home Base - 60.64 m2</b>		
No Asbestos		
<b>B00Q - R0011 - Home Base Store - 6.09 m2</b>		
No Asbestos		
<b>B00Q - R0012 - Distribution Board - .39 m2</b>		
No Asbestos		<b>Note: No inspection of live electrical installation</b>
<b>B00Q - R0013 - Movement - 6.26 m2</b>		
No Asbestos		
<b>B00Q - R0014 - Special Programs Room - 33.13 m2</b>		
No Asbestos		
<b>B00Q - R0015 - Special Programs Store - 5.84 m2</b>		
No Asbestos		
<b>B00Q - R0016 - Cleaning Distributed Store - 5.7 m2</b>		
No Asbestos		
<b>B00Q - R0017 - External Movement - 81.25 m2</b>		
No Asbestos		
<b>B00R - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00R - R0001 - Practical Activities - 1hb - 19.22 m2</b>		
No Asbestos		
<b>B00R - R0002 - Home Base - 60.54 m2</b>		
No Asbestos		
<b>B00R - R0003 - Home Base Store - 6.13 m2</b>		
No Asbestos		
<b>B00R - R0004 - Withdrawal Space - 2hb - 11.74 m2</b>		
No Asbestos		
<b>B00R - R0005 - Practical Activities - 1hb - 19.87 m2</b>		
No Asbestos		

<b>B00R - R0006 - Home Base - 60.54 m2</b>		
No Asbestos		
<b>B00R - R0007 - Home Base Store - 6.13 m2</b>		
No Asbestos		
<b>B00R - R0008 - Distribution Board - .39 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00R - R0009 - External Movement - 46.28 m2</b>		
No Asbestos		
<b>B00S - Pupil Facilities - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00S - R0001 - Toilets - Girls/Disabled Cubicle - 16.16 m2</b>		
No Asbestos		
<b>B00S - R0002 - Toilets - Boys/Disabled Cubicle - 12.01 m2</b>		
No Asbestos		
<b>B00S - R0003 - External Movement - 7.52 m2</b>		
No Asbestos		

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020