


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Harbord Public School (2133)
Region:	Northern Sydney AMU
State Electorate:	Manly
Local Government Area:	Northern Beaches

Last Reviewed By:	Greencap 13-AUG-2014
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00D - General Learning - 2010 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00D - R0001 - Practical Activities - 1hb - 19.31 m2							
No Asbestos							
B00D - R0002 - Home Base - 58.76 m2							
No Asbestos							
B00D - R0003 - Home Base Store - 6.03 m2							
No Asbestos							
B00D - R0004 - Withdrawal Space - 1hb - 9.33 m2							
No Asbestos							
B00D - R0005 - Practical Activities - 1hb - 18.14 m2							
No Asbestos							
B00D - R0006 - Home Base Store - 6.27 m2							
No Asbestos							
B00D - R0007 - Home Base - 60.26 m2							
No Asbestos							
B00D - R0008 - Withdrawal Space - 2hb - 11.56 m2							
No Asbestos							
B00D - R0009 - Practical Activities - 1hb - 18.8 m2							
No Asbestos							
B00D - R0010 - Home Base - 59.94 m2							
No Asbestos							
B00D - R0011 - Home Base Store - 6.31 m2							
No Asbestos							
B00D - R0012 - External Movement - 68.91 m2							
No Asbestos							
B00D - R0013 - Distribution Board - .65 m2							
No Asbestos							Note: No inspection of live electrical installation
B00D - R0014 - Garden Store - 4.24 m2							
No Asbestos							
B00D - R0015 - External Stairs - 2.26 m2							
No Asbestos							
B00D - R1001 - Practical Activities - 1hb - 19.29 m2							
No Asbestos							
B00D - R1002 - Home Base - 58.24 m2							
No Asbestos							
B00D - R1003 - Home Base Store - 6 m2							
No Asbestos							
B00D - R1004 - Withdrawal Space - 1hb - 9.06 m2							
No Asbestos							
B00D - R1005 - Practical Activities - 1hb - 17.7 m2							
No Asbestos							
B00D - R1006 - Home Base Store - 6.37 m2							
No Asbestos							
B00D - R1007 - Home Base - 60.1 m2							
No Asbestos							
B00D - R1008 - Withdrawal Space - 2hb - 11.56 m2							

No Asbestos							
B00D - R1009 - Practical Activities - 1hb - 19.77 m2							
No Asbestos							
B00D - R1010 - Home Base - 59.62 m2							
No Asbestos							
B00D - R1011 - Home Base Store - 6.31 m2							
No Asbestos							
B00D - R1012 - External Movement - 59.98 m2							
No Asbestos							
B00D - R1013 - Distribution Board - .64 m2							
Note: No inspection of live electrical installation							
No Asbestos							
B00D - R1014 - External Stairs - 10.96 m2							
No Asbestos							
B00H - General Learning - 1960 - Steel							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Other-Community Use - 53.61 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Other-Community Use - 53.61 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0003 - Cleaning Supplies - 5.88 m2							
No Asbestos							
B00H - R0004 - External Movement - 24.54 m2							
No Asbestos							
B00H - R0005 - General Storeroom - 5.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00J - Other - After School Care - 1960 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00J - R0001 - Other-Community Use - 54.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00J - R0002 - Other-Community Use - 54.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0004 - Clerical Office - 11.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0005 - General Storeroom - 3.04 m2							
No Asbestos							
B00J - R0006 - Staff Toilet - 2.41 m2							
No Asbestos							
B00J - R0007 - External Movement - 17.69 m2							
No Asbestos							
B00J - R0008 - External Movement - 4.07 m2							
No Asbestos							
B00K - General Learning/Pupil Facilities - 1963 - Brick/Block							
Exterior							
External Wall Structure - Awnings	Flat AC Sheeting	8	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	130m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	30m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	40	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00K - R0001 - Toilets - Boys/Girls - 3.99 m2							
No Asbestos							
B00K - R0009 - General Storeroom - 6.31 m2							
No Asbestos							
B00K - R0012 - Home Base - 56.36 m2							
No Asbestos							
B00K - R0013 - Home Base Store - 4 m2							
No Asbestos							
B00K - R0019 - Home Base Store - 4.21 m2							
No Asbestos							
B00K - R0022 - Practical Activities - 1hb - 13.69 m2							
No Asbestos							
B00K - R0023 - Home Base - 53.56 m2							
No Asbestos							
B00K - R0024 - Withdrawal Space - 1hb - 4.71 m2							
No Asbestos							
B00K - R0025 - Distribution Board - .82 m2							
						Note: No inspection of live electrical installation	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0026 - Practical Activities - 1hb - 13.56 m2							
No Asbestos							

B00K - R0027 - Home Base Store - 6.98 m2							
No Asbestos							
B00K - R0028 - Withdrawal Space - 1hb - 8.08 m2							
No Asbestos							
B00K - R0029 - Home Base Store - 6.69 m2							
No Asbestos							
B00K - R0030 - Home Base - 58.7 m2							
No Asbestos							
B00K - R0031 - Practical Activities - 1hb - 6.64 m2							
No Asbestos							
B00K - R0032 - Practical Activities - 1hb - 6.39 m2							
No Asbestos							
B00K - R0033 - Distribution Board - .76 m2							Note: No inspection of live electrical installation
No Asbestos							
B00K - R0034 - Home Base - 59.78 m2							
No Asbestos							
B00K - R0035 - Home Base Store - 6.97 m2							
No Asbestos							
B00K - R0036 - External Movement - 83.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R0037 - External Stairs - 4.51 m2							
No Asbestos							
B00K - R9001 - Canteen Office/Store - 3 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9002 - Canteen Office/Store - 3.17 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9003 - Canteen - 24.08 m2							
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9009 - Cleaning Distributed Store - 1.45 m2							
No Asbestos							
B00K - R9010 - Cleaning Distributed Store - 2.72 m2							
No Asbestos							
B00K - R9012 - Sports Store - 9.82 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9014 - Out Of School Hours Care Centre - 81.58 m2							
No Asbestos							
B00K - R9016 - Toilets - Girls - 38.23 m2							

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9017 - Toilets - Boys - 51.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9018 - General Storeroom - 5.56 m2							
No Asbestos							
B00K - R9019 - Cleaning Supplies - 12.61 m2							
No Asbestos							
B00K - R9020 - Sports Store - 7.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9021 - Movement - 13.83 m2							
No Asbestos							
B00K - R9022 - Sports Store - 14.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00K - R9023 - Garden Store - 14.86 m2							
No Asbestos							
B00K - R9024 - External Movement - 134.7 m2							
No Asbestos							
B00K - R9025 - External Stairs - 3.91 m2							
No Asbestos							
B00K - R9026 - External Movement - 5.07 m2							
No Asbestos							
B00L - Communal Facilities - 1928 - Brick/Block							
Exterior							
External Wall Structure - Awnings	Flat AC Sheeting	20	South-west	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	125m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00L - R0010 - External Movement - 31.99 m2							
No Asbestos							
B00L - R0012 - Toilets - Boys - 15.08 m2							
No Asbestos							
B00L - R0013 - Disabled Shower/Toilet - 5.51 m2							
No Asbestos							
B00L - R0014 - Toilets - Girls - 16.3 m2							
No Asbestos							
B00L - R0015 - Movement - 15.52 m2							
No Asbestos							
B00L - R0016 - Distribution Board - .39 m2							
No Asbestos							
B00L - R0017 - Raised Platform - 92.21 m2							
No Asbestos							

Note: No inspection of live electrical installation

B00L - R0018 - Movement - 2.56 m2							
No Asbestos							
B00L - R0019 - Communal Space - 288.9 m2							
No Asbestos							
B00L - R0020 - P.E Store - 18.34 m2							
No Asbestos							
B00L - R0021 - Hall Chair Store - 13.27 m2							
No Asbestos							
B00L - R0022 - External Movement - 91.45 m2							
No Asbestos							
B00Q - General Learning - 1912 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00Q - R0003 - Staff Room Annexe - 12.9 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00Q - R0004 - General Storeroom - 2.22 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00Q - R0005 - External Movement - 2.47 m2							
No Asbestos							
B00Q - R0012 - Practical Activities - 1hb - 17.18 m2							
No Asbestos							
B00Q - R0013 - Home Base - 64.28 m2							
No Asbestos							
B00Q - R0014 - Practical Activities - 1hb - 13.45 m2							
No Asbestos							
B00Q - R0015 - Withdrawal Space - 1hb - 10.16 m2							
No Asbestos							
B00Q - R0016 - Home Base Store - 4.9 m2							
No Asbestos							
B00Q - R0017 - Distribution Board - .66 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00Q - R0018 - Movement - 42.99 m2							
No Asbestos							
B00Q - R0019 - Home Base Store - 9.25 m2							
No Asbestos							
B00Q - R0020 - Stairs - 7.36 m2							
No Asbestos							
B00Q - R0021 - Practical Activities - 1hb - 12.75 m2							
No Asbestos							
B00Q - R0022 - Home Base - 57.86 m2							
No Asbestos							
B00Q - R1007 - Practical Activities - 1hb - 17.3 m2							
No Asbestos							
B00Q - R1008 - Home Base - 64.46 m2							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00Q - R1009 - Practical Activities - 1hb - 13.45 m2							
No Asbestos							
B00Q - R1010 - Home Base Store - 10.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00Q - R1011 - Withdrawal Space - 2hb - 15.78 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00Q - R1012 - Home Base Store - 8.41 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00Q - R1013 - Stairs - 10.95 m2							
No Asbestos							
B00Q - R1014 - Movement - 11.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00Q - R1015 - Home Base - 57.24 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00Q - R9001 - Movement - 2.73 m2							
No Asbestos							
B00Q - R9002 - General Storeroom - 3.06 m2							
No Asbestos							
B00Q - R9003 - General Storeroom - 4.41 m2							
No Asbestos							
B00R - General Learning/Library - 2003 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00R - R0001 - Home Base - 59.89 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00R - R0002 - Home Base Store - 6.15 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00R - R0003 - Practical Activities - 1hb - 19.13 m2							
No Asbestos							
B00R - R0004 - Main Switch Board - 3.8 m2							
No Asbestos							
B00R - R0005 - Withdrawal Space - 2hb - 11.84 m2							

Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0006 - Home Base - 59.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0007 - Practical Activities - 1hb - 19.27 m2		
No Asbestos		
B00R - R0008 - Home Base Store - 6.15 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0009 - Distribution Board - .34 m2		
Note: No inspection of live electrical installation		
No Asbestos		
B00R - R0011 - Library Office/Workroom - 27.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0012 - K.L.A. Store - 19.77 m2		
No Asbestos		
B00R - R0013 - Communications Room - 8.01 m2		
No Asbestos		
B00R - R0014 - Movement - 4.49 m2		
No Asbestos		
B00R - R0015 - Movement - 4.71 m2		
No Asbestos		
B00R - R0016 - Staff Room - 57.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0017 - Staff Room Annexe - 26.63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0018 - Distribution Board - .88 m2		
Note: No inspection of live electrical installation		
No Asbestos		
B00R - R0019 - Cleaning Distributed Store - 5.9 m2		
No Asbestos		
B00R - R0020 - Deputy Principal - 12.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0021 - Deputy Principal - 12.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0022 - Staff Toilet - 4.73 m2		
No Asbestos		
B00R - R0023 - Staff Toilet - 4.73 m2		
No Asbestos		
B00R - R0024 - Staff Toilet - 4.73 m2		
No Asbestos		
B00R - R0025 - Security Store - 13.46 m2		
No Asbestos		
B00R - R0026 - Disabled Toilet - 5.8 m2		
No Asbestos		
B00R - R0027 - Sick Bay - 8.75 m2		
No Asbestos		
B00R - R0028 - Movement - 41.52 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0029 - Principal - 16.89 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0030 - Interview - 12.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0031 - Clerical Office/Workroom - 57.59 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0032 - Entry Vestibule - 23.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0034 - Lift - 4.84 m2		
No Asbestos		
B00R - R0035 - External Stairs - 12.64 m2		
No Asbestos		
B00R - R0036 - External Stairs - 19.58 m2		
No Asbestos		
B00R - R0037 - External Stairs - 17.26 m2		
No Asbestos		
B00R - R0038 - External Movement - 324.11 m2		
No Asbestos		
B00R - R0039 - Special Programs Room - 53.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R0040 - Reading Area - 178.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1001 - Home Base - 59.67 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1002 - Home Base Store - 6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1003 - Practical Activities - 1hb - 19.62 m2		
No Asbestos		
B00R - R1004 - Withdrawal Space - 2hb - 11.77 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1005 - Home Base - 59.28 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1006 - Practical Activities - 1hb - 19.16 m2		
No Asbestos		
B00R - R1007 - Home Base Store - 5.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1008 - Home Base Store - 5.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1009 - Home Base - 59.63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1010 - Practical Activities - 1hb - 18.38 m2		
No Asbestos		
B00R - R1011 - Withdrawal Space - 2hb - 11.65 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1012 - Home Base - 59.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1013 - Practical Activities - 1hb - 19.19 m2		
No Asbestos		
B00R - R1014 - Home Base Store - 6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1015 - Home Base Store - 6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1016 - Home Base - 59.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1017 - Practical Activities - 1hb - 19.12 m2		
No Asbestos		
B00R - R1018 - Movement - 4.69 m2		
No Asbestos		
B00R - R1019 - Plant - 4.51 m2		
No Asbestos		
B00R - R1020 - Withdrawal Space - 2hb - 11.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1021 - Home Base - 59.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1022 - Practical Activities - 1hb - 19.19 m2		
No Asbestos		
B00R - R1023 - Home Base Store - 5.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1024 - Home Base Store - 5.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1025 - Home Base - 59.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1026 - Practical Activities - 1hb - 18.21 m2		
No Asbestos		
B00R - R1028 - Withdrawal Space - 2hb - 11.74 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1029 - Home Base - 59.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1030 - Practical Activities - 1hb - 19.07 m2		
No Asbestos		
B00R - R1031 - Home Base Store - 6.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00R - R1032 - Distribution Board - .66 m2		
No Asbestos		Note: No inspection of live electrical installation
B00R - R1033 - Distribution Board - .66 m2		
No Asbestos		Note: No inspection of live electrical installation

B00R - R1034 - Lift - 4.84 m2		
No Asbestos		
B00R - R1035 - External Stairs - 19.59 m2		
No Asbestos		
B00R - R1036 - External Stairs - 12.4 m2		
No Asbestos		
B00R - R1037 - External Stairs - 16.33 m2		
No Asbestos		
B00R - R1038 - External Movement - 235.08 m2		
No Asbestos		
B00S - Pupil Facilities - 2006 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00S - R0001 - Canteen - 43.53 m2		
No Asbestos		
B00S - R0002 - Canteen Office/Store - 9.57 m2		
No Asbestos		
B00S - R0003 - External Movement - 34.29 m2		
No Asbestos		
B00S - R0004 - Canteen Covered Area - 143.89 m2		
No Asbestos		
B00T - Mechanical Services - 2016 - Fibre Cement Clad		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00T - R0001 - Plant - 28.44 m2		
No Asbestos		
B00T - R0002 - Plant - 2.8 m2		
No Asbestos		
B0A1 - General Learning - 2016 - Concrete Framed		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B0A1 - R0001 - Movement - 192.98 m2		
No Asbestos		
B0A1 - R0002 - Stairs - 7.64 m2		
No Asbestos		
B0A1 - R0003 - Lift - 2.13 m2		
No Asbestos		
B0A1 - R0004 - General Storeroom - 7.35 m2		
No Asbestos		
B0A1 - R0005 - Practical Activities - 90.47 m2		

No Asbestos	
B0A1 - R0006 - General Storeroom - 7.12 m2	
No Asbestos	
B0A1 - R0007 - Toilets - Boys - 34.12 m2	
No Asbestos	
B0A1 - R0008 - Access Shower/Toilet - 5.92 m2	
No Asbestos	
B0A1 - R0009 - Movement - 13.48 m2	
No Asbestos	
B0A1 - R0010 - Practical Activities - 34.4 m2	
No Asbestos	
B0A1 - R0011 - Breakout Area - 23.27 m2	
No Asbestos	
B0A1 - R0012 - Home Base - 60.72 m2	
No Asbestos	
B0A1 - R0013 - Home Base - 58.19 m2	
No Asbestos	
B0A1 - R0014 - Home Base - 55.97 m2	
No Asbestos	
B0A1 - R0015 - Home Base - 61.44 m2	
No Asbestos	
B0A1 - R0016 - Practical Activities - 35.07 m2	
No Asbestos	
B0A1 - R0017 - Breakout Area - 26.4 m2	
No Asbestos	
B0A1 - R0018 - Home Base - 60.66 m2	
No Asbestos	
B0A1 - R0019 - Home Base - 58.92 m2	
No Asbestos	
B0A1 - R0020 - External Stairs - 9.84 m2	
No Asbestos	
B0A1 - R0021 - Toilets - Girls - 45.27 m2	
No Asbestos	
B0A1 - R0022 - Cleaning Distributed Store - 1.98 m2	
No Asbestos	
B0A1 - R0023 - Distribution Board - .73 m2	Note: No inspection of live electrical installation
No Asbestos	
B0A1 - R0024 - Stairs - 4.88 m2	
No Asbestos	
B0A1 - R0025 - External Movement - 231.52 m2	
No Asbestos	
B0A1 - R0026 - External Movement - 7.52 m2	
No Asbestos	
B0A1 - R0027 - External Movement - 12.52 m2	
No Asbestos	
B0A1 - R1001 - Movement - 208.62 m2	
No Asbestos	
B0A1 - R1002 - Stairs - 7.84 m2	
No Asbestos	
B0A1 - R1003 - Stairs - 8.11 m2	
No Asbestos	

B0A1 - R1004 - Breakout Area - 108.4 m2	
No Asbestos	
B0A1 - R1005 - Toilets - Girls - 7.23 m2	
No Asbestos	
B0A1 - R1006 - Toilets - Boys - 9.97 m2	
No Asbestos	
B0A1 - R1007 - Access Shower/Toilet - 10.1 m2	
No Asbestos	
B0A1 - R1008 - General Storeroom - 11.08 m2	
No Asbestos	
B0A1 - R1009 - Movement - 5.21 m2	
No Asbestos	
B0A1 - R1010 - Practical Activities - 34.22 m2	
No Asbestos	
B0A1 - R1011 - Outdoor Learning Area - 29.49 m2	
No Asbestos	
B0A1 - R1012 - Home Base - 60.75 m2	
No Asbestos	
B0A1 - R1013 - Home Base - 60.5 m2	
No Asbestos	
B0A1 - R1014 - Home Base - 58.41 m2	
No Asbestos	
B0A1 - R1015 - Home Base - 59.69 m2	
No Asbestos	
B0A1 - R1016 - Practical Activities - 34.59 m2	
No Asbestos	
B0A1 - R1017 - Practical Activities - 27.03 m2	
No Asbestos	
B0A1 - R1018 - Home Base - 60.45 m2	
No Asbestos	
B0A1 - R1019 - Home Base - 60.98 m2	
No Asbestos	
B0A1 - R1020 - External Stairs - 9.49 m2	
No Asbestos	
B0A1 - R1021 - Communications Cupboard - 8 m2	
No Asbestos	
B0A1 - R1022 - Staff Room - 31.55 m2	
No Asbestos	
B0A1 - R1023 - Tiered Learning Space - 29.2 m2	
No Asbestos	
B0A1 - R1024 - Staff Kitchen - 10.33 m2	
No Asbestos	
B0A1 - R1025 - K.L.A. Store - 21.09 m2	
No Asbestos	
B0A1 - R1027 - Library Office/Workroom - 19.52 m2	
No Asbestos	
B0A1 - R1028 - Reading Area - 108.57 m2	
No Asbestos	
B0A1 - R1029 - Distribution Board - .72 m2	Note: No inspection of live electrical installation
No Asbestos	
B0A1 - R1030 - Toilet - Lobby - 2.39 m2	
No Asbestos	

B0A1 - R1031 - Plant - 1.15 m2	
No Asbestos	
B0A1 - R1032 - Stairs - 7.24 m2	
No Asbestos	
B0A1 - R1033 - Stairs - 2.85 m2	
No Asbestos	
B0A1 - R1034 - External Movement - 6.65 m2	
No Asbestos	
B0A1 - R1035 - External Stairs - 4.38 m2	
No Asbestos	
B0A1 - R1036 - Reading Area - 79.95 m2	
No Asbestos	
B0A1 - R1037 - External Movement - 2.31 m2	
No Asbestos	
B0A1 - R1038 - External Movement - 2.33 m2	
No Asbestos	
B0A1 - R1039 - External Movement - 2.55 m2	
No Asbestos	
B0A1 - R1040 - External Movement - 2.42 m2	
No Asbestos	
B0A1 - R1041 - External Movement - 2.65 m2	
No Asbestos	
B0A1 - R1042 - External Movement - 2.67 m2	
No Asbestos	
B0A1 - R1043 - External Movement - 2.68 m2	
No Asbestos	
B0A1 - R1044 - External Movement - 4.71 m2	
No Asbestos	
B0A1 - R2001 - Movement - 71.49 m2	
No Asbestos	
B0A1 - R2002 - Toilets - Girls - 11.18 m2	
No Asbestos	
B0A1 - R2003 - Stairs - 15.98 m2	
No Asbestos	
B0A1 - R2004 - Breakout Area - 131.68 m2	
No Asbestos	
B0A1 - R2005 - Toilet - Lobby - 2.5 m2	
No Asbestos	
B0A1 - R2006 - Toilets - Boys - 11.24 m2	
No Asbestos	
B0A1 - R2007 - Access Shower/Toilet - 6.28 m2	
No Asbestos	
B0A1 - R2008 - General Storeroom - 11.52 m2	
No Asbestos	
B0A1 - R2009 - Movement - 4.11 m2	
No Asbestos	
B0A1 - R2010 - Practical Activities - 61.68 m2	
No Asbestos	
B0A1 - R2011 - Home Base - 61.17 m2	
No Asbestos	
B0A1 - R2012 - Home Base - 62.6 m2	
No Asbestos	

B0A1 - R2013 - Home Base - 60.66 m2	
No Asbestos	
B0A1 - R2014 - Home Base - 58.93 m2	
No Asbestos	
B0A1 - R2015 - Practical Activities - 34.97 m2	
No Asbestos	
B0A1 - R2016 - Covered Outdoor Learning Area - 33.76 m2	
No Asbestos	
B0A1 - R2017 - Home Base - 58.85 m2	
No Asbestos	
B0A1 - R2018 - Home Base - 59.28 m2	
No Asbestos	
B0A1 - R2019 - External Stairs - 13.93 m2	
No Asbestos	
B0A1 - R2020 - Reading Area - 114.14 m2	
No Asbestos	
B0A1 - R2021 - Special Programs Room - 16.16 m2	
No Asbestos	
B0A1 - R2022 - Special Programs Room - 10.29 m2	
No Asbestos	
B0A1 - R2023 - Movement - 18.98 m2	
No Asbestos	
B0A1 - R2024 - General Storeroom - 11.6 m2	
No Asbestos	
B0A1 - R2025 - Special Programs Room - 36.5 m2	
No Asbestos	
B0A1 - R2026 - Tiered Learning Space - 36.81 m2	
No Asbestos	
B0A1 - R2027 - Stairs - 11.08 m2	
No Asbestos	
B0A1 - R2028 - Distribution Board - .8 m2	
No Asbestos	Note: No inspection of live electrical installation
B0A1 - R2029 - External Movement - 6.64 m2	
No Asbestos	
B0A1 - R2030 - Breakout Area - 106.29 m2	
No Asbestos	
B0A1 - R2031 - External Movement - 2.31 m2	
No Asbestos	
B0A1 - R2032 - External Movement - 2.3 m2	
No Asbestos	
B0A1 - R2033 - External Movement - 9.41 m2	
No Asbestos	
B0A1 - R2034 - External Movement - 7.54 m2	
No Asbestos	
B0A1 - R2035 - External Movement - 2.75 m2	
No Asbestos	
B0A1 - R2036 - External Movement - 8.71 m2	
No Asbestos	
B0A1 - R9001 - Plant - 83.39 m2	
No Asbestos	
B0A1 - R9002 - Main Switch Board - 13.38 m2	

No Asbestos	
-------------	--

Demountables

OS 603 13584 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 01-DEC-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found