


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Henty Public School (2154)
Region:	Southern NSW AMU
State Electorate:	Albury
Local Government Area:	Greater Hume

Last Reviewed By:	WSP 07-FEB-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1973 - Brick/Veneer							
Exterior							
Gable Verge Lining	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	8	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Clerical Office - 16.03 m2							
No Asbestos							
B00A - R0002 - External Movement - 34.9 m2							
Ceiling Structures/Linings	Flat AC Sheeting	35m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0003 - Distribution Board - .66 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical - Backing Board	Resinous Board	2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	5m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0004 - Entry Vestibule - 11.38 m2							
No Asbestos							
B00A - R0005 - Movement - 7.54 m2							
No Asbestos							
B00A - R0006 - Staff Room Annexe - 8.24 m2							
No Asbestos							
B00A - R0007 - Duplicating Workroom - 8.27 m2							
No Asbestos							
B00A - R0008 - Sick Bay - 16.94 m2							
No Asbestos							
B00A - R0009 - Staff Room - 24.22 m2							
No Asbestos							
B00A - R0010 - Cleaning Supplies - 4.81 m2							
No Asbestos							
B00A - R0013 - General Storeroom - 6.57 m2							
No Asbestos							
B00A - R0014 - Staff Toilet - 3.1 m2							
No Asbestos							
B00A - R0015 - Principal - 19.85 m2							
No Asbestos							
B00A - R0016 - Staff Toilet - 2.5 m2							
Wall Linings Internal	Flat AC Sheeting						
B00A - R0017 - Staff Toilet - 2.5 m2							

Wall Linings Internal	Flat AC Sheeting						
B00A - R0018 - Toilet - Lobby - 1.24 m2							
Wall Linings Internal	Flat AC Sheeting						
B00A - R0019 - Toilet - Lobby - 1.24 m2							
Wall Linings Internal	Flat AC Sheeting						
B00B - General Learning - 1973 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	20m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	18	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	36m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - External Movement - 59.35 m2							
Ceiling Structures/Linings	Flat AC Sheeting	59m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	18m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0002 - Home Base - 98.91 m2							
No Asbestos							
B00B - R0003 - Toilets - Boys/Girls - 4.22 m2							
No Asbestos							
B00B - R0004 - Home Base - 73.85 m2							
No Asbestos							
B00B - R0005 - Home Base - 73.86 m2							
No Asbestos							
B00B - R0006 - Covered Outdoor Learning Area - 29.98 m2							
No Asbestos							
B00C - Pupil Facilities - 1973 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	25m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00C - R0001 - Toilets - Girls - 39.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0002 - General Storeroom - 17.26 m2							

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting						
B00C - R0003 - Toilets - Boys - 41.23 m2							
Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - Pupil Facilities - 1961 - Timber							
Exterior							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00D - R0001 - General Storeroom - 12.09 m2							
No Asbestos							
B00D - R0002 - Movement - 57 m2							
Floor Coverings Res/Textile	Compressed AC Sheet						
B00E - Communal Facilities/General Learning - 1938 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00E - R0005 - Home Base - 48.56 m2							
No Asbestos							
B00E - R0006 - Personal Effects Storage - 5.84 m2							
No Asbestos							
B00E - R0007 - External Movement - 1.93 m2							
No Asbestos							
B00E - R0008 - Withdrawal Space - 1hb - 14.9 m2							
No Asbestos							
B00E - R0009 - External Movement - 1.7 m2							
No Asbestos							
B00E - R0010 - Sports Store - 15.53 m2							
No Asbestos							
B00E - R0011 - General Storeroom - 7.71 m2							
No Asbestos							
B00E - R0012 - Communal Space - 115.61 m2							
No Asbestos							
B00E - R0013 - Raised Platform - 30.5 m2							
No Asbestos							
B00E - R0014 - Movement - 3.84 m2							
No Asbestos							
B00E - R0015 - Movement - 28.62 m2							
No Asbestos							
B00E - R0016 - Movement - 19.3 m2							
No Asbestos							
B00F - Library/Pupil Facilities - 1906 - Brick/Block							
Exterior							

Eaves Linings	Flat AC Sheeting	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Fibre Cement Casting (Monocrete)	12m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00F - R0001 - Home Base - 66.33 m2							
Wall Linings Internal	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0002 - Home Base Store - 6.39 m2							
No Asbestos							
B00F - R0003 - General Storeroom - 5.91 m2							
No Asbestos							
B00F - R0004 - Communal Space - 66.04 m2							
No Asbestos							
B00F - R0009 - External Movement - 28.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0011 - General Storeroom - 3.81 m2							
No Asbestos							
B00F - R0012 - Personal Effects Storage - 3.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0013 - General Storeroom - 5.61 m2							
No Asbestos							
B00F - R0014 - General Storeroom - 3.49 m2							
No Asbestos							
B00F - R0015 - Reading Area - 110.68 m2							
No Asbestos							
B00F - R0016 - Canteen - 26.09 m2							
No Asbestos							
B00G - Special Purpose - 1973 - Brick/Veneer							
Exterior							
Gable Verge Lining	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Fibre Cement Casting (Monocrete)	12m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - Kiln Room - 26.52 m2							
No Asbestos							
B00G - R0002 - Home Base - 79.69 m2							

Electrical - Backing Board	Resinous Board	1	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0003 - Craft Store - 19.51 m2							
No Asbestos							
B00G - R0004 - External Movement - 13.12 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00H - Building Services - 2003 - Fibre Cement Clad							
Exterior							
Eaves Linings	Flat AC Sheeting	12m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Wall Cladding	Fibre Cement Casting (Monocrete)	32m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior							
B00H - R0001 - Garden Store - 20.85 m2							
No Asbestos							
B00I - Building Services - 2006 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00I - R0001 - General Assistant/Bulk Store - 6.16 m2							
No Asbestos							

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020