

# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hornsby North Public School (4365)
Region:	Northern Sydney AMU
State Electorate:	Hornsby
Local Government Area:	Hornsby

Last Reviewed By:	AECOM 28-JUN-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

4365 - Hornsby North Public School  
Site Plan (10432)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - General Learning/Pupil Facilities - 1975 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Sports Store - 6.25 m2</b>							
No Asbestos							
<b>B00A - R0002 - Practical Activities - 1hb - 52.33 m2</b>							
No Asbestos							
<b>B00A - R0003 - Home Base - 52.55 m2</b>							
No Asbestos							
<b>B00A - R0004 - External Movement - 27.8 m2</b>							
No Asbestos							
<b>B00B - General Learning - 1971 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting						
Eaves Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Flat Roof	Non Accessible Area						
<b>Interior</b>							
<b>B00B - R0001 - Withdrawal Space - 1hb - 8.76 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0002 - Practical Activities - 1hb - 13.48 m2</b>							
No Asbestos							
<b>B00B - R0004 - Home Base - 40.26 m2</b>							
No Asbestos							
<b>B00B - R0007 - Home Base - 40.26 m2</b>							
No Asbestos							
<b>B00B - R0009 - Practical Activities - 1hb - 13.48 m2</b>							
No Asbestos							
<b>B00B - R0010 - Withdrawal Space - 1hb - 8.76 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0011 - Distribution Board - .21 m2</b>							
No Asbestos							Note: No inspection of live electrical installation
<b>B00B - R0012 - External Movement - 33.38 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0013 - External Movement - 5.58 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0014 - External Movement - 5.58 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - General Learning - 1966 - Brick/Block</b>							

Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	19m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior							
B00C - R0001 - Toilets - Girls - 21.02 m2							
Partition Walls (Cubicles)	Flat AC Sheeting						
B00C - R0002 - Cleaning Distributed Store - 3.54 m2							
No Asbestos							
B00C - R0003 - Toilets - Boys - 21.03 m2							
Partition Walls (Cubicles)	Flat AC Sheeting						
B00C - R0005 - Home Base - 47.54 m2							
No Asbestos							
B00C - R0007 - Practical Activities - 1hb - 27.4 m2							
No Asbestos							
B00C - R0008 - Practical Activities - 1hb - 8.48 m2							
No Asbestos							
B00C - R0009 - Practical Activities - 1hb - 8.48 m2							
No Asbestos							
B00C - R0011 - Home Base - 46.55 m2							
No Asbestos							
B00C - R0013 - Movement - 4.76 m2							
No Asbestos							
B00C - R0014 - Staff Room Annexe - 13.11 m2							
No Asbestos							
B00C - R0016 - Security Store - 8.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0017 - Distribution Board - .21 m2							
No Asbestos							Note: No inspection of live electrical installation
B00C - R0018 - External Movement - 50.12 m2							
Ceiling Structures/Linings	Flat AC Sheeting	51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0019 - External Movement - 11.39 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - General Learning/Library - 1975 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	19m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00D - R0001 - Toilets - Girls - 8.88 m2							
Partition Walls (Cubicles)	Flat AC Sheeting						

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R0002 - Toilets - Boys - 8.82 m2</b>								
Partition Walls (Cubicles)	Flat AC Sheeting							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R0003 - Movement - 13.71 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - ( X3 )							
<b>B00D - R0004 - Cleaning Distributed Store - 1.64 m2</b>								
No Asbestos								
<b>B00D - R0005 - Distribution Board - 1.52 m2</b>						<b>Note: No inspection of live electrical installation</b>		
Electrical - Mounting Board	Resinous Board	1	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
<b>B00D - R0006 - Library Office/Workroom - 20.7 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - ( X3 )							
<b>B00D - R0007 - Library Office/Workroom - 8.7 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00D - R0008 - Security Store - 12.61 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - ( X3 )							
<b>B00D - R0009 - Reading Area - 250.84 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - ( X5 )							
<b>B00D - R0010 - Seminar/Study - 14.13 m2</b>								
No Asbestos								
<b>B00D - R0011 - Seminar/Study - 13.4 m2</b>								
No Asbestos								
<b>B00D - R0012 - External Movement - 47.36 m2</b>								
No Asbestos								
<b>B00D - R0013 - External Stairs - 18.57 m2</b>								
No Asbestos								
<b>B00D - R1002 - Home Base - 62.14 m2</b>								
No Asbestos								
<b>B00D - R1004 - Practical Activities - 1hb - 27.07 m2</b>								
No Asbestos								
<b>B00D - R1006 - Home Base - 62.14 m2</b>								
No Asbestos								
<b>B00D - R1008 - External Movement - 48.35 m2</b>								
No Asbestos								
<b>B00D - R1009 - External Stairs - 18.57 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R9002 - Withdrawal Space - 1hb - 42.15 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - ( X5 )							
<b>B00D - R9004 - General Storeroom - 8.27 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							

<b>B00D - R9005 - Library Office/Workroom - 8.27 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
<b>B00D - R9007 - Withdrawal Space - 1hb - 47.15 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00D - R9009 - Plant - 27.55 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R9010 - Sports Store - 14.85 m2</b>							
No Asbestos							
<b>B00D - R9011 - External Movement - 55.89 m2</b>							
No Asbestos							
<b>B00E - Communal Facilities - 1975 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting						
Eaves Linings	Flat AC Sheeting	15m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	39m2	North, south	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00E - R0001 - P.E Store - 12.46 m2</b>							
No Asbestos							
<b>B00E - R0002 - Garden Store - 18.34 m2</b>							
No Asbestos							
<b>B00E - R0003 - Communal Space - 241.65 m2</b>							
No Asbestos							
<b>B00E - R0004 - Toilets - Boys - 12 m2</b>							
Partition Walls (Cubicles)	Flat AC Sheeting	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0005 - Movement - 11.74 m2</b>							
No Asbestos							
<b>B00E - R0006 - Raised Platform - 49.5 m2</b>							
No Asbestos							
<b>B00E - R0007 - Toilets - Girls - 14.65 m2</b>							
Partition Walls (Cubicles)	Flat AC Sheeting						
<b>B00E - R0008 - Movement - 8.68 m2</b>							
No Asbestos							
<b>B00E - R0009 - Distribution Board - .21 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00E - R0010 - Canteen - 46.81 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0011 - Canteen Office/Store - 3.1 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0012 - Canteen Office/Store - 5.99 m2</b>							
Electrical - Mounting Board	Resinous Board	1	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00E - R0014 - Staff Toilet - 2.41 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0015 - Cleaning Distributed Store - 3.17 m2</b>							
No Asbestos							
<b>B00E - R0016 - Hall Chair Store - 7.36 m2</b>							
No Asbestos							
<b>B00E - R0017 - External Movement - 37.78 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0019 - General Storeroom - 8.68 m2</b>							
No Asbestos							
<b>B00E - R0020 - External Movement - 23.12 m2</b>							
No Asbestos							
<b>B00F - General Learning - 1975 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	65m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	30	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Packing	14	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Underfloor Voids - Infill	Flat AC Sheeting	0.5	East	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00F - R0001 - Staff Room - 66.42 m2</b>							
No Asbestos							
<b>B00F - R0002 - General Storeroom - 10.35 m2</b>							
No Asbestos							
<b>B00F - R0003 - Staff Toilet - 3.24 m2</b>							
Wall Linings Internal	Flat AC Sheeting	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0004 - Staff Toilet - 4.23 m2</b>							
Wall Linings Internal	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0005 - Cleaning Distributed Store - 2.54 m2</b>							
No Asbestos							
<b>B00F - R0006 - Movement - 11.48 m2</b>							
No Asbestos							
<b>B00F - R0007 - Library Office/Workroom - 12.96 m2</b>							
No Asbestos							
<b>B00F - R0008 - Home Base - 56.65 m2</b>							
No Asbestos							
<b>B00F - R0009 - Home Base Store - 6.32 m2</b>							
No Asbestos							
<b>B00F - R0010 - Personal Effects Storage - 7.2 m2</b>							

No Asbestos							
<b>B00F - R0011 - Movement - 7.2 m2</b>							
No Asbestos							
<b>B00F - R0012 - Home Base Store - 6.28 m2</b>							
No Asbestos							
<b>B00F - R0013 - Home Base - 56.65 m2</b>							
No Asbestos							
<b>B00F - R0014 - Home Base - 57.36 m2</b>							
No Asbestos							
<b>B00F - R0015 - Home Base Store - 5.76 m2</b>							
No Asbestos							
<b>B00F - R0017 - Personal Effects Storage - 8.48 m2</b>							
No Asbestos							
<b>B00F - R0018 - Movement - 6.98 m2</b>							
No Asbestos							
<b>B00F - R0019 - Home Base Store - 5.76 m2</b>							
No Asbestos							
<b>B00F - R0020 - Home Base - 57.28 m2</b>							
No Asbestos							
<b>B00F - R0021 - External Movement - 129.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	130m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
<b>B00F - R9001 - General Assistant/Bulk Store - 29.21 m2</b>							
No Asbestos							
<b>B00F - R9002 - General Storeroom - 67.6 m2</b>							
No Asbestos							
<b>B00F - R9003 - Cleaning Supplies - 41.34 m2</b>							
No Asbestos							
<b>B00F - R9004 - Toilets - Boys - 16.22 m2</b>							
Partition Walls (Cubicles)	Flat AC Sheeting	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00F - R9005 - Toilets - Girls - 16.01 m2</b>							
Partition Walls (Cubicles)	Flat AC Sheeting	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R9006 - General Storeroom - 12.7 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00G - Administration/General Learning - 1970 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00G - R0001 - Movement - 1.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0002 - Personal Effects Storage - 6.59 m2</b>							
No Asbestos							
<b>B00G - R0003 - Home Base Store - 5.13 m2</b>							



No Asbestos							
<b>B00G - R0004 - Home Base - 56.74 m2</b>							
No Asbestos							
<b>B00G - R0005 - Home Base - 56.82 m2</b>							
No Asbestos							
<b>B00G - R0006 - Home Base Store - 5.13 m2</b>							
No Asbestos							
<b>B00G - R0007 - Cleaning Distributed Store - .54 m2</b>							
No Asbestos							
<b>B00G - R0008 - Movement - 6.13 m2</b>							
No Asbestos							
<b>B00G - R0009 - Personal Effects Storage - 6.77 m2</b>							
No Asbestos							
<b>B00G - R0010 - Distribution Board - .09 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
No Asbestos							
<b>B00G - R0011 - Movement - 1.63 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0012 - Cleaning Distributed Store - .54 m2</b>							
No Asbestos							
<b>B00G - R0013 - Home Base Store - 5.13 m2</b>							
No Asbestos							
<b>B00G - R0014 - Home Base - 56.9 m2</b>							
No Asbestos							
<b>B00G - R0015 - Home Base - 56.83 m2</b>							
No Asbestos							
<b>B00G - R0016 - Home Base Store - 5.13 m2</b>							
No Asbestos							
<b>B00G - R0017 - Sports Store - 6.58 m2</b>							
No Asbestos							
<b>B00G - R0018 - Movement - 1.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0019 - External Movement - 84.68 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0021 - Principal - 20.78 m2</b>							
No Asbestos							
<b>B00G - R0022 - Entry Vestibule - 36.28 m2</b>							
No Asbestos							
<b>B00G - R0023 - External Movement - 5.51 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0024 - Distribution Board - 3.13 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Wall Linings Internal	Flat AC Sheeting	2m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00G - R0025 - Cleaning Distributed Store - .94 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0026 - Staff Toilet - 4.15 m2</b>							
Wall Linings Internal	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00G - R0027 - Sick Bay - 8.52 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R0028 - Therapy - 4.14 m2</b>							
Wall Linings Internal	Flat AC Sheeting	5m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00G - R0029 - Movement - 26.55 m2</b>							
No Asbestos							
<b>B00G - R0030 - Duplicating Workroom - 14.15 m2</b>							
No Asbestos							
<b>B00G - R0031 - General Storeroom - 6.84 m2</b>							
No Asbestos							
<b>B00G - R0032 - Deputy Principal - 13.95 m2</b>							
No Asbestos							
<b>B00G - R0033 - Library Office/Workroom - 14.15 m2</b>							
No Asbestos							
<b>B00G - R0034 - External Movement - 4.84 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - General Learning - 1975 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	AC Fragments/Debris						
<b>Interior</b>							
<b>B00H - R0001 - Toilets - Boys/Girls - 3.04 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
<b>B00H - R0003 - Practical Activities - 1hb - 19.52 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0005 - Home Base - 87.01 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00H - R0006 - Home Base - 86.99 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00H - R0008 - Practical Activities - 1hb - 19.52 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0010 - Toilets - Boys/Girls - 3.04 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
<b>B00H - R0011 - External Movement - 65.53 m2</b>							
No Asbestos							
<b>B00I - Staff Facilities - 1975 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00I - R0001 - External Movement - 11.99 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0002 - Movement - 16.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0003 - Interview - 12.75 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0004 - Staff Toilet - 1.63 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0005 - Clerical Office - 10.64 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - R0006 - Resource/Toy Space - 9.62 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - General Learning - 2006 - Fibre Cement Clad</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00J - R0001 - Movement - 38.47 m2</b>							
No Asbestos							
<b>B00J - R0002 - Practical Activities - 1hb - 19.4 m2</b>							
No Asbestos							
<b>B00J - R0003 - Home Base Store - 6.02 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00J - R0004 - Home Base - 59.2 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00J - R0005 - Withdrawal Space - 2hb - 11.36 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00J - R0006 - Home Base - 59.19 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00J - R0007 - Home Base Store - 6.02 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00J - R0008 - Practical Activities - 1hb - 19.41 m2</b>							
No Asbestos							
<b>B00K - General Learning - 2010 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00K - R0001 - Practical Activities - 1hb - 20.48 m2</b>							
No Asbestos							

<b>B00K - R0002 - Home Base - 58.48 m2</b>	
No Asbestos	
<b>B00K - R0003 - Withdrawal Space - 1hb - 9.2 m2</b>	
No Asbestos	
<b>B00K - R0004 - Home Base Store - 5.96 m2</b>	
No Asbestos	
<b>B00K - R0005 - Practical Activities - 1hb - 18.81 m2</b>	
No Asbestos	
<b>B00K - R0006 - Home Base Store - 6.23 m2</b>	
No Asbestos	
<b>B00K - R0007 - Home Base - 60.28 m2</b>	
No Asbestos	
<b>B00K - R0008 - Withdrawal Space - 2hb - 11.67 m2</b>	
No Asbestos	
<b>B00K - R0009 - Practical Activities - 1hb - 18.82 m2</b>	
No Asbestos	
<b>B00K - R0010 - Home Base - 60.28 m2</b>	
No Asbestos	
<b>B00K - R0011 - Home Base Store - 6.18 m2</b>	
No Asbestos	
<b>B00K - R0012 - General Storeroom - 5.06 m2</b>	
No Asbestos	
<b>B00K - R0013 - General Storeroom - 6.37 m2</b>	
No Asbestos	
<b>B00K - R0014 - External Movement - 83.13 m2</b>	
No Asbestos	
<b>B00K - R0015 - External Stairs - 14.15 m2</b>	
No Asbestos	
<b>B00K - R0016 - External Stairs - 12.26 m2</b>	
No Asbestos	
<b>B00K - R1001 - Practical Activities - 1hb - 20.48 m2</b>	
No Asbestos	
<b>B00K - R1002 - Home Base - 58.48 m2</b>	
No Asbestos	
<b>B00K - R1003 - Withdrawal Space - 1hb - 9.2 m2</b>	
No Asbestos	
<b>B00K - R1004 - Home Base Store - 5.96 m2</b>	
No Asbestos	
<b>B00K - R1005 - Practical Activities - 1hb - 18.81 m2</b>	
No Asbestos	
<b>B00K - R1006 - Home Base Store - 6.23 m2</b>	
No Asbestos	
<b>B00K - R1007 - Home Base - 60.28 m2</b>	
No Asbestos	
<b>B00K - R1008 - Withdrawal Space - 2hb - 11.67 m2</b>	
No Asbestos	
<b>B00K - R1009 - Practical Activities - 1hb - 18.82 m2</b>	
No Asbestos	
<b>B00K - R1010 - Home Base - 60.28 m2</b>	
No Asbestos	
<b>B00K - R1011 - Home Base Store - 6.18 m2</b>	
No Asbestos	

<b>B00K - R1012 - External Movement - 83.13 m2</b>	
No Asbestos	
<b>B00K - R1013 - External Stairs - 21.11 m2</b>	
No Asbestos	
<b>B00K - R1014 - External Stairs - 21.04 m2</b>	
No Asbestos	

## Demountables

### OS 602 10310 - Learning Unit - Standard With P.A.A. - Placement Date : 14-JAN-2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 602 11925 - Learning Unit - Standard With P.A.A. - Placement Date : 03-FEB-2005

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 603 12325 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 24-OCT-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 603 13282 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 09-DEC-2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 603 13291 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 11-JAN-2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 603 13359 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 24-OCT-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 15157 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995

No Asbestos Found

### OS 602 15221 - Learning Unit - Standard With P.A.A. - Placement Date : 23-NOV-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 19010 - Learning Unit - Standard With P.A.A A/C - Placement Date : 25-NOV-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 19122 - Learning Unit - Standard With P.A.A A/C - Placement Date : 25-NOV-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

**OS 606 19258 - Learning Unit - Standard With P.A.A A/C - Placement Date : 25-JAN-2020**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 606 19262 - Learning Unit - Standard With P.A.A A/C - Placement Date : 25-JAN-2020**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 606 19594 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-JAN-2019**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 606 19666 - Learning Unit - Standard With P.A.A A/C - Placement Date : 02-APR-2019**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found