

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hillvue Public School (4437)
Region:	North Western NSW AMU
State Electorate:	Tamworth
Local Government Area:	Tamworth

Last Reviewed By:	WSP 08-AUG-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

4437 - Hillvue Public School
Site Plan (10430)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Library - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0004 - General Storeroom - 12.98 m2							
No Asbestos							
B00A - R0005 - Sick Bay - 9.46 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0007 - Clerical Office/Workroom - 10.1 m2							
No Asbestos							
B00A - R0008 - Entry Vestibule - 12.8 m2							
No Asbestos							
B00A - R0009 - Principal - 15.97 m2							
No Asbestos							
B00A - R0010 - Staff Toilet - 3.65 m2							
No Asbestos							
B00A - R0011 - General Storeroom - 1.62 m2							
No Asbestos							
B00A - R0012 - Deputy Principal - 15.97 m2							
No Asbestos							
B00A - R0013 - Movement - 86.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	86m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0014 - Reading Area - 92.7 m2							
No Asbestos							
B00A - R0017 - Reading Area - 53.73 m2							
No Asbestos							
B00A - R0018 - Main Switch Board - 7.09 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0019 - Canteen Office/Store - 4.09 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0020 - Canteen - 27.53 m2							
No Asbestos							
B00A - R0021 - Canteen Office/Store - 4.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0022 - Movement - 4.77 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0023 - Staff Toilet - 2.31 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0024 - Cleaning Supplies - 9.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00A - R0025 - Uniform Shop - 6.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0026 - Cleaning Distributed Store - 9.29 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0027 - Staff Toilet - 3.99 m2							
No Asbestos							
B00A - R0028 - Staff Toilet - 9.53 m2							
No Asbestos							
B00A - R0029 - Movement - 11.17 m2							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0030 - Cleaning Distributed Store - 4.51 m2							
No Asbestos							
B00A - R0031 - Interview - 14.6 m2							
No Asbestos							
B00A - R0032 - General Storeroom - 9.45 m2							
No Asbestos							
B00A - R0033 - Security Store - 9.26 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0034 - Staff Room Annexe - 9.37 m2							
No Asbestos							
B00A - R0035 - Movement - 9.7 m2							
No Asbestos							
B00A - R0036 - Deputy Principal - 15.69 m2							
No Asbestos							
B00A - R0037 - Staff Toilet - 1.91 m2							
No Asbestos							
B00A - R0038 - General Storeroom - 1.27 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0039 - Staff Room Annexe - 20.08 m2							
No Asbestos							
B00A - R0040 - Staff Kitchen - 5.92 m2							
No Asbestos							
B00A - R0041 - Staff Room - 77.66 m2							
No Asbestos							
B00A - R0042 - External Movement - 173.78 m2							
Ceiling Structures/Linings	Flat AC Sheeting	175m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0043 - Library Office/Workroom - 21.37 m2							
No Asbestos							
B00A - R0044 - Clerical Office - 25.89 m2							
No Asbestos							
B00B - Communal Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						

Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00B - R0001 - Communal Space - 91.28 m2							
Ceiling Structures/Linings	Flat AC Sheeting	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0002 - External Movement - 76.33 m2							
Wall Linings Internal - Infill	Compressed AC Sheet						
Ceiling Structures/Linings	Flat AC Sheeting	77m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - Building Services - 1974 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	10m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00C - R0001 - General Assistant/Bulk Store - 30.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - Communal Facilities - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00D - R0003 - External Movement - 95.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	96m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0004 - Communal Space - 126.17 m2							
Requires Inspection							
B00E - Building Services - 2002 - Metal Shed							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00E - R0001 - General Assistant/Bulk Store - 53.29 m2							
No Asbestos							
B00F - Communal Facilities - 2011 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00F - R0001 - Communal Space - 146.46 m2							
No Asbestos							
B00F - R0002 - Raised Platform - 59.42 m2							

No Asbestos		
B00F - R0003 - Hall Chair Store - 9.65 m2		
No Asbestos		
B00F - R0004 - Communal/Performance Store - 9.49 m2		
No Asbestos		
B00F - R0005 - P.E Store - 13.14 m2		
No Asbestos		
B00F - R0006 - Toilet - Lobby - 2.3 m2		
No Asbestos		
B00F - R0007 - Toilets - Girls - 7.25 m2		
No Asbestos		
B00F - R0008 - Sound Cupboard - 2.05 m2		
No Asbestos		
B00F - R0009 - Toilet - Lobby - 3.23 m2		
No Asbestos		
B00F - R0010 - Toilets - Boys - 5.65 m2		
No Asbestos		
B00F - R0011 - Cleaning Distributed Store - 3.57 m2		
No Asbestos		
B00F - R0012 - General Storeroom - 1.62 m2		
No Asbestos		
B00F - R0013 - Main Switch Board - 3.42 m2		
No Asbestos		
B00F - R0014 - Access Shower/Toilet/Change - 6.82 m2		
No Asbestos		
B00F - R0015 - Covered Outdoor Learning Area - 157.75 m2		
No Asbestos		
B00F - R0016 - Movement - 7.18 m2		
No Asbestos		
B00F - R0017 - Movement - 12.4 m2		
No Asbestos		
B00F - R0018 - Ramp - 11.85 m2		
No Asbestos		
B00G - Storage - 2014 - Steel		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00G - R0001 - Garden Store - 16.27 m2		
No Asbestos		
B00G - R0002 - Covered Outdoor Learning Area - 41.68 m2		
No Asbestos		
B00H - Storage - 2016 - Metal Shed		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Ceiling Voids	No Asbestos Found						
Interior							
B00H - R0001 - Garage/Carport - 44.23 m2							
No Asbestos							
B00J - Storage - 2016 - Metal Shed							
Exterior							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00J - R0001 - External Movement - 19.41 m2							
No Asbestos							
B00J - R0002 - General Assistant/Bulk Store - 35.7 m2							
No Asbestos							
B011 - General Learning/Support Unit - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B011 - R0001 - Personal Effects Storage - 6.72 m2							
No Asbestos							
B011 - R0002 - Home Base Store - 6.72 m2							
No Asbestos							
B011 - R0003 - Home Base - 86.58 m2							
No Asbestos							
B011 - R0005 - Cleaning Distributed Store - 2.28 m2							
No Asbestos							
B011 - R0006 - Distribution Board - 2.44 m2							
No Asbestos							
B011 - R0007 - Sports Store - 16.77 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0008 - General Storeroom - 16.71 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0009 - Home Base Store - E - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0010 - Personal Effects - E - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0011 - Home Base - E - 56.74 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0012 - Home Base - 56.89 m2							
No Asbestos							
B011 - R0013 - Personal Effects Storage - 6.95 m2							

Note: No inspection of live electrical installation

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0014 - Home Base Store - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0015 - External Movement - 120.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	121m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0016 - Handwashing Facilities - 1.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B011 - R0017 - Toilets - Boys/Girls - 1.59 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B012 - R0001 - Distribution Board - 2.44 m2				Note: No inspection of live electrical installation			
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
B012 - R0002 - Cleaning Distributed Store - 2.28 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0004 - Home Base - 86.45 m2							
No Asbestos							
B012 - R0005 - Home Base Store - 7.01 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0006 - Personal Effects Storage - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0007 - Home Base Store - 7.11 m2							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0008 - Personal Effects Storage - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0009 - Home Base - 56.81 m2							
No Asbestos							
B012 - R0010 - Home Base - 56.97 m2							
No Asbestos							
B012 - R0011 - Personal Effects Storage - 6.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0012 - Home Base Store - 6.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0013 - Toilets - Girls - 16.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0014 - Toilets - Boys - 16.43 m2							

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0015 - External Movement - 116 m2							
Ceiling Structures/Linings	Flat AC Sheeting	117m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0016 - Handwashing Facilities - 1.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B012 - R0017 - Toilets - Boys/Girls - 1.59 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B013 - R0001 - Personal Effects Storage - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0002 - Home Base Store - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0003 - Home Base - 56.74 m2							
No Asbestos							
B013 - R0004 - Home Base - 56.82 m2							
No Asbestos							
B013 - R0005 - Personal Effects Storage - 6.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0006 - Home Base Store - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0007 - Home Base Store - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0008 - Personal Effects Storage - 6.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0009 - Home Base - 85.86 m2							
No Asbestos							
B013 - R0011 - Cleaning Distributed Store - 2.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0012 - Distribution Board - 2.47 m2							
						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0013 - Toilets - Boys - 16.39 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0014 - Toilets - Girls - 16.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0015 - External Movement - 119.27 m2							

Ceiling Structures/Linings	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0016 - Handwashing Facilities - 1.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B013 - R0017 - Toilets - Boys/Girls - 1.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B014 - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B014 - R0001 - Practical Activities - 1hb - 18.36 m2							
No Asbestos							
B014 - R0002 - Home Base - 51.18 m2							
No Asbestos							
B014 - R0003 - Home Base - 51.18 m2							
No Asbestos							
B014 - R0004 - Practical Activities - 1hb - 18.36 m2							
No Asbestos							
B014 - R0005 - Home Base Store - 10.28 m2							
No Asbestos							
B014 - R0006 - Toilets - Girls - 12.46 m2							
No Asbestos							
B014 - R0007 - Toilets - Boys - 12.24 m2							
No Asbestos							
B014 - R0008 - Distribution Board - .83 m2							
No Asbestos							Note: No inspection of live electrical installation
B014 - R0009 - Home Base Store - 2.24 m2							
No Asbestos							
B014 - R0010 - Cleaning Distributed Store - 2.71 m2							
No Asbestos							
B014 - R0011 - Toilets - Boys/Girls - 3.57 m2							
No Asbestos							
B014 - R0012 - Home Base - 75.16 m2							
No Asbestos							
B014 - R0013 - Practical Activities - 1hb - 18.37 m2							
No Asbestos							
B014 - R0014 - External Movement - 129.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	130m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0P1 - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						

Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B0P1 - R0001 - Home Base - 63.57 m2								
No Asbestos								
B0P1 - R0002 - Toilets - Girls - 19.51 m2								
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P1 - R0003 - Cleaning Distributed Store - 1.92 m2								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P1 - R0004 - Toilets - Boys - 21.68 m2								
Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P1 - R0005 - Home Base - 63.43 m2								
No Asbestos								
B0P1 - R0006 - Home Base - 63.42 m2								
Floor Coverings Res/Textile	Vinyl Tiles	5m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P1 - R0007 - Practical Activities - 1hb - 79.98 m2								
No Asbestos								
B0P1 - R0008 - General Storeroom - .88 m2								
No Asbestos								
B0P1 - R0009 - General Storeroom - .88 m2								
No Asbestos								
B0P1 - R0010 - Cleaning Distributed Store - .87 m2								
No Asbestos								
B0P1 - R0011 - Distribution Board - .87 m2								
						Note: No inspection of live electrical installation		
Electrical - Mounting Board	Resinous Board	1	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P1 - R0012 - Home Base - 63.43 m2								
No Asbestos								
B0P1 - R0013 - External Movement - 138.99 m2								
Ceiling Structures/Linings	Flat AC Sheeting	140m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal - Infill	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal - Infill	Compressed AC Sheet	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B0P2 - General Learning/Pupil Facilities - 1969 - Brick/Block								
Exterior								
Ceiling Voids - Flat Roof	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Interior								
B0P2 - R0001 - Home Base - 56.42 m2								
No Asbestos								
B0P2 - R0002 - Home Base - 56.41 m2								
No Asbestos								
B0P2 - R0003 - Home Base - 55.96 m2								

No Asbestos							
B0P2 - R0004 - Practical Activities - 1hb - 12.73 m2							
No Asbestos							
B0P2 - R0005 - Distribution Board - 1.22 m2							Note: No inspection of live electrical installation
No Asbestos							
B0P2 - R0006 - Toilets - Girls - 16.88 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0P2 - R0007 - Home Base - 57.99 m2							
No Asbestos							
B0P2 - R0008 - Practical Activities - 1hb - 57.02 m2							
No Asbestos							
B0P2 - R0009 - Toilets - Boys - 18.42 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0P2 - R0010 - General Storeroom - 14.73 m2							
No Asbestos							
B0P2 - R0011 - External Movement - 164.94 m2							
Ceiling Structures/Linings	Flat AC Sheeting	166m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B0P3 - General Learning/Pupil Facilities - 1969 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B0P3 - R0001 - Toilets - Girls - 16.91 m2							
No Asbestos							
B0P3 - R0002 - Practical Activities - 1hb - 18.36 m2							
No Asbestos							
B0P3 - R0003 - Home Base - 52.9 m2							
No Asbestos							
B0P3 - R0004 - Home Base - 51.96 m2							
No Asbestos							
B0P3 - R0005 - Practical Activities - 1hb - 18.36 m2							
No Asbestos							
B0P3 - R0006 - General Storeroom - 12.39 m2							
No Asbestos							
B0P3 - R0007 - Toilets - Boys - 17.36 m2							
No Asbestos							
B0P3 - R0008 - Practical Activities - 1hb - 17.82 m2							
No Asbestos							
B0P3 - R0009 - Home Base - 51.72 m2							
No Asbestos							
B0P3 - R0010 - Home Base - 52.74 m2							
No Asbestos							
B0P3 - R0011 - Practical Activities - 1hb - 17.82 m2							
No Asbestos							
B0P3 - R0012 - Cleaning Distributed Store - .79 m2							
No Asbestos							

B0P3 - R0013 - General Storeroom - 12.37 m2

No Asbestos

B0P3 - R0014 - Distribution Board - .75 m2**Note: No inspection of live electrical installation**

No Asbestos

B0P3 - R0015 - External Movement - 142.99 m2

Ceiling Structures/Linings	Flat AC Sheeting	144m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020