

Asbestos Register


(Hazardous Materials and Risk Assessment)

School:	Hampden Park Public School (4494)
Region:	South Western Sydney AMU
State Electorate:	Lakemba
Local Government Area:	Canterbury-Bankstown

Last Reviewed By:	Greencap 30-NOV-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

4494 - Hampden Park Public School
Site Plan (11662)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1995 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 17.76 m2							
No Asbestos							
B00A - R0002 - Plant - 9.51 m2							
No Asbestos							
B00A - R0003 - Special Programs Room - 30.29 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Special Programs Room - 43.65 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0005 - Special Programs Store - 1.66 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Main Switch Board - 3.03 m2							
No Asbestos							
B00A - R0007 - Cleaning Distributed Store - 2.52 m2							
No Asbestos							
B00A - R0008 - Home Base - 59.39 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - General Storeroom - 6.71 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0010 - Distribution Board - 1.01 m2							
No Asbestos							Note: No inspection of live electrical installation
B00A - R0011 - Practical Activities - 1hb - 29.94 m2							
No Asbestos							
B00A - R0012 - Home Base Store - 5.92 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Withdrawal Space - 1hb - 5.9 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - Home Base - 50.35 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0015 - Practical Activities - 1hb - 31.24 m2							
No Asbestos							
B00A - R0016 - Home Base Store - 5.9 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0017 - Withdrawal Space - 1hb - 5.92 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0018 - Home Base - 50.64 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0019 - Movement - 88.12 m2							
No Asbestos							
B00B - General Learning/Pupil Facilities - 1995 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							

B00B - R0001 - Home Base - 46.56 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0002 - Practical Activities - 1hb - 28.39 m2		
No Asbestos		
B00B - R0003 - Home Base Store - 5.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0004 - Withdrawal Space - 1hb - 5.88 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0005 - Home Base - 50.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0006 - Practical Activities - 1hb - 26.75 m2		
No Asbestos		
B00B - R0007 - Home Base Store - 6.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0008 - Withdrawal Space - 1hb - 6.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0009 - Home Base - 49.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - Distribution Board - .91 m2		
No Asbestos		Note: No inspection of live electrical installation
B00B - R0011 - Movement - 180.06 m2		
No Asbestos		
B00B - R0012 - Toilets - Girls - 25.61 m2		
No Asbestos		
B00B - R0013 - Disabled Toilet - 5.25 m2		
No Asbestos		
B00B - R0014 - Toilets - Boys - 22.1 m2		
No Asbestos		
B00B - R0015 - Stairs - 12.69 m2		
No Asbestos		
B00B - R1001 - Home Base Store - 9.73 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1002 - Practical Activities - 1hb - 28.52 m2		
No Asbestos		
B00B - R1003 - Home Base - 56.27 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1004 - Withdrawal Space - 1hb - 11.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1005 - Home Base - 56.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1006 - Practical Activities - 1hb - 28.23 m2		
No Asbestos		
B00B - R1007 - Home Base Store - 9.77 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1008 - Practical Activities - 1hb - 30.82 m2		
No Asbestos		
B00B - R1009 - Home Base Store - 5.93 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1010 - Withdrawal Space - 1hb - 6.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1011 - Home Base - 52.48 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1012 - Distribution Board - .96 m2		Note: No inspection of live electrical installation
No Asbestos		
B00B - R1013 - Cleaning Distributed Store - 6.19 m2		
No Asbestos		
B00B - R1014 - Staff Toilet - 7.35 m2		
No Asbestos		
B00B - R1015 - Special Programs Room - 31.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1016 - Movement - 105.84 m2		
No Asbestos		
B00B - R1017 - Stairs - 18.28 m2		
No Asbestos		
B00C - Administration/Staff Facilities - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00C - R0001 - Movement - 121.51 m2		
No Asbestos		
B00C - R0002 - Staff Room - 80.66 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0003 - Distribution Board - .64 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0008 - Sick Bay - 10.93 m2		
No Asbestos		
B00C - R0009 - Sick Bay - Shower/Toilet - 6.07 m2		
No Asbestos		
B00C - R0010 - Deputy Principal - 13.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0011 - Interview - 13.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0012 - Principal - 16.63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0013 - Community Clinic - 13.21 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0014 - Staff Toilet - 3.16 m2		
No Asbestos		
B00C - R0015 - Community Clinic - 6.83 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0016 - Entry Vestibule - 29.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0017 - Plant - .57 m2		
No Asbestos		
B00C - R0020 - Staff Room Annexe - 13.08 m2		
No Asbestos		
B00C - R0021 - Security Store - 17.59 m2		
No Asbestos		
B00C - R0022 - Movement - 55.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0023 - Cleaning Supplies - 12.81 m2		

No Asbestos		
B00C - R0024 - Clerical Office/Workroom - 50.89 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0025 - Deputy Principal - Type 2 - 26.87 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0026 - Toilet - Lobby - 4.34 m2		
No Asbestos		
B00C - R0027 - Staff Toilet - 2.1 m2		
No Asbestos		
B00C - R0028 - Toilet - Lobby - 1.96 m2		
No Asbestos		
B00C - R0029 - Staff Toilet - 1.96 m2		
No Asbestos		
B00D - Library/General Learning - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0001 - Movement - 195.65 m2		
No Asbestos		
B00D - R0002 - Reading Area - 282.67 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - Library Office/Workroom - 27.06 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0004 - Communications Room - 13.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0005 - General Storeroom - 12.04 m2		
No Asbestos		
B00D - R0006 - Distribution Board - .81 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0007 - Stairs - 12.73 m2		
No Asbestos		
B00D - R0008 - Stairs - 7.39 m2		
No Asbestos		
B00D - R1001 - Movement - 144.05 m2		
No Asbestos		
B00D - R1002 - Practical Activities - 1hb - 27.63 m2		
No Asbestos		
B00D - R1003 - Home Base Store - 5.92 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1004 - Withdrawal Space - 1hb - 6.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1005 - Home Base - 52.48 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1006 - Home Base - 52.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1007 - Withdrawal Space - 1hb - 6.31 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1008 - Home Base Store - 5.87 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00D - R1009 - Practical Activities - 1hb - 27.42 m2		
No Asbestos		
B00D - R1010 - Distribution Board - 1.01 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R1011 - Practical Activities - 1hb - 30.82 m2		
No Asbestos		
B00D - R1012 - Home Base Store - 5.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1013 - Withdrawal Space - 1hb - 6.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1014 - Home Base - 52.56 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1015 - Home Base - 63.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1016 - General Storeroom - 6.07 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1017 - Toilets - Girls - 9.8 m2		
No Asbestos		
B00D - R1018 - Toilets - Boys - 8.4 m2		
No Asbestos		
B00D - R1019 - Stairs - 12.81 m2		
No Asbestos		
B00D - R1020 - Stairs - 18.37 m2		
No Asbestos		
B00E - General Learning/Staff Facilities - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00E - R0001 - Movement - 83.55 m2		
No Asbestos		
B00E - R0002 - Disabled Toilet - 5.47 m2		
No Asbestos		
B00E - R0003 - Cleaning Distributed Store - 3.84 m2		
No Asbestos		
B00E - R0004 - Special Programs Room - 30.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0005 - Distribution Board - 1.02 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0006 - Distribution Board - .86 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0007 - Practical Activities - 1hb - 27.31 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0008 - Home Base Store - 8.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0009 - Home Base - 54.59 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0010 - Withdrawal Space - 1hb - 11.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0011 - Home Base - 54.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00E - R0012 - Home Base Store - 8.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0013 - Practical Activities - 1hb - 27.31 m2		
No Asbestos		
B00E - R0014 - Practical Activities - 1hb - 31.28 m2		
No Asbestos		
B00E - R0015 - Home Base Store - 5.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0016 - Withdrawal Space - 1hb - 5.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - Home Base - 51.35 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0018 - Staff Room Annexe - 40.61 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0019 - General Storeroom - 5.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - General Learning/Pupil Facilities - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Movement - 197.44 m2		
No Asbestos		
B00F - R0002 - Toilets - Boys - 15.22 m2		
No Asbestos		
B00F - R0003 - Kiln Room - 6.91 m2		
No Asbestos		
B00F - R0004 - Toilets - Girls - 19.37 m2		
No Asbestos		
B00F - R0005 - Practical Activities - 1hb - 28.19 m2		
No Asbestos		
B00F - R0006 - Home Base Store - 9.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0007 - Home Base - 53.72 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0008 - Withdrawal Space - 1hb - 12.09 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0009 - Home Base - 53.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0010 - Home Base Store - 9.28 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0011 - Practical Activities - 1hb - 26.81 m2		
No Asbestos		
B00F - R0012 - Distribution Board - 1.13 m2		
No Asbestos		Note: No inspection of live electrical installation
B00F - R0013 - General Assistant/Bulk Store - 19.44 m2		
No Asbestos		
B00F - R0014 - Cleaning Supplies - 14.16 m2		
No Asbestos		
B00F - R0015 - Stairs - 12.73 m2		
No Asbestos		

B00F - R1001 - Movement - 106.28 m2							
No Asbestos							
B00F - R1002 - Practical Activities - 1hb - 28.52 m2							
No Asbestos							
B00F - R1003 - Home Base Store - 9.73 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1004 - Home Base - 56.04 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1005 - Withdrawal Space - 1hb - 11.59 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1006 - Home Base - 56.38 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1007 - Home Base Store - 9.85 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1008 - Practical Activities - 1hb - 28.02 m2							
No Asbestos							
B00F - R1009 - Distribution Board - .95 m2							Note: No inspection of live electrical installation
No Asbestos							
B00F - R1010 - Practical Activities - 1hb - 30.74 m2							
No Asbestos							
B00F - R1011 - Home Base - 52.35 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1012 - Withdrawal Space - 1hb - 6.27 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1013 - Home Base Store - 5.9 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1014 - Staff Toilet - 7.45 m2							
No Asbestos							
B00F - R1015 - Cleaning Distributed Store - 4.91 m2							
No Asbestos							
B00F - R1016 - Special Programs Room - 37 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00F - R1017 - Stairs - 18.38 m2							
No Asbestos							
B00G - Communal Facilities/General Learning - 1979 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Wall Cladding	Flat AC Sheeting						
Gable Ends	Flat AC Sheeting	20m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Ends	No Asbestos Found						
Interior							
B00G - M0001 - Withdrawal Space - 1hb - 19.56 m2							
No Asbestos							
B00G - M0002 - Staff Room Annexe - 8.26 m2							
No Asbestos							
B00G - M0003 - General Storeroom - 26.78 m2							
No Asbestos							
B00G - R0001 - Withdrawal Space - 1hb - 7.25 m2							

No Asbestos		
B00G- R0002 - Home Base - 50.01 m2		
No Asbestos		
B00G- R0003 - Movement - 8.85 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00G- R0004 - Home Base Store - 2.67 m2		
No Asbestos		
B00G- R0005 - Withdrawal Space - 1hb - 10.17 m2		
No Asbestos		
B00G- R0006 - Movement - 26.88 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00G- R0007 - Practical Activities - 1hb - 49.45 m2		
No Asbestos		
B00G- R0008 - Craft Store - 2.64 m2		
No Asbestos		
B00G- R0009 - Home Base - 50.38 m2		
No Asbestos		
B00G- R0010 - Practical Activities - 1hb - 7.79 m2		
No Asbestos		
B00G- R0011 - Movement - 8.28 m2		
Wall Linings Internal - Infill	Flat AC Sheeting	
Ceiling Structures/Linings	Flat AC Sheeting	
B00G- R0012 - Toilets - Boys/Girls - 3.32 m2		
No Asbestos		
B00G- R0013 - Home Base Store - 2.71 m2		
No Asbestos		
B00G- R0014 - Distribution Board - .67 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00G- R0015 - Cleaning Distributed Store - .7 m2		
No Asbestos		
B00G- R0016 - Distribution Board - .58 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00G- R0017 - Staff Shower/Change - 5.07 m2		
No Asbestos		
B00G- R0018 - Staff Toilet - 2.67 m2		
No Asbestos		
B00G- R0019 - Canteen Office/Store - 2.17 m2		
No Asbestos		
B00G- R0020 - Canteen - 37.01 m2		
No Asbestos		
B00G- R0021 - Movement - 38.74 m2		
No Asbestos		
B00G- R0022 - Movement - 57.41 m2		
Wall Linings Internal - Service Risers / Boxing	Flat AC Sheeting	
Ceiling Structures/Linings	Flat AC Sheeting	
B00G- R0023 - Distribution Board - .88 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00G- R0024 - Communal Space - 184.42 m2		
No Asbestos		
B00G- R0025 - Raised Platform - 40.34 m2		
No Asbestos		

B00G - R0026 - Movement - 7.43 m2		
No Asbestos		
B00G - R0027 - Hall Chair Store - 4.87 m2		
No Asbestos		
B00G - R0028 - Hall Chair Store - 10.96 m2		
No Asbestos		
B00G - R0029 - Hall Chair Store - 4.08 m2		
No Asbestos		
B00G - R0030 - Movement - 8.2 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00G - R0031 - General Storeroom - 20.68 m2		
No Asbestos		
B00G - R0032 - Withdrawal Space - 1hb - 11.58 m2		
No Asbestos		
B00G - R0033 - Movement - 140.25 m2		
No Asbestos		
B00G - R0034 - Toilets - Boys - 4.83 m2		
No Asbestos		
B00G - R0035 - Toilets - Girls - 4.85 m2		
No Asbestos		
B00G - R0036 - General Storeroom - 6.01 m2		
No Asbestos		
B00G - R0037 - Movement - 3.73 m2		
No Asbestos		
B00G - R0038 - Staff Room Annexe - 11.03 m2		
No Asbestos		
B00G - R0039 - General Storeroom - 2.99 m2		
No Asbestos		
B00G - R0040 - Toilets - Boys/Girls - 4.68 m2		
No Asbestos		
B00G - R0041 - Practical Activities - 1hb - 9.42 m2		
No Asbestos		
B00H - General Learning - 2004 - Fibre Cement Clad		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00H - R0001 - Movement - 38.51 m2		
No Asbestos		
B00H - R0002 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B00H - R0003 - Home Base Store - 6.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0004 - Home Base - 59.23 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0005 - Withdrawal Space - 2hb - 11.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0006 - Home Base - 59.21 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0007 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00H - R0008 - Practical Activities - 1hb - 19.42 m2

No Asbestos

B00J - General Learning - 2004 - Fibre Cement Clad**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area

Ceiling Voids No Asbestos Found

Interior**B00J - R0001 - Movement - 38.51 m2**

No Asbestos

B00J - R0002 - Practical Activities - 1hb - 19.4 m2

No Asbestos

B00J - R0003 - Home Base Store - 6.01 m2

Floor Coverings Res/Textile No Asbestos Found

B00J - R0004 - Home Base - 59.23 m2

Floor Coverings Res/Textile No Asbestos Found

B00J - R0005 - Withdrawal Space - 2hb - 11.37 m2

Floor Coverings Res/Textile No Asbestos Found

B00J - R0006 - Home Base - 59.21 m2

Floor Coverings Res/Textile No Asbestos Found

B00J - R0007 - Home Base Store - 6.02 m2

Floor Coverings Res/Textile No Asbestos Found

B00J - R0008 - Practical Activities - 1hb - 19.42 m2

No Asbestos

B00K - General Learning - 2011 - Brick/Veneer**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - Practical Activities - 18.98 m2**

No Asbestos

B00K - R0002 - Home Base - 60.88 m2

No Asbestos

B00K - R0003 - Home Base Store - 6.11 m2

No Asbestos

B00K - R0004 - Withdrawal Space - 2hb - 11.4 m2

No Asbestos

B00K - R0005 - Practical Activities - 17.73 m2

No Asbestos

B00K - R0006 - Home Base - 60.94 m2

No Asbestos

B00K - R0007 - Home Base Store - 6.15 m2

No Asbestos

B00K - R0008 - Practical Activities - 18.98 m2

No Asbestos

B00K - R0009 - Home Base - 59.24 m2

No Asbestos

B00K - R0010 - Withdrawal Space - 1hb - 7.45 m2

No Asbestos

B00K - R0011 - Home Base Store - 6.16 m2

No Asbestos

B00K - R0012 - External Movement - 93.49 m2	
No Asbestos	
B00K - R0013 - External Stairs - 9.91 m2	
No Asbestos	
B00K - R0014 - Distribution Board - 1.06 m2	Note: No inspection of live electrical installation
No Asbestos	
B00K - R1001 - Practical Activities - 19.21 m2	
No Asbestos	
B00K - R1002 - Home Base - 61.27 m2	
No Asbestos	
B00K - R1003 - Home Base Store - 6.12 m2	
No Asbestos	
B00K - R1004 - Withdrawal Space - 2hb - 11.78 m2	
No Asbestos	
B00K - R1005 - Practical Activities - 19.21 m2	
No Asbestos	
B00K - R1006 - Home Base - 61.33 m2	
No Asbestos	
B00K - R1007 - Home Base Store - 6.19 m2	
No Asbestos	
B00K - R1008 - Practical Activities - 19.06 m2	
No Asbestos	
B00K - R1009 - Home Base - 59.47 m2	
No Asbestos	
B00K - R1010 - Withdrawal Space - 1hb - 7.66 m2	
No Asbestos	
B00K - R1011 - Home Base Store - 6.14 m2	
No Asbestos	
B00K - R1012 - External Movement - 79.64 m2	
No Asbestos	
B00K - R1013 - External Stairs - 15.24 m2	
No Asbestos	

Demountables

OS 606 10877 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-MAR-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 10886 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-MAR-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

NS 101 11230 - Learning Unit - Double Primary/PAA - Placement Date : 17-JAN-2008

No Asbestos Found

OS 751 14453 - Learning Unit - ESL - Placement Date : 29-OCT-1996

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Esl

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos

R2- Esl

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos

OS 602 14655 - Learning Unit - Standard With P.A.A. - Placement Date : 14-DEC-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 14844 - Learning Unit - Standard With P.A.A. - Placement Date : 29-OCT-1996

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 16303 - Learning Unit - Standard With P.A.A A/C - Placement Date : 21-JAN-2019

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 16318 - Learning Unit - Standard With P.A.A. - Placement Date : 29-OCT-1996

No Asbestos Found

OS 606 19051 - Learning Unit - Standard With P.A.A A/C - Placement Date : 22-SEP-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19743 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-MAR-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19744 - Learning Unit - Standard With P.A.A A/C - Placement Date : 25-MAR-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found