

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hambledon Public School (4590)
Region:	Western Sydney AMU
State Electorate:	Riverstone
Local Government Area:	Blacktown

Last Reviewed By:	Greencap 11-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1995 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 17.05 m2							
No Asbestos							
B00A - R0002 - Entry Vestibule - 22.05 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0003 - Clerical Office - 17.62 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Sick Bay - 8.58 m2							
No Asbestos							
B00A - R0005 - Staff Toilet - 7.1 m2							
No Asbestos							
B00A - R0006 - Interview - 13.16 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0007 - Deputy Principal - 13.16 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0008 - Staff Room Annexe - 13.16 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Cleaning Distributed Store - 4.52 m2							
No Asbestos							
B00A - R0010 - Staff Room - 45.36 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0011 - Staff Room Annexe - 19.5 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - Staff Toilet - 4.91 m2							
No Asbestos							
B00A - R0013 - Staff Toilet - 4.91 m2							
No Asbestos							
B00A - R0014 - Staff Toilet - 4.82 m2							
No Asbestos							
B00A - R0015 - General Storeroom - 18.22 m2							
No Asbestos							
B00A - R0016 - Principal - 16.8 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0017 - Duplicating Workroom - 19.69 m2							
No Asbestos							
B00A - R0018 - Movement - 33.84 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0019 - Distribution Board - .42 m2							
No Asbestos					Note: No inspection of live electrical installation		
B00A - R0020 - Movement - 69.44 m2							
No Asbestos							
B00B - Communal Facilities - 1995 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							

B00B - R0001 - Disabled Toilet - 5.44 m2		
No Asbestos		
B00B - R0002 - Toilets - Girls - 7.22 m2		
No Asbestos		
B00B - R0003 - General Storeroom - 12.69 m2		
No Asbestos		
B00B - R0004 - Plant - .56 m2		
No Asbestos		
B00B - R0005 - Hall Chair Store - 9.21 m2		
No Asbestos		
B00B - R0006 - Toilets - Boys - 8.73 m2		
No Asbestos		
B00B - R0007 - Shower/Change - 2.61 m2		
No Asbestos		
B00B - R0008 - Communal Space - 141.46 m2		
No Asbestos		
B00B - R0009 - Raised Platform - 47.79 m2		
No Asbestos		
B00B - R0010 - Main Switch Board - 2.04 m2		
No Asbestos		
B00B - R0011 - General Assistant/Bulk Store - 16.96 m2		
No Asbestos		
B00B - R0012 - General Storeroom - 14.05 m2		
No Asbestos		
B00B - R0013 - Canteen Office/Store - 8.61 m2		
No Asbestos		
B00B - R0014 - Canteen - 26.75 m2		
No Asbestos		
B00B - R0015 - Movement - 7.81 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0016 - Staff Toilet - 2.54 m2		
No Asbestos		
B00B - R0017 - Community Clinic - 19.86 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0018 - Garden Store - 7.29 m2		
No Asbestos		
B00B - R0019 - Uniform Shop - 6.48 m2		
No Asbestos		
B00B - R0020 - Cleaning Supplies - 9.24 m2		
No Asbestos		
B00B - R0021 - Movement - 16.39 m2		
No Asbestos		
B00B - R0022 - Movement - 113.75 m2		
No Asbestos		
B00C - General Learning - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00C - R0001 - Toilets - Girls - 17.07 m2		
No Asbestos		

B00C - R0002 - Kiln Room - 5.65 m2		
No Asbestos		
B00C - R0003 - Toilets - Boys - 14.54 m2		
No Asbestos		
B00C - R0004 - Movement - 2.6 m2		
No Asbestos		
B00C - R0005 - Home Base Store - 6.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0006 - Withdrawal Space - 1hb - 3.27 m2		
No Asbestos		
B00C - R0007 - Practical Activities - 1hb - 20.18 m2		
No Asbestos		
B00C - R0008 - Home Base - 54.93 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0009 - Withdrawal Space - 1hb - 10.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0010 - Home Base - 54.88 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0011 - Home Base Store - 6.7 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0012 - Practical Activities - 1hb - 20.11 m2		
No Asbestos		
B00C - R0013 - Withdrawal Space - 1hb - 3.28 m2		
No Asbestos		
B00C - R0014 - Movement - 4.54 m2		
No Asbestos		
B00C - R0015 - Distribution Board - .43 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0016 - Home Base Store - 5.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0017 - Withdrawal Space - 1hb - 3.18 m2		
No Asbestos		
B00C - R0018 - Practical Activities - 1hb - 20.06 m2		
No Asbestos		
B00C - R0019 - Home Base - 55.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0020 - Withdrawal Space - 1hb - 10.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0021 - Home Base - 55.08 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0022 - Practical Activities - 1hb - 20.14 m2		
No Asbestos		
B00C - R0023 - Withdrawal Space - 1hb - 3.19 m2		
No Asbestos		
B00C - R0024 - Home Base Store - 6.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0025 - Movement - 4.5 m2		
No Asbestos		
B00C - R0026 - Distribution Board - .43 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0027 - Home Base Store - 5.96 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0028 - Withdrawal Space - 1hb - 3.19 m2		
No Asbestos		
B00C - R0029 - Practical Activities - 1hb - 20.14 m2		
No Asbestos		
B00C - R0030 - Home Base - 55.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0031 - Withdrawal Space - 1hb - 10.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0032 - Home Base - 55.09 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0033 - Practical Activities - 1hb - 20.03 m2		
No Asbestos		
B00C - R0034 - Withdrawal Space - 1hb - 3.13 m2		
No Asbestos		
B00C - R0035 - Home Base Store - 6.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0036 - Movement - 2.6 m2		
No Asbestos		
B00C - R0037 - Movement - 196.44 m2		
No Asbestos		
B00D - Library - 1995 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0001 - Movement - 44.63 m2		
No Asbestos		
B00D - R0002 - Reading Area - 163.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - Library Office/Workroom - 23.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0004 - Communications Room - 12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - General Learning/Support Unit - 1995 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00E - R0001 - Home Base Store - 6.33 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0002 - Withdrawal Space - 1hb - 5.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0003 - Movement - 2.89 m2		
No Asbestos		
B00E - R0004 - Home Base - 54.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0005 - Practical Activities - 1hb - 22.87 m2		
No Asbestos		
B00E - R0006 - Distribution Board - .27 m2		
No Asbestos		Note: No inspection of live electrical installation

B00E - R0007 - Practical Activities - S - 1hb - 22.87 m2		
No Asbestos		
B00E - R0008 - Home Base - S - 54.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0009 - Movement - 2.62 m2		
No Asbestos		
B00E - R0010 - Withdrawal - S - 5.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0011 - Home Base Store - S - 6.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0012 - Toilets - Boys - 16.27 m2		
No Asbestos		
B00E - R0013 - Disabled Toilet - 5.67 m2		
No Asbestos		
B00E - R0014 - Toilets - Girls - 21.08 m2		
No Asbestos		
B00E - R0015 - Home Base Store - 6.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0016 - Withdrawal Space - 1hb - 5.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - Movement - 2.64 m2		
No Asbestos		
B00E - R0018 - Home Base - 54.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0019 - Practical Activities - 1hb - 22.8 m2		
No Asbestos		
B00E - R0020 - Distribution Board - .3 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0021 - Practical Activities - 1hb - 22.8 m2		
No Asbestos		
B00E - R0022 - Home Base - 54.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0023 - Movement - 2.65 m2		
No Asbestos		
B00E - R0024 - Withdrawal Space - 1hb - 5.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0025 - Home Base Store - 6.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0026 - Movement - 133.28 m2		
No Asbestos		
B00F - Tiered Learning - 1995 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00F - R0001 - Special Programs Room - 32.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0002 - Special Programs Store - 2.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0003 - Plant - 4.46 m2		

No Asbestos		
B00F - R0004 - Cleaning Distributed Store - 8.48 m2		
No Asbestos		
B00I - General Learning - 2004 - Fibre Cement Clad		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00I - R0001 - Movement - 38.47 m2		
No Asbestos		
B00I - R0002 - Practical Activities - 1hb - 19.39 m2		
No Asbestos		
B00I - R0003 - Home Base Store - 6.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0004 - Home Base - 59.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0005 - Withdrawal Space - 2hb - 11.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0006 - Home Base - 59.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0007 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00I - R0008 - Practical Activities - 1hb - 19.41 m2		
No Asbestos		
B00J - General Learning - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00J - R0001 - External Movement - 130.13 m2		
No Asbestos		
B00J - R0002 - Home Base Store - 6.23 m2		
No Asbestos		
B00J - R0003 - Home Base - 79.44 m2		
No Asbestos		
B00J - R0004 - Withdrawal Space - 2hb - 11.4 m2		
No Asbestos		
B00J - R0005 - Home Base - 79.29 m2		
No Asbestos		
B00J - R0006 - Home Base Store - 6.16 m2		
No Asbestos		
B00J - R0007 - Home Base Store - 6.16 m2		
No Asbestos		
B00J - R0008 - Home Base - 79.43 m2		
No Asbestos		
B00J - R0009 - Withdrawal Space - 2hb - 11.4 m2		
No Asbestos		
B00J - R0010 - Home Base - 78.63 m2		
No Asbestos		
B00J - R0011 - Home Base Store - 6.09 m2		
No Asbestos		

B00J - R0012 - Home Base Store - 6.09 m2	
No Asbestos	
B00J - R0013 - Home Base - 78.77 m2	
No Asbestos	
B00J - R0014 - Withdrawal Space - 2hb - 11.4 m2	
No Asbestos	
B00J - R0015 - Home Base - 79.25 m2	
No Asbestos	
B00J - R0016 - Home Base Store - 6.15 m2	
No Asbestos	

Demountables

OS 602 10106 - Learning Unit - Standard With P.A.A. - Placement Date : 23-DEC-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 841 11039 - Boys Toilet - Placement Date : 06-JUN-2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 750 11220 - Learning Unit - ESL - Placement Date : 26-SEP-2008

No Asbestos Found

OS 840 11435 - Girls Toilet - Placement Date : 06-JUN-2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12772 - Learning Unit - Standard With P.A.A. - Placement Date : 30-DEC-2005

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 602 12776 - Learning Unit - Standard With P.A.A. - Placement Date : 28-JAN-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 13563 - Learning Unit - Standard With P.A.A. - Placement Date : 08-APR-1997

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 602 13643 - Learning Unit - Standard With P.A.A. - Placement Date : 19-JAN-2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 14193 - Learning Unit - Standard With P.A.A. - Placement Date : 09-JAN-1997

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
R2- Home Base Store			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos
OS 602 14374 - Learning Unit - Standard With P.A.A. - Placement Date : 09-FEB-1998			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
Exterior			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
Interior			
R1- Learning space/withdrawal/entry			
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
R2- Home Base Store			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos
OS 603 18163 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 23-NOV-2012			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19142 - Learning Unit - Standard With P.A.A A/C - Placement Date : 08-JAN-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19578 - Learning Unit - Standard With P.A.A A/C - Placement Date : 15-JAN-2019			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19658 - Learning Unit - Standard With P.A.A A/C - Placement Date : 15-JAN-2019			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			