

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hassall Grove Public School (4598)
Region:	Western Sydney AMU
State Electorate:	Mount Druit
Local Government Area:	Blacktown

Last Reviewed By:	Greencap 11-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

4598 - Hassall Grove Public School
Site Plan (11618)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1992 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0001 - General Storeroom - 8.26 m2							
No Asbestos							
B00A - R0002 - Practical Activities - 1hb - 21.09 m2							
No Asbestos							
B00A - R0003 - Home Base - 64.51 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Home Base Store - 6.09 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0005 - Home Base - 59.91 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Practical Activities - 1hb - 21.45 m2							
No Asbestos							
B00A - R0007 - Home Base Store - 5.97 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0008 - Withdrawal Space - 1hb - 12.38 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Distribution Board - .78 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00A - R0010 - General Assistant/Bulk Store - 17.62 m2							
No Asbestos							
B00A - R0011 - Home Base Store - 6 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - Practical Activities - 1hb - 21.53 m2							
No Asbestos							
B00A - R0013 - Home Base - 60.14 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - Practical Activities - 1hb - 21.47 m2							
No Asbestos							
B00A - R0015 - Home Base - 67.51 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0016 - General Storeroom - 7.25 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0017 - Staff Room Annexe - 16.26 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0018 - Disabled Toilet - 5.16 m2							
No Asbestos							
B00A - R0019 - Cleaning Supplies - 3.21 m2							
No Asbestos							
B00A - R0020 - Movement - 91.22 m2							
No Asbestos							
B00B - General Learning - 1992 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							

B00B - R0001 - Movement - 86.96 m2		
No Asbestos		
B00B - R0002 - Cleaning Supplies - 6.22 m2		
No Asbestos		
B00B - R0003 - Home Base Store - 6.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0004 - Home Base - 65.38 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0005 - Practical Activities - 1hb - 21.33 m2		
No Asbestos		
B00B - R0006 - Practical Activities - 1hb - 21.31 m2		
No Asbestos		
B00B - R0007 - Home Base - 60.21 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0008 - Home Base Store - 6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0009 - Withdrawal Space - 1hb - 12.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - Home Base Store - 6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0011 - Home Base - 60.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0012 - Practical Activities - 1hb - 21.42 m2		
No Asbestos		
B00B - R0013 - Distribution Board - .64 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00B - R0014 - Sports Store - 18.74 m2		
No Asbestos		
B00B - R0015 - Practical Activities - 1hb - 21.21 m2		
No Asbestos		
B00B - R0016 - Home Base - 66.81 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0017 - Home Base Store - 5.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0018 - Special Programs Room - 34.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0019 - Special Programs Store - 1.88 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0020 - Toilets - Boys - 8 m2		
No Asbestos		
B00B - R0021 - Toilets - Boys - 20.33 m2		
No Asbestos		
B00B - R0022 - Plant - 4.64 m2		
No Asbestos		
B00C - General Learning - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00C - R0001 - Toilets - Girls - 17.48 m2		
No Asbestos		

B00C - R0002 - Toilets - Girls - 25.04 m2		
No Asbestos		
B00C - R0003 - Cleaning Supplies - 3.42 m2		
No Asbestos		
B00C - R0004 - Home Base Store - 6.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0005 - Home Base - 64.51 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0006 - Practical Activities - 1hb - 21.07 m2		
No Asbestos		
B00C - R0007 - Practical Activities - 1hb - 21.58 m2		
No Asbestos		
B00C - R0008 - Home Base - 66.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0009 - Home Base Store - 5.55 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0010 - Distribution Board - .69 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0011 - Staff Toilet - 2.75 m2		
No Asbestos		
B00C - R0012 - Entry Vestibule - 8.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0013 - Community Clinic - 20.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0014 - Garden Store - 8.58 m2		
No Asbestos		
B00C - R0015 - Movement - 55.8 m2		
No Asbestos		
B00D - Administration - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00D - R0001 - Main Switch Board - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0002 - Entry Vestibule - 19.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - Interview - 13.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0004 - Sick Bay - Shower/Toilet - 8.95 m2		
No Asbestos		
B00D - R0005 - Sick Bay - 10.03 m2		
No Asbestos		
B00D - R0006 - Deputy Principal - 12.31 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0007 - Deputy Principal - 13.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0008 - Distribution Board - .8 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0009 - Cleaning Supplies - 2.8 m2		
No Asbestos		

B00D - R0010 - Disabled Toilet - 4.74 m2		
No Asbestos		
B00D - R0011 - Staff Toilet - 6.34 m2		
No Asbestos		
B00D - R0012 - Staff Toilet - 6.34 m2		
No Asbestos		
B00D - R0013 - Staff Toilet - 6.34 m2		
No Asbestos		
B00D - R0014 - Staff Room - 57.61 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0015 - Staff Room Annexe - 23 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0016 - General Storeroom - 17.4 m2		
No Asbestos		
B00D - R0017 - Principal - 17.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0018 - Duplicating Workroom - 34.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0019 - Clerical Office - 18.27 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0020 - Movement - 42.84 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0021 - Movement - 143.45 m2		
No Asbestos		
B00E - Pupil Facilities - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00E - R0001 - Canteen - 43.32 m2		
No Asbestos		
B00E - R0002 - Canteen Office/Store - 10.29 m2		
No Asbestos		
B00E - R0003 - Canteen Covered Area - 110.75 m2		
No Asbestos		
B00F - General Learning - 1994 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00F - R0001 - Home Base - 57.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0002 - Practical Activities - 1hb - 22.31 m2		
No Asbestos		
B00F - R0003 - Home Base Store - 6.48 m2		
No Asbestos		
B00F - R0004 - Withdrawal Space - 1hb - 12.57 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0005 - Home Base - 57.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0006 - Home Base Store - 6.52 m2		

No Asbestos		
B00F - R0007 - Practical Activities - 1hb - 22.67 m2		
No Asbestos		
B00F - R0008 - Distribution Board - .44 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0009 - Movement - 65.52 m2		
No Asbestos		
B00F - R0010 - Toilets - Girls - 12.06 m2		
No Asbestos		
B00F - R0011 - Cleaning Supplies - 5.16 m2		
No Asbestos		
B00F - R0012 - Toilets - Boys - 9.27 m2		
No Asbestos		
B00G - General Learning - 1994 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00G - R0001 - Home Base - 57.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0002 - Practical Activities - 1hb - 22.67 m2		
No Asbestos		
B00G - R0003 - Home Base Store - 6.52 m2		
No Asbestos		
B00G - R0004 - Withdrawal Space - 1hb - 12.57 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0005 - Home Base - 57.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0006 - Home Base Store - 6.48 m2		
No Asbestos		
B00G - R0007 - Practical Activities - 1hb - 22.31 m2		
No Asbestos		
B00G - R0008 - Distribution Board - .44 m2		Note: No inspection of live electrical installation
No Asbestos		
B00G - R0009 - Movement - 35.03 m2		
No Asbestos		
B00H - Library - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00H - R0001 - Reading Area - 227.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0002 - Library Office/Workroom - 26.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0003 - Communications Room - 14.82 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0004 - Movement - 42.9 m2		
No Asbestos		
B00H - R0005 - Distribution Board - .64 m2		Note: No inspection of live electrical installation
No Asbestos		

B00I - Communal Facilities - 1994 - Brick/Block

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00I - R0001 - Movement - 65.29 m2

No Asbestos	
-------------	--

B00I - R0002 - Movement - 7.15 m2

No Asbestos	
-------------	--

B00I - R0003 - Raised Platform - 41.22 m2

No Asbestos	
-------------	--

B00I - R0004 - Movement - 7.07 m2

No Asbestos	
-------------	--

B00I - R0005 - Toilets - Boys - 8.69 m2

No Asbestos	
-------------	--

B00I - R0006 - Toilets - Girls - 8.9 m2

No Asbestos	
-------------	--

B00I - R0007 - Shower/Change - 3.43 m2

No Asbestos	
-------------	--

B00I - R0008 - Cleaning Supplies - 3.74 m2

No Asbestos	
-------------	--

B00I - R0009 - P.E Store - 15.65 m2

No Asbestos	
-------------	--

B00I - R0010 - Hall Chair Store - 12.11 m2

No Asbestos	
-------------	--

B00I - R0011 - General Storeroom - 12.95 m2

No Asbestos	
-------------	--

B00I - R0012 - Communal Space - 210.99 m2

No Asbestos	
-------------	--

B00I - R0013 - Plant - .56 m2

No Asbestos	
-------------	--

B00I - R0014 - No Access - .67 m2

No Asbestos	
-------------	--

B00J - General Learning - 2005 - Fibre Cement Clad

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00J - R0001 - External Movement - 38.48 m2

No Asbestos	
-------------	--

B00J - R0002 - Practical Activities - 1hb - 19.4 m2

No Asbestos	
-------------	--

B00J - R0003 - Home Base Store - 6.02 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00J - R0004 - Home Base - 59.19 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00J - R0005 - Withdrawal Space - 2hb - 11.36 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00J - R0006 - Home Base - 59.19 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00J - R0007 - Home Base Store - 6.02 m2

Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0008 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B00K - General Learning - 2005 - Fibre Cement Clad		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00K - R0001 - External Movement - 38.48 m2		
No Asbestos		
B00K - R0002 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B00K - R0003 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0004 - Home Base - 59.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0005 - Withdrawal Space - 2hb - 11.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0006 - Home Base - 59.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0007 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0008 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B00L - Other-Community Use - 2006 - Steel		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00L - R0001 - Other-Community Use - 53.41 m2		
No Asbestos		
B00L - R0002 - Other-Community Use - 9.44 m2		
No Asbestos		
B00M - General Learning - 2011 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00M - R0001 - Home Base - 60.72 m2		
No Asbestos		
B00M - R0002 - Home Base Store - 6.22 m2		
No Asbestos		
B00M - R0003 - Practical Activities - 1hb - 18.69 m2		
No Asbestos		
B00M - R0004 - Withdrawal Space - 2hb - 11.47 m2		
No Asbestos		
B00M - R0005 - External Movement - 52.09 m2		
No Asbestos		
B00M - R0006 - Practical Activities - 1hb - 19.02 m2		
No Asbestos		

B00M - R0007 - Home Base - 60.55 m2		
No Asbestos		
B00M - R0008 - Home Base Store - 6.22 m2		
No Asbestos		
B00N - General Learning/Pupil Facilities - 2011 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00N - R0001 - Withdrawal Space - 1hb - 8.84 m2		
No Asbestos		
B00N - R0002 - Home Base Store - 5.72 m2		
No Asbestos		
B00N - R0003 - Home Base - 59.53 m2		
No Asbestos		
B00N - R0004 - Practical Activities - 1hb - 18.83 m2		
No Asbestos		
B00N - R0005 - External Movement - 95.1 m2		
No Asbestos		
B00N - R0006 - Practical Activities/Movement - 1hb - 18.87 m2		
No Asbestos		
B00N - R0007 - Home Base Store - 6.22 m2		
No Asbestos		
B00N - R0008 - Home Base - 60.55 m2		
No Asbestos		
B00N - R0009 - Withdrawal Space - 2hb - 11.56 m2		
No Asbestos		
B00N - R0010 - Practical Activities - 1hb - 18.86 m2		
No Asbestos		
B00N - R0011 - Home Base - 60.7 m2		
No Asbestos		
B00N - R0012 - Home Base Store - 6.25 m2		
No Asbestos		
B00N - R0013 - External Movement - 7.65 m2		
No Asbestos		
B00N - R0014 - Toilets - Boys - 9.04 m2		
No Asbestos		
B00N - R0015 - Toilets - Girls - 12.12 m2		
No Asbestos		
B00Q - General Learning - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00Q - R0001 - Movement - 208.89 m2		
No Asbestos		
B00R - Other - 2007 - Metal Shed		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		

B00R - R0001 - General Storeroom - 66.94 m2

No Asbestos	
-------------	--

Demountables**NS 100 11255 - Learning Unit - Single Primary/PAA - Placement Date : 18-JAN-2005**

No Asbestos Found

OS 844 11406 - Country Toilet - Reltc - Boys/Girls - Placement Date : 20-MAR-2015**Exterior**

Eaves Linings	Flat AC Sheeting	2.88m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Staff Toilet**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Assumed Asbestos

R2- Staff Toilet

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Assumed Asbestos

OS 602 11700 - Learning Unit - Standard With P.A.A. - Placement Date : 03-FEB-2000**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.****Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Learning space/withdrawal/entry**

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 603 12143 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 30-JUN-1995

No Asbestos Found

OS 601 14289 - Learning Unit - Standard/Withdrawal - Placement Date : 30-JUN-1995**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Entry**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 602 16199 - Learning Unit - Standard With P.A.A. - Placement Date : 09-FEB-1998**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior			
R1- Learning space/withdrawal/entry			
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
R2- Home Base Store			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos