


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hinchinbrook Public School (4613)
Region:	South Western Sydney AMU
State Electorate:	Liverpool
Local Government Area:	Liverpool

Last Reviewed By:	Greencap 13-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1996 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 96.27 m2							
No Asbestos							
B00A - R0002 - Personal Effects Storage - 3.04 m2							
No Asbestos							
B00A - R0003 - Home Base Store - 5.81 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Distribution Board - .57 m2							
No Asbestos					Note: No inspection of live electrical installation		
B00A - R0005 - Movement - 2.05 m2							
No Asbestos							
B00A - R0006 - Practical Activities - 1hb - 20.48 m2							
No Asbestos							
B00A - R0007 - Home Base - 54.22 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0008 - Withdrawal Space - 1hb - 11.06 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Home Base - 54.27 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0010 - Practical Activities - 1hb - 20.59 m2							
No Asbestos							
B00A - R0011 - Personal Effects Storage - 3.07 m2							
No Asbestos							
B00A - R0012 - Home Base Store - 6.47 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Toilets - Boys - 10.06 m2							
No Asbestos							
B00A - R0014 - Toilets - Girls - 10.03 m2							
No Asbestos							
B00B - Administration - 1996 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00B - R0001 - Staff Room - 58.66 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00B - R0002 - Staff Room - 25.27 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00B - R0003 - Distribution Board - .56 m2							
No Asbestos					Note: No inspection of live electrical installation		
B00B - R0004 - Cleaning Distributed Store - 4.88 m2							
No Asbestos							
B00B - R0005 - Staff Toilet - 3.99 m2							
No Asbestos							
B00B - R0006 - Staff Toilet - 3.99 m2							
No Asbestos							

B00B - R0007 - Staff Toilet - 3.99 m2		
No Asbestos		
B00B - R0008 - Deputy Principal - 12.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0009 - Interview - 12.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - Sick Bay - Shower/Toilet - 4.1 m2		
No Asbestos		
B00B - R0011 - Shower/Change - 2.55 m2		
No Asbestos		
B00B - R0012 - Sick Bay - 8.65 m2		
No Asbestos		
B00B - R0013 - Clerical Office - 17.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0014 - Entry Vestibule - 17.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0015 - Duplicating Workroom - 32.51 m2		
No Asbestos		
B00B - R0016 - Principal - 16.73 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0017 - Security Store - 18.3 m2		
No Asbestos		
B00B - R0018 - Deputy Principal - 12.74 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0019 - Movement - 39.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0020 - Movement - 102.13 m2		
No Asbestos		
B00C - Library/General Learning - 1996 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00C - R0001 - Special Programs Room - 42.14 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0002 - Special Programs Store - 2.07 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0003 - Plant - 6.8 m2		
No Asbestos		
B00C - R0004 - Cleaning Distributed Store - 7.62 m2		
No Asbestos		
B00C - R0005 - Communications Room - 11.84 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0006 - Distribution Board - .42 m2		
No Asbestos		Note: No inspection of live electrical installation
B00C - R0007 - Library Office/Workroom - 26.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0008 - Reading Area - 224.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0009 - Distribution Board - .55 m2		
No Asbestos		Note: No inspection of live electrical installation

B00C - R0010 - Practical Activities - 1hb - 22.84 m2		
No Asbestos		
B00C - R0011 - Home Base Store - 5.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0012 - Withdrawal Space - 1hb - 4.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0013 - Home Base - 49.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0014 - Personal Effects Storage - 3.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0015 - Personal Effects Storage - 3.87 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0016 - Home Base - 49.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0017 - Practical Activities - 1hb - 22.87 m2		
No Asbestos		
B00C - R0018 - Home Base Store - 5.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0019 - Withdrawal Space - 1hb - 4.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0020 - Movement - 90.87 m2		
No Asbestos		
B00C - R0021 - Movement - 12.68 m2		
No Asbestos		
B00C - R0022 - Movement - 48.03 m2		
No Asbestos		
B00D - General Learning - 1996 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00D - R0001 - Personal Effects Storage - 2.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0002 - Home Base Store - 5.59 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - Distribution Board - .52 m2		
Note: No inspection of live electrical installation		
No Asbestos		
B00D - R0004 - Practical Activities - 1hb - 20.55 m2		
No Asbestos		
B00D - R0005 - Home Base - 55.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0006 - Withdrawal Space - 1hb - 11.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0007 - Home Base - 55.23 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0008 - Practical Activities - 1hb - 20.62 m2		
No Asbestos		
B00D - R0009 - Personal Effects Storage - 2.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0010 - Home Base Store - 6.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00D - R0011 - Personal Effects Storage - 2.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0012 - Home Base Store - 6.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0013 - Practical Activities - 1hb - 20.55 m2		
No Asbestos		
B00D - R0014 - Home Base - 55.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0015 - Withdrawal Space - 1hb - 11.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0016 - Home Base - 55.23 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0017 - Personal Effects Storage - 3.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0018 - Home Base Store - 5.63 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0019 - Toilets - Girls - 17.73 m2		
No Asbestos		
B00D - R0020 - Kiln Room - 6.11 m2		
No Asbestos		
B00D - R0021 - Toilets - Boys - 18.65 m2		
No Asbestos		
B00D - R0022 - Movement - 14.08 m2		
No Asbestos		
B00D - R0023 - Movement - 127.76 m2		
No Asbestos		
B00D - R0024 - Distribution Board - .55 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0025 - Practical Activities - 1hb - 20.55 m2		
No Asbestos		
B00D - R0026 - Movement - 2.46 m2		
No Asbestos		
B00D - R0027 - Movement - 5 m2		
No Asbestos		
B00E - General Learning - 1996 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00E - R0001 - Drinking Facilities - 4.62 m2		
No Asbestos		
B00E - R0002 - Toilets - Boys - 8.72 m2		
No Asbestos		
B00E - R0003 - Toilets - Girls - 11.86 m2		
No Asbestos		
B00E - R0004 - Distribution Board - .42 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0005 - Practical Activities - 1hb - 27.1 m2		
No Asbestos		
B00E - R0006 - Home Base - 50.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	

B00E - R0007 - Home Base Store - 5.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0008 - Withdrawal Space - 1hb - 5.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0009 - Home Base - 50.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0010 - Practical Activities - 1hb - 26.68 m2		
No Asbestos		
B00E - R0011 - Home Base Store - 5.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0012 - Withdrawal Space - 1hb - 5.96 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0013 - Withdrawal Space - 1hb - 5.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0014 - Home Base Store - 5.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0015 - Practical Activities - 1hb - 26.68 m2		
No Asbestos		
B00E - R0016 - Home Base - 50.26 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - Home Base - 50.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0018 - Practical Activities - 1hb - 25.93 m2		
No Asbestos		
B00E - R0019 - Home Base Store - 5.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0020 - Withdrawal Space - 1hb - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0021 - Distribution Board - .45 m2		
No Asbestos		Note: No inspection of live electrical installation
B00E - R0022 - Distribution Board - .43 m2		
No Asbestos		Note: No inspection of live electrical installation
B00E - R0023 - Withdrawal Space - 1hb - 5.93 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0024 - Home Base Store - 5.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0025 - Practical Activities - 1hb - 26 m2		
No Asbestos		
B00E - R0026 - Home Base - 50.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0027 - Home Base - 50.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0028 - Practical Activities - 1hb - 26.71 m2		
No Asbestos		
B00E - R0029 - Withdrawal Space - 1hb - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0030 - Home Base Store - 5.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0031 - Movement - 179.17 m2		
No Asbestos		
B00E - R0032 - Movement - 31.55 m2		
No Asbestos		

B00F - Communal Facilities - 1996 - Brick/Veneer

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00F - R0001 - Sports Store - 13.78 m2

No Asbestos

B00F - R0002 - Community Clinic - 18.32 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00F - R0003 - Staff Toilet - 2.16 m2

No Asbestos

B00F - R0004 - Community Clinic - 6.8 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00F - R0005 - Toilets - Girls - 10.08 m2

No Asbestos

B00F - R0006 - Distribution Board - .98 m2

Note: No inspection of live electrical installation

No Asbestos

B00F - R0007 - Plant - .69 m2

No Asbestos

B00F - R0008 - Raised Platform - 46.51 m2

No Asbestos

B00F - R0009 - Communal Space - 216.93 m2

No Asbestos

B00F - R0010 - Toilets - Boys - 10.02 m2

No Asbestos

B00F - R0011 - P.E Store - 16.65 m2

No Asbestos

B00F - R0012 - Hall Chair Store - 11.1 m2

No Asbestos

B00F - R0013 - General Storeroom - 2.82 m2

No Asbestos

B00F - R0014 - Staff Shower/Change - 2.27 m2

No Asbestos

B00F - R0015 - Movement - 26.03 m2

No Asbestos

B00F - R0016 - Movement - 290.45 m2

No Asbestos

B00G - Pupil Facilities - 1996 - Brick/Block

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00G - R0001 - Canteen - 43.66 m2

No Asbestos

B00G - R0002 - Canteen Office/Store - 11.36 m2

No Asbestos

B00G - R0003 - Distribution Board - .47 m2

Note: No inspection of live electrical installation

No Asbestos

B00G - R0004 - Cleaning Supplies - 12.8 m2

No Asbestos

B00G - R0005 - Cleaning Supplies - 13.4 m2

No Asbestos		
B00G - R0006 - General Assistant/Bulk Store - 15.64 m2		
No Asbestos		
B00G - R0007 - Garden Store - 13.19 m2		
No Asbestos		
B00G - R0008 - Hall Chair Store - 2.64 m2		
No Asbestos		
B00G - R0009 - Disabled Toilet - 4.85 m2		
No Asbestos		
B00G - R0010 - Main Switch Board - 1.27 m2		
No Asbestos		
B00G - R0011 - Movement - 73.79 m2		
No Asbestos		
B00H - General Learning - 2006 - Fibre Cement Clad		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00H - R0001 - Movement - 38.48 m2		
No Asbestos		
B00H - R0002 - Practical Activities - 1hb - 19.4 m2		
No Asbestos		
B00H - R0003 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0004 - Home Base - 59.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0005 - Withdrawal Space - 2hb - 11.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0006 - Home Base - 59.19 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0007 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0008 - Practical Activities - 1hb - 19.41 m2		
No Asbestos		
B00I - General Learning - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00I - R0001 - External Movement - 41.84 m2		
No Asbestos		
B00I - R0002 - Practical Activities/Movement - 1hb - 19.16 m2		
No Asbestos		
B00I - R0003 - Home Base Store - 6.08 m2		
No Asbestos		
B00I - R0004 - Home Base - 61.11 m2		
No Asbestos		
B00I - R0005 - Withdrawal Space - 2hb - 11.74 m2		
No Asbestos		
B00I - R0006 - Home Base - 61.06 m2		
No Asbestos		

B00I - R0007 - Home Base Store - 6.08 m2		
No Asbestos		
B00I - R0008 - Practical Activities/Movement - 1hb - 18.7 m2		
No Asbestos		
B00I - R0009 - No Access - .42 m2		
No Asbestos		
B00J - General Learning - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00J - R0001 - External Movement - 44.68 m2		
No Asbestos		
B00J - R0002 - Practical Activities/Movement - 1hb - 19.16 m2		
No Asbestos		
B00J - R0003 - Home Base Store - 6.09 m2		
No Asbestos		
B00J - R0004 - Home Base - 61.16 m2		
No Asbestos		
B00J - R0005 - Withdrawal Space - 2hb - 11.77 m2		
No Asbestos		
B00J - R0006 - Home Base - 61.13 m2		
No Asbestos		
B00J - R0007 - Home Base Store - 6.08 m2		
No Asbestos		
B00J - R0008 - Practical Activities/Movement - 1hb - 18.7 m2		
No Asbestos		
B00J - R0009 - No Access - .42 m2		
No Asbestos		
B00K - General Learning - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00K - R0001 - External Movement - 45.03 m2		
No Asbestos		
B00K - R0002 - Practical Activities - 1hb - 19.16 m2		
No Asbestos		
B00K - R0003 - Home Base Store - 6.08 m2		
No Asbestos		
B00K - R0004 - Home Base - 61.11 m2		
No Asbestos		
B00K - R0005 - Withdrawal Space - 2hb - 11.74 m2		
No Asbestos		
B00K - R0006 - Home Base - 61.06 m2		
No Asbestos		
B00K - R0007 - Home Base Store - 6.08 m2		
No Asbestos		
B00K - R0008 - Practical Activities/Movement - 1hb - 18.73 m2		
No Asbestos		
B00K - R0009 - No Access - .42 m2		

No Asbestos	
-------------	--

Demountables

OS 602 11859 - Learning Unit - Standard With P.A.A. - Placement Date : 09-MAR-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 751 13444 - Learning Unit - ESL - Placement Date : 05-JAN-2001

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Esl

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos

R2- Esl

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos

OS 602 14577 - Learning Unit - Standard With P.A.A. - Placement Date : 02-MAY-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 16623 - Learning Unit - Standard With P.A.A. - Placement Date : 19-JUL-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19031 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-JUL-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found