

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Harcourt Public School (5118)
Region:	South Western Sydney AMU
State Electorate:	Canterbury
Local Government Area:	Canterbury-Bankstown

Last Reviewed By:	WSP 08-JUL-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Library - 1975 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0002 - Cleaning Distributed Store - 1.7 m2							
No Asbestos							
B00A - R0003 - Distribution Board - 1.13 m2							
						Note: No inspection of live electrical installation	
No Asbestos							
B00A - R0004 - Staff Toilet - 3.5 m2							
No Asbestos							
B00A - R0005 - Staff Toilet - 3.21 m2							
No Asbestos							
B00A - R0006 - Community Clinic - 17.82 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0007 - Interview - 13.23 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0008 - Deputy Principal - 13.18 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0009 - Staff Room Annexe - 13.23 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0010 - Principal - 20.2 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0013 - Duplicating Workroom - 12.41 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0015 - General Storeroom - 16.03 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0016 - Movement - 20.02 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
B00A - R0017 - Movement - 2.73 m2							

No Asbestos								
B00A - R0018 - Movement - 4.03 m2								
No Asbestos								
B00A - R0019 - Movement - 4.03 m2								
No Asbestos								
B00A - R0020 - Movement - 4.03 m2								
No Asbestos								
B00A - R0021 - Movement - 4.03 m2								
No Asbestos								
B00A - R0022 - Clerical Office/Workroom - 24.64 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00A - R0023 - Entry Vestibule - 16.29 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00A - R0024 - Staff Room - 59.52 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00A - R0025 - Staff Kitchen - 18.45 m2								
No Asbestos								
B00A - R1002 - Staff Toilet - 3.28 m2								
No Asbestos								
B00A - R1003 - Staff Toilet - 3.29 m2								
No Asbestos								
B00A - R1004 - Movement - 5.71 m2								
No Asbestos								
B00A - R1005 - Cleaning Distributed Store - 1.65 m2								
No Asbestos								
B00A - R1006 - Distribution Board - 1.12 m2								
						Note: No inspection of live electrical installation		
No Asbestos								
B00A - R1007 - Library Office/Workroom - 22.42 m2								
No Asbestos								
B00A - R1008 - Communications Room - 16.09 m2								
No Asbestos								
B00A - R1009 - Library Office/Workroom - 7.91 m2								
No Asbestos								
B00A - R1012 - General Storeroom - 26.42 m2								
No Asbestos								
B00A - R1013 - Special Programs Room - 33.82 m2								
No Asbestos								
B00A - R1014 - Reading Area - 168.91 m2								
No Asbestos								
B00B - General Learning/Pupil Facilities - 1975 - Brick/Block								
Exterior								
Wall Linings Internal - Infill	Flat AC Sheeting							
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00B - R0001 - Movement - 116.03 m2								
No Asbestos								

B00B - R0002 - Cleaning Supplies - 11.86 m2							
No Asbestos							
B00B - R0003 - Home Base - 81.18 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0004 - Practical Activities - 1hb - 21.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Toilets - Boys/Girls - 3.11 m2							
No Asbestos							
B00B - R0006 - Movement - 44.97 m2							
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Toilets - Girls - 34.8 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	Ceiling (West)	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Cleaning Supplies - 11.2 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	North, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0009 - Toilets - Boys - 34.85 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	Ceiling (East)	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0010 - Main Switch Board - 10.68 m2							
No Asbestos							
B00B - R0011 - Movement - 86.37 m2							
No Asbestos							
B00B - R0012 - Craft Store - 11.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0013 - Movement - 3.7 m2							
No Asbestos							
B00B - R0014 - Movement - 3.53 m2							
No Asbestos							
B00B - R0015 - Practical Activities - 1hb - 20.72 m2							
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0016 - Toilets - Boys/Girls - 3.1 m2							
No Asbestos							
B00B - R0017 - Home Base - 81.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0018 - Movement - 3.95 m2							
No Asbestos							
B00B - R0019 - Movement - 3.95 m2							
No Asbestos							
B00B - R0020 - Movement - 3.95 m2							
No Asbestos							
B00B - R0021 - Movement - 3.95 m2							
No Asbestos							
B00B - R0022 - Movement - 3.95 m2							
No Asbestos							
B00B - R0023 - Movement - 3.95 m2							
No Asbestos							
B00B - R0024 - Stairs - 5.76 m2							
No Asbestos							

B00B - R0025 - Stairs - 5.76 m2							
No Asbestos							
B00B - R1001 - General Storeroom - 18.85 m2							
No Asbestos							
B00B - R1002 - Movement - 49.62 m2							
No Asbestos							
B00B - R1003 - Movement - 44.55 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	5m2	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1004 - Movement - 45.15 m2							
Floor Coverings Res/Textile	Vinyl Tiles	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1005 - Practical Activities - 1hb - 26.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1006 - Home Base - 55.01 m2							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1007 - Home Base - 55.45 m2							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1008 - Practical Activities - 1hb - 25.86 m2							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1009 - Movement - 87.59 m2							
No Asbestos							
B00B - R1010 - Staff Toilet - 1.71 m2							
No Asbestos							
B00B - R1011 - Distribution Board - .28 m2						Note: No inspection of live electrical installation	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1012 - Practical Activities - 1hb - 26.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1013 - Home Base - 61.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1014 - Toilets - Boys - 1.74 m2							
No Asbestos							
B00B - R1015 - Toilets - Girls - 1.54 m2							
No Asbestos							
B00B - R1016 - Home Base - 61.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1017 - Practical Activities - 1hb - 25.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1018 - Cleaning Distributed Store - 1.71 m2							
No Asbestos							
B00B - R1019 - Stairs - 8.67 m2							
No Asbestos							
B00B - R1020 - Stairs - 8.51 m2							
No Asbestos							
B00B - R1021 - Stairs - 8.51 m2							
No Asbestos							

B00B - R1022 - Stairs - 8.67 m2							
No Asbestos							
B00B - R2006 - Cleaning Distributed Store - 1.77 m2							
No Asbestos							
B00B - R2007 - Movement - 46.23 m2							
Floor Coverings Res/Textile	Vinyl Tiles	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2008 - Practical Activities - 1hb - 26.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2009 - Home Base - 55.75 m2							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2010 - Home Base - 55.54 m2							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2011 - Practical Activities - 1hb - 25.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2013 - Staff Toilet - 1.77 m2							
No Asbestos							
B00B - R2014 - Practical Activities - 1hb - 26.11 m2							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2015 - Home Base - 56.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2016 - Toilets - Boys - 1.78 m2							
No Asbestos							
B00B - R2017 - Toilets - Girls - 1.83 m2							
No Asbestos							
B00B - R2018 - Home Base - 57.62 m2							
Floor Coverings Res/Textile	Vinyl Tiles	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2019 - Practical Activities - 1hb - 25.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R2020 - General Storeroom - 14.76 m2							
No Asbestos							
B00B - R2021 - Stairs - 17.92 m2							
No Asbestos							
B00B - R2022 - General Storeroom - 29.61 m2							
No Asbestos							
B00B - R2023 - Movement - 80.21 m2							
No Asbestos							
B00B - R2024 - Stairs - 22.68 m2							
No Asbestos							
B00B - R2025 - Movement - 69.12 m2							
No Asbestos							
B00C - General Learning/Communal Facilities - 1975 - Brick/Block							
Exterior							
Ceiling Voids	Packing	2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Interior							

B00C - R0001 - Movement - 3.87 m2							
No Asbestos							
B00C - R0002 - Communal Space - 222.21 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (120 - 250 m2) - (X15)						
B00C - R0003 - Movement - 3.87 m2							
No Asbestos							
B00C - R0005 - Movement - 29.34 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0006 - Movement - 3.06 m2							
No Asbestos							
B00C - R0007 - Movement - 2.9 m2							
No Asbestos							
B00C - R0009 - Toilets - Girls - 11.2 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0010 - Movement - 31.19 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0011 - Raised Platform - 17.1 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0012 - Hall Chair Store - 2.39 m2							
No Asbestos							
B00C - R0013 - Distribution Board - .35 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00C - R0014 - General Storeroom - 9.52 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0015 - Canteen Office/Store - 3.53 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0016 - Movement - 1.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0017 - Staff Toilet - 2.18 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00C - R0018 - Distribution Board - .09 m2							
							Note: No inspection of live electrical installation
No Asbestos							
B00C - R0019 - Canteen - 39.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00C - R0020 - Movement - 3.41 m2							
No Asbestos							
B00C - R0021 - Movement - 2.57 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0022 - Hall Chair Store - 2.39 m2							

No Asbestos							
B00C - R0023 - Movement - 2.51 m2							
No Asbestos							
B00C - R0024 - Toilets - Boys - 10.74 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R0025 - Stairs - 6.71 m2							
No Asbestos							
B00C - R0026 - Movement - 26.33 m2							
No Asbestos							
B00C - R0027 - General Assistant/Bulk Store - 24.93 m2							
No Asbestos							
B00C - R0028 - External Movement - 61.83 m2							
No Asbestos							
B00C - R0029 - Lift - 1.21 m2							
No Asbestos							
B00C - R1001 - Movement - 2.61 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1002 - Practical Activities - 1hb - 27.95 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1003 - Home Base - 50.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1004 - Home Base - 50.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1005 - Practical Activities - 1hb - 27.95 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1006 - Movement - 71.17 m2							
No Asbestos							
B00C - R1007 - Movement - 36.39 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1008 - General Assistant/Bulk Store - 10.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1009 - Movement - 2.46 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	2.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1010 - General Storeroom - 14.21 m2							

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1011 - Practical Activities - 1hb - 27.67 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00C - R1012 - Home Base - 49.86 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1013 - Home Base - 49.86 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1014 - Practical Activities - 1hb - 27.58 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1015 - Movement - 2.51 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	2.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1016 - Security Store - 10.01 m2							
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R1017 - Distribution Board - .38 m2 Note: No inspection of live electrical installation							
No Asbestos							
B00C - R1018 - Stairs - 9.58 m2							
No Asbestos							
B00C - R1019 - Stairs - 9.58 m2							
No Asbestos							
B00C - R1020 - External Movement - 61.83 m2							
No Asbestos							
B00C - R2001 - Movement - 2.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R2002 - Practical Activities - 1hb - 28.2 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	2.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R2003 - Home Base - 50.98 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R2004 - Home Base - 50.98 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R2005 - Practical Activities - 1hb - 28.2 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2006 - Movement - 47.2 m2								
No Asbestos								
B00C - R2007 - Kiln Room - 21.12 m2								
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2008 - Movement - 36.28 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2009 - Toilets - Girls - 9.99 m2								
No Asbestos								
B00C - R2010 - Movement - 2.62 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2011 - Practical Activities - 1hb - 27.34 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2012 - Home Base - 49.77 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2013 - General Storeroom - 9.12 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2014 - Home Base - 49.77 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2015 - Practical Activities - 1hb - 27.34 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2016 - Movement - 2.59 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00C - R2017 - Toilets - Boys - 11.01 m2								
No Asbestos								
B00C - R2018 - Distribution Board - .46 m2								
Note: No inspection of live electrical installation								
Ceiling Structures/Linings	Flat AC Sheeting	1m2	On the floor	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00C - R2019 - Stairs - 17.81 m2								
No Asbestos								
B00C - R2020 - External Movement - 61.83 m2								

No Asbestos	
B00G - General Learning/Special Purpose Learning - 2010 - Brick/Veneer	
Exterior	
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
Interior	
B00G- R0001 - External Movement - 93.63 m2	
No Asbestos	
B00G- R0002 - Practical Activities - 18.79 m2	
No Asbestos	
B00G- R0003 - Home Base Store - 6.1 m2	
No Asbestos	
B00G- R0004 - Home Base - 60.52 m2	
No Asbestos	
B00G- R0005 - Withdrawal Space - 2hb - 11.84 m2	
No Asbestos	
B00G- R0006 - Home Base - 60.52 m2	
No Asbestos	
B00G- R0007 - Practical Activities - 18.04 m2	
No Asbestos	
B00G- R0008 - Home Base Store - 6.1 m2	
No Asbestos	
B00G- R0009 - Distribution Board - .76 m2	
	Note: No inspection of live electrical installation
No Asbestos	
B00G- R0010 - Special Programs Room - Type 1 - 38.12 m2	
No Asbestos	
B00G- R0011 - General Storeroom - 10.87 m2	
No Asbestos	
B00G- R0012 - Special Programs Room - Type 1 - 38.13 m2	
No Asbestos	
B00G- R0013 - General Storeroom - 10.87 m2	
No Asbestos	
B00G- R0014 - External Stairs - 8.62 m2	
No Asbestos	
B00G- R0015 - External Stairs - 9.3 m2	
No Asbestos	
B00G- R1001 - External Movement - 84.18 m2	
No Asbestos	
B00G- R1002 - Practical Activities - 21.54 m2	
No Asbestos	
B00G- R1003 - Home Base - 66 m2	
No Asbestos	
B00G- R1004 - Withdrawal Space - 2hb - 7.69 m2	
No Asbestos	
B00G- R1005 - Home Base Store - 6.07 m2	
No Asbestos	
B00G- R1006 - Practical Activities - 18.79 m2	
No Asbestos	
B00G- R1007 - Home Base Store - 6.1 m2	
No Asbestos	
B00G- R1008 - Home Base - 60.52 m2	

No Asbestos	
B00G - R1009 - Withdrawal Space - 2hb - 11.84 m2	
No Asbestos	
B00G - R1010 - Home Base - 60.52 m2	
No Asbestos	
B00G - R1011 - Practical Activities - 18.79 m2	
No Asbestos	
B00G - R1012 - Home Base Store - 6.1 m2	
No Asbestos	
B00G - R1013 - External Stairs - 16.01 m2	
No Asbestos	
B00G - R1014 - External Stairs - 8.62 m2	
No Asbestos	
B00H - General Learning/Building Services - 2014 - Brick/Veneer	
Exterior	
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
Interior	
B00H - R0001 - P.E Store - 16.87 m2	
No Asbestos	
B00H - R0002 - Cleaning Distributed Store - 3.17 m2	
No Asbestos	
B00H - R0003 - Staff Toilet - 9.67 m2	
No Asbestos	
B00H - R0004 - Toilets - Girls - 39.93 m2	
No Asbestos	
B00H - R0005 - Garden Store - 13.96 m2	
No Asbestos	
B00H - R0006 - Toilets - Boys - 41.7 m2	
No Asbestos	
B00H - R0007 - Access Shower/Toilet - 10.18 m2	
No Asbestos	
B00H - R0008 - Sports Store - 16.78 m2	
No Asbestos	
B00H - R0009 - Practical Activities - 1hb - 20.52 m2	
No Asbestos	
B00H - R0010 - Home Base Store - 7.05 m2	
No Asbestos	
B00H - R0011 - Home Base - 66.65 m2	
No Asbestos	
B00H - R0012 - Withdrawal Space - 2hb - 11.9 m2	
No Asbestos	
B00H - R0013 - Home Base - 65.76 m2	
No Asbestos	
B00H - R0014 - Practical Activities - 1hb - 20.34 m2	
No Asbestos	
B00H - R0015 - Home Base Store - 7.05 m2	
No Asbestos	
B00H - R0016 - Plant - 1.01 m2	
No Asbestos	
B00H - R0017 - Distribution Board - 2.13 m2	
Note: No inspection of live electrical installation	

No Asbestos	
B00H - R0018 - External Movement - 138.92 m2	
No Asbestos	
B00H - R0019 - External Movement - 31.44 m2	
No Asbestos	
B00H - R0020 - External Stairs - 6.25 m2	
No Asbestos	
B00H - R1001 - Practical Activities - 1hb - 20.4 m2	
No Asbestos	
B00H - R1002 - Home Base Store - 6.88 m2	
No Asbestos	
B00H - R1003 - Home Base - 65.83 m2	
No Asbestos	
B00H - R1004 - Withdrawal Space - 2hb - 12.06 m2	
No Asbestos	
B00H - R1005 - Home Base - 68.23 m2	
No Asbestos	
B00H - R1006 - Home Base Store - 6.81 m2	
No Asbestos	
B00H - R1007 - Practical Activities - 1hb - 20.14 m2	
No Asbestos	
B00H - R1008 - Practical Activities - 1hb - 19.92 m2	
No Asbestos	
B00H - R1009 - Home Base Store - 6.81 m2	
No Asbestos	
B00H - R1010 - Home Base - 65.97 m2	
No Asbestos	
B00H - R1011 - Withdrawal Space - 2hb - 11.35 m2	
No Asbestos	
B00H - R1012 - Practical Activities - 1hb - 20.66 m2	
No Asbestos	
B00H - R1013 - Home Base - 65.91 m2	
No Asbestos	
B00H - R1014 - Home Base Store - 6.88 m2	
No Asbestos	
B00H - R1015 - Distribution Board - 1.27 m2	Note: No inspection of live electrical installation
No Asbestos	
B00H - R1016 - External Movement - 112.17 m2	
No Asbestos	
B00H - R1017 - External Stairs - 22.55 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020