

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Hornsby South Public School (5191)</b>
<b>Region:</b>	<b>Northern Sydney AMU</b>
<b>State Electorate:</b>	<b>Hornsby</b>
<b>Local Government Area:</b>	<b>Hornsby</b>

<b>Last Reviewed By:</b>	WSP 13-JUL-2016
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - General Learning - 1965 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	8m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B00A - R0001 - Practical Activities - 1hb - 16.09 m2</b>							
Floor Coverings Res/Textile	Vinyl Sheet						
<b>B00A - R0002 - Toilets - Boys/Girls - 2.81 m2</b>							
No Asbestos							
<b>B00A - R0003 - Home Base - 74.96 m2</b>							
No Asbestos							
<b>B00A - R0004 - Home Base - 72.74 m2</b>							
No Asbestos							
<b>B00A - R0005 - Toilets - Boys/Girls - 2.81 m2</b>							
No Asbestos							
<b>B00A - R0006 - Practical Activities - 1hb - 16.09 m2</b>							
Floor Coverings Res/Textile	Vinyl Sheet						
<b>B00A - R0008 - Toilets - Boys - 18.76 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0009 - Security Store - 15.25 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Compressed AC Sheet						
<b>B00A - R0010 - Toilets - Girls - 18.76 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0011 - Disabled Toilet - 10.95 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00A - R0012 - Movement - 62.34 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	63m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - General Learning/Library - 1965 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B00B - R0001 - Movement - 61.59 m2</b>							
No Asbestos							

<b>B00B - R0002 - Practical Activities - 1hb - 11.15 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0003 - Home Base - 58 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00B - R0004 - Home Base - 57.56 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00B - R0005 - Practical Activities - 1hb - 11.15 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00B - R0006 - Toilets - Boys - 27.77 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0007 - Cleaning Supplies - 5.6 m2</b>							
No Asbestos							
<b>B00B - R0008 - Toilets - Girls - 20.45 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0009 - Movement - 24.84 m2</b>							
No Asbestos							
<b>B00B - R1001 - Movement - 40.64 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1002 - Reading Area - 168.64 m2</b>							
No Asbestos							
<b>B00B - R1003 - Library Office/Workroom - 14.58 m2</b>							
No Asbestos							
<b>B00B - R1004 - Communications Room - 10.22 m2</b>							
No Asbestos							
<b>B00B - R1005 - Uniform Shop - 13.59 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1006 - General Storeroom - 5.43 m2</b>							
No Asbestos							
<b>B00B - R1007 - Security Store - 13.48 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - General Learning - 1964 - Brick/Block</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0001 - Movement - 68.06 m2</b>							
No Asbestos							
<b>B00C - R0002 - Practical Activities - 1hb - 11.15 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0003 - Home Base - 57.94 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - ( X5 )							
<b>B00C - R0004 - Practical Activities - 1hb - 11.15 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - ( X3 )							
<b>B00C - R0005 - Home Base - 57.94 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - ( X5 )							
<b>B00C - R0006 - Home Base - 57.5 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - ( X5 )							
<b>B00C - R0007 - Practical Activities - 1hb - 11.15 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - ( X3 )							
<b>B00C - R0008 - Movement - 26.21 m2</b>								
No Asbestos								
<b>B00C - R0009 - Garden Store - 19.54 m2</b>								
No Asbestos								
<b>B00C - R0010 - Distribution Board - .68 m2</b>								
No Asbestos <span style="float: right;"><b>Note: No inspection of live electrical installation</b></span>								
<b>B00C - R0011 - Cleaning Distributed Store - 6.65 m2</b>								
No Asbestos								
<b>B00C - R0012 - Stairs - 7.05 m2</b>								
No Asbestos								
<b>B00C - R1001 - Special Programs Room - 72.16 m2</b>								
No Asbestos								
<b>B00C - R1002 - Home Base - 58.46 m2</b>								
No Asbestos								
<b>B00C - R1003 - Practical Activities - 1hb - 11.42 m2</b>								
No Asbestos								
<b>B00C - R1004 - Home Base - 59.37 m2</b>								
No Asbestos								
<b>B00C - R1005 - Practical Activities - 1hb - 11.42 m2</b>								
No Asbestos								
<b>B00C - R1006 - Movement - 74.1 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	71m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00C - R1007 - Movement - 9.3 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00C - R1008 - Staff Toilet - 5.39 m2</b>								
No Asbestos								
<b>B00C - R1009 - Cleaning Distributed Store - 3.27 m2</b>								
No Asbestos								
<b>B00C - R1010 - Staff Toilet - 5.38 m2</b>								
No Asbestos								
<b>B00C - R1011 - Stairs - 6.38 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - Administration - 1973 - Brick/Veneer</b>								
<b>Exterior</b>								
Ceiling Voids - Raked Ceiling	No Asbestos Found							

Underfloor Voids - Slab on Ground	No Asbestos Found							
Gable Verge Lining	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Eaves Linings	Flat AC Sheeting	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
<b>Interior</b>								
<b>B00D - R0001 - Movement - 22.45 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Crocidolite (blue asbestos)	
<b>B00D - R0002 - General Storeroom - 8.9 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0003 - Principal - 21.45 m2</b>								
No Asbestos								
<b>B00D - R0004 - Clerical Office - 15.05 m2</b>								
No Asbestos								
<b>B00D - R0005 - Interview - 13.79 m2</b>								
No Asbestos								
<b>B00D - R0006 - Deputy Principal - 16.33 m2</b>								
No Asbestos								
<b>B00D - R0007 - Duplicating Workroom - 11.86 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0008 - General Storeroom - 11.89 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0009 - Security Store - 11.92 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0010 - Staff Room - 56.35 m2</b>								
No Asbestos								
<b>B00D - R0011 - Sick Bay - 15.94 m2</b>								
No Asbestos								
<b>B00D - R0012 - Deputy Principal - 10.47 m2</b>								
No Asbestos								
<b>B00D - R0013 - Movement - 1.35 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Crocidolite (blue asbestos)	
<b>B00D - R0014 - Staff Toilet - 3.55 m2</b>								
Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
<b>B00D - R0015 - Cleaning Supplies - 3.47 m2</b>								
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
<b>B00D - R0016 - Staff Toilet - 3.55 m2</b>								
Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
<b>B00D - R0017 - Main Switch Board - 2.98 m2</b>								
Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00D - R0018 - General Storeroom - .48 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	

<b>B00D - R0019 - Entry Vestibule - 37.58 m2</b>							
No Asbestos							
<b>B00D - R9001 - Kiln Room - 12.16 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00D - R9002 - General Storeroom - 26.51 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - General Learning - 1973 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B00E - R0001 - Personal Effects Storage - 4.54 m2</b>							
No Asbestos							
<b>B00E - R0002 - Sports Store - 4.74 m2</b>							
Electrical - Mounting Board	Resinous Board	1	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00E - R0003 - Home Base Store - 4.28 m2</b>							
No Asbestos							
<b>B00E - R0004 - Home Base - 48.69 m2</b>							
No Asbestos							
<b>B00E - R0005 - Practical Activities - 1hb - 7.95 m2</b>							
No Asbestos							
<b>B00E - R0006 - Home Base - 57.44 m2</b>							
No Asbestos							
<b>B00E - R0007 - Home Base Store - 4.12 m2</b>							
No Asbestos							
<b>B00E - R0008 - Movement - 5.94 m2</b>							
No Asbestos							
<b>B00E - R0009 - Personal Effects Storage - 8.47 m2</b>							
Wall Linings Internal - Splash back	Compressed AC Sheet	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R0010 - Home Base Store - 4.17 m2</b>							
No Asbestos							
<b>B00E - R0011 - Home Base - 57.6 m2</b>							
No Asbestos							
<b>B00E - R0012 - Home Base Store - .61 m2</b>							
No Asbestos							
<b>B00E - R0013 - Movement - 1.62 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0014 - Home Base Store - .65 m2</b>							
No Asbestos							
<b>B00E - R0015 - Home Base - 57.28 m2</b>							
No Asbestos							
<b>B00E - R0016 - Home Base Store - 5.37 m2</b>							
No Asbestos							
<b>B00E - R0017 - Personal Effects Storage - 5.64 m2</b>							
No Asbestos							

<b>B00E - R0018 - Movement - 2.47 m2</b>							
No Asbestos							
<b>B00E - R0022 - Stairs - 15.84 m2</b>							
No Asbestos							
<b>B00E - R0023 - Movement - 34.56 m2</b>							
No Asbestos							
<b>B00E - R0024 - Movement - 83.26 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	84m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R9001 - General Storeroom - 99.58 m2</b>							
No Asbestos							
<b>B00E - R9002 - Movement - 25.54 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R9003 - Canteen - 19.75 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R9004 - Canteen Office/Store - 4.02 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R9005 - Canteen Office/Store - 3.44 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R9006 - Sports Store - 24.68 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R9007 - Cleaning Distributed Store - 3.88 m2</b>							
No Asbestos							
<b>B00E - R9008 - Movement - 35.7 m2</b>							
No Asbestos							
<b>B00E - R9009 - Stairs - 10.86 m2</b>							
No Asbestos							
<b>B00F - Communal Facilities - 1965 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00F - R0001 - Disabled Toilet - 4.55 m2</b>							
No Asbestos							
<b>B00F - R0002 - Plant - .68 m2</b>							
No Asbestos							
<b>B00F - R0003 - Hall Chair Store - 9.51 m2</b>							
No Asbestos							
<b>B00F - R0004 - Communal/Performance Store - 14.32 m2</b>							
No Asbestos							
<b>B00F - R0006 - Movement - 11.95 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00F - R0008 - Movement - 53.96 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00F - R0009 - Plant - .38 m2</b>							



No Asbestos		
<b>B00F - R0010 - Distribution Board - .73 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0011 - Plant - .61 m2</b>		
No Asbestos		
<b>B00F - R0012 - Lift - 2.01 m2</b>		
No Asbestos		
<b>B00F - R0013 - Communal Space - 150.6 m2</b>		
No Asbestos		
<b>B00F - R0014 - Raised Platform - 44.89 m2</b>		
No Asbestos		
<b>B00G - Other-After School Care - 2000 - Timber</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00G - R0001 - Other-After School Care - 52.12 m2</b>		
No Asbestos		
<b>B00G - R0002 - Staff Kitchen - 8.02 m2</b>		
No Asbestos		
<b>B00G - R0003 - Toilets-Unisex - 2.06 m2</b>		
No Asbestos		
<b>B00G - R0004 - Movement - 1.56 m2</b>		
No Asbestos		
<b>B00G - R0005 - Out Of School Hours Care Centre - 8.12 m2</b>		
No Asbestos		
<b>B00G - R0006 - Out Of School Hours Care Centre - 3.63 m2</b>		
No Asbestos		
<b>B00H - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0001 - Practical Activities - 1hb - 19.19 m2</b>		
No Asbestos		
<b>B00H - R0002 - Home Base - 60.37 m2</b>		
No Asbestos		
<b>B00H - R0003 - Home Base Store - 6.17 m2</b>		
No Asbestos		
<b>B00H - R0004 - Withdrawal Space - 2hb - 11.62 m2</b>		
No Asbestos		
<b>B00H - R0005 - Practical Activities - 1hb - 19.14 m2</b>		
No Asbestos		
<b>B00H - R0006 - Home Base - 60.36 m2</b>		
No Asbestos		
<b>B00H - R0007 - Home Base Store - 6.09 m2</b>		
No Asbestos		
<b>B00H - R0008 - Garden Store - 12.58 m2</b>		
No Asbestos		

<b>B00H - R0009 - General Assistant/Bulk Store - 15.29 m2</b>	
No Asbestos	
<b>B00H - R0010 - Sports Store - 12.15 m2</b>	
No Asbestos	
<b>B00H - R0011 - External Movement - 45.23 m2</b>	
No Asbestos	
<b>B00H - R0012 - External Movement - 12.69 m2</b>	
No Asbestos	
<b>B00H - R1001 - Practical Activities - 1hb - 18.87 m2</b>	
No Asbestos	
<b>B00H - R1002 - Home Base - 60.16 m2</b>	
No Asbestos	
<b>B00H - R1003 - Home Base Store - 6.09 m2</b>	
No Asbestos	
<b>B00H - R1004 - Withdrawal Space - 2hb - 11.62 m2</b>	
No Asbestos	
<b>B00H - R1005 - Practical Activities - 1hb - 18.91 m2</b>	
No Asbestos	
<b>B00H - R1006 - Home Base - 60.53 m2</b>	
No Asbestos	
<b>B00H - R1007 - Home Base Store - 6.09 m2</b>	
No Asbestos	
<b>B00H - R1008 - External Movement - 41.29 m2</b>	
No Asbestos	
<b>B00I - Pupil Facilities - 2011 - Brick/Veneer</b>	
<b>Exterior</b>	
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found
<b>Interior</b>	
<b>B00I - R0001 - Toilets - Boys - 33.09 m2</b>	
No Asbestos	
<b>B00I - R0002 - Cleaning Distributed Store - .81 m2</b>	
No Asbestos	
<b>B00I - R0003 - Disabled Shower/Toilet - 8.93 m2</b>	
No Asbestos	
<b>B00I - R0004 - Toilets - Girls - 33.09 m2</b>	
No Asbestos	
<b>B00I - R0005 - External Movement - 33.92 m2</b>	
No Asbestos	

## Demountables

### OS 602 10356 - Learning Unit - Standard With P.A.A. - Placement Date : 21-NOV-2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 750 11276 - Learning Unit - ESL - Placement Date : 11-MAR-1999

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Eaves Linings	Flat AC Sheeting	5.76m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Esl

End Wall Panel	Flat AC Sheeting	50m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Assumed Asbestos

### OS 603 11591 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 13-DEC-2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 750 11599 - Learning Unit - ESL - Placement Date : 24-NOV-2015

No Asbestos Found

### OS 601 11772 - Learning Unit - Standard/Withdrawal - Placement Date : 03-FEB-2006

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

##### R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

##### R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

### OS 602 13463 - Learning Unit - Standard With P.A.A. - Placement Date : 24-NOV-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 603 14053 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 22-DEC-2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 14455 - Learning Unit - Standard With P.A.A. - Placement Date : 24-NOV-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 14859 - Learning Unit - Standard With P.A.A. - Placement Date : 21-NOV-2016

No Asbestos Found

### OS 602 17695 - Learning Unit - Standard With P.A.A. - Placement Date : 03-FEB-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

**OS 606 19151 - Learning Unit - Standard With P.A.A A/C - Placement Date : 20-DEC-2017**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 606 19153 - Learning Unit - Standard With P.A.A A/C - Placement Date : 20-DEC-2017**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found