



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - General Learning - 1950 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Cleaning Supplies Store - 5.81 m2</b>							
No Asbestos							
<b>B00A - R0002 - Security Store - 12.77 m2</b>							
No Asbestos							
<b>B00A - R0003 - Movement - 3.22 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	3.22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0004 - General Learning Space - 53.65 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0005 - General Learning Space - 53.51 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0006 - Principal - 12.69 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	0.2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0007 - Interview - 9.32 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0008 - Clerical Office - 14.02 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0009 - Interview - 8.48 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0010 - Commonroom - 30.36 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0011 - Home Base - 53.65 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0012 - Duplicating Workroom - 9.36 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0013 - Staff Toilet - 7.61 m2</b>							
No Asbestos							
<b>B00A - R0014 - Staff Toilet - 2.82 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0015 - Movement - 41.13 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	41.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0016 - Movement - 8.82 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0017 - Movement - 18.01 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0018 - Movement - 21.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	21.2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0019 - Movement - 2.16 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0020 - Movement - 2.16 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - Pupil Facilities - 1950 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground							
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00B - R0001 - Toilets - Boys - 25.18 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00B - R0002 - Toilets - Girls - 26.79 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00C - Communal Facilities - 2001 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						

Eaves Linings	Flat AC Sheeting	180m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids - Slab on Ground							
<b>Interior</b>							
<b>B00C - R0001 - Shower/Change - 30.39 m2</b>							
No Asbestos							
<b>B00C - R0002 - Stairs - 10.36 m2</b>							
No Asbestos							
<b>B00C - R0003 - Movement - 43.46 m2</b>							
No Asbestos							
<b>B00C - R0004 - Stairs - 10.37 m2</b>							
No Asbestos							
<b>B00C - R0005 - Shower/Change - 32.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00C - R0006 - General Storeroom - .79 m2</b>							
No Asbestos							
<b>B00C - R0007 - Control Room - 14.69 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00C - R0008 - Toilets - Boys - 9.04 m2</b>							
No Asbestos							
<b>B00C - R0009 - Cleaning Supplies Store - 2.01 m2</b>							
No Asbestos							
<b>B00C - R0010 - Movement - 3.12 m2</b>							
No Asbestos							
<b>B00C - R0011 - Stairs - 10.36 m2</b>							
No Asbestos							
<b>B00C - R0012 - Movement - 43.39 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00C - R0013 - Stairs - 10.37 m2</b>							
No Asbestos							
<b>B00C - R0014 - Hall Chair Store - 2 m2</b>							
No Asbestos							
<b>B00C - R0015 - Movement - 3.1 m2</b>							
No Asbestos							
<b>B00C - R0016 - Toilets - Girls - 9.15 m2</b>							
No Asbestos							
<b>B00C - R0017 - Movement - 6.07 m2</b>							
No Asbestos							
<b>B00C - R0018 - Movement - 6.11 m2</b>							
No Asbestos							
<b>B00C - R0019 - Movement - 416.5 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	417m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00C - R0020 - Main Switchroom - 3.01 m2</b>							
No Asbestos							
<b>B00C - R9001 - No Access - 2.5 m2</b>							

No Asbestos							
<b>B00C - R9002 - Sports Store - 29.97 m2</b>							
No Asbestos							
<b>B00C - R9003 - Multi-Purpose Space - 579.52 m2</b>							
No Asbestos							
<b>B00C - R9004 - Hall Chair Store - 33.33 m2</b>							
No Asbestos							
<b>B00C - R9005 - General Storeroom - 2.99 m2</b>							
No Asbestos							
<b>B00C - R9006 - Stairs - .26 m2</b>							
No Asbestos							
<b>B00C - R9007 - Movement - 8.6 m2</b>							
No Asbestos							
<b>B00C - R9008 - Stage - 40.53 m2</b>							
No Asbestos							
<b>B00C - R9009 - Movement - 8.6 m2</b>							
No Asbestos							
<b>B00C - R9010 - Stairs - .26 m2</b>							
No Asbestos							
<b>B00C - R9011 - General Storeroom - 2.97 m2</b>							
No Asbestos							
<b>B00C - R9012 - Hall Chair Store - 32.39 m2</b>							
No Asbestos							
<b>B00C - R9013 - Sports Store - 27.02 m2</b>							
No Asbestos							
<b>B00C - R9014 - Staff Kitchen - 4.92 m2</b>							
No Asbestos							
<b>B00C - R9015 - Stairs - 10.36 m2</b>							
No Asbestos							
<b>B00C - R9016 - Stairs - 10.37 m2</b>							
No Asbestos							
<b>B00C - R9017 - Stairs - 10.36 m2</b>							
No Asbestos							
<b>B00C - R9018 - Stairs - 10.37 m2</b>							
No Asbestos							
<b>B00D - General Learning - 1930 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	50m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0002 - Practical Activities - 78.84 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00D - R0003 - General Storeroom - 11.01 m2</b>							
No Asbestos							
<b>B00D - R0004 - General Storeroom - 11.13 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	11.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

<b>B00D - R0005 - Practical Activities - 36.97 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	36.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0006 - Practical Activities - 58.82 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	58.82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0007 - Practical Activities - 7.45 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7.45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
<b>B00D - R0008 - General Storeroom - 17.72 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	17.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0009 - General Storeroom - 17.79 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	17.79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0010 - Practical Activities - 82.84 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00D - R0011 - Movement - 48.15 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	48.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00D - R0012 - General Storeroom - 18.67 m2</b>							
No Asbestos							
<b>B00D - R0013 - Kiln Room - 4.69 m2</b>							
No Asbestos							
<b>B00E - General Learning - 1950 - Timber</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	20m2	North & East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground							
Ceiling Voids	Requires Inspection						
<b>Interior</b>							
<b>B00E - R0002 - External Movement - 25.58 m2</b>							
No Asbestos							
<b>B00E - R0003 - Sports Store - 47.11 m2</b>							
Wall Linings Internal	Flat AC Sheeting	120m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.11m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0004 - Practical Activities - 46.53 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.53m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.53m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0005 - Sports Store - 15.36 m2</b>							

No Asbestos							
<b>B00F - General Learning - 1950 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00F - R0002 - Home Base - Bd/Cd/Ed - 76.87 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	76.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0003 - Staff Toilet - 2.59 m2</b>							
No Asbestos							
<b>B00F - R0004 - Staff Kitchen - 14.28 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	14.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0005 - Movement - 22.08 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	22.08m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0006 - Home Base - Bd/Cd/Ed - 53.44 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0007 - Movement - 4.33 m2</b>							
No Asbestos							
<b>B00F - R0008 - Toilet - Lobby - 2.4 m2</b>							
No Asbestos							
<b>B00F - R0009 - Staff Toilet - 1.68 m2</b>							
No Asbestos							
<b>B00F - R0010 - Staff Toilet - 1.69 m2</b>							
No Asbestos							
<b>B00F - R0011 - Staff Room - 53.59 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0012 - Distribution Board - .36 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
Electrical - Backing Board	Resinous Board	2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0013 - Movement - 1.92 m2</b>							
No Asbestos							
<b>B00F - R0014 - Toilet - Lobby - 1.36 m2</b>							
No Asbestos							
<b>B00F - R0015 - Toilets - Boys - 1.89 m2</b>							
No Asbestos							
<b>B00F - R0016 - Toilet - Lobby - 2.44 m2</b>							
No Asbestos							
<b>B00F - R0017 - Toilets - Girls - 1.82 m2</b>							
No Asbestos							
<b>B00F - R0018 - Movement - 28.48 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	28.48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0019 - Movement - 11.24 m2</b>							



Ceiling Structures/Linings	Flat AC Sheeting	11.24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0020 - Home Base - 53.52 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0021 - Movement - 6.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0022 - Movement - 3.2 m2</b>							
No Asbestos							
<b>B00F - R0023 - General Storeroom - 5.73 m2</b>							
No Asbestos							
<b>B00F - R0024 - Clerical Office - 12.69 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12.69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0025 - External Movement - 3.82 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3.82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00G - Other-Commercial - 1930 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Flat AC Sheeting	30m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting	40m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00G - R0001 - No Access - 454.44 m2</b>							
No Asbestos							
<b>B00H - Other-Commercial - 1960 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground							
Eaves Linings	Flat AC Sheeting	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>Interior</b>							
<b>B00H - R0001 - No Access - 16.64 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	16.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>B00I - Library - 2010 - Fibre Cement Clad</b>							
<b>Exterior</b>							
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00I - R0001 - External Movement - 21.16 m2</b>							

No Asbestos							
<b>B00I - R0002 - Reading Area - 61.22 m2</b>							
No Asbestos							
<b>B00I - R0003 - K.L.A. Store - 6.24 m2</b>							
No Asbestos							
<b>B00I - R0004 - Practical Activities/Movement - 1hb - 3.8 m2</b>							
No Asbestos							
<b>B00J - General Learning/Pupil Facilities - 1925 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Gable Verge Lining	Flat AC Sheeting	5m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>Interior</b>							
<b>B00J - R0001 - External Movement - 11.79 m2</b>							
No Asbestos							
<b>B00J - R0002 - Toilets - Boys - 3.79 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00J - R0003 - Home Base - 39 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00J - R0004 - Home Base Store - 3.55 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00J - R0005 - Movement - 6.66 m2</b>							
No Asbestos							
<b>B00J - R0006 - Canteen - 10.84 m2</b>							
No Asbestos							
<b>B00J - R0007 - Covered Outdoor Learning Area - 33.74 m2</b>							
No Asbestos							
<b>B00K - General Learning - 2014 - Metal Shed</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Flat AC Sheeting						
<b>Interior</b>							
<b>B00K - R0001 - Garden Store - 18.25 m2</b>							
No Asbestos							
<b>B00L - General Learning - 1960 - Greenhouse</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground							
<b>Interior</b>							
<b>B00L - R0001 - Practical Activities - 6.69 m2</b>							
Electrical - Box/ Cabinet	Flat AC Sheeting						
<b>B00M - General Learning - 1975 - Greenhouse</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground							

Ceiling Voids - Raked Ceiling							
<b>Interior</b>							
<b>B00M - R0001 - Practical Activities - 9.24 m2</b>							
No Asbestos							
<b>B00N - General Learning - 2005 - Steel</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof							
Underfloor Voids - Slab on Ground							
<b>Interior</b>							
<b>B00N - R0001 - General Storeroom - 13.62 m2</b>							
No Asbestos							
<b>B00N - R0002 - Practical Activities - 36.72 m2</b>							
No Asbestos							
<b>B00N - R0003 - Garden Store - 13.68 m2</b>							
No Asbestos							

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020