

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Holroyd School (5633)
Region:	South Western Sydney AMU
State Electorate:	Granville
Local Government Area:	Cumberland

Last Reviewed By:	WSP 11-SEP-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1972 - Brick/Block							
Exterior							
External Wall Structure - Awnings	Flat AC Sheeting	20	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0002 - External Movement - 68.96 m2							
Ceiling Structures/Linings	Flat AC Sheeting	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	10m2	North, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00A - R0003 - Duplicating Workroom - 12.22 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00A - R0004 - General Storeroom - 15.09 m2							
No Asbestos							
B00A - R0010 - Staff Toilet - 4.21 m2							
No Asbestos							
B00A - R0012 - Distribution Board - .67 m2							
No Asbestos							
B00A - R0013 - Cleaning Distributed Store - 2.67 m2							
No Asbestos							
B00A - R0014 - Staff Toilet - 4.17 m2							
No Asbestos							
B00A - R0017 - Cleaning Distributed Store - 3.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00A - R0018 - Toilets - Girls - 13.85 m2							
Partition Walls (Cubides)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00A - R0019 - Principal - 19.72 m2							
No Asbestos							
B00A - R0022 - Special Programs Room - 13.4 m2							
No Asbestos							
B00A - R0023 - Home Base - M - 69.7 m2							
No Asbestos							
B00A - R0024 - Communications Cupboard - 1.27 m2							
No Asbestos							
B00A - R0025 - Toilet - Lobby - 4.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0026 - Access Shower/Toilet/Change - 22.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0027 - Movement - 5.69 m2							
No Asbestos							
B00A - R0028 - Staff Room Annexe - 10.12 m2							
No Asbestos							

Note: No inspection of live electrical installation

B00A - R0029 - External Movement - 19.79 m2							
No Asbestos							
B00B - Support Unit - 1972 - Brick/Block							
Exterior							
External Wall Structure - Awnings	Flat AC Sheeting	8	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - External Movement - 30.78 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	South, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00B - R0002 - Covered Vehicle Area/Porte Cochere - 32.68 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	6m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00B - R0003 - Main Switch Board - 5.89 m2							
No Asbestos							
B00B - R0004 - Home Base Store - M - 4.59 m2							
No Asbestos							
B00B - R0005 - Toilet - M - 3.37 m2							
No Asbestos							
B00B - R0006 - Home Base - M - 44.32 m2							
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00B - R0007 - Home Base - M - 42.36 m2							
Floor Coverings Res/Textile	Vinyl Tiles	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00B - R0008 - Home Base Store - M - 6.68 m2							
No Asbestos							
B00B - R0009 - Practical Activities - M - 1hb - 1.67 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00B - R0010 - External Movement - 21.67 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	4m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - Support Unit - 1972 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - Wheelchair Store - 32.33 m2							
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0002 - Canteen - 18.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0004 - Home Base Store - S - 8.41 m2							

No Asbestos							
B00C - R0005 - Staff Kitchen - 8.82 m2							
No Asbestos							
B00C - R0006 - Practical Activities - S - 1hb - 28.13 m2							
No Asbestos							
B00C - R0007 - Home Base - S - 56.93 m2							
No Asbestos							
B00C - R0008 - Toilet - S - 5.56 m2							
Wall Linings Internal	Flat AC Sheeting						
B00C - R0009 - Movement - 1.99 m2							
Wall Linings Internal	Flat AC Sheeting						
B00C - R0010 - Toilet - S - 35.57 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0011 - Canteen Office/Store - 2.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0012 - Canteen Office/Store - 4.91 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0013 - Staff Toilet - 2.18 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	West	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - R0014 - Distribution Board - .78 m2							
Note: No inspection of live electrical installation							
No Asbestos							
B00C - R0015 - External Movement - 102.88 m2							
Ceiling Structures/Linings	Flat AC Sheeting	103m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0016 - Home Base - S - 42.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0017 - Practical Activities - S - 1hb - 1.53 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0018 - General Storeroom - 4.68 m2							
No Asbestos							
B00C - R0019 - Home Base Store - S - 7.87 m2							
No Asbestos							
B00C - R0020 - Staff Kitchen - 8.59 m2							
No Asbestos							
B00C - R0021 - Practical Activities - S - 1hb - 23.06 m2							
No Asbestos							
B00C - R0022 - Home Base - S - 42.61 m2							
No Asbestos							
B00C - R0023 - External Movement - 4.07 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0024 - General Storeroom - 6.54 m2							
No Asbestos							
B00C - R0025 - P.E Store - 3.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)

B00C - R0026 - Toilets - Boys - 14.32 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0029 - Distribution Board - .78 m2							
Note: No inspection of live electrical installation							
No Asbestos							
B00C - R0034 - Movement - 26.79 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	26m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0035 - Outdoor Learning Area - 38.4 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	20m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0037 - External Movement - 19.63 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0038 - External Movement - 14.88 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	6m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0039 - External Movement - 33.67 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	16m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00C - R0041 - Practical Activities - M - 1hb - 6.69 m2							
No Asbestos							
B00C - R0042 - Practical Activities - M - 1hb - 6.69 m2							
No Asbestos							
B00C - R0043 - Home Base Store - M - 7.68 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0044 - Special Programs Room - 7.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0045 - External Movement - 61.73 m2							
No Asbestos							
B00C - R0046 - Home Base - 58.84 m2							
No Asbestos							
B00C - R0047 - Toilets-Unisex - 9.83 m2							
No Asbestos							
B00C - R0048 - Staff Toilet - 9.97 m2							
No Asbestos							
B00C - R0049 - Cleaning Distributed Store - 8 m2							
No Asbestos							
B00F - Support Unit/Special Purpose - 1972 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

Interior							
B00F - R0001 - External Movement - 14.06 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00F - R0002 - P.E Store - 7.18 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00F - R0003 - Staff Room Annexe - 7.02 m2							
No Asbestos							
B00F - R0005 - Home Base - M - 44.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0006 - Home Base Store - M - 6.96 m2							
No Asbestos							
B00F - R0007 - Home Base Store - M - 6.96 m2							
No Asbestos							
B00F - R0008 - Practical Activities - M - 1hb - 52.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0009 - Toilet - M - 4.52 m2							
No Asbestos							
B00F - R0012 - Laundry - 15.62 m2							
No Asbestos							
B00F - R0013 - Outdoor Learning Area - 74.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	30m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00F - R0014 - Movement - 16.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	10m2	South, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00F - R0015 - External Movement - 22.04 m2							
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
Wall Linings Internal - Infill	Compressed AC Sheet	8m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (White asbestos)
B00G - Support Unit - 1972 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00G - R0001 - Toilets - Boys - 10.64 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R0002 - Toilets - Girls - 10.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R0003 - Disabled Toilet - 14 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R0004 - Movement - 4.48 m2							

Ceiling Structures/Linings	Flat AC Sheeting							
B00G - R0005 - Hydrotherapy - Pool - 175.28 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00G - R0006 - Shower/Change - 7.77 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00G - R0007 - Shower/Change - 7.82 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00G - R0008 - Plant - 6.91 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00G - R0009 - External Movement - 1.72 m2								
No Asbestos								
B00G - R0010 - External Movement - 32.28 m2								
No Asbestos								
B00G - R0011 - Hydrotherapy - Pool - 295.98 m2								
Non Accessible								
B00J - Administration - 1984 - Brick/Block								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00J - R0002 - Staff Room - 11.64 m2								
No Asbestos								
B00J - R0003 - Staff Toilet - 3.81 m2								
No Asbestos								
B00J - R0004 - Staff Toilet - 3.03 m2								
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	North, East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
B00J - R0005 - Movement - 2.67 m2								
No Asbestos								
B00J - R0006 - Staff Room Annexe - 13.64 m2								
No Asbestos								
B00J - R0007 - Movement - 14.16 m2								
No Asbestos								
B00J - R0008 - Covered Vehicle Area/Porte Cochere - 103.46 m2								
Ceiling Structures/Linings	Flat AC Sheeting	104m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
B00J - R0009 - Community Clinic - 13.75 m2								
No Asbestos								
B00J - R0010 - Staff Kitchen - 21.42 m2								
No Asbestos								
B00J - R0011 - Covered Outdoor Learning Area - S - 183.98 m2								
No Asbestos								
B00M - Library - 2002 - Brick/Veneer								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00M - R0001 - Reading Area - 179.96 m2								

Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0002 - Library Office/Workroom - 24.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0003 - Communications Room - 8.07 m2		
No Asbestos		
B00M - R0004 - No Access - 14.4 m2		
No Asbestos		
B00M - R0005 - Distribution Board - .56 m2		Note: No inspection of live electrical installation
No Asbestos		
B00M - R0006 - External Movement - 47.53 m2		
No Asbestos		
B00N - Communal Facilities - 2002 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00N - R0001 - External Movement - 28.76 m2		
No Asbestos		
B00N - R0002 - Raised Platform - 55.06 m2		
No Asbestos		
B00N - R0003 - Movement - 27.86 m2		
No Asbestos		
B00N - R0004 - External Movement - 28.88 m2		
No Asbestos		
B00N - R0005 - Hall Chair Store - 11.06 m2		
No Asbestos		
B00N - R0006 - Main Switch Board - 2.21 m2		
No Asbestos		
B00N - R0007 - Cleaning Distributed Store - 3.41 m2		
No Asbestos		
B00N - R0008 - Movement - 6.7 m2		
No Asbestos		
B00N - R0009 - Sports Store - 17.24 m2		
No Asbestos		
B00N - R0010 - P.E Store - 17.19 m2		
No Asbestos		
B00N - R0011 - Toilets - Girls - 12.63 m2		
No Asbestos		
B00N - R0012 - Covered Outdoor Learning Area - 188.84 m2		
No Asbestos		
B00N - R0013 - Communal Space - 201 m2		
No Asbestos		
B00N - R0014 - Access Shower/Toilet - 5.66 m2		
No Asbestos		
B00N - R0015 - Toilets - Boys - 11.03 m2		
No Asbestos		
B00N - R0016 - Communications Cupboard - 1.86 m2		
No Asbestos		
B00N - R0017 - Communal/Performance Store - 26.8 m2		

No Asbestos		
B00N - R0018 - Movement - 6.54 m2		
No Asbestos		
B00N - R0019 - Communal/Performance Store - 10.93 m2		
No Asbestos		
B00N - R0020 - Movement - 8.22 m2		
No Asbestos		
B00N - R0021 - Cleaning Supplies - 6.84 m2		
No Asbestos		
B00O - Support Unit - 2002 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00O - R0001 - External Movement - 102.81 m2		
No Asbestos		
B00O - R0002 - Distribution Board - .57 m2		Note: No inspection of live electrical installation
No Asbestos		
B00O - R0003 - Home Base Store - M - 4.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0004 - Withdrawal - M - 9.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0005 - Withdrawal - M - 9.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0006 - Home Base Store - M - 5.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0007 - Home Base - M - 59.57 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0008 - Home Base - M - 59.64 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0009 - Practical Activities - M - 1hb - 15.71 m2		
No Asbestos		
B00O - R0010 - Practical Activities - M - 1hb - 15.68 m2		
No Asbestos		
B00O - R0011 - Movement - 21.93 m2		
No Asbestos		
B00O - R0012 - Toilets - Boys - 38.47 m2		
No Asbestos		
B00O - R0013 - Laundry - 7.72 m2		
No Asbestos		
B00O - R0014 - Toilets - Grls - 38.78 m2		
No Asbestos		
B00O - R0015 - Movement - 22.02 m2		
No Asbestos		
B00O - R0016 - Practical Activities - M - 1hb - 15.82 m2		
No Asbestos		
B00O - R0017 - Practical Activities - M - 1hb - 15.68 m2		

No Asbestos		
B00O - R0018 - Home Base - M - 59.62 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0019 - Home Base - M - 59.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0020 - Home Base Store - M - 5.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0021 - Withdrawal - M - 9.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0022 - Withdrawal - M - 9.41 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0023 - Home Base Store - M - 4.58 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - R0024 - Distribution Board - .57 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00Q - Music - 2004 - Timber		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00Q - R0001 - External Movement - 46.32 m2		
No Asbestos		
B00Q - R0002 - Staff Room - 9.9 m2		
No Asbestos		
B00Q - R0003 - Staff Room - 10.04 m2		
No Asbestos		
B00Q - R0004 - Movement - 3.88 m2		
No Asbestos		
B00Q - R0005 - Staff Toilet - 3.44 m2		
No Asbestos		
B00Q - R0006 - Staff Toilet - 6.21 m2		
No Asbestos		
B00Q - R0007 - Covered Outdoor Learning Area - 10.69 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00Q - R0008 - Special Programs Room - 29.58 m2		
No Asbestos		
B00Q - R0009 - Movement - 1.4 m2		
No Asbestos		
B00Q - R0010 - Special Programs Store - 9.14 m2		
No Asbestos		
B00Q - R0011 - Toilets - Boys/Girls - 4.84 m2		
Wall Linings Internal	Flat AC Sheeting	
B00Q - R0012 - Special Programs Store - 10.16 m2		
No Asbestos		
B00Q - R0013 - Special Programs Store - 9.25 m2		
No Asbestos		

B00R - Special Purpose - 2004 - Timber**Exterior**

Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior**B00R - R0001 - Special Programs Store - 9.14 m2**

No Asbestos

B00R - R0002 - Toilets - Boys/Girls - 4.84 m2

No Asbestos

B00R - R0003 - Special Programs Room - 64.54 m2

No Asbestos

B00R - R0004 - External Movement - 20.83 m2

Ceiling Structures/Linings	Flat AC Sheeting	
----------------------------	------------------	--

B00R - R0005 - Special Programs Room - 16.08 m2

No Asbestos

B00R - R0006 - Staff Toilet - 6.18 m2

No Asbestos

B00R - R0007 - External Movement - 10.53 m2

No Asbestos

B00S - Administration - 2006 - Brick/Veneer**Exterior**

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior**B00S - R0001 - Staff Room - 83.62 m2**

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00S - R0002 - Staff Room Annexe - 36.29 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00S - R0003 - Deputy Principal - 12.98 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00S - R0004 - Sick Bay - 9.12 m2

No Asbestos

B00S - R0005 - Clerical Office/Workroom - 52.65 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00S - R0006 - Movement - 52.02 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

B00S - R0007 - Staff Toilet - 4.79 m2

No Asbestos

B00S - R0008 - Staff Toilet - 4.88 m2

No Asbestos

B00S - R0009 - Staff Toilet - 4.8 m2

No Asbestos

B00S - R0010 - Security Store - 11.25 m2

No Asbestos

B00S - R0011 - Entry Vestibule - 21.81 m2

Floor Coverings Res/Textile	No Asbestos Found	
B00S - R0012 - Principal - 30.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00S - R0013 - Deputy Principal - 12.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00S - R0014 - Cleaning Distributed Store - 4.22 m2		
No Asbestos		
B00S - R0015 - Main Switch Board - 1.21 m2		
No Asbestos		
B00S - R0016 - Access Shower/Toilet - 5.79 m2		
No Asbestos		
B00S - R0017 - External Movement - 82.27 m2		
No Asbestos		
B00T - Support Unit (M P S)/Pupil Facilities - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00T - R0001 - Practical Activities - M - 1hb - 37.8 m2		
No Asbestos		
B00T - R0002 - Home Base - M - 34.21 m2		
No Asbestos		
B00T - R0003 - Home Base Store - M - 4.72 m2		
No Asbestos		
B00T - R0004 - Withdrawal - M - 8.81 m2		
No Asbestos		
B00T - R0005 - Practical Activities - M - 1hb - 37.8 m2		
No Asbestos		
B00T - R0006 - Home Base - M - 34.21 m2		
No Asbestos		
B00T - R0007 - Home Base Store - M - 5.49 m2		
No Asbestos		
B00T - R0008 - Withdrawal - M - 8.85 m2		
No Asbestos		
B00T - R0009 - Practical Activities - S - 1hb - 37.8 m2		
No Asbestos		
B00T - R0010 - Home Base - M - 34.21 m2		
No Asbestos		
B00T - R0011 - Home Base Store - S - 4.72 m2		
No Asbestos		
B00T - R0012 - Withdrawal - S - 8.84 m2		
No Asbestos		
B00T - R0013 - Practical Activities - S - 1hb - 37.8 m2		
No Asbestos		
B00T - R0014 - Home Base - S - 34.21 m2		
No Asbestos		
B00T - R0015 - Home Base Store - S - 5.49 m2		
No Asbestos		
B00T - R0016 - Withdrawal - S - 8.85 m2		

No Asbestos		
B00T - R0017 - Movement - 10.97 m2		
No Asbestos		
B00T - R0018 - Access Shower/Toilet/Change - 29.41 m2		
No Asbestos		
B00T - R0019 - Toilet - M - 4.69 m2		
No Asbestos		
B00T - R0020 - Movement - 11.07 m2		
No Asbestos		
B00T - R0021 - Distribution Board - .39 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00T - R0022 - Distribution Board - .42 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00T - R0023 - Plant - .69 m2		
No Asbestos		
B00T - R0024 - Other - 18.87 m2		
No Asbestos		
B00T - R0025 - Other - 18.95 m2		
No Asbestos		
B00T - R0026 - External Movement - 129.53 m2		
No Asbestos		
B00T - R0027 - External Movement - 52.96 m2		
No Asbestos		
B00U - Support Unit (M P S) - 2014 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
No Asbestos		
Interior		
B00U - R0001 - External Movement - 129.69 m2		
No Asbestos		
B00U - R0002 - Ramp - 55.41 m2		
No Asbestos		
B00U - R0003 - Laundry - S - 6.62 m2		
No Asbestos		
B00U - R0004 - Home Base Store - 6.57 m2		
No Asbestos		
B00U - R0005 - Cleaning Distributed Store - 5.59 m2		
No Asbestos		
B00U - R0006 - Withdrawal Space - 1hb - 7.57 m2		
No Asbestos		
B00U - R0007 - Breakout Area - 11.73 m2		
No Asbestos		
B00U - R0008 - Access Shower/Toilet - Type 2 - 7.61 m2		
No Asbestos		
B00U - R0009 - Toilets-Unisex - 21.18 m2		
No Asbestos		
B00U - R0010 - Home Base - 59.06 m2		
No Asbestos		
B00U - R0011 - Practical Activities - 1hb - 18.98 m2		
No Asbestos		

B00U - R0012 - Practical Activities - 1hb - 18.98 m2	
No Asbestos	
B00U - R0013 - Home Base - 59.15 m2	
No Asbestos	
B00U - R0014 - Breakout Area - 9.55 m2	
No Asbestos	
B00U - R0015 - Withdrawal Space - 1hb - 9.54 m2	
No Asbestos	
B00U - R0016 - Withdrawal Space - 1hb - 9.42 m2	
No Asbestos	
B00U - R0017 - Home Base Store - 5.98 m2	
No Asbestos	
B00U - R0018 - Distribution Board - 1.53 m2	
	Note: No inspection of live electrical installation
No Asbestos	
B00U - R0019 - Practical Activities - 1hb - 18.94 m2	
No Asbestos	
B00U - R0020 - Home Base Store - 5.95 m2	
No Asbestos	
B00U - R0021 - Home Base - 59.15 m2	
No Asbestos	
B00U - R0022 - Breakout Area - 9.57 m2	
No Asbestos	
B00U - R0023 - Access Shower/Toilet - Type 2 - 7.61 m2	
No Asbestos	
B00U - R0024 - Toilets-Unisex - 21.05 m2	
No Asbestos	
B00U - R0025 - Distribution Board - 1.53 m2	
	Note: No inspection of live electrical installation
No Asbestos	
B00U - R0026 - Practical Activities - 1hb - 18.96 m2	
No Asbestos	
B00U - R0027 - Home Base - 59.15 m2	
No Asbestos	
B00U - R0028 - Breakout Area - 9.53 m2	
No Asbestos	
B00U - R0029 - Withdrawal Space - 1hb - 9.51 m2	
No Asbestos	
B00U - R0030 - Withdrawal Space - 1hb - 9.45 m2	
No Asbestos	
B00U - R0031 - Home Base Store - 6.02 m2	
No Asbestos	
B00U - R0032 - Home Base Store - 5.98 m2	
No Asbestos	
B00U - R0033 - Practical Activities - 1hb - 18.94 m2	
No Asbestos	
B00U - R0034 - Home Base - 59.15 m2	
No Asbestos	
B00U - R0035 - Breakout Area - 9.56 m2	
No Asbestos	
B00U - R0036 - Access Shower/Toilet - Type 2 - 7.55 m2	
No Asbestos	
B00U - R0037 - Disabled Toilet - 6.95 m2	
No Asbestos	

B00U - R0038 - Practical Activities - 1hb - 18.99 m2		
No Asbestos		
B00U - R0039 - Home Base - 59.01 m2		
No Asbestos		
B00U - R0040 - Toilets-Unisex - 20.98 m2		
No Asbestos		
B00U - R0041 - Breakout Area - 13.89 m2		
No Asbestos		
B00U - R0042 - Withdrawal Space - 1hb - 10.03 m2		
No Asbestos		
B00U - R0043 - Plant - 10.86 m2		
No Asbestos		
B00U - R0044 - Home Base Store - 6.98 m2		
No Asbestos		
B00V - Support Unit (M P S) - 2014 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
No Asbestos		
Interior		
B00V - R0001 - External Movement - 87.64 m2		
No Asbestos		
B00V - R0002 - Practical Activities - 1hb - 29.69 m2		
No Asbestos		
B00V - R0003 - Home Base - 48.22 m2		
No Asbestos		
B00V - R0004 - Disabled Toilet - 6.52 m2		
No Asbestos		
B00V - R0005 - Cleaning Distributed Store - 7.63 m2		
No Asbestos		
B00V - R0006 - Home Base Store - 9.45 m2		
No Asbestos		
B00V - R0007 - Withdrawal Space - 1hb - 9.53 m2		
No Asbestos		
B00V - R0008 - Breakout Area - 13.37 m2		
No Asbestos		
B00V - R0009 - Toilets-Unisex - 21.11 m2		
No Asbestos		
B00V - R0010 - Access Shower/Toilet - Type 2 - 7.61 m2		
No Asbestos		
B00V - R0011 - Breakout Area - 9.55 m2		
No Asbestos		
B00V - R0012 - Withdrawal Space - 1hb - 9.5 m2		
No Asbestos		
B00V - R0013 - Home Base Store - 5.98 m2		
No Asbestos		
B00V - R0014 - Home Base - 48.84 m2		
No Asbestos		
B00V - R0015 - Practical Activities - 1hb - 29.54 m2		
No Asbestos		
B00V - R0016 - Distribution Board - 1.53 m2		
Note: No inspection of live electrical installation		

No Asbestos		
B00V - R0017 - Practical Activities - 1hb - 29.42 m2		
No Asbestos		
B00V - R0018 - Home Base - 48.77 m2		
No Asbestos		
B00V - R0019 - Home Base Store - 5.98 m2		
No Asbestos		
B00V - R0020 - Withdrawal Space - 1hb - 9.45 m2		
No Asbestos		
B00V - R0021 - Breakout Area - 9.55 m2		
No Asbestos		
B00V - R0022 - Toilets-Unisex - 21.11 m2		
No Asbestos		
B00V - R0023 - Access Shower/Toilet - Type 2 - 7.61 m2		
No Asbestos		
B00V - R0024 - Breakout Area - 13.32 m2		
No Asbestos		
B00V - R0025 - Withdrawal Space - 1hb - 9.54 m2		
No Asbestos		
B00V - R0026 - Plant - 10.35 m2		
No Asbestos		
B00V - R0027 - Home Base Store - 6.64 m2		
No Asbestos		
B00V - R0028 - Laundry - S - 6.65 m2		
No Asbestos		
B00V - R0029 - Home Base - 48.63 m2		
No Asbestos		
B00V - R0030 - Practical Activities - 1hb - 29.33 m2		
No Asbestos		
B00W - Support Unit (M P S) - 2014 - Brick/Veneer		
Exterior		
No Asbestos		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00W - R0001 - External Movement - 47.59 m2		
No Asbestos		
B00W - R0002 - Practical Activities - 1hb - 28.73 m2		
No Asbestos		
B00W - R0003 - Toilets-Unisex - 6.43 m2		
No Asbestos		
B00W - R0004 - Home Base Store - 6.57 m2		
No Asbestos		
B00W - R0005 - Cleaning Distributed Store - 4.37 m2		
No Asbestos		
B00W - R0006 - General Storeroom - 5.75 m2		
No Asbestos		
B00W - R0007 - Withdrawal Space - 1hb - 9.54 m2		
No Asbestos		
B00W - R0008 - Home Base - 49.31 m2		
No Asbestos		

B00W - R0009 - Breakout Area - 10.55 m2		
No Asbestos		
B00W - R0010 - Toilets-Unisex - 21.18 m2		
No Asbestos		
B00W - R0011 - Access Shower/Toilet - Type 2 - 7.61 m2		
No Asbestos		
B00W - R0012 - Breakout Area - 13.37 m2		
No Asbestos		
B00W - R0013 - Plant - 7.25 m2		
No Asbestos		
B00W - R0014 - Withdrawal Space - 1hb - 9.9 m2		
No Asbestos		
B00W - R0015 - Home Base Store - 6.28 m2		
No Asbestos		
B00W - R0016 - Laundry - S - 6.74 m2		
No Asbestos		
B00W - R0017 - Home Base - 45.17 m2		
No Asbestos		
B00W - R0018 - Practical Activities - 1hb - 32.71 m2		
No Asbestos		
B00W - R0019 - Distribution Board - 1.24 m2		Note: No inspection of live electrical installation
No Asbestos		
B00X - Support Unit (M P S) - 2014 - Brick/Veneer		
Exterior		
No Asbestos		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00X - R0001 - External Movement - 97.44 m2		
No Asbestos		
B00X - R0002 - Practical Activities - 1hb - 33.14 m2		
No Asbestos		
B00X - R0003 - Home Base - 44.97 m2		
No Asbestos		
B00X - R0004 - Laundry - S - 6.71 m2		
No Asbestos		
B00X - R0005 - Home Base Store - 6.66 m2		
No Asbestos		
B00X - R0006 - General Storeroom - 8.93 m2		
No Asbestos		
B00X - R0007 - Withdrawal Space - 1hb - 9.54 m2		
No Asbestos		
B00X - R0008 - Breakout Area - 13.84 m2		
No Asbestos		
B00X - R0009 - Access Shower/Toilet - Type 2 - 7.64 m2		
No Asbestos		
B00X - R0010 - Toilets-Unisex - 19.07 m2		
No Asbestos		
B00X - R0011 - Breakout Area - 10.39 m2		
No Asbestos		
B00X - R0012 - Withdrawal Space - 1hb - 9.45 m2		

No Asbestos	
B00X - R0013 - Home Base Store - 5.98 m2	
No Asbestos	
B00X - R0014 - Home Base - 44.9 m2	
No Asbestos	
B00X - R0015 - Practical Activities - 1hb - 33 m2	
No Asbestos	
B00X - R0016 - Practical Activities - 1hb - 33.01 m2	
No Asbestos	
B00X - R0017 - Home Base - 45.04 m2	
No Asbestos	
B00X - R0018 - Withdrawal Space - 1hb - 9.57 m2	
No Asbestos	
B00X - R0019 - Breakout Area - 10.35 m2	
No Asbestos	
B00X - R0020 - Access Shower/Toilet - Type 2 - 7.57 m2	
No Asbestos	
B00X - R0021 - Toilets-Unisex - 19.1 m2	
No Asbestos	
B00X - R0022 - Breakout Area - 14.7 m2	
No Asbestos	
B00X - R0023 - Withdrawal Space - 1hb - 9.57 m2	
No Asbestos	
B00X - R0024 - Plant - 6.7 m2	
No Asbestos	
B00X - R0025 - Cleaning Distributed Store - 3.95 m2	
No Asbestos	
B00X - R0026 - Home Base Store - 6.17 m2	
No Asbestos	
B00X - R0027 - Toilets-Unisex - 6.62 m2	
No Asbestos	
B00X - R0028 - Home Base - 44.97 m2	
No Asbestos	
B00X - R0029 - Practical Activities - 1hb - 33.11 m2	
No Asbestos	
B00X - R0030 - General Storeroom - 14.2 m2	
No Asbestos	
B00X - R0031 - General Storeroom - 9.26 m2	
No Asbestos	
B00X - R0032 - Garden Store - 11.43 m2	
No Asbestos	
B00X - R0033 - General Storeroom - 8.23 m2	
No Asbestos	
B00X - R0034 - Home Base Store - 5.98 m2	
No Asbestos	
B00X - R0035 - Distribution Board - 1.54 m2	Note: No inspection of live electrical installation
No Asbestos	
B00X - R0036 - External Movement - 11.29 m2	
No Asbestos	

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020