


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Hawkesbury High School (8565)
Region:	Western Sydney AMU
State Electorate:	Hawkesbury
Local Government Area:	Hawkesbury

Last Reviewed By:	Greencap 13-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration - 1989 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
<b>Interior</b>							
<b>B00A - R0001 - Duplicating Workroom - 26.27 m2</b>							
No Asbestos							
<b>B00A - R0002 - Teachers Aides - 12.97 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0003 - Interview/Office - Type 1 - 12.97 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0004 - Cleaning Store - Distributed - 3.99 m2</b>							
No Asbestos							
<b>B00A - R0005 - Distribution Board Cupboard - .67 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00A - R0006 - Deputy Principal Office - 15.59 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0008 - Interview/Office - Type 1 - 13.44 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0009 - Toilets-Disabled - 4.18 m2</b>							
No Asbestos							
<b>B00A - R0010 - Security Store - 21.44 m2</b>							
No Asbestos							
<b>B00A - R0011 - Principal Office - 18.8 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0012 - Staff - Toilet - 6.48 m2</b>							
No Asbestos							
<b>B00A - R0015 - Clinic - Girls - 12.07 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0016 - Toilets-Girls - 2.53 m2</b>							
No Asbestos							
<b>B00A - R0017 - Toilets-Boys - 2.53 m2</b>							
No Asbestos							
<b>B00A - R0018 - Clinic - Boys - 12.07 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0019 - Movement - 75.44 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0021 - Movement - 168.03 m2</b>							
No Asbestos							
<b>B00A - R0022 - External Movement - 9.96 m2</b>							
No Asbestos							
<b>B00A - R0023 - Administration - Clerical - 56.55 m2</b>							
No Asbestos							
<b>B00A - R0024 - Public Reception - 29.76 m2</b>							
No Asbestos							
<b>B00A - R0025 - Interview/Meeting - 26.08 m2</b>							
No Asbestos							
<b>B00A - R0026 - Staff Lounge - 16.09 m2</b>							

No Asbestos		
<b>B00A - R0027 - Staff Kitchen - 5.69 m2</b>		
No Asbestos		
<b>B00B - Science/Technological &amp; Applied Studies - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00B - R0001 - Movement - 33.74 m2</b>		
No Asbestos		
<b>B00B - R0002 - Movement - 27.32 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0003 - Laboratory L.S. - 93.13 m2</b>		
No Asbestos		
<b>B00B - R0004 - Laboratory L.S. - 92.61 m2</b>		
No Asbestos		
<b>B00B - R0005 - Chemical Store - 13.17 m2</b>		
No Asbestos		
<b>B00B - R0006 - Apparatus Store - 40.97 m2</b>		
No Asbestos		
<b>B00B - R0007 - Laboratory L.S. - 92.91 m2</b>		
No Asbestos		
<b>B00B - R0008 - Preparation - 83.63 m2</b>		
No Asbestos		
<b>B00B - R0009 - General Storeroom - 12.49 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0010 - Movement - 33.11 m2</b>		
No Asbestos		
<b>B00B - R0011 - Laboratory L.S. - 91.26 m2</b>		
No Asbestos		
<b>B00B - R0012 - Laboratory L.S. - 91.26 m2</b>		
No Asbestos		
<b>B00B - R0013 - Staff Study - 36.28 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0014 - Distribution Board Cupboard - 1.33 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0015 - Stairs - .49 m2</b>		
No Asbestos		
<b>B00B - R1001 - Staff - Toilet - 5.59 m2</b>		
No Asbestos		
<b>B00B - R1002 - Distribution Board Cupboard - 1.26 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R1003 - Cleaning Store - Distributed - 2.23 m2</b>		
No Asbestos		
<b>B00B - R1004 - Secure Storeroom - 17.52 m2</b>		
No Asbestos		
<b>B00B - R1005 - Movement - 31.56 m2</b>		
No Asbestos		
<b>B00B - R1006 - Laundry - 6.96 m2</b>		
No Asbestos		
<b>B00B - R1007 - Staff Study - 22.39 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1008 - Food Technology L.S. - 104.45 m2</b>		
No Asbestos		
<b>B00B - R1011 - Food Technology L.S. - 104.46 m2</b>		
No Asbestos		
<b>B00B - R1012 - Movement - 18.78 m2</b>		
No Asbestos		
<b>B00B - R1013 - Computer Learning Space - 74.35 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1014 - Movement - 72.53 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1015 - Design L.S. - 75.96 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R1016 - Pantry - 15.75 m2</b>		
No Asbestos		
<b>B00B - R1017 - Preparation - 15.83 m2</b>		
No Asbestos		
<b>B00B - R1018 - Stairs - 1.98 m2</b>		
No Asbestos		
<b>B00C - General Learning/Library - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00C - R0001 - Serviced Learning Space - 51.62 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0002 - General Learning Space - 53.17 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0003 - Staff Study - 26.99 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0004 - General Learning Space - 48.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0006 - Toilets-Girls - 16.31 m2</b>		
No Asbestos		
<b>B00C - R0007 - General Storeroom - 17.54 m2</b>		
No Asbestos		
<b>B00C - R0008 - Distribution Board Cupboard - 1.15 m2</b>		
No Asbestos		<b>Note: No inspection of live electrical installation</b>
<b>B00C - R0009 - Study Space - 13.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0010 - Study Space - 15.17 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0011 - Seminar - 18.57 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0012 - Seminar - 19.73 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0013 - Main Area - 380.11 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0014 - Librarian - 10.69 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0015 - Workroom - 34.79 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0016 - Audio Visual Workroom - 25.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0017 - General Learning Space - 48.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0018 - Computer Learning Space - 60.38 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0019 - Computer Resource - 9.73 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0020 - Computer Store - 10.26 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0021 - Serviced Learning Space - 48.18 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0023 - Movement - 3.1 m2</b>		
No Asbestos		
<b>B00C - R0025 - Staff Study - 15.13 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0026 - Senior Study - 13.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0027 - General Storeroom - 17.55 m2</b>		
No Asbestos		
<b>B00C - R0028 - Distribution Board Cupboard - 1.15 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R0029 - Disabled Shower/Toilet - 16.22 m2</b>		
No Asbestos		
<b>B00C - R0032 - Movement - 21.17 m2</b>		
No Asbestos		
<b>B00C - R0033 - Movement - 22.16 m2</b>		
No Asbestos		
<b>B00C - R0034 - Movement - 42 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0035 - Movement - 4.63 m2</b>		
No Asbestos		
<b>B00C - R0036 - Movement - 43.23 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0038 - Stairs - 13.01 m2</b>		
No Asbestos		
<b>B00C - R0039 - Stairs - 12.48 m2</b>		
No Asbestos		
<b>B00C - R0040 - Movement - 49.93 m2</b>		
No Asbestos		
<b>B00C - R1001 - General Learning Space - 49.47 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1002 - General Learning Space - 39.79 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1003 - Staff Study - 39.79 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1004 - General Learning Space - 48.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1005 - General Learning Space - 48.27 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1007 - Study Space - 14.92 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1008 - General Storeroom - 18.12 m2</b>		
No Asbestos		
<b>B00C - R1009 - Distribution Board Cupboard - .68 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R1010 - Interview/Office - Type 1 - 14.71 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1011 - Interview/Office - Type 1 - 14.71 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1012 - Seminar - 12.52 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1013 - Seminar - 14.46 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1014 - General Learning Space - 80.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1015 - Cleaning Store - Distributed - 3.24 m2</b>		
No Asbestos		
<b>B00C - R1016 - General Learning Space - 48.26 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1017 - General Learning Space - 48.02 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1018 - Staff Study - 39.77 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1019 - General Learning Space - 39.77 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1021 - Study Space - 14.72 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1022 - General Storeroom - 17.93 m2</b>		
No Asbestos		
<b>B00C - R1023 - Distribution Board Cupboard - .62 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R1024 - Darkroom Space - 27.07 m2</b>		
No Asbestos		
<b>B00C - R1025 - General Learning Space - 49.48 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1027 - Movement - 4.86 m2</b>		
No Asbestos		
<b>B00C - R1028 - General Storeroom - 2.06 m2</b>		
No Asbestos		
<b>B00C - R1031 - Movement - 19.15 m2</b>		
No Asbestos		
<b>B00C - R1032 - Movement - 46.29 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1033 - Movement - 50.5 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R1034 - Movement - 20.93 m2</b>		
No Asbestos		
<b>B00C - R1035 - Stairs - 12.18 m2</b>		
No Asbestos		
<b>B00C - R1036 - Stairs - 13.44 m2</b>		
No Asbestos		
<b>B00C - R1037 - Movement - 38.5 m2</b>		

No Asbestos		
<b>B00D - Staff Facilities/Pupil Facilities - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00D - R0001 - Toilets-Girls - 26.56 m2</b>		
No Asbestos		
<b>B00D - R0002 - Distribution Board Cupboard - .67 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0003 - Commonroom - 89.45 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0004 - Staff - Toilet - 5.35 m2</b>		
No Asbestos		
<b>B00D - R0005 - Movement - 22.57 m2</b>		
No Asbestos		
<b>B00D - R0006 - Staff - Toilet - 5.36 m2</b>		
No Asbestos		
<b>B00E - Tiered Learning - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00E - R0001 - Cleaning Store - Distributed - 3.24 m2</b>		
No Asbestos		
<b>B00E - R0002 - Movement - 23.02 m2</b>		
No Asbestos		
<b>B00E - R0003 - Tiered Learning Area - 71.88 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0004 - Toilets-Boys - 19.51 m2</b>		
No Asbestos		
<b>B00E - R0005 - Cleaning Supplies Store - 19.06 m2</b>		
No Asbestos		
<b>B00E - R0006 - General Storeroom - 9.63 m2</b>		
No Asbestos		
<b>B00E - R0007 - Distribution Board Cupboard - 1.02 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0008 - Tiered Learning Store - 2.45 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - Art - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00F - R0001 - Toilets-Girls - 17.86 m2</b>		
No Asbestos		
<b>B00F - R0002 - Staff Study - 17.11 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0003 - Resources Space - 20.25 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0004 - Resources Store - 8.9 m2</b>		



Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0005 - Bulk Store - 21.3 m2</b>		
No Asbestos		
<b>B00F - R0006 - Cleaning Store - Distributed - 3.31 m2</b>		
No Asbestos		
<b>B00F - R0007 - Workshop - 60.55 m2</b>		
No Asbestos		
<b>B00F - R0008 - Workshop - 60.65 m2</b>		
No Asbestos		
<b>B00F - R0009 - Workshop - 60.73 m2</b>		
No Asbestos		
<b>B00F - R0010 - Machine Storage - 13.08 m2</b>		
No Asbestos		
<b>B00F - R0011 - Main Switchroom - 9.73 m2</b>		
No Asbestos		
<b>B00F - R0012 - Art Learning Space - 61.26 m2</b>		
No Asbestos		
<b>B00F - R0013 - External Movement - 81.25 m2</b>		
No Asbestos		
<b>B00G - Music/Technological &amp; Applied Studies - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00G - R0001 - Materials Store - 19.02 m2</b>		
No Asbestos		
<b>B00G - R0003 - General Storeroom - 3.78 m2</b>		
No Asbestos		
<b>B00G - R0005 - Materials Technology L.S. - 93.03 m2</b>		
No Asbestos		
<b>B00G - R0006 - Metal Technology Bay - 34.79 m2</b>		
No Asbestos		
<b>B00G - R0007 - Movement - 5.97 m2</b>		
No Asbestos		
<b>B00G - R0008 - Materials Technology L.S. - 93.02 m2</b>		
No Asbestos		
<b>B00G - R0009 - Materials Store - 31 m2</b>		
No Asbestos		
<b>B00G - R0010 - Materials Technology L.S. - 93.02 m2</b>		
No Asbestos		
<b>B00G - R0011 - Wood Technology Bay - 34.46 m2</b>		
No Asbestos		
<b>B00G - R0012 - Dust Extraction Space - 7.38 m2</b>		
No Asbestos		
<b>B00G - R0013 - Materials Technology L.S. - 93.02 m2</b>		
No Asbestos		
<b>B00G - R0014 - Movement - 6.26 m2</b>		
No Asbestos		
<b>B00G - R0015 - Staff - Toilet - 4.14 m2</b>		
No Asbestos		

<b>B00G - R0016 - Staff Study - 22.94 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0017 - Toilets-Boys - 16.53 m2</b>		
No Asbestos		
<b>B00G - R0018 - Cleaning Store - Distributed - 3.91 m2</b>		
No Asbestos		
<b>B00G - R0019 - Distribution Board Cupboard - 1.05 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R0020 - Machine Storage - 19.69 m2</b>		
No Asbestos		
<b>B00G - R0021 - Design L.S. - 55.53 m2</b>		
No Asbestos		
<b>B00G - R0022 - Seminar/Technology Space - 25.64 m2</b>		
No Asbestos		
<b>B00G - R0023 - General Learning Space - 55.54 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0024 - External Movement - 97.7 m2</b>		
No Asbestos		
<b>B00G - R0025 - Plant - 3.37 m2</b>		
No Asbestos		
<b>B00G - R0026 - Welding/Hot Metals Area - 3.49 m2</b>		
No Asbestos		
<b>B00G - R0027 - Welding/Hot Metals Area - 4.08 m2</b>		
No Asbestos		
<b>B00G - R0028 - Welding/Hot Metals Area - 3.68 m2</b>		
No Asbestos		
<b>B00G - R0029 - Metal Technology Bay - 61.19 m2</b>		
No Asbestos		
<b>B00G - R0030 - Welding/Hot Metals Area - 3.51 m2</b>		
No Asbestos		
<b>B00G - R0031 - General Storeroom - 11.61 m2</b>		
No Asbestos		
<b>B00G - R0032 - General Storeroom - 46.3 m2</b>		
No Asbestos		
<b>B00G - R0033 - External Movement - 70.2 m2</b>		
No Asbestos		
<b>B00G - R1001 - Music Learning Space - 58.92 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R1002 - Study Space - 24.86 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R1003 - Interview/Office - Type 1 - 12.46 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R1004 - Staff Study - 15.16 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R1005 - Music Store - 18.4 m2</b>		
No Asbestos		
<b>B00G - R1006 - Distribution Board Cupboard - .4 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R1007 - Cleaning Store - Distributed - 2.81 m2</b>		
No Asbestos		
<b>B00G - R1008 - Practice/Seminar - 28.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	

<b>B00G - R1009 - Music Learning Space - 72.88 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R1010 - Movement - 75.9 m2</b>		
No Asbestos		
<b>B00G - R1011 - Movement - 33.94 m2</b>		
No Asbestos		
<b>B00G - R1012 - Distribution Board Cupboard - .72 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R1013 - Movement - 22.96 m2</b>		
No Asbestos		
<b>B00G - R1014 - Toilets-Disabled - 4.19 m2</b>		
No Asbestos		
<b>B00G - R1015 - Student Canteen - 60.63 m2</b>		
No Asbestos		
<b>B00G - R1016 - General Storeroom - 6.99 m2</b>		
No Asbestos		
<b>B00J - Multi Purpose Facilities - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area	
<b>Interior</b>		
<b>B00J - R0001 - Sport Equipment Store - 36.79 m2</b>		
No Asbestos		
<b>B00J - R0002 - General Assistants - 17.19 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00J - R0003 - Distribution Board Cupboard - .72 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R0004 - General Storeroom - 12.73 m2</b>		
No Asbestos		
<b>B00J - R0005 - General Storeroom - 2.01 m2</b>		
No Asbestos		
<b>B00J - R0006 - Chair Store - 32.64 m2</b>		
No Asbestos		
<b>B00J - R0007 - Bulk Store - 7.27 m2</b>		
No Asbestos		
<b>B00J - R0008 - Multi-Purpose Space - 474.2 m2</b>		
No Asbestos		
<b>B00J - R0009 - Toilets-Boys - 15.49 m2</b>		
No Asbestos		
<b>B00J - R0010 - Movement - 18.45 m2</b>		
No Asbestos		
<b>B00J - R0011 - Shower/Change - 16.92 m2</b>		
No Asbestos		
<b>B00J - R0012 - Staff - Toilet - 3.25 m2</b>		
No Asbestos		
<b>B00J - R0013 - External Movement - 3.37 m2</b>		
No Asbestos		
<b>B00J - R0014 - Sport Equipment Store - 21.98 m2</b>		
No Asbestos		
<b>B00J - R0015 - External Movement - 1.99 m2</b>		
No Asbestos		

<b>B00J - R0016 - Cleaning Supplies Store - 15.49 m2</b>		
No Asbestos		
<b>B00J - R0017 - Staff Change - 6.12 m2</b>		
No Asbestos		
<b>B00J - R0018 - External Movement - 3.37 m2</b>		
No Asbestos		
<b>B00J - R0019 - Cleaning Store - Distributed - 3.2 m2</b>		
No Asbestos		
<b>B00J - R0020 - Shower/Change - 16.92 m2</b>		
No Asbestos		
<b>B00J - R0021 - Movement - 58.44 m2</b>		
No Asbestos		
<b>B00J - R0022 - Toilets-Girls - 15.48 m2</b>		
No Asbestos		
<b>B00J - R0023 - Stage - 96.15 m2</b>		
No Asbestos		
<b>B00J - R0024 - Movement - 18.45 m2</b>		
No Asbestos		
<b>B00J - R0025 - Shower/Change - 21.03 m2</b>		
No Asbestos		
<b>B00J - R0026 - Shower/Change - 18.01 m2</b>		
No Asbestos		
<b>B00J - R0027 - Shower/Change - 18 m2</b>		
No Asbestos		
<b>B00J - R0028 - Shower/Change - 20.96 m2</b>		
No Asbestos		
<b>B00J - R0029 - Control Room - 1.68 m2</b>		
No Asbestos		
<b>B00J - R0030 - External Movement - 28.31 m2</b>		
No Asbestos		
<b>B00K - Agricultural Science - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - General Storeroom - 7.91 m2</b>		
No Asbestos		
<b>B00K - R0002 - Plant Space - 10.73 m2</b>		
No Asbestos		
<b>B00K - R0003 - Class Tools Storage - 36.93 m2</b>		
No Asbestos		
<b>B00K - R0004 - Animal Space - 26.29 m2</b>		
No Asbestos		
<b>B00K - R0005 - Machine Storage - 36.93 m2</b>		
No Asbestos		
<b>B00K - R0007 - External Movement - 35.83 m2</b>		
No Asbestos		

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020