

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Inverell Public School (2209)
Region:	North Western NSW AMU
State Electorate:	Northern Tablelands
Local Government Area:	Inverell

Last Reviewed By:	Greencap 01-APR-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Staff Facilities - 1968 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 3.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0002 - Staff Room Annexe - 22.52 m2							
No Asbestos							
B00A - R0003 - Staff Room - 59.95 m2							
No Asbestos							
B00A - R0004 - Cleaning Distributed Store - 3.01 m2							
No Asbestos							
B00A - R0005 - Movement - 7.63 m2							
No Asbestos							
B00A - R0006 - Main Switch Board - 4.33 m2							
No Asbestos							
B00A - R0007 - Movement - 1.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0008 - Clerical Office - 17.67 m2							
No Asbestos							
B00A - R0009 - Duplicating Workroom - 28.79 m2							
No Asbestos							
B00A - R0010 - Security Store - 17.27 m2							
No Asbestos							
B00A - R0011 - Principal - 16.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0012 - Movement - 29.56 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0013 - Deputy Principal - 14.6 m2							
No Asbestos							
B00A - R0014 - Interview - 13.97 m2							
No Asbestos							
B00A - R0015 - Sick Bay - 8.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
B00A - R0016 - Movement - 2.94 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
B00A - R0017 - Sick Bay - Shower/Toilet - 10.19 m2							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)

B00A - R0018 - Movement - 17.34 m2							
No Asbestos							
B00A - R0019 - Entry Vestibule - 16.36 m2							
No Asbestos							
B00A - R0020 - Movement - 3.06 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0021 - Staff Toilet - 4.08 m2							
No Asbestos							
B00A - R0022 - Staff Toilet - 4.13 m2							
No Asbestos							
B00B - General Learning/Support Unit - 1884 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00B - R0001 - Home Base - 94.06 m2							
No Asbestos							
B00B - R0002 - Practical Activities - 1hb - 40.13 m2							
No Asbestos							
B00B - R0003 - Disabled Toilet - 16.49 m2							
No Asbestos							
B00B - R0004 - Movement - 3.96 m2							
No Asbestos							
B00B - R0005 - General Storeroom - 9.69 m2							
No Asbestos							
B00B - R0006 - Kin Room - 7.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00B - R0007 - Movement - 81.94 m2							
Ceiling Structures/Linings	Flat AC Sheeting	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00B - R0008 - Staff Room Annexe - 11.59 m2							
No Asbestos							
B00B - R0009 - Practical Activities - 1hb - 39.85 m2							
No Asbestos							
B00B - R0010 - Home Base - 93.59 m2							
No Asbestos							
B00B - R0011 - Movement - 13.03 m2							
Electrical - Backing Board	Resinous Board	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0012 - Movement - 73.35 m2							
No Asbestos							
B00B - R0013 - Home Base - 79.14 m2							
No Asbestos							
B00B - R0014 - Practical Activities - M - 1hb - 4.79 m2							
No Asbestos							
B00B - R0015 - Home Base - M - 54.56 m2							
No Asbestos							
B00B - R0016 - Music Store - 13.23 m2							
Floor Coverings Res/Textile	Vinyl Tiles						

B00B - R0017 - Movement - 43.92 m2							
No Asbestos							
B00C - Pupil Facilities - 1968 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	24m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00C - R0002 - Toilets - Boys - 57.41 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0003 - Toilets - Girls - 62.7 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0004 - Movement - 159.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0005 - Canteen - 27.84 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0006 - Canteen Office/Store - 6.21 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0007 - Canteen Office/Store - 6.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0008 - External Movement - 17.5 m2							
Requires Inspection							
B00C - R0009 - External Movement - 92.14 m2							
Requires Inspection							
B00D - General Learning/Library - 1968 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	North, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						

Wall Linings Internal	Flat AC Sheeting	40	North, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00D - R0001 - Library Office/Workroom - 24.37 m2							
No Asbestos							
B00D - R0002 - Reading Area - 223.29 m2							
No Asbestos							
B00D - R0003 - Distribution Board - .98 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Flat AC Sheeting						
B00D - R0004 - Movement - 89.13 m2							
Wall Linings Internal	Flat AC Sheeting	30m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00D - R0005 - Home Base - 57 m2							
Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	3	Variable positions	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)	Assumed Asbestos
B00D - R0006 - Home Base Store - 5.11 m2							
No Asbestos							
B00D - R0007 - Personal Effects Storage - 8.09 m2							
No Asbestos							
B00D - R0008 - Home Base - 56.84 m2							
Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	3	Variable positions	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)	Assumed Asbestos
B00D - R0009 - Home Base Store - 4.75 m2							
No Asbestos							
B00D - R0010 - Personal Effects Storage - 9.36 m2							
No Asbestos							
B00D - R0011 - Movement - 5.65 m2							
No Asbestos							
B00D - R0012 - Home Base Store - P - 4.79 m2							
No Asbestos							
B00D - R0013 - Home Base - P - 56.99 m2							
Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	2	Variable positions	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)	Assumed Asbestos
B00D - R0014 - Distribution Board - .8 m2							
Note: No inspection of live electrical installation							
No Asbestos							
B00D - R0015 - Home Base Store - 5.19 m2							
No Asbestos							
B00D - R0016 - Practical Activities - 1hb - 7.91 m2							
No Asbestos							
B00D - R0017 - Home Base - 60.57 m2							
No Asbestos							
B00D - R0018 - Special Programs Room - 53.35 m2							
No Asbestos							
B00D - R0019 - Special Programs Store - 2.25 m2							

No Asbestos		
B00D - R0020 - Communications Room - 14.91 m2		
No Asbestos		
B00D - R0021 - Plant - 4.02 m2		
No Asbestos		
B00E - Communal Facilities/Pupil Facilities - 1995 - Brick/Block		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00E - R0001 - Toilets - Girls - 7.62 m2		
No Asbestos		
B00E - R0002 - Garden Store - 12.53 m2		
No Asbestos		
B00E - R0003 - P.E. Store - 16.07 m2		
No Asbestos		
B00E - R0004 - Sports Store - 15.36 m2		
No Asbestos		
B00E - R0005 - Plant - .49 m2		
No Asbestos		
B00E - R0006 - Cleaning Supplies - 2.53 m2		
No Asbestos		
B00E - R0007 - Distribution Board - .59 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0008 - Disabled Toilet - 4.82 m2		
No Asbestos		
B00E - R0009 - Movement - 10.02 m2		
No Asbestos		
B00E - R0010 - Movement - 82.77 m2		
No Asbestos		
B00E - R0011 - Movement - 10 m2		
No Asbestos		
B00E - R0012 - Communal Space - 201.06 m2		
No Asbestos		
B00E - R0013 - General Storeroom - 20.16 m2		
No Asbestos		
B00E - R0014 - Hall Chair Store - 9.84 m2		
No Asbestos		
B00E - R0015 - General Assistant/Bulk Store - 22.21 m2		
No Asbestos		
B00E - R0016 - Toilets - Boys - 5.7 m2		
No Asbestos		
B00E - R0017 - Shower/Change - 2.35 m2		
No Asbestos		
B00E - R0018 - Movement - 14.48 m2		
No Asbestos		
B00E - R0019 - Raised Platform - 49.83 m2		
No Asbestos		
B00E - R0020 - Movement - 13.33 m2		
No Asbestos		
B00F - General Learning/Support Unit - 1962 - Brick/Veneer		

Exterior							
Eaves Linings	Flat AC Sheeting	50m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	40m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	30	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00F - R0001 - Home Base Store - 5.09 m2							
No Asbestos							
B00F - R0002 - Personal Effects Storage - 8.88 m2							
No Asbestos							
B00F - R0003 - Home Base - 53.57 m2							
Plant / Equipment - Thermocon Heater	Encapsulated Asbestos material within unit	2	Variable positions	Friable Asbestos (5)	Low (1)	High Priority (6-8)	Assumed Asbestos
B00F - R0004 - Practical Activities - 1hb - 2.9 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0005 - Home Base - 85.28 m2							
Plant / Equipment - Thermocon Heater	Encapsulated Asbestos material within unit	3	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00F - R0006 - Practical Activities - 1hb - 2.52 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0007 - Toilets - Boys/Girls - 3.53 m2							
No Asbestos							
B00F - R0008 - Home Base Store - 4.06 m2							
No Asbestos							
B00F - R0009 - Personal Effects Storage - 6.19 m2							
Wall Linings Internal - Electrical Box / Cabinet	Flat AC Sheeting	3m2	Internal Lining	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00F - R0010 - Toilets - Boys - 36.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0011 - Movement - 7.73 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00F - R0012 - Toilets - Girls - 37.02 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0013 - Drinking Facilities - 23.96 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00F - R0014 - Home Base - 83.61 m2							

Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	1	Variable positions	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)	Assumed Asbestos
B00F - R0015 - Practical Activities - 1hb - 2.57 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0016 - Toilets - Boys/Girls - 4.41 m2							
No Asbestos							
B00F - R0017 - Home Base Store - 4.29 m2							
No Asbestos							
B00F - R0018 - Personal Effects Storage - 7.31 m2							
No Asbestos							
B00F - R0019 - Craft Store - 18.79 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0020 - General Storeroom - 6.49 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Plant / Equipment - Thermacon Heater	Encapsulated Asbestos material within unit	1	South	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)	Assumed Asbestos
B00F - R0021 - Movement - 93.25 m2							
Wall Linings Internal	Flat AC Sheeting	20m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	94m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - General Learning/Staff Facilities - 1910 - Timber							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Movement - 35.76 m2							
No Asbestos							
B00H - R0002 - Home Base - 52.55 m2							
No Asbestos							
B00H - R0003 - Staff Room Annexe - 10.44 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0004 - Movement - 11.52 m2							
No Asbestos							
B00H - R0005 - Home Base - 52.81 m2							
No Asbestos							
B00H - R0006 - Movement - 21.83 m2							
No Asbestos							
B00H - R0007 - Practical Activities - 1hb - 9.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0008 - Home Base - 53.08 m2							
No Asbestos							
B00I - Administration - 1925 - Timber Shed							
Exterior							

External Wall Structure	Flat AC Sheeting						
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Requires Inspection						
Interior							
B00I - R0001 - General Storeroom - 11.47 m2							
No Asbestos							
B00J - General Learning - 2011 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00J - R0001 - External Movement - 92.58 m2							
No Asbestos							
B00J - R0002 - Practical Activities - 1hb - 19.07 m2							
No Asbestos							
B00J - R0003 - Home Base Store - 6.21 m2							
No Asbestos							
B00J - R0004 - Home Base - 60.28 m2							
No Asbestos							
B00J - R0005 - Special Programs Room - 11.6 m2							
No Asbestos							
B00J - R0006 - Practical Activities - 1hb - 19.19 m2							
No Asbestos							
B00J - R0007 - Home Base - 60.08 m2							
No Asbestos							
B00J - R0008 - Home Base Store - 6.22 m2							
No Asbestos							
B00J - R0009 - Cleaning Distributed Store - 4.47 m2							
No Asbestos							
B00J - R0010 - Practical Activities - 1hb - 15.12 m2							
No Asbestos							
B00J - R0011 - Home Base Store - 6.22 m2							
No Asbestos							
B00J - R0012 - Home Base - 60.08 m2							
No Asbestos							
B00J - R0013 - Special Programs Room - 11.59 m2							
No Asbestos							
B00J - R0014 - Practical Activities - 1hb - 14.99 m2							
No Asbestos							
B00J - R0015 - Home Base - 60.08 m2							
No Asbestos							
B00J - R0016 - Home Base Store - 6.22 m2							
No Asbestos							
B00J - R0017 - Staff Toilet - 4.32 m2							
No Asbestos							
B00K - Storage - 2011 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
No Asbestos							
Underfloor Voids	No Asbestos Found						

Interior		
B00K - R0001 - P.E Store - 42.73 m2		
No Asbestos		
B00L - Pupil Facilities - 2011 - Fibre Cement Clad		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
No Asbestos		
Interior		
B00L - R0001 - External Movement - 30.07 m2		
No Asbestos		
B00L - R0002 - Shelter - 86.03 m2		
No Asbestos		
B00M - Storage - 2013 - Metal Shed		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00M - R0001 - Sports Store - 16.43 m2		
No Asbestos		

Demountables

OS 602 10051 - Learning Unit - Standard With P.A.A. - Placement Date : 13-JUL-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 11645 - Learning Unit - Standard/Withdrawal - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

OS 602 13429 - Learning Unit - Standard With P.A.A. - Placement Date : 13-JUL-2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19217 - Learning Unit - Standard With P.A.A A/C - Placement Date : 24-MAY-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 19498 - Learning Unit - Standard With P.A.A. - Placement Date : 26-NOV-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found