


# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	Jindabyne Central School (2237)
<b>Region:</b>	Southern NSW AMU
<b>State Electorate:</b>	Monaro
<b>Local Government Area:</b>	Snowy Monaro

Last Reviewed By:	WSP 25-AUG-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/General Learning - 1964 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00A - R0001 - Duplicating Workroom - 11.68 m2</b>							
No Asbestos							
<b>B00A - R0002 - Staff Toilet - 3.88 m2</b>							
No Asbestos							
<b>B00A - R0003 - Staff Toilet - 4.03 m2</b>							
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00A - R0004 - Sick Bay - 6.98 m2</b>							
No Asbestos							
<b>B00A - R0005 - Staff Room Annexe - 10.6 m2</b>							
No Asbestos							
<b>B00A - R0006 - Main Switch Board - 5.27 m2</b>							
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0007 - External Movement - 5.16 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0008 - Entry Vestibule - 20.44 m2</b>							
No Asbestos							
<b>B00A - R0009 - Movement - 14.07 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0010 - Cleaning Distributed Store - 4.55 m2</b>							
No Asbestos							
<b>B00A - R0011 - Withdrawal Space - 1hb - 19.7 m2</b>							
No Asbestos							
<b>B00A - R0012 - Principal - 15.34 m2</b>							
No Asbestos							
<b>B00A - R0013 - Clerical Office/Workroom - 19.68 m2</b>							
No Asbestos							
<b>B00A - R0017 - General Storeroom - 3.87 m2</b>							
No Asbestos							
<b>B00A - R0018 - Staff Room Annexe - 8.07 m2</b>							
No Asbestos							
<b>B00A - R0019 - Personal Effects Storage - 13.12 m2</b>							
No Asbestos							
<b>B00A - R0020 - Home Base Store - 3.87 m2</b>							
No Asbestos							
<b>B00A - R0021 - Home Base - 57.39 m2</b>							
No Asbestos							
<b>B00A - R0022 - Home Base - 57.47 m2</b>							

No Asbestos							
<b>B00A - R0023 - Home Base Store - 6.71 m2</b>							
No Asbestos							
<b>B00A - R0024 - P.E Store - 7.8 m2</b>							
No Asbestos							
<b>B00A - R0026 - Movement - 53.29 m2</b>							
No Asbestos							
<b>B00A - R0027 - External Movement - 4.53 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0028 - Cleaning Distributed Store - 6.15 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0029 - Toilets - Boys - 24 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0032 - Cleaning Distributed Store - .58 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00A - R0033 - Toilets - Girls - 30.28 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0034 - Cleaning Distributed Store - 2.51 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0035 - Distribution Board - .46 m2</b>							
							<b>Note: No inspection of live electrical installation</b>
Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0036 - External Movement - 3.94 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0039 - Personal Effects Storage - 14.5 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0040 - Home Base - 56.54 m2</b>							
No Asbestos							
<b>B00A - R0041 - Home Base - 85.61 m2</b>							
No Asbestos							
<b>B00A - R0042 - Home Base Store - 4.17 m2</b>							
No Asbestos							
<b>B00A - R0043 - Personal Effects Storage - 10.19 m2</b>							
No Asbestos							
<b>B00A - R0044 - Covered Outdoor Learning Area - 166.12 m2</b>							
No Asbestos							
<b>B00A - R0045 - Movement - 90.63 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0046 - Access Shower/Toilet - 10.6 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
<b>B00A - R0047 - Clerical Office - 29.48 m2</b>							
No Asbestos							
<b>B00A - R0048 - Duplicating Workroom - 20.34 m2</b>							

No Asbestos		
<b>B00A - R0049 - Interview/Office - Type 3 - 20.75 m2</b>		
No Asbestos		
<b>B00A - R0050 - Movement - 36.95 m2</b>		
No Asbestos		
<b>B00A - R0051 - External Movement - 6.92 m2</b>		
No Asbestos		
<b>B00A - R0052 - External Movement - .83 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00B - Communal Facilities/General Learning - 1966 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Wall Cladding	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - R0001 - Communal Space - 90.82 m2</b>		
No Asbestos		
<b>B00B - R0002 - Cleaning Distributed Store - 2.99 m2</b>		
No Asbestos		
<b>B00B - R0006 - Distribution Board - .84 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0009 - Movement - 23.91 m2</b>		
No Asbestos		
<b>B00B - R0011 - Canteen Office/Store - 11.95 m2</b>		
No Asbestos		
<b>B00B - R0012 - Canteen - 34.71 m2</b>		
No Asbestos		
<b>B00B - R0013 - Canteen Covered Area - 105.39 m2</b>		
No Asbestos		
<b>B00C - Building Services - 1966 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00C - R0001 - General Assistant/Bulk Store - 23.77 m2</b>		
No Asbestos		
<b>B00F - General Learning - 2004 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0002 - Practical Activities - 1hb - 18.71 m2</b>		
No Asbestos		
<b>B00F - R0003 - Home Base Store - 6.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0004 - Home Base - 59.56 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0005 - Withdrawal Space - 2hb - 11.59 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0006 - Home Base - 59.62 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0007 - Home Base Store - 6.16 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0008 - Practical Activities - 1hb - 18.93 m2</b>		
No Asbestos		
<b>B00F - R0009 - Distribution Board - .46 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0010 - Practical Activities - 1hb - 17.83 m2</b>		
No Asbestos		
<b>B00F - R0011 - Home Base Store - 6.16 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0012 - Home Base - 60.15 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0013 - Withdrawal Space - 2hb - 11.73 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0014 - Home Base - 60.61 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0015 - Home Base Store - 6.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0016 - Practical Activities - 1hb - 18.99 m2</b>		
No Asbestos		
<b>B00F - R0017 - External Movement - 114.1 m2</b>		
No Asbestos		
<b>B00G - Library - 2004 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00G - R0001 - External Movement - 81.04 m2</b>		
No Asbestos		
<b>B00G - R0003 - Special Programs Store - 6.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0004 - Distribution Board - .87 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R0006 - Seminar/Study - 13.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0007 - Seminar/Study - 13.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0008 - Library Office/Workroom - 25.96 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0009 - K.L.A. Store - 20.58 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0010 - Communications Room - 8.9 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0011 - Special Programs Store - 9.38 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0012 - Special Programs Room - 63.6 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0013 - Movement - 19.96 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0014 - Access Shower/Toilet - 5.55 m2</b>		
No Asbestos		
<b>B00G - R0015 - Cleaning Distributed Store - 4.74 m2</b>		
No Asbestos		
<b>B00G - R0021 - Reading Area - 216.6 m2</b>		
No Asbestos		
<b>B00G - R0022 - Seminar/Study - 63.49 m2</b>		
No Asbestos		
<b>B00G - R0023 - Special Programs Room - 32.51 m2</b>		
No Asbestos		
<b>B00H - General Learning/Staff Facilities - 2006 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0001 - General Learning Space - Type 1 - 58.54 m2</b>		
No Asbestos		
<b>B00H - R0002 - General Learning Space - Type 11 - 28.81 m2</b>		
No Asbestos		
<b>B00H - R0003 - General Learning Space - Type 11 - 29.03 m2</b>		
No Asbestos		
<b>B00H - R0004 - General Learning Space - Type 1 - 58.47 m2</b>		
No Asbestos		
<b>B00H - R0005 - General Learning Space - Type 2 - 68.16 m2</b>		
No Asbestos		
<b>B00H - R0006 - General Learning Space - Type 1 - 59.28 m2</b>		
No Asbestos		
<b>B00H - R0007 - Interview/Meeting - 13.11 m2</b>		
No Asbestos		
<b>B00H - R0008 - Preparation/Printing - 29.1 m2</b>		
No Asbestos		
<b>B00H - R0009 - Movement - 142.55 m2</b>		
No Asbestos		
<b>B00H - R0010 - Staff Lounge - 66.67 m2</b>		
No Asbestos		
<b>B00H - R0011 - Staff Study - 28.96 m2</b>		

No Asbestos		
<b>B00H - R0012 - General Learning Space - Type 11 - 28.96 m2</b>		
No Asbestos		
<b>B00H - R0013 - Staff Study - 87.25 m2</b>		
No Asbestos		
<b>B00H - R0014 - Secure Storeroom - 19.8 m2</b>		
No Asbestos		
<b>B00H - R0015 - Cleaning Distributed Store - 3.52 m2</b>		
No Asbestos		
<b>B00H - R0016 - Staff Toilet - 5.67 m2</b>		
No Asbestos		
<b>B00H - R0017 - Staff Toilet - 4.86 m2</b>		
No Asbestos		
<b>B00H - R0018 - Shared Learning Space - 47.58 m2</b>		
No Asbestos		
<b>B00H - R0019 - Staff Study - 13.94 m2</b>		
No Asbestos		
<b>B00H - R0020 - Staff Study - 14.05 m2</b>		
No Asbestos		
<b>B00H - R0021 - Distribution Board Cupboard - .69 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R0022 - Staff Shower/Change - 26.43 m2</b>		
No Asbestos		
<b>B00H - R0023 - Distribution Board Cupboard - .75 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R0024 - Staff Room Annexe - 18.9 m2</b>		
No Asbestos		
<b>B00H - R0025 - External Movement - 35.65 m2</b>		
No Asbestos		
<b>B00H - R0026 - External Movement - 118.48 m2</b>		
No Asbestos		
<b>B00I - Technological &amp; Applied Studies/Science - 2006 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00I - R0001 - General Learning Space - Type 7 - 58.91 m2</b>		
No Asbestos		
<b>B00I - R0002 - General Learning Space - Type 12 - 59.06 m2</b>		
No Asbestos		
<b>B00I - R0003 - General Learning Space - Type 13 - 76.86 m2</b>		
No Asbestos		
<b>B00I - R0004 - General Learning Space - Type 3 - 59.13 m2</b>		
No Asbestos		
<b>B00I - R0005 - General Learning Space - Type 10 - 31.34 m2</b>		
No Asbestos		
<b>B00I - R0006 - Laundry - 9.67 m2</b>		
No Asbestos		
<b>B00I - R0007 - Movement - 112.03 m2</b>		
No Asbestos		
<b>B00I - R0008 - Seminar - Type 1 - 20.73 m2</b>		



No Asbestos	
<b>B001 - R0009 - Materials Workshop - Type 2 - 69.06 m2</b>	
No Asbestos	
<b>B001 - R0010 - Resource/Project Store - 20.71 m2</b>	
No Asbestos	
<b>B001 - R0011 - Materials Store - Type 2 - 19.47 m2</b>	
No Asbestos	
<b>B001 - R0012 - Kiln Space - 5.37 m2</b>	
No Asbestos	
<b>B001 - R0013 - Welding/Hot Metals Area - 5.62 m2</b>	
No Asbestos	
<b>B001 - R0014 - Workshop Area - 50.95 m2</b>	
No Asbestos	
<b>B001 - R0015 - Kitchen - Type 3 - 69.87 m2</b>	
No Asbestos	
<b>B001 - R0016 - Visual Arts Store - 17.89 m2</b>	
No Asbestos	
<b>B001 - R0017 - Materials Store - Type 1 - 12.14 m2</b>	
No Asbestos	
<b>B001 - R0018 - Practice/Seminar - 10.4 m2</b>	
No Asbestos	
<b>B001 - R0019 - Performance Store - 9.28 m2</b>	
No Asbestos	
<b>B001 - R0020 - Preparation - Materials - 16.35 m2</b>	
No Asbestos	
<b>B001 - R0021 - Science Laboratory - 66.76 m2</b>	
No Asbestos	
<b>B001 - R0022 - External Movement - 39.42 m2</b>	
No Asbestos	
<b>B001 - R0023 - Preparation - Science - 37.16 m2</b>	
No Asbestos	
<b>B001 - R0024 - Apparatus Store - 14.65 m2</b>	
No Asbestos	
<b>B001 - R0025 - Chemical Store - 11.87 m2</b>	
No Asbestos	
<b>B001 - R0026 - Toilets - Boys - 15.76 m2</b>	
No Asbestos	
<b>B001 - R0027 - Distribution Board Cupboard - .73 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B001 - R0028 - Toilets - Girls - 16.3 m2</b>	
No Asbestos	
<b>B001 - R0029 - Distribution Board Cupboard - .68 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B001 - R0030 - Dust Extraction Space - 7.03 m2</b>	
No Asbestos	
<b>B001 - R0031 - Distribution Board Cupboard - 1.31 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B001 - R0032 - L.P.G Store - 1.4 m2</b>	
No Asbestos	
<b>B001 - R0033 - Music Store - 9.26 m2</b>	
No Asbestos	
<b>B001 - R9027 - Sport Equipment Store - 25.12 m2</b>	

No Asbestos		
<b>B00I - R9028 - Bulk Store - 13.35 m2</b>		
No Asbestos		
<b>B00I - R9029 - Archive Store - 15.17 m2</b>		
No Asbestos		
<b>B00I - R9032 - Main Switch Board Cupboard - 2.79 m2</b>		
No Asbestos		
<b>B00J - Physical Education/Pupil Facilities - 2006 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00J - R0002 - Change - 29.53 m2</b>		
No Asbestos		
<b>B00J - R0003 - External Movement - 14.46 m2</b>		
No Asbestos		
<b>B00J - R0004 - Chair Store - 12.19 m2</b>		
No Asbestos		
<b>B00J - R0005 - General Assistant/Bulk Store - 14.99 m2</b>		
No Asbestos		
<b>B00J - R0006 - P.E Store - 25.43 m2</b>		
No Asbestos		
<b>B00J - R0007 - Cleaning Distributed Store - 5.65 m2</b>		
No Asbestos		
<b>B00J - R0008 - Distribution Board Cupboard - 1.34 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00J - R0009 - Change - 29.3 m2</b>		
No Asbestos		
<b>B00J - R0011 - Disabled Shower/Toilet - 5.87 m2</b>		
No Asbestos		
<b>B00J - R0012 - P.E Store - 28 m2</b>		
No Asbestos		
<b>B00J - R0013 - Gymnasium - 604.06 m2</b>		
No Asbestos		
<b>B00J - R0014 - External Movement - 143.98 m2</b>		
No Asbestos		
<b>B00L - Administration/General Learning - 2011 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00L - R0001 - External Movement - 9.23 m2</b>		
No Asbestos		
<b>B00L - R0002 - Entry Vestibule - 25.6 m2</b>		
No Asbestos		
<b>B00L - R0003 - External Movement - 9.97 m2</b>		
No Asbestos		
<b>B00L - R0004 - Movement - 48.2 m2</b>		

No Asbestos	
<b>B00L - R0005 - Interview - 13.26 m2</b>	
No Asbestos	
<b>B00L - R0006 - Principal - 16.67 m2</b>	
No Asbestos	
<b>B00L - R0007 - Clerical Office - 12.37 m2</b>	
No Asbestos	
<b>B00L - R0008 - Deputy Principal - 13.15 m2</b>	
No Asbestos	
<b>B00L - R0009 - Staff Kitchen - 8.21 m2</b>	
No Asbestos	
<b>B00L - R0010 - Staff Room - 57.41 m2</b>	
No Asbestos	
<b>B00L - R0011 - Plant - .62 m2</b>	
No Asbestos	
<b>B00L - R0012 - Deputy Principal - 16.33 m2</b>	
No Asbestos	
<b>B00L - R0013 - Student Waiting - 8.62 m2</b>	
No Asbestos	
<b>B00L - R0014 - Staff - Toilet - 5.15 m2</b>	
No Asbestos	
<b>B00L - R0015 - Staff - Toilet - 5.15 m2</b>	
No Asbestos	
<b>B00L - R0016 - Staff - Toilet - 5.15 m2</b>	
No Asbestos	
<b>B00L - R0017 - External Movement - 38.07 m2</b>	
No Asbestos	
<b>B00L - R0018 - Distribution Board - 1.39 m2</b>	<b>Note: No inspection of live electrical installation</b>
No Asbestos	
<b>B00L - R0019 - External Stairs - 15.73 m2</b>	
No Asbestos	
<b>B00L - R0020 - Cleaning Distributed Store - 4.38 m2</b>	
No Asbestos	
<b>B00L - R0021 - Access Shower/Toilet/Change - 5.5 m2</b>	
No Asbestos	
<b>B00L - R0022 - Sick Bay - 10.1 m2</b>	
No Asbestos	
<b>B00L - R0023 - Security Store - 14.86 m2</b>	
No Asbestos	
<b>B00L - R0024 - Clerical Office - 26.15 m2</b>	
No Asbestos	
<b>B00L - R0025 - Public Reception - 39.61 m2</b>	
No Asbestos	
<b>B00L - R1001 - External Movement - 28.57 m2</b>	
No Asbestos	
<b>B00L - R1002 - General Storeroom - 9.85 m2</b>	
No Asbestos	
<b>B00L - R1003 - Withdrawal Space - 1hb - 58.71 m2</b>	
No Asbestos	
<b>B00L - R1004 - Practical Activities - 12.49 m2</b>	
No Asbestos	
<b>B00L - R1005 - Home Base - 70.25 m2</b>	

No Asbestos							
<b>B00L - R1006 - Home Base - 69.56 m2</b>							
No Asbestos							
<b>B00L - R1007 - Seminar - Type 1 - 29.05 m2</b>							
No Asbestos							
<b>B00L - R1008 - Home Base - 66.94 m2</b>							
No Asbestos							
<b>B00L - R1009 - General Storeroom - 5.44 m2</b>							
No Asbestos							
<b>B00L - R1010 - Distribution Board - .6 m2</b>							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00L - R1011 - General Storeroom - 5.4 m2</b>							
No Asbestos							
<b>B00L - R1012 - External Stairs - 20.16 m2</b>							
No Asbestos							
<b>B00M - Other-Vacant - 1966 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Electrical - Backing Board	Resinous Board	1	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00M - R0001 - Movement - 2.25 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00M - R0002 - Residential Laundry - 4.24 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Wall Linings Internal	Flat AC Sheeting	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
<b>B00M - R0003 - Residential Pantry - 2.25 m2</b>							
No Asbestos							
<b>B00M - R0004 - Residential Kitchen - 10.45 m2</b>							
No Asbestos							
<b>B00M - R0005 - Residential Dining Room - 8.13 m2</b>							
No Asbestos							
<b>B00M - R0006 - Residential Living Room - 19.44 m2</b>							
No Asbestos							
<b>B00M - R0007 - Movement - 2.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>B00M - R0008 - Residential Bedroom - 14.46 m2</b>							
No Asbestos							
<b>B00M - R0009 - Movement - 4.43 m2</b>							
No Asbestos							
<b>B00M - R0010 - Residential Bedroom - 10.61 m2</b>							
No Asbestos							
<b>B00M - R0011 - General Storeroom - .31 m2</b>							
No Asbestos							
<b>B00M - R0012 - Residential Showers - 3.98 m2</b>							

No Asbestos							
<b>B00M - R0013 - Staff - Toilet - 1.55 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00M - R0014 - Residential Living Room - 10.68 m2</b>							
No Asbestos							
<b>B00M - R0015 - Residential Bedroom - 10.58 m2</b>							
No Asbestos							
<b>B00N - Administration - 1966 - Fibre Clad Shed</b>							
<b>Exterior</b>							
Wall Cladding	Flat AC Sheeting						
Gable Ends	Flat AC Sheeting	5m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00N - R0001 - General Storeroom - 7.14 m2</b>							
Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>B00N - R0002 - General Storeroom - 18.74 m2</b>							
Wall Linings Internal	Flat AC Sheeting						

## Demountables

### OS 602 10161 - Learning Unit - Standard With P.A.A. - Placement Date : 23-JAN-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 602 10188 - Learning Unit - Standard With P.A.A. - Placement Date : 09-JAN-1995

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

##### R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

### OS 600 10464 - Learning Unit - Small - Placement Date : 25-NOV-2014

#### Exterior

Eaves Linings	Flat AC Sheeting	8.64m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- General Learning Space

End Wall Panel	Flat AC Sheeting	50m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

### OS 600 10543 - Learning Unit - Small - Placement Date : 21-JAN-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 520 10596 - Staff Study - Placement Date : 21-JAN-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 700 10836 - Art Learning Space/Workshop/Store - Placement Date : 10-AUG-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 11283 - Learning Unit - Standard With P.A.A. - Placement Date : 29-APR-2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 600 11565 - Learning Unit - Small - Placement Date : 25-NOV-2014

#### Exterior

Eaves Linings	Flat AC Sheeting	8.64m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
<b>Interior</b>			
<b>R1- General Learning Space</b>			
End Wall Panel	Flat AC Sheeting	50m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
<b>OS 602 11776 - Learning Unit - Standard With P.A.A. - Placement Date : 28-OCT-1996</b>			
<b>Exterior</b>			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
<b>Interior</b>			
<b>R1- Learning space/withdrawal/entry</b>			
Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
<b>R2- Home Base Store</b>			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos
<b>OS 700 12247 - Art Learning Space/Workshop/Store - Placement Date : 21-JAN-2010</b>			
<b>Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.</b>			
No Asbestos Found			
<b>OS 602 12420 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995</b>			
No Asbestos Found			
<b>OS 602 12670 - Learning Unit - Standard With P.A.A. - Placement Date : 13-JAN-2016</b>			
<b>Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.</b>			
No Asbestos Found			
<b>NS 321 13200 - Toilets - Boys - Placement Date : 21-JAN-2010</b>			
No Asbestos Found			
<b>NS 320 13201 - Toilets - Girls - Placement Date : 21-JAN-2010</b>			
No Asbestos Found			
<b>NS 220 13416 - Science Learning/Preparation Space - Placement Date : 19-NOV-2008</b>			
No Asbestos Found			
<b>OS 601 14233 - Learning Unit - Standard/Withdrawal - Placement Date : 12-SEP-2001</b>			
<b>Exterior</b>			
Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos
<b>Interior</b>			
<b>R1- Entry</b>			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
<b>R2- General Learning Space</b>			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
<b>R3- Store</b>			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
<b>OS 600 14738 - Learning Unit - Small - Placement Date : 19-NOV-2008</b>			
<b>Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.</b>			

No Asbestos Found

**OS 600 15647 - Learning Unit - Small - Placement Date : 05-JAN-2018**

No Asbestos Found

**OS 602 16271 - Learning Unit - Standard With P.A.A. - Placement Date : 07-SEP-1995**

**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

**Interior**

**R1- Learning space/withdrawal/entry**

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

**R2- Home Base Store**

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

**OS 600 17663 - Learning Unit - Small - Placement Date : 03-FEB-2017**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 600 17711 - Learning Unit - Small - Placement Date : 21-JAN-2010**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 600 19314 - Learning Unit - Small - Placement Date : 29-MAY-2018**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 601 19436 - Learning Unit - Standard/Withdrawal - Placement Date : 13-SEP-2018**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 600 19618 - Learning Unit - Small - Placement Date : 24-JAN-2019**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found