

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Jewells Public School (4469)
Region:	Hunter/Central Coast AMU
State Electorate:	Swansea
Local Government Area:	Lake Macquarie

Last Reviewed By:	AECOM 28-JUN-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Communal Facilities/Pupil Facilities - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	100m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00A - R0001 - Toilets - Girls - 24.26 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0002 - Plant - 4.79 m2							
No Asbestos							
B00A - R0003 - Toilets - Boys - 24.27 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0004 - Movement - 22.86 m2							
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0005 - Drinking Facilities - 11.36 m2							
No Asbestos							
B00A - R0006 - P.E Store - 13.29 m2							
No Asbestos							
B00A - R0007 - Communal Space - 249.76 m2							
No Asbestos							
B00A - R0008 - Hall Chair Store - 4.44 m2							
No Asbestos							
B00A - R0009 - Hall Chair Store - 4.43 m2							
No Asbestos							
B00A - R0010 - Raised Platform - 20.05 m2							
No Asbestos							
B00A - R0012 - Movement - 39.49 m2							
No Asbestos							
B00A - R0013 - Cleaning Supplies - 12.54 m2							
No Asbestos							
B00A - R0014 - Canteen - 46.14 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0015 - Canteen Office/Store - 5.41 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0016 - Staff Toilet - 3.27 m2							
No Asbestos							
B00A - R0017 - Kiln Room - 10.84 m2							
No Asbestos							
B00A - R0018 - Movement - 47.46 m2							
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0019 - Canteen Office/Store - 3.21 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0020 - Cleaning Supplies - 8.49 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0021 - Movement - 21.85 m2							

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - Administration/Staff Facilities - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	100m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00B - R0001 - Movement - 51.93 m2							
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0002 - Security Store - 11.81 m2							
No Asbestos							
B00B - R0003 - Staff Toilet - 6.07 m2							
No Asbestos							
B00B - R0004 - Movement - 55.23 m2							
No Asbestos							
B00B - R0005 - Disabled Toilet - 4.13 m2							
No Asbestos							
B00B - R0006 - Staff Toilet - 6.03 m2							
No Asbestos							
B00B - R0007 - Cleaning Distributed Store - 1.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0008 - Sick Bay - 9.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0009 - Clerical Office - 13.11 m2							
No Asbestos							
B00B - R0010 - Clerical Office - 12.12 m2							
No Asbestos							
B00B - R0011 - Clerical Office - 15.18 m2							
No Asbestos							
B00B - R0012 - Entry Vestibule - 3.53 m2							
No Asbestos							
B00B - R0013 - Principal - 23.33 m2							
No Asbestos							
B00B - R0014 - Staff Room Annexe - 13.58 m2							
No Asbestos							
B00B - R0015 - Community Clinic - 18.84 m2							
No Asbestos							
B00B - R0016 - Main Switch Board - 8.7 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0017 - Staff Room Annexe - 10.72 m2							
No Asbestos							
B00B - R0018 - Security Store - 2.86 m2							
No Asbestos							
B00B - R0019 - Movement - 81.22 m2							
Ceiling Structures/Linings	Flat AC Sheeting	79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0020 - Stairs - 5.79 m2							
No Asbestos							

B00B - R1002 - Movement - 4.12 m2							
No Asbestos							
B00B - R1003 - Stairs - 16.9 m2							
No Asbestos							
B00B - R1004 - Staff Room - 68.66 m2							
Requires Inspection							
B00B - R1005 - Withdrawal - M - 19.25 m2							
Requires Inspection							
B00B - R1006 - Staff Kitchen - 16.12 m2							
Requires Inspection							
B00C - General Learning - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00C - R0001 - Movement - 37.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0002 - Home Base - 58.7 m2							
No Asbestos							
B00C - R0003 - Practical Activities - 1hb - 19.07 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - General Learning/Pupil Facilities - 1980 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids - Flat Roof	Non Accessible Area						
Interior							
B00D - R0001 - Movement - 55.91 m2							
Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	15m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0002 - Home Base - 59.27 m2							
No Asbestos							
B00D - R0003 - Practical Activities - 1hb - 18.32 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - R0004 - Toilets - Boys - 15.04 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0005 - Cleaning Distributed Store - 1.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - R0006 - Plant - 2.79 m2							
No Asbestos							
B00D - R0007 - Toilets - Girls - 14.88 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - General Learning - 1980 - Brick/Veneer							

Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00E - R0001 - Movement - 35.48 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	12m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0002 - Practical Activities - 1hb - 18.3 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0003 - Home Base - 58.12 m2							
No Asbestos							
B00E - R0004 - Home Base - 58.28 m2							
No Asbestos							
B00E - R0005 - Practical Activities - 1hb - 18.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - General Learning/Other-After School Care - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00F - R0001 - General Storeroom - 12.16 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0002 - Distribution Board - 1.08 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0003 - General Storeroom - 11.81 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0004 - General Storeroom - 12.64 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0005 - Cleaning Distributed Store - 1.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00F - R0006 - Movement - 45.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0007 - Home Base Store - 10.52 m2							
No Asbestos							
B00F - R0008 - Home Base - 78.64 m2							
No Asbestos							
B00F - R0009 - Toilets - Boys/Girls - 3.12 m2							
No Asbestos							
B00F - R0010 - Practical Activities - 1hb - 18.89 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - General Learning/Pupil Facilities - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						

Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00G - R0001 - Practical Activities - 1hb - 18.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0002 - Home Base - 58.2 m2							
No Asbestos							
B00G - R0003 - Home Base - 58.12 m2							
No Asbestos							
B00G - R0004 - Practical Activities - 1hb - 18.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00G - R0005 - Toilets - Boys - 8.52 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0006 - Toilets - Girls - 7.93 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0007 - Movement - 16.43 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - General Learning/Pupil Facilities - 1980 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00H - R0001 - Movement - 35.78 m2							
Ceiling Structures/Linings	Flat AC Sheeting	36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Practical Activities - 1hb - 18.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0003 - Toilets - Boys/Girls - 3.09 m2							
No Asbestos							
B00H - R0004 - Home Base - 77.49 m2							
No Asbestos							
B00H - R0005 - Home Base - 77.71 m2							
No Asbestos							
B00H - R0006 - Practical Activities - 1hb - 18.34 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00H - R0007 - Toilets - Boys/Girls - 3.3 m2							
No Asbestos							
B00H - R0008 - Movement - 25.15 m2							
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - Building Services - 1980 - Metal Shed							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							

B00I - R0001 - General Assistant/Bulk Store - 12.19 m2		
No Asbestos		
B00J - Library - 2001 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00J - R0001 - Communications Room - 16.95 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0002 - Library Office/Workroom - 26.81 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0003 - Reading Area - 221.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0004 - Special Programs Room - 42.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0005 - Staff Toilet - 4.74 m2		
No Asbestos		
B00J - R0006 - Cleaning Distributed Store - 3.58 m2		
No Asbestos		
B00J - R0007 - Special Programs Store - 7.81 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0009 - External Movement - 117.38 m2		
No Asbestos		
B00K - Special Purpose - 1996 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Interior		
B00K - R0001 - Movement - 2.86 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00K - R0002 - Special Programs Store - 3.19 m2		
No Asbestos		
B00K - R0003 - Staff Shower/Change - 3.19 m2		
Wall Linings Internal	Flat AC Sheeting	
B00K - R0004 - Special Programs Room - 98.92 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0005 - Movement - 2.54 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00L - Pre-School Facilities - 1999 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - Movement - 46.24 m2		
No Asbestos		
B00L - R0002 - Movement - 27.55 m2		
No Asbestos		

B00L - R0003 - Out Of School Hours Care Centre - 67.88 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0004 - Staff Room - 6.18 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0005 - Staff Room Annexe - 3.44 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - General Learning - 2006 - Fibre Cement Clad		
Exterior		
Underfloor Voids	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00M - R0001 - Movement - 38.51 m2		
No Asbestos		
B00M - R0002 - Practical Activities - 1hb - 19.41 m2		
No Asbestos		
B00M - R0003 - Home Base Store - 6.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0004 - Home Base - 59.24 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0005 - Withdrawal Space - 2hb - 11.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0006 - Home Base - 59.24 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0007 - Home Base Store - 6.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0008 - Practical Activities - 1hb - 19.42 m2		
No Asbestos		
B00N - General Learning - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00N - R0001 - External Movement - 129.08 m2		
No Asbestos		
B00N - R0002 - Practical Activities - 1hb - 15.05 m2		
No Asbestos		
B00N - R0003 - Home Base - 60.45 m2		
No Asbestos		
B00N - R0004 - Home Base Store - 6.02 m2		
No Asbestos		
B00N - R0005 - Withdrawal Space - 2hb - 11.58 m2		
No Asbestos		
B00N - R0006 - Practical Activities - 1hb - 15.02 m2		
No Asbestos		
B00N - R0007 - Home Base - 60.22 m2		
No Asbestos		
B00N - R0008 - Home Base Store - 6.07 m2		
No Asbestos		
B00N - R0009 - Main Switch Board - .56 m2		
No Asbestos		
B00N - R0010 - Withdrawal Space - 1hb - 9.17 m2		

No Asbestos	
B00N - R0011 - Practical Activities - 1hb - 15.45 m2	
No Asbestos	
B00N - R0012 - Home Base - 58.61 m2	
No Asbestos	
B00N - R0013 - Home Base Store - 5.96 m2	
No Asbestos	
B00N - R0014 - Practical Activities - 1hb - 15.05 m2	
No Asbestos	
B00N - R0015 - Home Base - 60.45 m2	
No Asbestos	
B00N - R0016 - Home Base Store - 6.02 m2	
No Asbestos	
B00N - R0017 - Withdrawal Space - 2hb - 11.58 m2	
No Asbestos	
B00N - R0018 - Practical Activities - 1hb - 15.02 m2	
No Asbestos	
B00N - R0019 - Home Base - 60.52 m2	
No Asbestos	
B00N - R0020 - Home Base Store - 5.96 m2	
No Asbestos	
B00N - R0021 - Main Switch Board - .56 m2	
No Asbestos	
B00N - R0022 - Withdrawal Space - 1hb - 9.17 m2	
No Asbestos	
B00N - R0023 - Practical Activities - 1hb - 15.47 m2	
No Asbestos	
B00N - R0024 - Home Base - 58.61 m2	
No Asbestos	
B00N - R0025 - Home Base Store - 5.96 m2	
No Asbestos	
B00N - R0027 - Personal Effects Storage - 4.58 m2	
No Asbestos	
B00N - R0028 - Personal Effects Storage - 3.63 m2	
No Asbestos	
B00N - R0029 - Personal Effects Storage - 4.91 m2	
No Asbestos	
B00N - R0030 - Personal Effects Storage - 4.58 m2	
No Asbestos	
B00N - R0031 - Personal Effects Storage - 3.63 m2	
No Asbestos	
B00N - R0032 - Personal Effects Storage - 4.91 m2	
No Asbestos	

Demountables

OS 841 10186 - Boys Toilet - Placement Date : 19-JUL-2005

Exterior

Eaves Linings	Flat AC Sheeting	2.88m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Toilets-Boys

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Assumed Asbestos
End Wall Panel	Flat AC Sheeting	36m2	Assumed Asbestos
Toilet Partitions	Compressed AC Sheet	6m2	Assumed Asbestos

OS 840 16492 - Girls Toilet - Placement Date : 08-JUN-2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found