


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	John Purchase Public School (4572)
Region:	Northern Sydney AMU
State Electorate:	Epping
Local Government Area:	Hornsby

Last Reviewed By:	WSP 12-SEP-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1986 - Brick/Block							
Exterior							
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0002 - Entry Vestibule - 9.06 m2							
No Asbestos							
B00A - R0003 - Clerical Office - 14.39 m2							
No Asbestos							
B00A - R0004 - Sick Bay - 8.93 m2							
No Asbestos							
B00A - R0005 - Clerical/Printing - 21.55 m2							
No Asbestos							
B00A - R0006 - Speech Therapy - 13.07 m2							
No Asbestos							
B00A - R0007 - Staff Toilet - 6 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0008 - Cleaning Distributed Store - 1.84 m2							
No Asbestos							
B00A - R0009 - Staff Toilet - 6.02 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
B00A - R0011 - External Movement - 21.92 m2							
No Asbestos							
B00A - R0012 - Staff Room Annexe - 19.17 m2							
No Asbestos							
B00A - R0013 - Distribution Board - .67 m2							
No Asbestos							Note: No inspection of live electrical installation
B00A - R0014 - Security Store - 10.16 m2							
No Asbestos							
B00A - R0015 - Deputy Principal - 12.56 m2							
No Asbestos							
B00A - R0016 - Principal - 17.35 m2							
No Asbestos							
B00A - R0017 - Security Store - 13.12 m2							
No Asbestos							
B00A - R0018 - Clerical Office - 14.36 m2							
No Asbestos							
B00A - R0019 - Movement - 10.46 m2							
No Asbestos							
B00A - R0020 - Movement - 39.76 m2							
No Asbestos							
B00A - R0021 - External Movement - 83.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00A - R0022 - External Movement - 5.38 m2							
No Asbestos							
B00A - R0023 - Staff Room - 39.07 m2							
No Asbestos							
B00A - R0024 - Staff Kitchen - 6.97 m2							
No Asbestos							
B00B - General Learning - 1986 - Brick/Block							

Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Interior		
B00B - R0001 - Withdrawal Space - 2hb - 11.96 m2		
No Asbestos		
B00B - R0002 - Home Base - 59.53 m2		
No Asbestos		
B00B - R0003 - Home Base Store - 3.96 m2		
No Asbestos		
B00B - R0004 - Practical Activities - 2hb - 35.78 m2		
No Asbestos		
B00B - R0005 - Distribution Board - .96 m2		
No Asbestos		Note: No inspection of live electrical installation
B00B - R0006 - Security Store - 4.25 m2		
No Asbestos		
B00B - R0007 - Home Base Store - 3.96 m2		
No Asbestos		
B00B - R0008 - Home Base - 59.51 m2		
No Asbestos		
B00B - R0009 - External Movement - 13.98 m2		
No Asbestos		
B00B - R0010 - External Movement - 13.86 m2		
No Asbestos		
B00B - R0011 - External Movement - 39.77 m2		
No Asbestos		
B00C - General Learning - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00C - R0001 - External Movement - 20.36 m2		
No Asbestos		
B00C - R0002 - Withdrawal Space - 2hb - 11.92 m2		
No Asbestos		
B00C - R0003 - Home Base - 59.6 m2		
No Asbestos		
B00C - R0004 - Home Base Store - 3.96 m2		
No Asbestos		
B00C - R0005 - Practical Activities - 2hb - 35.57 m2		
No Asbestos		
B00C - R0006 - Home Base - 59.6 m2		
No Asbestos		
B00C - R0007 - Home Base Store - 4 m2		
No Asbestos		
B00C - R0008 - Security Store - 4.92 m2		
No Asbestos		
B00C - R0009 - Distribution Board - 1.01 m2		
No Asbestos		Note: No inspection of live electrical installation
B00C - R0010 - Security Store - 4.9 m2		

No Asbestos		
B00C - R0011 - Home Base Store - 3.98 m2		
No Asbestos		
B00C - R0012 - Home Base - 59.67 m2		
No Asbestos		
B00C - R0013 - Practical Activities - 2hb - 35.66 m2		
No Asbestos		
B00C - R0014 - Home Base Store - 3.98 m2		
No Asbestos		
B00C - R0015 - Home Base - 59.53 m2		
No Asbestos		
B00C - R0016 - External Movement - 14.44 m2		
No Asbestos		
B00C - R0017 - Withdrawal Space - 2hb - 12.03 m2		
No Asbestos		
B00C - R0018 - External Movement - 27.78 m2		
No Asbestos		
B00C - R0019 - External Movement - 63.77 m2		
No Asbestos		
B00D - Library - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00D - R0002 - Distribution Board - 1.22 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0003 - Security Store - 2.46 m2		
No Asbestos		
B00D - R0004 - Plant - 4.95 m2		
No Asbestos		
B00D - R0005 - Resource/Toy Space - 34.85 m2		
No Asbestos		
B00D - R0006 - Movement - 20.49 m2		
No Asbestos		
B00D - R0007 - Reading Area - 148.75 m2		
No Asbestos		
B00D - R0008 - Library Office/Workroom - 24.39 m2		
No Asbestos		
B00D - R0009 - Security Store - 12.29 m2		
No Asbestos		
B00D - R0010 - External Movement - 3.85 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00D - R0011 - External Movement - 165.16 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00E - General Learning - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00E - R0001 - External Movement - 14.43 m2		
No Asbestos		

B00E - R0002 - Withdrawal Space - 2hb - 11.92 m2		
No Asbestos		
B00E - R0003 - Home Base - 59.6 m2		
No Asbestos		
B00E - R0004 - Home Base Store - 3.96 m2		
No Asbestos		
B00E - R0005 - Security Store - 4.22 m2		
No Asbestos		
B00E - R0006 - Distribution Board - .95 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0007 - Practical Activities - 2hb - 35.66 m2		
No Asbestos		
B00E - R0008 - Home Base Store - 3.92 m2		
No Asbestos		
B00E - R0009 - Home Base - 59.47 m2		
No Asbestos		
B00E - R0010 - External Movement - 20.22 m2		
No Asbestos		
B00E - R0011 - External Movement - 32.28 m2		
No Asbestos		
B00F - General Learning - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00F - R0001 - External Movement - 13.52 m2		
No Asbestos		
B00F - R0002 - Withdrawal Space - 2hb - 11.99 m2		
No Asbestos		
B00F - R0003 - Home Base - 59.51 m2		
No Asbestos		
B00F - R0004 - Home Base Store - 3.94 m2		
No Asbestos		
B00F - R0005 - Distribution Board - .59 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0006 - Security Store - 4.69 m2		
No Asbestos		
B00F - R0007 - Practical Activities - 2hb - 35.54 m2		
No Asbestos		
B00F - R0008 - Home Base Store - 3.96 m2		
No Asbestos		
B00F - R0009 - Home Base - 59.37 m2		
No Asbestos		
B00F - R0010 - External Movement - 13.97 m2		
No Asbestos		
B00F - R0011 - External Movement - 32.3 m2		
No Asbestos		
B00G - Communal Facilities - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior	
B00G- R0001 - Uniform Shop - 15.44 m2	
No Asbestos	
B00G- R0002 - Cleaning Supplies - 6.46 m2	
No Asbestos	
B00G- R0003 - Movement - 5.86 m2	
No Asbestos	
B00G- R0004 - External Movement - 16.4 m2	
No Asbestos	
B00G- R0005 - Communal/Performance Store - 12.87 m2	
No Asbestos	
B00G- R0006 - Staff Kitchen - 9.04 m2	
No Asbestos	
B00G- R0008 - General Storeroom - 2.06 m2	
No Asbestos	
B00G- R0010 - Toilets - Girls - 13.01 m2	
No Asbestos	
B00G- R0011 - Movement - 7.33 m2	
No Asbestos	
B00G- R0014 - Main Switch Board - 8.94 m2	
No Asbestos	
B00G- R0017 - Movement - 7.41 m2	
No Asbestos	
B00G- R0018 - Toilets - Boys - 13.24 m2	
No Asbestos	
B00G- R0019 - Communal/Performance Store - 6.94 m2	
No Asbestos	
B00G- R0021 - Communications Cupboard - .56 m2	
No Asbestos	
B00G- R0022 - External Movement - 28.05 m2	
No Asbestos	
B00G- R0026 - Access Shower/Toilet/Change - 14.3 m2	
No Asbestos	
B00G- R0027 - External Movement - 9.96 m2	
No Asbestos	
B00G- R0028 - Lift - 2.46 m2	
No Asbestos	
B00G- R0029 - Communal Space - 135.4 m2	
No Asbestos	
B00G- R0030 - Raised Platform - 34.34 m2	
No Asbestos	
B00G- R0031 - Stairs - 7.04 m2	
No Asbestos	
B00G- R0034 - General Storeroom - 3.81 m2	
No Asbestos	
B00G- R0035 - General Storeroom - 3.59 m2	
No Asbestos	
B00G- R0037 - General Storeroom - 3.81 m2	
No Asbestos	
B00G- R0038 - General Storeroom - 3.81 m2	
No Asbestos	
B00G- R0040 - Garden Store - 16.66 m2	

No Asbestos		
B00G - R0041 - P.E Store - 9.12 m2		
No Asbestos		
B00G - R0042 - P.E Store - 6.71 m2		
No Asbestos		
B00G - R0043 - Communal Space - 56.69 m2		
No Asbestos		
B00G - R0044 - Communal Space - 56.79 m2		
No Asbestos		
B00G - R0045 - Hall Chair Store - 5.2 m2		
No Asbestos		
B00G - R0046 - Hall Chair Store - 8.05 m2		
No Asbestos		
B00G - R0047 - External Movement - 22.28 m2		
No Asbestos		
B00H - Pupil Facilities - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00H - R0001 - Canteen - 28.63 m2		
No Asbestos		
B00H - R0002 - Canteen Office/Store - 5.8 m2		
No Asbestos		
B00H - R0003 - Canteen Office/Store - 4.64 m2		
No Asbestos		
B00H - R0004 - Distribution Board - .91 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0005 - Canteen Covered Area - 67.58 m2		
No Asbestos		
B00J - Pupil Facilities - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00J - R0001 - Toilets - Girls - 16.11 m2		
Partition Walls (Cubicles)	Compressed AC Sheet	
B00J - R0003 - Toilets - Boys - 16.11 m2		
Partition Walls (Cubicles)	Compressed AC Sheet	
B00J - R0004 - Cleaning Distributed Store - 1.15 m2		
No Asbestos		
B00J - R0007 - External Movement - 34.36 m2		
No Asbestos		
B00J - R0008 - External Movement - 4.4 m2		
No Asbestos		
B00J - R0009 - External Movement - 4.45 m2		
No Asbestos		
B00K - Pupil Facilities - 1986 - Brick/Block		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior		
B00K - R0001 - Toilets - Boys - 16.16 m2		
Partition Walls (Cubicles)	Compressed AC Sheet	
B00K - R0002 - Cleaning Distributed Store - 1.13 m2		
No Asbestos		
B00K - R0003 - Toilets - Girls - 16.14 m2		
Partition Walls (Cubicles)	Compressed AC Sheet	
B00K - R0006 - External Movement - 25.57 m2		
Ceiling Structures/Linings	Flat AC Sheeting	
B00L - General Learning - 1985 - Brick/Veneer		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00L - R0001 - External Movement - 2.58 m2		
No Asbestos		
B00L - R0002 - Withdrawal Space - 1hb - 5.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0003 - Home Base Store - 5.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0004 - Distribution Board - .53 m2		
No Asbestos		Note: No inspection of live electrical installation
B00L - R0006 - Practical Activities - 1hb - 22.62 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0007 - Practical Activities - 1hb - 22.62 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0009 - Home Base Store - 6.5 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0010 - Withdrawal Space - 1hb - 5.38 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0011 - External Movement - 2.57 m2		
No Asbestos		
B00L - R0012 - Home Base - 56.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0013 - Home Base - 56.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00L - R0014 - External Movement - 58.67 m2		
No Asbestos		
B00M - General Learning - 1985 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Interior		
B00M - R0001 - External Movement - 6.38 m2		
No Asbestos		
B00M - R0002 - General Assistant/Bulk Store - 9.73 m2		
No Asbestos		
B00M - R0003 - Distribution Board - .52 m2		
No Asbestos		Note: No inspection of live electrical installation
B00M - R0004 - Kiln Room - 6.46 m2		

No Asbestos		
B00M - R0006 - Home Base Store - 5.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0007 - Withdrawal Space - 1hb - 4.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0008 - Home Base - 55.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0009 - Home Base - 55.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0010 - Practical Activities - 1hb - 22.7 m2		
No Asbestos		
B00M - R0011 - Practical Activities - 1hb - 22.7 m2		
No Asbestos		
B00M - R0013 - Home Base Store - 6.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0014 - Withdrawal Space - 1hb - 5.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00M - R0015 - External Movement - 2.59 m2		
No Asbestos		
B00M - R0016 - External Movement - 69.83 m2		
No Asbestos		
B00N - Special Purpose - 1985 - Brick/Veneer		
Exterior		
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00N - R0001 - Movement - 5.59 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0002 - General Storeroom - 11.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00N - R0003 - Computer Room - 64.93 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00O - General Learning - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00O - R0001 - Home Base - 57.85 m2		
No Asbestos		
B00O - R0002 - Home Base - 61.06 m2		
No Asbestos		
B00O - R0003 - Home Base - 60.88 m2		
No Asbestos		
B00O - R0004 - Practical Activities - 1hb - 20.62 m2		
No Asbestos		
B00O - R0005 - Withdrawal Space - 1hb - 8.97 m2		
No Asbestos		
B00O - R0006 - Home Base Store - 5.85 m2		
No Asbestos		
B00O - R0007 - Home Base Store - 6.12 m2		
No Asbestos		

B00O - R0008 - Practical Activities - 1hb - 18.79 m2		
No Asbestos		
B00O - R0009 - Withdrawal Space - 2hb - 11.62 m2		
No Asbestos		
B00O - R0010 - Practical Activities - 1hb - 18.73 m2		
No Asbestos		
B00O - R0011 - Home Base Store - 6.09 m2		
No Asbestos		
B00O - R0012 - External Movement - 70.29 m2		
No Asbestos		
B00P - Pupil Facilities - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00P - R0001 - Toilets - Girls - 22.74 m2		
No Asbestos		
B00P - R0002 - Toilets - Boys - 15.66 m2		
No Asbestos		
B00P - R0003 - Access Shower/Toilet/Change - 5.78 m2		
No Asbestos		
B00P - R0004 - External Movement - 21.65 m2		
No Asbestos		
B00Q - Other-After School Care - 1996 - Steel		
Exterior		
Underfloor Voids	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00Q - R0001 - Other-After School Care - 18.8 m2		
No Asbestos		
B00Q - R0002 - Other-After School Care - 14.3 m2		
No Asbestos		
B00Q - R0003 - Other-After School Care - 8.7 m2		
No Asbestos		
B00Q - R0004 - Other-After School Care - 70.02 m2		
No Asbestos		
B00Q - R0005 - Other-After School Care - 5.96 m2		
No Asbestos		
B00Q - R0006 - Other-After School Care - 10.7 m2		
No Asbestos		
B00Q - R0007 - Other-After School Care - 5.96 m2		
No Asbestos		
B00Q - R0008 - Other-After School Care - 48.61 m2		
No Asbestos		
B00Q - R0009 - Other-After School Care - 36.51 m2		
No Asbestos		
B00Q - R0010 - Other-After School Care - 33.86 m2		
No Asbestos		
B00R - Other-Community Use - 2012 - Brick/Block		
Exterior		
Underfloor Voids	No Asbestos Found	

Ceiling Voids	No Asbestos Found	
Interior		
B00R - R0001 - Other-Community Use - 11 m2		
No Asbestos		
B00R - R0002 - Other-Community Use - 3.44 m2		
No Asbestos		
B00R - R0003 - Other-Community Use - 1.9 m2		
No Asbestos		
B00R - R0004 - Other-Community Use - 13.93 m2		
No Asbestos		
B00R - R0005 - Other-Community Use - 19.11 m2		
No Asbestos		
B00R - R0006 - Other-Community Use - .43 m2		
No Asbestos		
B00R - R0007 - Other-Community Use - 19.08 m2		
No Asbestos		
B00R - R0008 - Other-Community Use - .44 m2		
No Asbestos		
B00R - R0009 - Other-Community Use - 5.32 m2		
No Asbestos		
B00R - R0010 - Other-Community Use - 5.04 m2		
No Asbestos		
B00R - R0011 - Other-Community Use - 5.29 m2		
No Asbestos		
B00R - R0012 - Other-Community Use - 54.9 m2		
No Asbestos		

Demountables

OS 602 10520 - Learning Unit - Standard With P.A.A. - Placement Date : 22-SEP-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11139 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 750 11313 - Learning Unit - ESL - Placement Date : 01-SEP-2003

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 13298 - Learning Unit - Standard With P.A.A. - Placement Date : 04-SEP-2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 13784 - Learning Unit - Standard With P.A.A. - Placement Date : 24-MAR-2009

No Asbestos Found

OS 602 14061 - Learning Unit - Standard With P.A.A. - Placement Date : 04-MAY-2007

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 602 14363 - Learning Unit - Standard With P.A.A. - Placement Date : 13-APR-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 15085 - Learning Unit - Standard With P.A.A. - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 602 16265 - Learning Unit - Standard With P.A.A. - Placement Date : 15-SEP-2000**Exterior**

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior**R1- Learning space/withdrawal/entry**

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos