


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	John Edmondson High School (8290)
Region:	South Western Sydney AMU
State Electorate:	Liverpool
Local Government Area:	Liverpool

Last Reviewed By:	Greencap 22-MAY-2008
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B001 - Other-Commercial - 2004 - Brick/Veneer							
Exterior							
Underfloor Voids	No Asbestos Found						
No Asbestos							
Ceiling Voids	No Asbestos Found						
Interior							
B001 - R0001 - No Access - 641.89 m2							
No Asbestos							
B00A - General Learning - 2004 - Brick/Veneer							
Exterior							
No Asbestos							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - G.L.S. Store - 19.63 m2							
No Asbestos							
B00A - R0002 - Cleaning Store - Distributed - 3.06 m2							
No Asbestos							
B00A - R0003 - Movement - 28.9 m2							
No Asbestos							
B00A - R0004 - Stairs - 12.1 m2							
No Asbestos							
B00A - R0005 - General Learning Space - Type 2 - 65.71 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Shared Learning Space - 43.56 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0007 - General Learning Space - Type 1 - 60.35 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0008 - Movement - 90.12 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Movement - 3.3 m2							
No Asbestos							
B00A - R0010 - Distribution Board Cupboard - .58 m2							
No Asbestos							Note: No inspection of live electrical installation
B00A - R0011 - General Learning Space - Type 1 - 59.92 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - General Learning Space - Type 1 - 59.16 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Seminar - Type 1 - 24.58 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - General Learning Space - Type 1 - 59.42 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						

B00A - R0015 - General Learning Space - Type 1 - 59.5 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1001 - G.L.S. Store - 19.61 m2		
No Asbestos		
B00A - R1002 - Cleaning Store - Distributed - 3.18 m2		
No Asbestos		
B00A - R1003 - Communications Cupboard - 2.01 m2		
No Asbestos		
B00A - R1004 - Movement - 95.92 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1005 - Movement - 6 m2		
No Asbestos		
B00A - R1006 - Stairs - 6.71 m2		
No Asbestos		
B00A - R1007 - General Learning Space - Type 2 - 65.37 m2		
Floor Coverings Res/Textile	No Asbestos Found	
No Asbestos		
B00A - R1008 - Shared Learning Space - 43.49 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1009 - General Learning Space - Type 1 - 60.35 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1010 - Movement - 3.28 m2		
No Asbestos		
B00A - R1011 - Distribution Board Cupboard - .6 m2		Note: No inspection of live electrical installation
No Asbestos		
B00A - R1012 - General Learning Space - Type 1 - 59.83 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1013 - General Learning Space - Type 1 - 59.16 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1014 - Seminar - Type 1 - 24.55 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1015 - General Learning Space - Type 1 - 59.26 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R1016 - General Learning Space - Type 1 - 59.27 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - General Learning - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		

B00B - R0001 - Movement - 236.79 m2		
No Asbestos		
B00B - R0002 - Stairs - 12.59 m2		
No Asbestos		
B00B - R0003 - General Learning Space - Type 1 - 60.35 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0004 - Shared Learning Space - 42.3 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0005 - General Learning Space - Type 2 - 65.54 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0006 - G.L.S. Store - 20.78 m2		
No Asbestos		
B00B - R0007 - Access Student Shower/Toilet - Type 2 - 19.87 m2		
No Asbestos		
B00B - R0008 - Student Laundry - Type 2 - 7.48 m2		
No Asbestos		
B00B - R0009 - Communications Cupboard - 2.1 m2		
No Asbestos		
B00B - R0010 - Movement - 105.21 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0011 - Staff - Toilet - 4.78 m2		
No Asbestos		
B00B - R0012 - Cleaning Store - Distributed - 3.08 m2		
No Asbestos		
B00B - R0013 - General Learning Space - Type 1 - 58.94 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0014 - General Learning Space - Type 1 - 59.88 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0015 - Seminar - Type 1 - 24.88 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0016 - General Learning Space - Type 1 - 59.88 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0017 - General Learning Space - Type 1 - 60.55 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0018 - Distribution Board Cupboard - .59 m2		
No Asbestos		
B00B - R1001 - Movement - 196.28 m2		
No Asbestos		
B00B - R1002 - Stairs - 20.52 m2		
No Asbestos		
B00B - R1003 - General Learning Space - Type 1 - 60.58 m2		
No Asbestos		

Note: No inspection of live electrical installation

Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1004 - Shared Learning Space - 43.8 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1005 - General Learning Space - Type 2 - 65.21 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1006 - G.L.S. Store - 21.16 m2		
No Asbestos		
B00B - R1007 - Cleaning Store - Distributed - 6.09 m2		
No Asbestos		
B00B - R1008 - Movement - 107.53 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1009 - General Learning Space - Type 1 - 59.25 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1010 - General Learning Space - Type 1 - 59.43 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1011 - Seminar - Type 1 - 24.82 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1012 - General Learning Space - Type 1 - 59.43 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1013 - General Learning Space - Type 1 - 60.41 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1014 - Distribution Board Cupboard - .59 m2		
No Asbestos		
B00C - Physical Education/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
Interior		
B00C - R0001 - Movement - 182.56 m2		
No Asbestos		
B00C - R0002 - General Learning Space - Type 1 - 59.42 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0003 - Fitness Laboratory - 97.67 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0004 - Seminar - Type 1 - 19.66 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0005 - Fitness Store - 19.77 m2		
No Asbestos		

Note: No inspection of live electrical installation

B00C - R0006 - Change - 22.48 m2		
No Asbestos		
B00C - R0007 - Change - 22.05 m2		
No Asbestos		
B00C - R0008 - Toilets-Girls - 59.15 m2		
No Asbestos		
B00C - R0009 - Toilets-Boys - 30.72 m2		
No Asbestos		
B00C - R0010 - Distribution Board Cupboard - .74 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0011 - General Learning Space - Type 1 - 58.68 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - Science/Staff Facilities - 2004 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
No Asbestos		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0002 - General Learning Space - Type 3 - 59.59 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0003 - Movement - 17.8 m2		
No Asbestos		
B00D - R0004 - Stairs - 13.73 m2		
No Asbestos		
B00D - R0005 - Movement - 121.21 m2		
No Asbestos		
B00D - R0006 - Botany/Zoology - 16.82 m2		
No Asbestos		
B00D - R0007 - Seminar - Type 2 - 19.77 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0008 - Movement - 83.65 m2		
No Asbestos		
B00D - R0009 - Movement - 37.63 m2		
No Asbestos		
B00D - R0010 - Movement - 13.17 m2		
No Asbestos		
B00D - R0012 - General Learning Space - Type 3 - 59.68 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0013 - General Learning Space - Type 3 - 59.5 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0014 - Distribution Board Cupboard - .95 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0015 - Cleaning Store - Distributed - 3.23 m2		
No Asbestos		
B00D - R0016 - Preparation - Science - 73.03 m2		

No Asbestos	
B00D - R0017 - Apparatus Store - 14.67 m2	
No Asbestos	
B00D - R0018 - Chemical Store - 11.63 m2	
No Asbestos	
B00D - R0019 - General Learning Space - Type 3 - 59.93 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R0020 - Science Laboratory - 50.81 m2	
No Asbestos	
B00D - R0021 - Science Laboratory - 50.51 m2	
No Asbestos	
B00D - R0022 - Science Laboratory - 50.81 m2	
No Asbestos	
B00D - R0023 - Science Laboratory - 50.42 m2	
No Asbestos	
B00D - R0024 - Shower - .53 m2	
No Asbestos	
B00D - R0025 - Shower - .54 m2	
No Asbestos	
B00D - R0026 - Shower - .53 m2	
No Asbestos	
B00D - R0027 - Shower - .62 m2	
No Asbestos	
B00D - R1001 - Staff Study - 200.48 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R1002 - Stairs - 6.14 m2	
No Asbestos	
B00D - R1003 - Movement - 5.3 m2	
No Asbestos	
B00D - R1004 - Interview/Meeting - 14.4 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R1005 - Interview/Meeting - 14.43 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R1006 - Preparation/Printing - 36.22 m2	
No Asbestos	
B00D - R1007 - Interview/Meeting - 12.84 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R1008 - Interview/Meeting - 12.8 m2	
No Asbestos	
Floor Coverings Res/Textile	No Asbestos Found
B00D - R1009 - Archive Store - 22.73 m2	
No Asbestos	
B00D - R1010 - Movement - 12.94 m2	
No Asbestos	
B00D - R1011 - Movement - 89.83 m2	
No Asbestos	

Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1012 - Staff Study - 201.27 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1013 - Movement - 30.34 m2		
No Asbestos		
B00D - R1014 - Staff Lounge - 108.61 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1015 - Access Staff Shower/Toilet - 5.93 m2		
No Asbestos		
B00D - R1016 - Communications Cupboard - 2.34 m2		
No Asbestos		
B00D - R1017 - Distribution Board Cupboard - .48 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R1018 - Cleaning Store - Distributed - 4.59 m2		
No Asbestos		
B00D - R1019 - Staff - Toilet - 4.79 m2		
No Asbestos		
B00D - R1020 - Staff - Toilet - 4.83 m2		
No Asbestos		
B00D - R1021 - Staff - Toilet - 4.76 m2		
No Asbestos		
B00D - R1022 - Staff - Toilet - 4.59 m2		
No Asbestos		
B00E - Administration - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00E - R0001 - Movement - 52.23 m2		
No Asbestos		
B00E - R0002 - Main Switchroom - 10.81 m2		
No Asbestos		
B00E - R0003 - Security Store - 12.38 m2		
No Asbestos		
B00E - R0004 - Staff - Toilet - 4.73 m2		
No Asbestos		
B00E - R0005 - Staff - Toilet - 4.69 m2		
No Asbestos		
B00E - R0006 - Interview/Office - Type 1 - 11.97 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0007 - Interview/Office - Type 1 - 13.21 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0008 - Public Reception - 39.92 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0009 - Visitors Office - 13.62 m2		

No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0010 - Administration - Clerical - 96.3 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0011 - Distribution Board Cupboard - .6 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0012 - Student Reception - 50.69 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0013 - Interview/Office - Type 2 - 13.36 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0014 - Clinic - Boys - 12.95 m2		
No Asbestos		
B00E - R0015 - Clinic-Toilets - 5.61 m2		
No Asbestos		
B00E - R0016 - Clinic - Girls - 13.44 m2		
No Asbestos		
B00E - R0017 - Deputy Principal Office - 13.16 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0018 - Deputy Principal Office - 13.2 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0019 - Cleaning Store - Distributed - 2.73 m2		
No Asbestos		
B00E - R0020 - Tea Room - 5.09 m2		
No Asbestos		
B00E - R0021 - Communications Cupboard - 1.69 m2		
No Asbestos		
B00E - R0022 - Movement - 7.54 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0023 - Principal Office - 19.14 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0024 - Movement - 215.94 m2		
No Asbestos		
B00F - Library/General Learning - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Communication Space - 12.99 m2		
No Asbestos		
B00F - R0002 - Computer Store - 10.14 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0003 - Computer Learning Space - 64.65 m2		

No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0004 - Main Area - 429.75 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0005 - Careers Advisers Office - 13.26 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0006 - Toilets-Disabled - 4.82 m2		
No Asbestos		
B00F - R0007 - Distribution Board Cupboard - .6 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0008 - Staff - Toilet - 5.61 m2		
No Asbestos		
B00F - R0009 - Main Entry - 23.46 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0010 - Movement - 195.5 m2		
No Asbestos		
B00F - R0011 - Senior Study - 63.14 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0012 - General Learning Space - Type 2 - 65.38 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0013 - Movement - 16.35 m2		
No Asbestos		
B00F - R0014 - Shared Learning Space - 43.53 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0015 - General Learning Space - Type 1 - 60.2 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0016 - Distribution Board Cupboard - .88 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0017 - Movement - 98.83 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0018 - General Learning Space - Type 1 - 59.75 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0019 - General Learning Space - Type 1 - 59.16 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0020 - Seminar - Type 1 - 24.53 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0021 - General Learning Space - Type 1 - 59.32 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0022 - General Learning Space - Type 1 - 59.24 m2		

No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0023 - Communications Cupboard - 1.9 m2		
No Asbestos		
B00F - R0024 - Cleaning Store - Distributed - 3.14 m2		
No Asbestos		
B00F - R0025 - G.L.S. Store - 19.58 m2		
No Asbestos		
B00F - R0026 - Library Administration - 75.55 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0027 - Seminar - Type 3 - 12.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
No Asbestos		
B00F - R0028 - Seminar - Type 3 - 12.96 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0029 - Seminar - Type 3 - 12.88 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0030 - System Administrators Office - 12.99 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0031 - Movement - 45.8 m2		
No Asbestos		
B00G - Technological & Applied Studies - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
Interior		
B00G - R0001 - Movement - 200.6 m2		
No Asbestos		
B00G - R0002 - Distribution Board Cupboard - .41 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00G - R0003 - Communications Cupboard - 1.94 m2		
No Asbestos		
B00G - R0004 - Materials Store - Type 1 - 14.61 m2		
No Asbestos		
B00G - R0005 - General Learning Space - Type 6 - 59.35 m2		
No Asbestos		
B00G - R0006 - General Learning Space - Type 7 - 59.56 m2		
No Asbestos		
B00G - R0007 - Seminar - Type 2 - 19.72 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0008 - General Learning Space - Type 6 - 59.73 m2		
No Asbestos		
B00G - R0009 - General Learning Space - Type 7 - 59.5 m2		
No Asbestos		
B00G - R0010 - Materials Store - Type 1 - 16.41 m2		

No Asbestos		
B00G - R0011 - Distribution Board Cupboard - .69 m2		Note: No inspection of live electrical installation
No Asbestos		
B00G - R0012 - Kitchen - Type 1 - 99.71 m2		
No Asbestos		
B00G - R0013 - Preparation - Materials - 29.55 m2		
No Asbestos		
B00G - R0014 - Laundry - 8.1 m2		
No Asbestos		
B00G - R0015 - Pantry - 24.9 m2		
No Asbestos		
B00G - R0016 - Cleaning Store - Distributed - 2.68 m2		
No Asbestos		
B00G - R0017 - Kitchen - Type 1 - 100.27 m2		
No Asbestos		
B00H - Technological & Applied Studies - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00H - R0001 - Movement - 371.06 m2		
No Asbestos		
B00H - R0002 - Staff - Toilet - 5.65 m2		
No Asbestos		
B00H - R0003 - Project Store - Type 1 - 44.25 m2		
No Asbestos		
B00H - R0004 - Materials Workshop - Type 2 - 173.59 m2		
No Asbestos		
B00H - R0005 - Distribution Board Cupboard - .68 m2		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0006 - Project Store - Type 1 - 45.29 m2		
No Asbestos		
B00H - R0007 - Materials Workshop - Type 2 - 173.37 m2		
No Asbestos		
B00H - R0008 - Outdoor Workshop - 92.26 m2		
No Asbestos		
B00H - R0009 - Pottery Store - 10.64 m2		
No Asbestos		
B00H - R0010 - Kiln Space - 9.27 m2		
No Asbestos		
B00H - R0011 - Welding/Hot Metals Area - 7.21 m2		
No Asbestos		
B00H - R0012 - L.P.G. Store - .84 m2		
No Asbestos		
B00H - R0013 - Dust Extraction Space - 6.41 m2		
No Asbestos		
B00H - R0014 - Materials Store - Type 2 - 35.52 m2		
No Asbestos		
B00H - R0015 - General Learning Space - Type 9 - 61.03 m2		
No Asbestos		

B00H - R0016 - General Learning Space - Type 8 - 61.03 m2		
No Asbestos		
B00H - R0017 - General Learning Space - Type 9 - 61.03 m2		
No Asbestos		
B00H - R0018 - General Learning Space - Type 8 - 60.97 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00H - R0019 - Movement - 30.05 m2		
No Asbestos		
B00I - Mechanical Services - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00I - R0001 - Lift - 2.1 m2		
No Asbestos		
B00I - R0002 - Plant - 4.83 m2		
No Asbestos		
B00I - R0003 - Movement - 87.72 m2		
No Asbestos		
B00I - R0004 - Stairs - 15.69 m2		
No Asbestos		
B00I - R1001 - Lift - 2.1 m2		
No Asbestos		
B00I - R1002 - Movement - 49.18 m2		
No Asbestos		
B00I - R1003 - Stairs - 20.15 m2		
No Asbestos		
B00J - Art/Performing Arts - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00J - R0001 - Movement - 411.72 m2		
No Asbestos		
B00J - R0002 - General Storeroom - 3.82 m2		
No Asbestos		
B00J - R0003 - Office/Store - 12.36 m2		
No Asbestos		
B00J - R0004 - Student Canteen - 53.18 m2		
No Asbestos		
B00J - R0005 - General Learning Space - Type 1 - 59.17 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0006 - General Learning Space - Type 1 - 60.01 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0007 - General Learning Space - Type 5 - 60.77 m2		

No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0008 - General Learning Space - Type 4 - 60.78 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0009 - Dark Room - 28.08 m2		
No Asbestos		
B00J - R0010 - Cleaning Store - Distributed - 2.94 m2		
No Asbestos		
B00J - R0011 - Visual Arts Store - 20.09 m2		
No Asbestos		
B00J - R0012 - Project Store - Type 3 - 28.13 m2		
No Asbestos		
B00J - R0013 - Communications Cupboard - 2 m2		
No Asbestos		
B00J - R0014 - Visual Arts Workshop - 152.59 m2		
No Asbestos		
B00J - R0015 - Performance Store - 20.05 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0016 - Practice/Seminar - 19.84 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00J - R0017 - Distribution Board Cupboard - .52 m2		
Note: No inspection of live electrical installation		
No Asbestos		
B00J - R0018 - Performance Workshop - 98.53 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - Multi Purpose Facilities/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00K - R0001 - Movement - 377.02 m2		
No Asbestos		
B00K - R0002 - Change - 59.03 m2		
No Asbestos		
B00K - R0003 - Toilets-Boys - 40.08 m2		
No Asbestos		
B00K - R0004 - Staff Shower - 9.7 m2		
No Asbestos		
B00K - R0005 - Toilets-Girls - 48.9 m2		
No Asbestos		
B00K - R0006 - Change - 58.91 m2		
No Asbestos		
B00K - R0007 - Movement - 17.7 m2		
No Asbestos		
B00K - R0008 - Movement - 1.23 m2		
No Asbestos		
B00K - R0009 - Stage - 95.7 m2		

No Asbestos		
B00K - R0010 - Access Staff Shower/Toilet - 6.71 m2		
No Asbestos		
B00K - R0011 - Gymnasium - 619.69 m2		
No Asbestos		
B00K - R0012 - Chair Store - 32.12 m2		
No Asbestos		
B00K - R0013 - Control Room - 12.03 m2		
No Asbestos		
B00K - R0014 - Sport Equipment Store - 25 m2		
No Asbestos		
B00K - R0015 - Outdoor Equipment Store - 19.41 m2		
No Asbestos		
B00K - R0016 - General Assistants - 11.15 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00K - R0017 - Maintenance Bulk Store - 12.78 m2		
No Asbestos		
B00K - R0018 - Garden Store Room - 14.73 m2		
No Asbestos		
B00K - R0019 - Cleaning Supplies Store - 6.06 m2		
No Asbestos		
B00K - R0020 - Cleaning Store - Distributed - 2.9 m2		
No Asbestos		
B00K - R0021 - Large Equipment Store - 23.55 m2		
No Asbestos		
B00K - R0022 - Distribution Board Cupboard - .69 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00K - R0023 - First Aid - 12.95 m2		
No Asbestos		
B00K - R0024 - Plant - .5 m2		
No Asbestos		
B00K - R0025 - Movement - 67.54 m2		
No Asbestos		
B00L - Storage - 2013 - Metal Shed		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - Bulk Store - 162.46 m2		
No Asbestos		

Demountables

OS 720 11664 - Science Laboratory/Prep Room - Placement Date : 12-APR-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 11979 - Learning Unit - Standard/Withdrawal - Placement Date : 30-DEC-2009

No Asbestos Found

OS 601 12236 - Learning Unit - Standard/Withdrawal - Placement Date : 21-JAN-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 600 13135 - Learning Unit - Small - Placement Date : 21-JAN-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 13794 - Learning Unit - Standard/Withdrawal - Placement Date : 30-DEC-2009

No Asbestos Found

NS 200 13952 - Art Learning Space/Workshop/Bulk Store - Placement Date : 29-DEC-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 14225 - Learning Unit - Standard/Withdrawal - Placement Date : 24-NOV-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found