

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	James Cook Boys Technology High School (8882)
Region:	Sydney AMU
State Electorate:	Rockdale
Local Government Area:	Bayside

Last Reviewed By:	WSP 28-JUL-2015
Last Revised By:	OHMS Hygiene 16-JUL-2020

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Music - 1956 - Brick/Block							
Exterior							
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	175m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Electrical - Backing Board	Bituminous Board	2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Packing	30	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids - Flat Roof	AC Fragments/Debris - Other AC Material						
Interior							
B00A - R0002 - Staff - Toilet - 7.14 m2							
No Asbestos							
B00A - R0003 - Cleaning Store - Distributed - 2.29 m2							
No Asbestos							
B00A - R0004 - Leading Teacher - 12.22 m2							
No Asbestos							
B00A - R0005 - Administration - Clerical - 24.72 m2							
No Asbestos							
B00A - R0006 - Printing/Photocopying - 22.38 m2							
No Asbestos							
B00A - R0010 - Music Learning Space - 78.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R0011 - Practice/Seminar - 25.86 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0012 - Music Store - 25.46 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0013 - Practice/Seminar - 25.93 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0014 - Music Learning Space - 78.83 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R0015 - Leading Teacher - 10.8 m2							
No Asbestos							
B00A - R0016 - Interview/Meeting - 17.24 m2							
No Asbestos							
B00A - R0017 - Administration - Clerical - 10.14 m2							
No Asbestos							
B00A - R0018 - Other-Vacant - .45 m2							
Non Accessible							
B00A - R0019 - Distribution Board Cupboard - .45 m2							
No Asbestos							
B00A - R0020 - Principal Office - 18.8 m2							

Note: No inspection of live electrical installation

No Asbestos							
B00A - R0021 - Staff - Toilet - 3.15 m2							
No Asbestos							
B00A - R0022 - General Storeroom - 5.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0023 - General Storeroom - 9.08 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0024 - Deputy Principal Office - 18.8 m2							
No Asbestos							
B00A - R0025 - Movement - 110.77 m2							
No Asbestos							
B00A - R0026 - External Movement - 11.16 m2							
No Asbestos							
B00A - R0027 - Commonroom - 114.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R0028 - Staff Kitchen - 6.75 m2							
No Asbestos							
B00A - R0029 - Staff - Toilet - 4.47 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0030 - Clinic - Boys - 8 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0031 - Staff Study - 13.21 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0032 - External Movement - 25.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0033 - External Movement - 10.16 m2							
No Asbestos							
B00A - R0034 - External Movement - 12.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - Science Learning/General Learning - 1956 - Brick/Block							
Exterior							
Underfloor Voids	Packing	30	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area						
External Roof Structure	Fibre Cement Pipe	4	To northern side of building	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Eaves Linings	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Interior							
B00B - R0003 - Staff Study - 16.96 m2							
No Asbestos							
B00B - R0004 - General Learning Space - 42.04 m2							
No Asbestos							

B00B - R0005 - Secure Storeroom - 15.14 m2							
No Asbestos							
B00B - R0006 - General Learning Space - 41.78 m2							
No Asbestos							
B00B - R0011 - Movement - 63.68 m2							
No Asbestos							
B00B - R0012 - Garden Store Room - 4.18 m2							
No Asbestos							
B00B - R0013 - Laboratory L.S. - 104.07 m2							
No Asbestos							
B00B - R0014 - Preparation - Science - 35.04 m2							
No Asbestos							
B00B - R0015 - Stairs - 2.22 m2							
No Asbestos							
B00B - R0016 - Preparation - Science - 18.01 m2							
No Asbestos							
B00B - R0017 - Laboratory L.S. - 103.79 m2							
No Asbestos							
B00B - R0018 - Other-Vacant - 4.95 m2							
Non Accessible							
B00B - R0019 - External Movement - 2.7 m2							
No Asbestos							
B00B - R0020 - External Stairs - 1.51 m2							
No Asbestos							
B00B - R0021 - External Movement - 3.82 m2							
No Asbestos							
B00B - R1001 - General Learning Space - 52.22 m2							
No Asbestos							
B00B - R1002 - General Learning Space - 52.37 m2							
No Asbestos							
B00B - R1004 - Resources Store - 12.46 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1005 - Cleaning Store - Distributed - 1.28 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1007 - Resources Store - 4.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1009 - Staff Study - 52.49 m2							
No Asbestos							
B00B - R1010 - Movement - 118.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles	119m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1011 - Handwashing Facilities - .86 m2							
No Asbestos							
B00B - R1012 - Computer Resource - 25.62 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1013 - Resources Store - 12.96 m2							
Floor Coverings Res/Textile	Vinyl Tiles						

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1014 - Tea Room - 4.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1015 - Staff Study - 14.03 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1016 - General Learning Space - 77.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1017 - Handwashing Facilities - 1.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R1018 - Stairs - 15.17 m2							
No Asbestos							
B00C - Pupil Facilities - 1956 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Interior							
B00C - R0001 - General Storeroom - 48.27 m2							
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Partition Walls (Cubicles)	Flat AC Sheeting						
B00C - R0002 - General Storeroom - 2.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R0003 - Toilets-Boys - 102.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	104m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00C - R0004 - Cleaning Store - Distributed - 2.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00D - Technological & Applied Studies - 1956 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	130m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	60m2	East facing, West facing, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Wall Cladding	Flat AC Sheeting						
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00D - R0002 - Resources Store - 9.21 m2							
No Asbestos							
B00D - R0003 - Resources Store - 4.99 m2							
No Asbestos							
B00D - R0006 - Materials Store - 23.92 m2							
Floor Coverings Res/Textile	Vinyl Tiles	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00D - R0007 - Materials Store - 39.85 m2							
No Asbestos							
B00D - R0008 - Distribution Board Cupboard - .38 m2							Note: No inspection of live electrical installation
No Asbestos							
B00D - R0009 - General Storeroom - 93.05 m2							
No Asbestos							
B00D - R0010 - Cleaning Store - Distributed - 5.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0011 - External Movement - 61.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0012 - General Storeroom - 2.06 m2							
No Asbestos							
B00D - R0013 - External Movement - 4.32 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0014 - General Storeroom - 35.77 m2							
No Asbestos							
B00D - R0015 - Materials Store - 48.46 m2							
No Asbestos							
B00D - R0016 - Welding Area - 56.98 m2							
No Asbestos							
B00D - R0017 - Materials Technology L.S. - 103.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting						
B00D - R0018 - Handwashing Facilities - 1.38 m2							
No Asbestos							
B00D - R0019 - Design/Technology L.S. - 54.51 m2							
Floor Coverings Res/Textile	Vinyl Tiles	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0020 - Handwashing Facilities - .51 m2							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - Science Learning/General Learning - 1968 - Brick/Block							
Exterior							
External Wall Structure	Compressed AC Sheet	60	East facing, West facing	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	Non Accessible Area						
Interior							
B00E - R0001 - Laboratory L.S. - 94.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0002 - Preparation - Science - 28.74 m2							
Floor Coverings Res/Textile	Vinyl Tiles	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Plant / Equipment - Fume Cupboard	Fibre Cement Pipe	2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0003 - Resources Store - 9.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Flat AC Sheeting	2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0004 - Laboratory L.S. - 92.67 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0005 - Chemical Store - 27.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R0006 - Cleaning Store - Distributed - 5.78 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R0007 - Interview/Office - Type 1 - 13.3 m2							
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R0010 - Distribution Board Cupboard - .92 m2 Note: No inspection of live electrical installation							
Electrical - Mounting Board	Resinous Board	2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0011 - Office/Store - 12.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0012 - Laboratory L.S. - 96.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles	97m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0013 - Preparation - Science - 28.74 m2							

Floor Coverings Res/Textile	Vinyl Tiles	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	1	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Plant / Equipment - Fume Cupboard		1	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Wnindow	Flat AC Sheeting	3	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0014 - Apparatus Store - 16.75 m2							
Floor Coverings Res/Textile	Vinyl Tiles	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R0015 - Resources Store - 9.88 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R0016 - Laboratory L.S. - 100.91 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Wnindow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0017 - Staff - Toilet - 5.73 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R0018 - Distribution Board Cupboard - .88 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00E - R0019 - Secure Storeroom - 9.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0020 - Computer Learning Space - 53.23 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnindow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0021 - Cleaning Store - Distributed - 5.28 m2							
No Asbestos							
B00E - R0022 - External Movement - 217.15 m2							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0023 - Other-Vacant - 1.34 m2							
No Asbestos							
B00E - R0024 - Staff Study - 25.71 m2							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R0025 - Movement - 4.47 m2							

No Asbestos							
B00E - R0026 - Stairs - 8.05 m2							
No Asbestos							
B00E - R0027 - External Stairs - .29 m2							
No Asbestos							
B00E - R0028 - External Stairs - 8.12 m2							
No Asbestos							
B00E - R0029 - External Movement - 2.81 m2							
No Asbestos							
B00E - R0030 - External Movement - 2.56 m2							
No Asbestos							
B00E - R0031 - External Movement - 2.78 m2							
No Asbestos							
B00E - R1001 - General Learning Space - 60.76 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnadow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1002 - General Learning Space - 45.87 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnadow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1003 - General Learning Space - 59.29 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnadow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1004 - Special Learning Space - 59.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles	68m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnadow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1006 - Resources Store - 24.24 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Wnadow	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1007 - Resources Store - 11.55 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R1008 - Distribution Board Cupboard - .88 m2							
Note: No inspection of live electrical installation							
Electrical - Mounting Board	Resinous Board	2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R1009 - Resources Store - 10.84 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R1010 - Staff Study - 16.2 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1011 - Cleaning Store - Distributed - 1.37 m2							
No Asbestos							
B00E - R1013 - General Learning Space - 50.41 m2							
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
B00E - R1014 - General Learning Space - 52.65 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1015 - General Learning Space - 52.51 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1016 - Computer Learning Space - 60.22 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1017 - Computer Resource - 17.24 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1018 - Computer Learning Space - 53.45 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Window	Flat AC Sheeting	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1019 - Toilets-Unisex - 4.69 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Window	Flat AC Sheeting	0.5	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R1020 - Movement - 10.36 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00E - R1021 - Distribution Board Cupboard - .86 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R1022 - Cleaning Store - Distributed - 1.42 m2							
No Asbestos							
B00E - R1023 - External Movement - 185.16 m2							
Floor Coverings Res/Textile	Vinyl Tiles	159m2	West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00E - R1024 - Tea Room - 7.45 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00E - R1025 - Staff Study - 38.67 m2							
Window	Flat AC Sheeting	2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R1026 - Staff Study - 32.47 m2							
Window	Flat AC Sheeting	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R1027 - Tea Room - 3.06 m2							
Window	Flat AC Sheeting	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R1028 - External Stairs - 8.12 m2							
No Asbestos							
B00E - R1029 - External Stairs - 8.2 m2							
No Asbestos							
B00E - R9001 - General Assistants - 14.08 m2							
No Asbestos							
B00E - R9002 - Archive Store - 10.77 m2							
No Asbestos							
B00E - R9003 - Gymnasium - 127.84 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (120 - 250 m2) - (X15)						
B00E - R9004 - Office/Store - 10.74 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00E - R9005 - Staff - Toilet - 1.96 m2							
No Asbestos							
B00E - R9006 - Toilets-Boys - 14.95 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R9008 - Plant - .76 m2							
No Asbestos							
B00E - R9009 - Plant - 22.33 m2							
Plumbing / Pipework	Fibre Cement Pipe	5	Exiting 2 boilers and entering riser to west of room	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9010 - General Storeroom - 53.69 m2							
No Asbestos							
B00E - R9011 - Toilet - Lobby - 4.04 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00E - R9012 - Shower - 45.93 m2							
No Asbestos							
B00E - R9013 - Stairs - 8.05 m2							

No Asbestos							
B00F - Physical Education - 1973 - Brick/Block							
Exterior							
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00F - M0001 - Movement - 84.65 m2							
No Asbestos							
B00F - M0002 - Stairs - 6.37 m2							
No Asbestos							
B00F - R0001 - Fitness Laboratory - 62.71 m2							
No Asbestos							
B00F - R0002 - Fitness Laboratory - 62.61 m2							
No Asbestos							
B00F - R0003 - Fitness Laboratory - 62.81 m2							
No Asbestos							
B00F - R0004 - Movement - 67.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00F - R0005 - Shower - 7.92 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00F - R0006 - Shower - 8.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00F - R0007 - Stairs - 3.14 m2							
No Asbestos							
B00F - R0008 - External Movement - 3.36 m2							
Ceiling Structures/Linings	Compressed AC Sheet						
B00G - Technological & Applied Studies/Art - 1956 - Brick/Block							
Exterior							
Underfloor Voids	Non Accessible Area						
Underfloor Voids	Packing	30	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids	Flat AC Sheeting	100	Throughout to former external wall cladding and eaves	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos), Crocidolite (blue asbestos)
Ceiling Voids - Flat Roof	AC Fragments/Debris - Flat AC Sheet						
Interior							
B00G - R0001 - Materials Technology L.S. - 65.52 m2							
No Asbestos							
B00G - R0002 - Design/Technology L.S. - 79.52 m2							
No Asbestos							
B00G - R0003 - Design/Technology L.S. - 66.07 m2							
No Asbestos							
B00G - R0004 - Resources Store - 18 m2							
Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0005 - Staff - Toilet - 7.55 m2							

No Asbestos							
B00G- R0006 - Art Learning Space - 69.02 m2							
No Asbestos							
B00G- R0007 - Resources Store - 23.36 m2							
No Asbestos							
B00G- R0008 - Art Learning Space - 60.54 m2							
No Asbestos							
B00G- R0009 - Resources Store - 3.82 m2							
No Asbestos							
B00G- R0010 - Art Learning Space - 51.99 m2							
No Asbestos							
B00G- R0011 - Art Learning Space - 61.7 m2							
No Asbestos							
B00G- R0012 - Staff Study - 18.58 m2							
No Asbestos							
B00G- R0013 - Kiln Space - 9.75 m2							
No Asbestos							
B00G- R0014 - Resources Store - 18.47 m2							
No Asbestos							
B00G- R0022 - Movement - 115.84 m2							
Floor Coverings Res/Textile	Vinyl Tiles	117m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G- R0023 - Materials Store - 16.18 m2							
No Asbestos							
B00G- R0024 - Movement - 15.57 m2							
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00G- R0026 - Materials Technology L.S. - 78.13 m2							
No Asbestos							
B00G- R0027 - Handwashing Facilities - 1.48 m2							
No Asbestos							
B00G- R0028 - Wood Technology Bay - 43.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Eastern section	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	3m2	Upper section around windows, eastern end of room	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00G- R0029 - Dust Extraction Space - 7.43 m2							
No Asbestos							
B00G- R0030 - Materials Technology L.S. - 86.98 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Western section	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	Upper section around windows, western end of room	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00G- R0031 - Handwashing Facilities - 1.38 m2							
No Asbestos							
B00G- R0032 - Staff Study - 23.96 m2							
No Asbestos							
B00G- R0033 - Tea Room - 1.78 m2							
No Asbestos							
B00G- R0034 - Darkroom Space - 4.97 m2							
No Asbestos							
B00G- R0035 - Dark Room - 20.45 m2							

No Asbestos							
B00G - R0036 - External Movement - 7.57 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00G - R0037 - Movement - 26.7 m2							
No Asbestos							
B00H - Pupil Facilities - 1956 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Interior							
B00H - R0005 - Covered Area - 158.46 m2							
Ceiling Structures/Linings	Flat AC Sheeting	160m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00H - R0006 - General Storeroom - 16.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00H - R0007 - Student Canteen - 41.89 m2							
No Asbestos							
B00H - R0008 - Movement - 8.35 m2							
No Asbestos							
B00H - R0009 - Office/Store - 6.22 m2							
No Asbestos							
B00H - R0010 - Toilet - Lobby - 2.8 m2							
No Asbestos							
B00H - R0011 - Staff - Toilet - 1.75 m2							
No Asbestos							
B00H - R0012 - Pantry - 3.43 m2							
No Asbestos							
B00H - R0013 - Distribution Board Cupboard - .39 m2						Note: No inspection of live electrical installation	
No Asbestos							
B00H - R0014 - External Movement - 2.13 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Eave above canopy	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
B00I - Library - 1956 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	170m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
External Wall Structure	Flat AC Sheeting						
Underfloor Voids	Packing	40	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Interior							
B00I - R0001 - Performance Workshop - 67.52 m2							
No Asbestos							
B00I - R0002 - General Learning Space - 52.24 m2							
No Asbestos							
B00I - R0003 - Resources Store - 3.82 m2							

No Asbestos	
B00I - R0004 - Distribution Board Cupboard - 1.23 m2	Note: No inspection of live electrical installation
No Asbestos	
B00I - R0005 - Interview/Office - Type 1 - 19.23 m2	
No Asbestos	
B00I - R0006 - Movement - 50.91 m2	
No Asbestos	
B00I - R0007 - Audio Visual Workroom - 25.71 m2	
No Asbestos	
B00I - R0008 - Library Administration - 35.55 m2	
No Asbestos	
B00I - R0009 - Librarian - 10.8 m2	
No Asbestos	
B00I - R0012 - Movement - 50.2 m2	
No Asbestos	
B00I - R0013 - Staff Study - 19.07 m2	
No Asbestos	
B00I - R0014 - Sport Equipment Store - 1.24 m2	
No Asbestos	
B00I - R0015 - Resources Store - 3.91 m2	
No Asbestos	
B00I - R0016 - General Learning Space - 52.15 m2	
No Asbestos	
B00I - R0017 - General Learning Space - 67.86 m2	
No Asbestos	
B00I - R0018 - External Movement - 3.89 m2	
No Asbestos	
B00I - R0019 - Handwashing Facilities - .73 m2	
No Asbestos	
B00I - R0020 - Cleaning Store - Distributed - 3.27 m2	
No Asbestos	
B00I - R0021 - Stairs - 2.71 m2	
No Asbestos	
B00I - R0022 - Main Entry - 12.84 m2	
No Asbestos	
B00I - R0023 - Main Area - 356.56 m2	
No Asbestos	
B00I - R0024 - Shared Study Space - 16.06 m2	
No Asbestos	
B00I - R0025 - Shared Study Space - 19.61 m2	
No Asbestos	
B00I - R0026 - Cleaning Store - Distributed - 4.03 m2	
No Asbestos	
B00I - R0027 - Stairs - 1.86 m2	
No Asbestos	
B00I - R0028 - Other-Vacant - .74 m2	
No Asbestos	
B00I - R0029 - External Movement - 3.85 m2	
No Asbestos	
B00I - R0030 - External Movement - 3.86 m2	
No Asbestos	

B00I - R0031 - External Movement - 3.82 m2							
No Asbestos							
B00I - R1001 - General Learning Space - 69.71 m2							
No Asbestos							
B00I - R1003 - Staff - Toilet - 4.07 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1004 - Cleaning Store - Distributed - 1.3 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1005 - Resources Store - 18.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1006 - Shared Study Space - 52.33 m2							
No Asbestos							
B00I - R1007 - General Learning Space - 52.48 m2							
No Asbestos							
B00I - R1008 - General Learning Space - 52.4 m2							
No Asbestos							
B00I - R1009 - General Learning Space - 52.12 m2							
No Asbestos							
B00I - R1010 - Staff Study - 18.77 m2							
No Asbestos							
B00I - R1011 - Resources Store - 1.25 m2							
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1012 - Resources Store - 4.18 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1013 - General Learning Space - 52.33 m2							
No Asbestos							
B00I - R1014 - General Learning Space - 69.18 m2							
No Asbestos							
B00I - R1015 - Movement - 151.05 m2							
Floor Coverings Res/Textile	Vinyl Tiles	156m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1016 - Staff Study - 49.7 m2							
Floor Coverings Res/Textile	Vinyl Tiles	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1017 - Tea Room - 2.54 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R1018 - Handwashing Facilities - .82 m2							
No Asbestos							
B00I - R1019 - Other-Vacant - .85 m2							
No Asbestos							
B00I - R1020 - Stairs - 15.38 m2							
No Asbestos							
B00I - R1021 - Stairs - 15.57 m2							
No Asbestos							
B00J - Multi Purpose Facilities - 1956 - Brick/Block							
Exterior							

Underfloor Voids	AC Fragments/Debris	20	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)
Underfloor Voids	Packing	40	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting						
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting						
Interior							
B00J - R0001 - Toilets-Boys - 7.84 m2							
No Asbestos							
B00J - R0002 - Multi-Purpose Space - 414.41 m2							
No Asbestos							
B00J - R0003 - Sport Equipment Store - 18.24 m2							
No Asbestos							
B00J - R0004 - Resources Store - 6.42 m2							
Ceiling Structures/Linings	Compressed AC Sheet						
B00J - R0005 - Toilets-Disabled - 4.79 m2							
No Asbestos							
B00J - R0006 - Chair Store - 16.39 m2							
No Asbestos							
B00J - R0007 - Movement - 12.65 m2							
No Asbestos							
B00J - R0010 - Stage - 87.92 m2							
No Asbestos							
B00J - R0011 - Movement - 15.4 m2							
No Asbestos							
B00J - R0012 - Distribution Board Cupboard - .59 m2							
No Asbestos							
B00J - R0013 - Toilets-Boys - 5.22 m2							
No Asbestos							
B00J - R0014 - Staff Kitchen - 9.68 m2							
No Asbestos							
B00J - R0015 - Toilets-Girls - 5.68 m2							
No Asbestos							
B00J - R0016 - Sport Equipment Store - 17.53 m2							
No Asbestos							
B00J - R0017 - Sport Equipment Store - 15.04 m2							
No Asbestos							
B00J - R0018 - Sport Equipment Store - 23.99 m2							
No Asbestos							
B00J - R0020 - Plant - 14.59 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0021 - Sport Equipment Store - 19.7 m2							
Ceiling Structures/Linings	Compressed AC Sheet						
B00J - R0022 - External Movement - 4.94 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0023 - Movement - 2.5 m2							

No Asbestos							
B00J - R0024 - Toilets-Boys - 4.36 m2							
No Asbestos							
B00J - R0025 - External Movement - 2.39 m2							
No Asbestos							
B00J - R0026 - External Movement - 3.02 m2							
No Asbestos							
B00J - R0027 - Movement - 1.8 m2							
No Asbestos							
B00J - R0028 - Cleaning Store - Distributed - 10.74 m2							
No Asbestos							
B00J - R0029 - Staff - Toilet - 1.54 m2							
No Asbestos							
B00J - R0030 - General Storeroom - 10.68 m2							
No Asbestos							
B00J - R0031 - Staff - Toilet - 1.56 m2							
No Asbestos							
B00J - R0032 - External Movement - 4.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0033 - Plant - .48 m2							
No Asbestos							
B00J - R0034 - External Movement - 3.43 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R0035 - External Movement - 3.05 m2							
No Asbestos							
B00J - R0036 - External Movement - 3.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00J - R1001 - Plant - 4.68 m2							
No Asbestos							
B00J - R1002 - General Storeroom - 7.24 m2							
Non Accessible							
B00J - R1003 - Movement - 10.26 m2							
No Asbestos							
B00J - R1004 - Movement - 3.71 m2							
No Asbestos							
B00J - R1005 - General Storeroom - 8.51 m2							
No Asbestos							
B00J - R9001 - Change - 28.21 m2							
No Asbestos							
B00J - R9002 - General Storeroom - 26.96 m2							
No Asbestos							
B00J - R9003 - Change - 28.17 m2							
No Asbestos							
B00J - R9004 - Cleaning Store - Distributed - .92 m2							
No Asbestos							
B00Z - Building Services - 1955 - Brick/Block							
Exterior							
No Asbestos							
Interior							

B00Z - R0001 - Plant - 2.68 m2

No Asbestos

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020