

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Kegworth Public School (2270)</b>
<b>Region:</b>	<b>Sydney AMU</b>
<b>State Electorate:</b>	<b>Balmain</b>
<b>Local Government Area:</b>	<b>Inner West</b>

<b>Last Reviewed By:</b>	WSP 14-FEB-2017
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - General Learning/Administration - 1887 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	400m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	Flat AC Sheeting	20	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00A - R0001 - Withdrawal Space - 1hb - 15.34 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0002 - Uniform Shop - 7.4 m2</b>							
No Asbestos							
<b>B00A - R0003 - Movement - 32.39 m2</b>							
No Asbestos							
<b>B00A - R0004 - Distribution Board - .85 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Door - Lining	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0005 - Staff Room - 46.53 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0006 - Staff Kitchen - 4.71 m2</b>							
No Asbestos							
<b>B00A - R0007 - Duplicating Workroom - 18.58 m2</b>							
No Asbestos							
<b>B00A - R0008 - Movement - 36.66 m2</b>							
No Asbestos							
<b>B00A - R0009 - Clerical Office/Workroom - 9.63 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0010 - Clerical Office - 11.66 m2</b>							
No Asbestos							
<b>B00A - R0011 - Deputy Principal - 17.66 m2</b>							
No Asbestos							
<b>B00A - R0012 - Principal - 23.16 m2</b>							
No Asbestos							
<b>B00A - R0013 - Sick Bay - 3.92 m2</b>							
No Asbestos							
<b>B00A - R0014 - Practical Activities - 1hb - 18.11 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0015 - Home Base - 55.77 m2</b>							
No Asbestos							
<b>B00A - R0016 - Home Base - 44.16 m2</b>							
No Asbestos							
<b>B00A - R0017 - Practical Activities - 1hb - 21.01 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0018 - Movement - 19.5 m2</b>							
No Asbestos							

<b>B00A - R0019 - Staff Toilet - 3.56 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0020 - Security Store - 10.28 m2</b>							
No Asbestos							
<b>B00A - R0021 - Movement - 25.23 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0023 - Movement - 38.27 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0024 - External Movement - 4.39 m2</b>							
No Asbestos							
<b>B00A - R0025 - Entry Vestibule - 4.84 m2</b>							
No Asbestos							
<b>B00A - R0026 - Toilets - Boys - 4.22 m2</b>							
No Asbestos							
<b>B00A - R0027 - Movement - 22.79 m2</b>							
No Asbestos							
<b>B00A - R0028 - Library Office/Workroom - 10.32 m2</b>							
No Asbestos							
<b>B00A - R0029 - Reading Area - 84.57 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00A - R0030 - Seminar/Study - 9.2 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0031 - Seminar/Study - 9.15 m2</b>							
No Asbestos							
<b>B00A - R0032 - Communications Room - 13.45 m2</b>							
No Asbestos							
<b>B00A - R0033 - Library Office/Workroom - 6.82 m2</b>							
No Asbestos							
<b>B00A - R0034 - Library Office/Workroom - 17.15 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0035 - Movement - 1.36 m2</b>							
No Asbestos							
<b>B00A - R0036 - Toilets - Girls - 3.61 m2</b>							
No Asbestos							
<b>B00A - R0037 - Cleaning Distributed Store - 1.72 m2</b>							
Wall Linings Internal	Flat AC Sheeting	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00A - R0038 - Distribution Board - .66 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Door - Lining	Flat AC Sheeting						
<b>B00A - R0039 - External Movement - 6.1 m2</b>							
No Asbestos							
<b>B00A - R0040 - Movement - 13.45 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0041 - Movement - 6.9 m2</b>							
No Asbestos							
<b>B00A - R0042 - General Assistant/Bulk Store - 8.77 m2</b>							
No Asbestos							

<b>B00A - R0043 - Toilets - Girls - 3.32 m2</b>							
No Asbestos							
<b>B00A - R0044 - Cleaning Distributed Store - 2.07 m2</b>							
No Asbestos							
<b>B00A - R0045 - Toilets - Boys - 3.34 m2</b>							
No Asbestos							
<b>B00A - R0046 - Movement - 33.21 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0047 - Practical Activities - 1hb - 20.14 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0048 - Home Base - 46.95 m2</b>							
No Asbestos							
<b>B00A - R0049 - Withdrawal Space - 1hb - 10.78 m2</b>							
No Asbestos							
<b>B00A - R0050 - Practical Activities - 1hb - 23.46 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0051 - Home Base - 52.51 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00A - R0052 - General Storeroom - 10.44 m2</b>							
No Asbestos							
<b>B00A - R0053 - Home Base - 54.73 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00A - R0054 - Practical Activities - 1hb - 19.29 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0055 - Movement - 79.22 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00A - R0056 - External Movement - 20.71 m2</b>							
No Asbestos							
<b>B00A - R0057 - Distribution Board - .58 m2</b>							<b>Note: No inspection of live electrical installation</b>
Door - Lining	Flat AC Sheeting						
<b>B00A - R0058 - Toilets - Boys - 14.46 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0059 - Toilets - Girls - 17.03 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0061 - Movement - 25.52 m2</b>							
No Asbestos							
<b>B00A - R0062 - Disabled Toilet - 2.5 m2</b>							
No Asbestos							
<b>B00A - R0063 - Practical Activities - 1hb - 25.74 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0064 - Home Base - 72.43 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
<b>B00A - R0065 - External Movement - 1.44 m2</b>							
No Asbestos							
<b>B00A - R0066 - External Movement - 1.44 m2</b>							
No Asbestos							
<b>B00A - R0067 - Drinking Facilities - 1.3 m2</b>							
No Asbestos							
<b>B00A - R0068 - Home Base - 62.55 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00A - R0069 - Practical Activities - 1hb - 25.1 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0070 - Toilets - Boys/Girls - 2.05 m2</b>							
No Asbestos							
<b>B00A - R0071 - External Movement - 1.44 m2</b>							
No Asbestos							
<b>B00A - R0072 - External Movement - 1.44 m2</b>							
No Asbestos							
<b>B00A - R0073 - Cleaning Supplies - 8.97 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0074 - Cleaning Distributed Store - 3.09 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0075 - Movement - 2.79 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00A - R0076 - Movement - 16.34 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00A - R0077 - Security Store - 9.53 m2</b>							
No Asbestos							
<b>B00A - R0078 - Movement - 40.09 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00A - R0079 - Movement - 19.26 m2</b>							
No Asbestos							
<b>B00A - R0080 - Staff Toilet - 4.81 m2</b>							
No Asbestos							
<b>B00A - R0081 - Staff Toilet - 5.45 m2</b>							
No Asbestos							
<b>B00A - R0082 - Security Store - 4.27 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0083 - Practical Activities - 1hb - 18.14 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles							
<b>B00A - R0084 - Home Base - 73.08 m2</b>								
No Asbestos								
<b>B00A - R0085 - Clerical Office - 14.19 m2</b>								
No Asbestos								
<b>B00A - R0086 - Movement - 8.65 m2</b>								
No Asbestos								
<b>B00A - R0087 - Movement - 15.17 m2</b>								
No Asbestos								
<b>B00A - R0088 - Cleaning Distributed Store - 1.48 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00A - R0089 - Stairs - 9.58 m2</b>								
No Asbestos								
<b>B00A - R0090 - Stairs - 17.08 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles							
<b>B00A - R0091 - Stairs - .21 m2</b>								
No Asbestos								
<b>B00A - R0092 - Stairs - 6.01 m2</b>								
No Asbestos								
<b>B00A - R0093 - Stairs - 6.22 m2</b>								
No Asbestos								
<b>B00A - R0096 - External Movement - 2.86 m2</b>								
No Asbestos								
<b>B00A - R0097 - External Stairs - 12.09 m2</b>								
No Asbestos								
<b>B00A - R1001 - Reading Area - 101.48 m2</b>								
No Asbestos								
<b>B00A - R1002 - Movement - 6.96 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00A - R1003 - Security Store - 8.83 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00A - R1004 - Personal Effects Storage - 15.83 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00A - R1005 - Toilets - Girls - 3.35 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00A - R1006 - Cleaning Distributed Store - 2.19 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00A - R1007 - Toilets - Boys - 3.34 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							
<b>B00A - R1008 - Movement - 86.08 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )							
<b>B00A - R1009 - Practical Activities - 1hb - 19.93 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							

<b>B00A - R1010 - Home Base - 49.34 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1011 - Security Store - 9.7 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1012 - Withdrawal Space - 1hb - 9.88 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1013 - Practical Activities - 1hb - 22.58 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1014 - Home Base - 52.04 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1015 - Home Base - 55.38 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1016 - Practical Activities - 1hb - 18.94 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1017 - Staff Room Annexe - 9.22 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1018 - Withdrawal Space - 1hb - 9.7 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1019 - Practical Activities - 1hb - 20.63 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1020 - Home Base - 54.67 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1021 - Security Store - 17.72 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1022 - Distribution Board - .44 m2</b>		
Door - Lining	Flat AC Sheeting	<b>Note: No inspection of live electrical installation</b>
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1023 - Home Base - 52.36 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1024 - Practical Activities - 1hb - 22.77 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1025 - Withdrawal Space - 1hb - 9.8 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1026 - Security Store - 9.6 m2</b>		



Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1027 - Home Base - 49.64 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )	
<b>B00A - R1028 - Practical Activities - 1hb - 20.43 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1029 - Movement - 15.72 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1030 - Toilets - Boys - 3.33 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1031 - Cleaning Distributed Store - 2.12 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1032 - Toilets - Girls - 3.3 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1033 - Movement - 6.93 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1034 - Staff Room Annexe - 9.06 m2</b>		
Floor Coverings Res/Textile	Vinyl Tiles	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )	
<b>B00A - R1035 - Seminar/Study - 28.59 m2</b>		
No Asbestos		
<b>B00A - R1036 - Stairs - 2.67 m2</b>		
No Asbestos		
<b>B00A - R1037 - Stairs - 4.98 m2</b>		
No Asbestos		
<b>B00A - R1038 - Stairs - 5.84 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R1039 - Stairs - 6.59 m2</b>		
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )	
<b>B00A - R9001 - General Storeroom - 17.99 m2</b>		
No Asbestos		
<b>B00A - R9002 - Main Switch Board - 8.46 m2</b>		
No Asbestos		
<b>B00A - R9011 - External Movement - 1.26 m2</b>		
No Asbestos		
<b>B00A - R9012 - External Movement - 1.26 m2</b>		
No Asbestos		
<b>B00A - R9013 - Drinking Facilities - 1.26 m2</b>		
No Asbestos		
<b>B00A - R9021 - Hall Chair Store - 9.48 m2</b>		
No Asbestos		
<b>B00A - R9022 - Movement - 4.47 m2</b>		
No Asbestos		

Non Accessible						
<b>B00A - R9023 - Cleaning Distributed Store - 2.69 m2</b>						
No Asbestos						
Non Accessible						
<b>B00A - R9024 - General Storeroom - 15.34 m2</b>						
No Asbestos						
<b>B00A - R9025 - Movement - 10.84 m2</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
<b>B00A - R9026 - Stairs - 4.36 m2</b>						
Non Accessible						
<b>B00A - R9031 - Communal/Performance Store - 9.92 m2</b>						
No Asbestos						
<b>B00A - R9032 - Hall Chair Store - 9.65 m2</b>						
No Asbestos						
<b>B00A - R9033 - Access Shower/Toilet - 7.28 m2</b>						
No Asbestos						
<b>B00A - R9034 - P.E Store - 17.4 m2</b>						
No Asbestos						
<b>B00A - R9035 - Sound Cupboard - 2.91 m2</b>						
No Asbestos						
<b>B00A - R9036 - Communal Space - 182.03 m2</b>						
No Asbestos						
<b>B00A - R9037 - Movement - 11.32 m2</b>						
No Asbestos						
<b>B00A - R9038 - Raised Platform - 48.52 m2</b>						
No Asbestos						
<b>B00A - R9039 - Ramp - 6.07 m2</b>						
No Asbestos						
<b>B00A - R9040 - Movement - 6.03 m2</b>						
No Asbestos						
<b>B00A - R9041 - Covered Outdoor Learning Area - 185.95 m2</b>						
No Asbestos						
<b>B00A - R9042 - External Stairs - 12.09 m2</b>						
No Asbestos						
<b>B00B - General Learning/Communal Facilities - 1977 - Brick/Block</b>						
<b>Exterior</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
<b>Interior</b>						
<b>B00B - R0001 - External Movement - 3.74 m2</b>						
No Asbestos						
<b>B00B - R0002 - Staff Room Annexe - 9.89 m2</b>						
No Asbestos						
<b>B00B - R0003 - Teachers Aide Special Ed - 13.3 m2</b>						
No Asbestos						
<b>B00B - R0004 - Movement - 51.22 m2</b>						
No Asbestos						
<b>B00B - R0005 - Raised Platform - 31.35 m2</b>						
No Asbestos						
<b>B00B - R0006 - Communal Space - 44.87 m2</b>						
No Asbestos						

<b>B00B - R0007 - Communal Space - 56.44 m2</b>							
No Asbestos							
<b>B00B - R0008 - Cleaning Distributed Store - 2.7 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R0009 - Distribution Board - .44 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Door - Lining	Flat AC Sheeting	1	All surfaces	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	<b>Chrysotile (white asbestos)</b>
<b>B00B - R0010 - External Movement - 1.65 m2</b>							
No Asbestos							
<b>B00B - R0011 - Stairs - 2.02 m2</b>							
No Asbestos							
<b>B00B - R1001 - Toilets - Boys - 2.28 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R1002 - Cleaning Distributed Store - 1.83 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R1003 - Special Programs Room - 52.48 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R1004 - Home Base - 52.41 m2</b>							
No Asbestos							
<b>B00B - R1005 - Home Base - 57.59 m2</b>							
No Asbestos							
<b>B00B - R1006 - General Storeroom - 5.51 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R1007 - Movement - 3.46 m2</b>							
No Asbestos							
<b>B00B - R1008 - Toilets - Girls - 1.84 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00B - R1009 - Movement - 29.59 m2</b>							
No Asbestos							
<b>B00B - R1010 - Stairs - 4.79 m2</b>							
No Asbestos							
<b>B00C - Other-After School Care - 1887 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0001 - Out Of School Hours Care Centre - 13.95 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00C - R0003 - Home Base - Pre - 74.03 m2</b>							
No Asbestos							
<b>B00C - R0004 - Garden Store - 7.38 m2</b>							
No Asbestos							
<b>B00C - R0005 - Sports Store - 3.3 m2</b>							
No Asbestos							
<b>B00C - R0006 - External Movement - 13.36 m2</b>							
No Asbestos							
<b>B00C - R0007 - External Movement - 14.68 m2</b>							

No Asbestos							
<b>B00C - R0008 - External Movement - 46.96 m2</b>							
No Asbestos							
<b>B00D - Pupil Facilities - 1887 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Toilets - Girls - 17.26 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0002 - Toilets - Boys - 17.17 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - Pre-School Facilities - 1887 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0010 - General Storeroom - 3.87 m2</b>							
No Asbestos							
<b>B00E - R0011 - General Storeroom - 7.35 m2</b>							
No Asbestos							
<b>B00E - R0012 - Laundry - Pre - 5.65 m2</b>							
No Asbestos							
<b>B00E - R0013 - General Storeroom - 5.58 m2</b>							
No Asbestos							
<b>B00E - R0014 - Practical Activities - Pre - 11.15 m2</b>							
No Asbestos							
<b>B00E - R0015 - Home Base - Pre - 58.54 m2</b>							
No Asbestos							
<b>B00E - R0016 - Toilets-Unisex - 12.05 m2</b>							
No Asbestos							
<b>B00E - R0017 - Kitchen - Pre - 4.87 m2</b>							
No Asbestos							
<b>B00E - R0018 - Staff Room - 17.96 m2</b>							
No Asbestos							
<b>B00E - R0019 - Staff Toilet - 1.74 m2</b>							
No Asbestos							
<b>B00E - R0020 - Movement - 3.42 m2</b>							
No Asbestos							
<b>B00E - R0021 - Movement - 3.65 m2</b>							
No Asbestos							
<b>B00E - R0022 - External Movement - 25.03 m2</b>							
No Asbestos							
<b>B00E - R0023 - No Access - .27 m2</b>							
No Asbestos							
<b>B00G - Other - 2006 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

<b>Interior</b>		
<b>B00G - R0001 - Plant - 3.27 m2</b>		
No Asbestos		
<b>B00H - Other - 2007 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0001 - General Storeroom - 21.73 m2</b>		
No Asbestos		
<b>B00J - Other - 2007 - Metal Shed</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00J - R0001 - General Storeroom - 7.72 m2</b>		
No Asbestos		
<b>B00K - Pupil Facilities/Other - 2011 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - Canteen - 26.42 m2</b>		
No Asbestos		
<b>B00K - R0002 - Canteen Office/Store - 9.24 m2</b>		
No Asbestos		
<b>B00K - R0003 - Toilets - Girls/Disabled Cubicle - 25 m2</b>		
No Asbestos		
<b>B00K - R0004 - Toilets - Boys/Disabled Cubicle - 15.29 m2</b>		
No Asbestos		
<b>B00K - R0005 - Cleaning Distributed Store - 1.51 m2</b>		
No Asbestos		
<b>B00K - R0006 - External Movement - 27.92 m2</b>		
No Asbestos		
<b>B00L - General Learning/Other - 2011 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00L - R0001 - Special Programs Room - 33.76 m2</b>		
No Asbestos		
<b>B00L - R0002 - Special Programs Store - 12.82 m2</b>		
No Asbestos		
<b>B00L - R0003 - Garden Store - 13.3 m2</b>		
No Asbestos		
<b>B00L - R0004 - General Assistant/Bulk Store - 15.72 m2</b>		
No Asbestos		
<b>B00L - R0005 - Sports Store - 12.56 m2</b>		
No Asbestos		

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020