

# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kellyville Public School (2274)
Region:	Western Sydney AMU
State Electorate:	Castle Hill
Local Government Area:	The Hills

Last Reviewed By:	WSP 14-MAY-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

2274 - Kellyville Public School  
Site Plan (12569)



1:949

Printed: 25-Jul-2020

# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Staff Facilities - 1898 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0002 - Staff Room - 98.15 m2</b>							
No Asbestos							
<b>B00A - R0003 - External Movement - 31.15 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	6m2	North, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0004 - Distribution Board - .34 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
No Asbestos							
<b>B00A - R0005 - General Storeroom - 19.09 m2</b>							
No Asbestos							
<b>B00B - Music - 1912 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00B - R0001 - External Movement - 16.65 m2</b>							
No Asbestos							
<b>B00B - R0002 - Special Programs Room - 44.36 m2</b>							
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	1m2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00C - Administration/General Learning - 1971 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	50m2	North, South, East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00C - R0001 - External Movement - 40.64 m2</b>							
No Asbestos							
<b>B00C - R0003 - Clerical Office - 19.08 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0009 - Main Switch Board - 8.26 m2</b>							
No Asbestos							
<b>B00C - R0010 - Staff Toilet - 5.22 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00C - R0013 - Security Store - 2.97 m2</b>							
No Asbestos							

<b>B00C - R0014 - Communications Room - 7.03 m2</b>							
No Asbestos							
<b>B00C - R0019 - Principal - 20.71 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0020 - Entry Vestibule - 29.59 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0021 - Movement - 18.45 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0022 - Sick Bay - Shower/Toilet - 7.58 m2</b>							
No Asbestos							
<b>B00C - R0023 - Sick Bay - 6.36 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0024 - Duplicating Workroom - 28.94 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0025 - Staff Toilet - 2.24 m2</b>							
Ceiling Structures/Linings - Decorative Coating	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00C - R0026 - Handwashing Facilities - 2.2 m2</b>							
Ceiling Structures/Linings - Decorative Coating	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00C - R0027 - Stairs - 3.55 m2</b>							
No Asbestos							
<b>B00C - R1002 - Home Base - 56.87 m2</b>							
No Asbestos							
<b>B00C - R1003 - Personal Effects Storage - 6.76 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1004 - Home Base Store - 6.75 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1006 - Home Base Store - 7.6 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1007 - Home Base Store - 6.8 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1008 - Personal Effects Storage - 6.79 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1009 - Home Base - 56.95 m2</b>							
No Asbestos							
<b>B00C - R1010 - Stairs - 5.9 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1011 - Movement - 55.5 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - General Learning/Administration - 1972 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	45m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	24	East, Upper portion, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00D - R0001 - External Movement - 71.52 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R0002 - Home Base - 59.11 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00D - R0003 - Home Base Store - 6.67 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Ceiling Structures/Linings - Decorative Coating	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0004 - Personal Effects Storage - 7.18 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0005 - Movement - 8.53 m2</b>							
No Asbestos							
<b>B00D - R0006 - Movement - 6.53 m2</b>							
No Asbestos							
<b>B00D - R0007 - Uniform Shop - 9.63 m2</b>							
No Asbestos							
<b>B00D - R0008 - Personal Effects Storage - 6.21 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0009 - Distribution Board - .87 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0010 - Home Base Store - 6.75 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0011 - Home Base - 58.63 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00D - R0015 - Interview - 15.52 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R0016 - Interview - 11.93 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R0017 - Movement - 7.47 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
<b>B00D - R0018 - Interview - 17.68 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R0019 - General Storeroom - 19.24 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00D - R0020 - Stairs - 1.57 m2</b>							
No Asbestos							
<b>B00D - R0021 - Stairs - 1.57 m2</b>							
No Asbestos							
<b>B00D - R1001 - Movement - 70.87 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R1002 - Home Base - 58.54 m2</b>							
No Asbestos							
<b>B00D - R1003 - Home Base Store - 6.75 m2</b>							
No Asbestos							
<b>B00D - R1004 - Personal Effects Storage - 7.31 m2</b>							
No Asbestos							
<b>B00D - R1005 - Movement - 6.53 m2</b>							
No Asbestos							
<b>B00D - R1006 - General Storeroom - 8.84 m2</b>							
No Asbestos							
<b>B00D - R1007 - Personal Effects Storage - 6.23 m2</b>							
No Asbestos							
<b>B00D - R1008 - Distribution Board - .87 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00D - R1009 - Home Base Store - 6.75 m2</b>							
No Asbestos							
<b>B00D - R1010 - Home Base - 58.87 m2</b>							
No Asbestos							
<b>B00D - R1011 - Home Base - 58.87 m2</b>							
No Asbestos							
<b>B00D - R1012 - Home Base Store - 6.75 m2</b>							
No Asbestos							
<b>B00D - R1013 - Personal Effects Storage - 7.26 m2</b>							
No Asbestos							
<b>B00D - R1014 - Stairs - 5.05 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9001 - External Movement - 24.53 m2</b>							
No Asbestos							
<b>B00D - R9002 - Toilets - Boys - 35.17 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	24m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9003 - Toilets - Girls - 37.55 m2</b>							

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South, East, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9004 - Cleaning Distributed Store - 8.26 m2</b>							
No Asbestos							
<b>B00D - R9005 - Movement - 4.49 m2</b>							
No Asbestos							
<b>B00D - R9006 - Stairs - 3.96 m2</b>							
No Asbestos							
<b>B00E - General Learning - 1955 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0002 - Home Base - 53.88 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting						
<b>B00E - R0003 - Home Base - 53.8 m2</b>							
No Asbestos							
<b>B00E - R0004 - Other-Community Use - 13.43 m2</b>							
No Asbestos							
<b>B00E - R0005 - Other-Community Use - 12.92 m2</b>							
No Asbestos							
<b>B00E - R0006 - Home Base Store - 4.97 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R0007 - Practical Activities - 2hb - 34.52 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00H - General Learning - 1969 - Brick/Veneer</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	10	East, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00H - R0001 - External Movement - 44.14 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0002 - Personal Effects Storage - 7.27 m2</b>							
No Asbestos							
<b>B00H - R0003 - Home Base Store - 6.32 m2</b>							

No Asbestos							
<b>B00H - R0004 - Home Base - 56.8 m2</b>							
No Asbestos							
<b>B00H - R0005 - Home Base - 85.27 m2</b>							
No Asbestos							
<b>B00H - R0006 - Toilets - Boys/Girls - 3.59 m2</b>							
Wall Linings Internal	Flat AC Sheeting	8m2	North, South, East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0007 - Home Base Store - 3.13 m2</b>							
No Asbestos							
<b>B00H - R0008 - Personal Effects Storage - 7.2 m2</b>							
No Asbestos							
<b>B00H - R9001 - P.E Store - 28.31 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00I - General Learning/Pupil Facilities - 1962 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	80m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	East & West	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00I - R0001 - Home Base Store - 5.62 m2</b>							
No Asbestos							
<b>B00I - R0002 - Personal Effects Storage - 7.71 m2</b>							
No Asbestos							
<b>B00I - R0003 - External Movement - 4.86 m2</b>							
No Asbestos							
<b>B00I - R0004 - Home Base - 56.77 m2</b>							
No Asbestos							
<b>B00I - R0005 - Home Base - 78.33 m2</b>							
No Asbestos							
<b>B00I - R0006 - External Movement - 4.83 m2</b>							
No Asbestos							
<b>B00I - R0007 - Personal Effects Storage - 6.01 m2</b>							
No Asbestos							
<b>B00I - R0008 - Home Base Store - 5.91 m2</b>							
No Asbestos							
<b>B00I - R0009 - Toilets - Boys/Girls - 1.76 m2</b>							
Wall Linings Internal	Flat AC Sheeting	15m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00I - R0010 - Toilets - Girls - 29.31 m2</b>							
No Asbestos							
<b>B00I - R0011 - Disabled Toilet - 5.69 m2</b>							
No Asbestos							
<b>B00I - R0012 - Toilets - Boys - 20.43 m2</b>							



No Asbestos							
<b>B00J - General Learning - 1969 - Brick/Veneer</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	35m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	17	South, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00J - R0001 - External Movement - 65.41 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0002 - Personal Effects Storage - 8.46 m2</b>							
No Asbestos							
<b>B00J - R0003 - Home Base Store - 4.92 m2</b>							
No Asbestos							
<b>B00J - R0004 - Home Base - 57.83 m2</b>							
No Asbestos							
<b>B00J - R0005 - Home Base - 57.6 m2</b>							
No Asbestos							
<b>B00J - R0006 - Home Base Store - 4.89 m2</b>							
No Asbestos							
<b>B00J - R0007 - Personal Effects Storage - 8.43 m2</b>							
No Asbestos							
<b>B00J - R0008 - Withdrawal Space - 2hb - 14.59 m2</b>							
No Asbestos							
<b>B00J - R0009 - General Storeroom - 7.07 m2</b>							
No Asbestos							
<b>B00J - R0016 - Cleaning Distributed Store - 3.13 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0017 - Practical Activities - 1hb - 16.52 m2</b>							
No Asbestos							
<b>B00J - R0018 - Home Base - 57.33 m2</b>							
No Asbestos							
<b>B00J - R9001 - General Assistant/Bulk Store - 58.15 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00J - R9002 - General Assistant/Bulk Store - 187.37 m2</b>							
No Asbestos							
<b>B00K - Other-After School Care - 1995 - Steel</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						

Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - Withdrawal - Pre - 18.12 m2</b>		
No Asbestos		
<b>B00K - R0002 - Other-Community Use - 36.8 m2</b>		
No Asbestos		
<b>B00K - R0003 - Kitchen - Pre - 13.68 m2</b>		
No Asbestos		
<b>B00K - R0004 - Toilets - Boys/Girls - Pre - 2.86 m2</b>		
No Asbestos		
<b>B00K - R0005 - Toilets - Boys/Girls - Pre - 5.68 m2</b>		
No Asbestos		
<b>B00K - R0006 - Withdrawal - Pre - 6.79 m2</b>		
No Asbestos		
<b>B00K - R0007 - Practical Activities - Pre - 6.69 m2</b>		
No Asbestos		
<b>B00K - R0008 - Staff Room - Pre - 8.76 m2</b>		
No Asbestos		
<b>B00K - R0009 - External Movement - 7.46 m2</b>		
No Asbestos		
<b>B00L - Communal Facilities/Pupil Facilities - 1997 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
<b>Interior</b>		
<b>B00L - R0001 - Canteen - 45.73 m2</b>		
No Asbestos		
<b>B00L - R0002 - Canteen Office/Store - 10.75 m2</b>		
No Asbestos		
<b>B00L - R0003 - External Movement - 8.7 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00L - R0004 - Cleaning Distributed Store - 3.17 m2</b>		
No Asbestos		
<b>B00L - R0005 - Disabled Toilet - 6.14 m2</b>		
No Asbestos		
<b>B00L - R0006 - Distribution Board - .77 m2</b>		
No Asbestos		<b>Note: No inspection of live electrical installation</b>
<b>B00L - R0007 - P.E. Store - 14.74 m2</b>		
No Asbestos		
<b>B00L - R0008 - Plant - .6 m2</b>		
No Asbestos		
<b>B00L - R0009 - Hall Chair Store - 10.06 m2</b>		
No Asbestos		
<b>B00L - R0010 - Toilets - Boys - 5.86 m2</b>		
No Asbestos		
<b>B00L - R0011 - Shower/Change - 2.51 m2</b>		
No Asbestos		
<b>B00L - R0012 - Toilets - Girls - 7.75 m2</b>		
No Asbestos		
<b>B00L - R0013 - External Movement - 14.77 m2</b>		

Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00L - R0014 - Community Clinic - 17.99 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00L - R0015 - Community Clinic - 2.45 m2</b>		
No Asbestos		
<b>B00L - R0016 - Community Clinic - 6.98 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00L - R0017 - External Movement - 14.8 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00L - R0018 - Raised Platform - 47.18 m2</b>		
No Asbestos		
<b>B00L - R0019 - Communal Space - 214.65 m2</b>		
No Asbestos		
<b>B00L - R0020 - External Movement - 149.27 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00M - Library/Staff Facilities - 1998 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
<b>Interior</b>		
<b>B00M - R0001 - Reading Area - 224.04 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00M - R0002 - Communications Room - 13.97 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00M - R0003 - Staff Toilet - 4.08 m2</b>		
No Asbestos		
<b>B00M - R0004 - No Access - 3.81 m2</b>		
No Asbestos		
<b>B00M - R0005 - Library Office/Workroom - 31.5 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00M - R0006 - Distribution Board - .81 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00M - R0007 - External Movement - 3.95 m2</b>		
No Asbestos		
<b>B00M - R0008 - External Movement - 55.67 m2</b>		
No Asbestos		
<b>B00N - General Learning - 2007 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00N - R0005 - External Movement - 43.07 m2</b>		
No Asbestos		
<b>B00N - R0006 - Practical Activities - 1hb - 19.48 m2</b>		
No Asbestos		
<b>B00N - R0007 - Home Base Store - 6.15 m2</b>		

No Asbestos		
<b>B00N - R0008 - Home Base - 60.6 m2</b>		
No Asbestos		
<b>B00N - R0009 - Withdrawal Space - 2hb - 11.35 m2</b>		
No Asbestos		
<b>B00N - R0010 - Home Base - 60.74 m2</b>		
No Asbestos		
<b>B00N - R0011 - Home Base Store - 6.19 m2</b>		
No Asbestos		
<b>B00N - R0012 - Practical Activities - 1hb - 19.51 m2</b>		
No Asbestos		
<b>B00O - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00O - R0001 - External Movement - 43.37 m2</b>		
No Asbestos		
<b>B00O - R0002 - Practical Activities - 1hb - 19.57 m2</b>		
No Asbestos		
<b>B00O - R0003 - Home Base Store - 6.09 m2</b>		
No Asbestos		
<b>B00O - R0004 - Home Base - 60.82 m2</b>		
No Asbestos		
<b>B00O - R0005 - Withdrawal Space - 2hb - 11.51 m2</b>		
No Asbestos		
<b>B00O - R0006 - Home Base - 60.78 m2</b>		
No Asbestos		
<b>B00O - R0007 - Home Base Store - 6.31 m2</b>		
No Asbestos		
<b>B00O - R0008 - Practical Activities - 1hb - 19.53 m2</b>		
No Asbestos		
<b>B00P - General Learning - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00P - R0001 - External Movement - 43.36 m2</b>		
No Asbestos		
<b>B00P - R0002 - Practical Activities - 1hb - 19.58 m2</b>		
No Asbestos		
<b>B00P - R0003 - Home Base Store - 6.08 m2</b>		
No Asbestos		
<b>B00P - R0004 - Home Base - 60.6 m2</b>		
No Asbestos		
<b>B00P - R0005 - Withdrawal Space - 2hb - 11.54 m2</b>		
No Asbestos		
<b>B00P - R0006 - Home Base - 60.8 m2</b>		
No Asbestos		
<b>B00P - R0007 - Home Base Store - 6.09 m2</b>		
No Asbestos		

<b>B00P - R0008 - Practical Activities - 1hb - 19.51 m2</b>	
No Asbestos	
<b>B00Q - General Learning/Other - 2007 - Steel</b>	
<b>Exterior</b>	
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found
<b>Interior</b>	
<b>B00Q - R0001 - External Movement - 20.84 m2</b>	
No Asbestos	
<b>B00Q - R0002 - Special Programs Room - 70.23 m2</b>	
No Asbestos	
<b>B00Q - R0003 - Special Programs Store - 8.65 m2</b>	
No Asbestos	
<b>B00Q - R0004 - Withdrawal Space - 1hb - 8.46 m2</b>	
No Asbestos	

## Demountables

### OS 602 10268 - Learning Unit - Standard With P.A.A. - Placement Date : 10-FEB-2009

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 12616 - Learning Unit - Standard With P.A.A. - Placement Date : 17-NOV-2015

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 12770 - Learning Unit - Standard With P.A.A. - Placement Date : 28-NOV-2014

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 13143 - Learning Unit - Standard With P.A.A A/C - Placement Date : 06-OCT-2016

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 13418 - Learning Unit - Standard With P.A.A A/C - Placement Date : 03-MAY-2017

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 13710 - Learning Unit - Standard With P.A.A. - Placement Date : 10-JAN-2018

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 14457 - Learning Unit - Standard With P.A.A. - Placement Date : 30-NOV-2016

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 15012 - Learning Unit - Standard With P.A.A. - Placement Date : 06-OCT-2016

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 15285 - Learning Unit - Standard With P.A.A. - Placement Date : 02-DEC-2015

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 606 19066 - Learning Unit - Standard With P.A.A A/C - Placement Date : 18-OCT-2017

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found