

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kent Road Public School (4160)
Region:	Northern Sydney AMU
State Electorate:	Ryde
Local Government Area:	Ryde

Last Reviewed By:	Greencap 13-AUG-2014
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1960 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - External Movement - 4.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0002 - Movement - 13.74 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0003 - Deputy Principal - 17.59 m2							
No Asbestos							
B00A - R0004 - Plant - .44 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0005 - General Storeroom - .42 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0006 - Cleaning Distributed Store - 2.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0007 - Personal Effects Storage - 9.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0008 - Home Base Store - 2.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0009 - Home Base - 65.01 m2							
No Asbestos							
B00A - R0010 - Home Base - 88.75 m2							
No Asbestos							
B00A - R0011 - Practical Activities - 1hb - 2.38 m2							
No Asbestos							
B00A - R0012 - Home Base Store - 2.54 m2							
No Asbestos							
B00A - R0013 - Personal Effects Storage - 9.63 m2							
No Asbestos							
B00A - R0014 - Toilets - Boys/Girls - 1.6 m2							
No Asbestos							

B00A - R0015 - Movement - 8.1 m2							
No Asbestos							
B00A - R0016 - External Movement - 3.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0017 - External Movement - 64.5 m2							
No Asbestos							
B00B - General Learning - 1966 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - Movement - 8.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0002 - Home Base - 65.37 m2							
No Asbestos							
B00B - R0003 - Home Base Store - 2.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0004 - Personal Effects Storage - 9.24 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0005 - Movement - 15.78 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0006 - Deputy Principal - 19.13 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0007 - General Storeroom - 2.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0008 - Personal Effects Storage - 9.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0009 - Home Base Store - 2.58 m2							
No Asbestos							
B00B - R0010 - Home Base - 65.19 m2							
No Asbestos							
B00C - General Learning - 1969 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - External Movement - 4.75 m2							

Ceiling Structures/Linings	Flat AC Sheeting							
B00C - R0002 - Home Base - 57.46 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00C - R0003 - Home Base Store - 3.99 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
Floor Coverings Res/Textile	Vinyl Tiles							
B00C - R0004 - Personal Effects Storage - 11.63 m2								
No Asbestos								
B00C - R0005 - Movement - 4.68 m2								
No Asbestos								
B00C - R0006 - Home Base - 57.46 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
B00C - R0007 - Staff Room - 22.88 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
B00C - R0008 - Movement - 6.18 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
Floor Coverings Res/Textile	Vinyl Tiles							
B00C - R0009 - External Movement - 4.88 m2								
Ceiling Structures/Linings	Flat AC Sheeting							
B00D - General Learning - 1968 - Brick/Veneer								
Exterior								
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Ceiling Voids	Non Accessible Area							
Underfloor Voids	No Asbestos Found							
Interior								
B00D - R0001 - External Movement - 4.67 m2								
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00D - R0002 - Movement - 2.96 m2								
No Asbestos								
B00D - R0003 - Personal Effects Storage - 4.15 m2								
No Asbestos								
B00D - R0004 - Toilets - Boys/Girls - 3.44 m2								
Wall Linings Internal	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0005 - Home Base - 85.43 m2								
No Asbestos								
B00D - R0006 - Home Base Store - 3.03 m2								
No Asbestos								
B00D - R0007 - Home Base - 56.9 m2								
No Asbestos								
B00D - R0008 - Home Base Store - 4.25 m2								
No Asbestos								

B00D - R0009 - Personal Effects Storage - 6.88 m2							
No Asbestos							
B00D - R0010 - Movement - 2.31 m2							
No Asbestos							
B00D - R0011 - External Movement - 4.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R9001 - Cleaning Supplies - 12.96 m2							
No Asbestos							
B00E - General Learning - 1960 - Brick/Veneer							
Exterior							
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Interior							
B00E - R0001 - Movement - 23.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	North facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0007 - Cleaning Supplies - 5.69 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00E - R0008 - Out Of School Hours Care Centre - 88.63 m2							
No Asbestos							
B00E - R0009 - Home Base Store - 3.73 m2							
No Asbestos							
B00E - R0010 - Covered Area - 45.5 m2							
No Asbestos							
B00H - Other-Commercial - 1960 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00H - R0001 - Other-Commercial - 6.48 m2							
No Asbestos							
B00H - R0002 - Other-Commercial - 21.19 m2							
No Asbestos							
B00H - R0003 - Special Programs Room - 86.46 m2							
No Asbestos							
B00H - R0004 - Other-Commercial - 32.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	8m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - General Learning - 1960 - Brick/Veneer							
Exterior							

Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00I - R0009 - Special Programs Room - Type 1 - 144 m2							
Require Inspection							
B00I - R0010 - External Movement - 58.39 m2							
Require Inspection							
B00J - General Learning/Administration - 1992 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Gable Verge Lining	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids	AC Fragments/Debris						
Interior							
B00J - R0021 - Plant - 16.02 m2							
Require Inspection							
B00J - R0022 - Distribution Board - .78 m2							
							Note: No inspection of live electrical installation
Require Inspection							
B00J - R0023 - Reading Area - 284.08 m2							
Require Inspection							
B00J - R0024 - Library Office/Workroom - 15.57 m2							
Require Inspection							
B00J - R0025 - K.L.A. Store - 20.25 m2							
Require Inspection							
B00J - R0026 - Staff Toilet - 5.71 m2							
Require Inspection							
B00J - R0027 - K.L.A. Store - 19.86 m2							
Require Inspection							
B00J - R0028 - External Movement - 78.69 m2							
Require Inspection							
B00L - Pupil Facilities - 1966 - Brick/Block							
Exterior							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00L - R0001 - Toilets - Girls - 32.5 m2							
No Asbestos							
B00L - R0002 - Cleaning Distributed Store - 7.63 m2							
No Asbestos							
B00L - R0003 - Toilets - Boys - 36.91 m2							
No Asbestos							
B00L - R0004 - Handwashing Facilities - 25.5 m2							
No Asbestos							
B00L - R0005 - General Storeroom - 7.63 m2							
Wall Linings Internal	Flat AC Sheeting						

B00M - Pupil Facilities - 1960 - Brick/Block

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
---------------------------	-------------------

Underfloor Voids	No Asbestos Found
------------------	-------------------

Interior

B00M - R0001 - Toilets - Boys - 49.53 m2

No Asbestos

B00M - R0002 - Handwashing Facilities - 21.99 m2

No Asbestos

B00M - R0003 - Handwashing Facilities - 18.59 m2

No Asbestos

B00M - R0004 - No Access - 41.91 m2

No Asbestos

B00N - Communal Facilities - 1960 - Brick/Block

Exterior

Eaves Linings	Flat AC Sheeting
---------------	------------------

Ceiling Voids	No Asbestos Found
---------------	-------------------

Underfloor Voids	No Asbestos Found
------------------	-------------------

Interior

B00N - R0006 - P.E Store - 12.88 m2

No Asbestos

B00N - R0007 - Hall Chair Store - 9.68 m2

No Asbestos

B00N - R0008 - Toilets - Girls - 15.49 m2

No Asbestos

B00N - R0009 - Shower/Change - 2.7 m2

No Asbestos

B00N - R0010 - Movement - 9.48 m2

No Asbestos

B00N - R0011 - Raised Platform - 49.28 m2

No Asbestos

B00N - R0013 - Movement - 7.75 m2

No Asbestos

B00N - R0014 - Toilets - Boys - 15.52 m2

No Asbestos

B00N - R0015 - Plant - .63 m2

No Asbestos

B00N - R0016 - General Assistant/Bulk Store - 14.58 m2

No Asbestos

B00N - R0017 - Garden Store - 7.84 m2

No Asbestos

B00N - R0018 - General Storeroom - 8.53 m2

No Asbestos

B00N - R0019 - Disabled Toilet - 5.33 m2

No Asbestos

B00N - R0020 - Cleaning Distributed Store - 2.16 m2

No Asbestos

B00N - R0021 - Movement - 4.77 m2

No Asbestos

B00N - R0022 - Movement - 4.77 m2	
No Asbestos	
B00N - R0023 - Plant - .63 m2	
No Asbestos	
B00N - R0027 - General Storeroom - 8.36 m2	
No Asbestos	
B00N - R0028 - General Storeroom - 18.61 m2	
No Asbestos	
B00N - R0031 - Distribution Board - 3.49 m2	Note: No inspection of live electrical installation
No Asbestos	
B00N - R0032 - External Movement - 79.78 m2	
Require Inspection	
B00N - R0033 - Covered Outdoor Learning Area - 38.52 m2	
Require Inspection	
B00N - R0034 - External Stairs - 4.46 m2	
Require Inspection	
B00N - R0035 - Communal Space - 312.18 m2	
Require Inspection	

Demountables

OS 844 10118 - Country Toilet - Reltc - Boys/Girls - Placement Date : 11-APR-2019

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 837 10468 - Disabled Toilet, Shower Change room - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 801 10549 - FSU - Placement Date : 12-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 10917 - Learning Unit - Standard With P.A.A. - Placement Date : 10-JAN-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 502 10996 - Admin Staff/Principal/Clerk/Dup/Clinic - Placement Date : 20-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11962 - Learning Unit - Standard With P.A.A. - Placement Date : 01-NOV-2013

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 840 12048 - Girls Toilet - Placement Date : 11-APR-2019

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12632 - Learning Unit - Standard With P.A.A. - Placement Date : 10-SEP-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12850 - Learning Unit - Standard With P.A.A. - Placement Date : 26-NOV-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12876 - Learning Unit - Standard With P.A.A. - Placement Date : 15-NOV-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 840 12907 - Girls Toilet - Placement Date : 12-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 12927 - Learning Unit - Standard/Withdrawal - Placement Date : 14-JAN-2015

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior			
R1- Entry			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos
R2- General Learning Space			
End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos
R3- Store			
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
OS 602 13269 - Learning Unit - Standard With P.A.A. - Placement Date : 28-JAN-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 13479 - Learning Unit - Standard With P.A.A. - Placement Date : 10-FEB-2016			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 13491 - Learning Unit - Standard With P.A.A. - Placement Date : 10-FEB-2016			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 841 14539 - Boys Toilet - Placement Date : 11-APR-2019			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 841 14645 - Boys Toilet - Placement Date : 12-DEC-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 15013 - Learning Unit - Standard With P.A.A. - Placement Date : 08-NOV-2016			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 15260 - Learning Unit - Standard With P.A.A. - Placement Date : 15-NOV-2012			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 534 16146 - Library/Group Study/Office/A V Store - Placement Date : 05-DEC-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 601 17120 - Learning Unit - Standard/Withdrawal - Placement Date : 15-MAY-2013			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 18285 - Learning Unit - Standard With P.A.A. - Placement Date : 17-JUL-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 18286 - Learning Unit - Standard With P.A.A. - Placement Date : 28-JUL-2017			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 602 18356 - Learning Unit - Standard With P.A.A. - Placement Date : 08-SEP-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			
No Asbestos Found			
OS 606 19013 - Learning Unit - Standard With P.A.A A/C - Placement Date : 05-JAN-2018			
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.			

No Asbestos Found

OS 606 19565 - Learning Unit - Standard With P.A.A A/C - Placement Date : 05-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19566 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19567 - Learning Unit - Standard With P.A.A A/C - Placement Date : 05-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19568 - Learning Unit - Standard With P.A.A A/C - Placement Date : 05-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19569 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19570 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19571 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19572 - Learning Unit - Standard With P.A.A A/C - Placement Date : 04-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 520 70142 - Staff Study - Placement Date : 20-DEC-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found