

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Kingswood South Public School (4339)</b>
<b>Region:</b>	<b>Western Sydney AMU</b>
<b>State Electorate:</b>	<b>Penrith</b>
<b>Local Government Area:</b>	<b>Penrith</b>

<b>Last Reviewed By:</b>	<b>WSP 09-MAR-2015</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration - 1970 - Fibre Cement Clad</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Community Clinic - 7 m2</b>							
No Asbestos							
<b>B00A - R0002 - Community Clinic - 4.38 m2</b>							
No Asbestos							
<b>B00A - R0003 - Community Clinic - 11.64 m2</b>							
No Asbestos							
<b>B00B - General Learning/Other-Community Use - 1934 - Brick/Block</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting						
Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	Fibre Cement Pipe	0.5	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Packing						
Underfloor Voids	Fibre Cement Pipe		East	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Packing		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>Interior</b>							
<b>B00B - R0001 - Movement - 71.39 m2</b>							
No Asbestos							
<b>B00B - R0002 - General Storeroom - 10.57 m2</b>							
No Asbestos							
<b>B00B - R0003 - Movement - 3.08 m2</b>							
No Asbestos							
<b>B00B - R0004 - Movement - 4.77 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R0005 - Home Base - 56.46 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0006 - Home Base - 56.38 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0007 - Personal Effects Storage - 8.72 m2</b>							
No Asbestos							
<b>B00B - R0008 - Movement - 6.12 m2</b>							
No Asbestos							
<b>B00B - R0009 - Cleaning Distributed Store - .59 m2</b>							
No Asbestos							
<b>B00B - R0010 - Movement - 1.47 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R0011 - Cleaning Distributed Store - .58 m2</b>							
No Asbestos							
<b>B00B - R0012 - Personal Effects Storage - 8.73 m2</b>							
No Asbestos							
<b>B00B - R0013 - Home Base - 56.54 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0014 - Home Base - 85.1 m2</b>							
No Asbestos							
<b>B00B - R0015 - Movement - 3.15 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R0016 - Personal Effects Storage - 10.6 m2</b>							
No Asbestos							
<b>B00B - R0017 - Movement - 3.77 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R0018 - Toilets - Boys/Girls - 3.83 m2</b>							
Wall Linings Internal	Flat AC Sheeting	16m2	North, East, South, and Partition walls	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>B00C - Pupil Facilities - 1970 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0001 - Drinking Facilities - 12.11 m2</b>							
No Asbestos							
<b>B00C - R0002 - Toilets - Girls - 24.68 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0003 - Cleaning Distributed Store - 3.48 m2</b>							
No Asbestos							
<b>B00C - R0004 - Toilets - Boys - 28.7 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0005 - Drinking Facilities - 12.07 m2</b>							
No Asbestos							
<b>B00C - R0006 - General Storeroom - 3.53 m2</b>							
No Asbestos							
<b>B00D - General Learning/Support Unit - 1970 - Brick/Veneer</b>							
<b>Exterior</b>							

Wall Linings Internal - Infill	Flat AC Sheeting	10	West	Good Condition (1)	Low (1)	Low Priority (2-3)	
Gable Verge Lining	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting						
Ceiling Voids	Flat AC Sheeting						
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting						
Eaves Linings	Flat AC Sheeting	14m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00D - R0018 - External Movement - 4.76 m2</b>							
No Asbestos							
<b>B00D - R0019 - Entry Vestibule - 6.92 m2</b>							
No Asbestos							
<b>B00D - R0020 - Practical Activities - Pre - 39.91 m2</b>							
No Asbestos							
<b>B00D - R0021 - Home Base - Pre - 49.03 m2</b>							
No Asbestos							
<b>B00D - R0022 - Kitchen - Pre - 5.54 m2</b>							
No Asbestos							
<b>B00D - R0023 - Toilets - Boys/Girls - Pre - 11.33 m2</b>							
No Asbestos							
<b>B00D - R0024 - Laundry - Pre - 1.69 m2</b>							
No Asbestos							
<b>B00D - R0025 - General Storeroom - 14.32 m2</b>							
No Asbestos							
<b>B00D - R0026 - Clerical Office - Pre - 13.49 m2</b>							
No Asbestos							
<b>B00D - R0027 - Practical Activities - Pre - 25.54 m2</b>							
No Asbestos							
<b>B00D - R0028 - Practical Activities - Pre - 37.62 m2</b>							
No Asbestos							
<b>B00D - R0029 - Toilet - Lobby - 1.93 m2</b>							
No Asbestos							
<b>B00D - R0030 - Staff Toilet - 1.93 m2</b>							
No Asbestos							
<b>B00D - R0031 - General Storeroom - Pre - 5.98 m2</b>							
No Asbestos							
<b>B00D - R0032 - Toilets - Boys/Girls - Pre - 10.6 m2</b>							
No Asbestos							
<b>B00D - R0033 - Ramp - 22.82 m2</b>							
No Asbestos							
<b>B00E - General Learning/Building Services - 1970 - Brick/Veneer</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Flat AC Sheeting						
Underfloor Voids	Packing		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
<b>Interior</b>							
<b>B00E - R0001 - Home Base - 56.93 m2</b>							
No Asbestos							
<b>B00E - R0002 - Home Base Store - 10.55 m2</b>							
No Asbestos							
<b>B00E - R0003 - Personal Effects Storage - 6.68 m2</b>							
No Asbestos							
<b>B00E - R0004 - Movement - 9.76 m2</b>							
Wall Linings Internal - Splash back	Flat AC Sheeting	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - R0005 - External Movement - 4.51 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - R0006 - Home Base - 56.78 m2</b>							
No Asbestos							
<b>B00E - R0013 - External Movement - 4.6 m2</b>							
No Asbestos							
<b>B00E - R0014 - External Movement - 375.77 m2</b>							
No Asbestos							
<b>B00E - R0015 - Library Office/Workroom - 17.95 m2</b>							
No Asbestos							
<b>B00E - R0016 - Staff Toilet - 5.46 m2</b>							
No Asbestos							
<b>B00E - R0017 - K.L.A. Store - 19.11 m2</b>							
No Asbestos							
<b>B00E - R0018 - Reading Area - 96.32 m2</b>							
No Asbestos							
<b>B00E - R0019 - Staff Kitchen - 3.42 m2</b>							
No Asbestos							
<b>B00E - R9001 - General Assistant/Bulk Store - 145.7 m2</b>							
No Asbestos							
<b>B00E - R9002 - General Assistant/Bulk Store - 56.69 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - R9003 - General Assistant/Bulk Store - 86.41 m2</b>							
No Asbestos							
<b>B00F - Pupil Facilities - 1970 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00F - R0001 - Drinking Facilities - 13.96 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0002 - Toilets - Girls - 32 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubides)	Compressed AC Sheet	16m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - General Learning/Pupil Facilities - 1972 - Brick/Block</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00G- R0001 - Movement - 29.69 m2</b>							
No Asbestos							
<b>B00G- R0002 - Home Base - 60.08 m2</b>							
No Asbestos							
<b>B00G- R0003 - Practical Activities - 1hb - 16.4 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0004 - Toilets - Girls - 11.09 m2</b>							
Partition Walls (Cubides)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0005 - Movement - 6.45 m2</b>							
No Asbestos							
<b>B00G- R0006 - Distribution Board - .55 m2</b>							
No Asbestos							
<b>B00G- R0007 - General Storeroom - 11.3 m2</b>							
No Asbestos							
<b>B00G- R0008 - Stairs - 5.22 m2</b>							
No Asbestos							
<b>B00G- R1001 - Movement - 73.05 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R1002 - Home Base - 60.36 m2</b>							
No Asbestos							
<b>B00G- R1003 - Practical Activities - 1hb - 16.3 m2</b>							
No Asbestos							
<b>B00G- R1004 - Craft Store - 11.02 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R1005 - Cleaning Distributed Store - 4.1 m2</b>							
No Asbestos							
<b>B00G- R1006 - Home Base - 54 m2</b>							
No Asbestos							
<b>B00G- R1007 - Home Base - 54.25 m2</b>							
No Asbestos							
<b>B00G- R1008 - General Storeroom - 6.14 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R1009 - Sports Store - 4.8 m2</b>							
No Asbestos							
<b>B00G- R1010 - Toilets - Boys - 16.17 m2</b>							

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R1011 - Practical Activities - 1hb - 19.15 m2</b>							
No Asbestos							
<b>B00G- R1012 - Practical Activities - 1hb - 19.15 m2</b>							
No Asbestos							
<b>B00G- R1013 - Stairs - 14.14 m2</b>							
No Asbestos							
<b>B00H - Pupil Facilities - 1970 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00H - R0001 - Drinking Facilities - 14.01 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R0002 - Toilets - Boys - 36.19 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0003 - Sports Store - 4.37 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R0005 - Sports Store - 4.41 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R0006 - Cleaning Distributed Store - 1.32 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00I - Other-D.E.C. Admin/Communal Facilities - 1970 - Brick/Veneer</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Packing		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00I - R0005 - Other - Regional Use - 7.89 m2</b>							
No Asbestos							
<b>B00I - R0007 - Other - Regional Use - 2.01 m2</b>							
No Asbestos							
<b>B00I - R0015 - Home Base - P - 57.04 m2</b>							
No Asbestos							



<b>B00I - R0016 - Home Base Store - P - 4 m2</b>							
No Asbestos							
<b>B00I - R0017 - Personal Effects Storage - 11.4 m2</b>							
No Asbestos							
<b>B00I - R0018 - Movement - 7.33 m2</b>							
No Asbestos							
<b>B00I - R0019 - General Storeroom - 4 m2</b>							
No Asbestos							
<b>B00I - R0020 - Special Programs Room - 56.58 m2</b>							
No Asbestos							
<b>B00I - R0027 - Toilet - Lobby - 2.93 m2</b>							
No Asbestos							
<b>B00I - R0028 - Staff Toilet - 1.85 m2</b>							
No Asbestos							
<b>B00I - R0029 - Staff Toilet - 1.83 m2</b>							
No Asbestos							
<b>B00I - R0030 - Toilet - Lobby - 2.9 m2</b>							
No Asbestos							
<b>B00I - R0031 - Principal - 30.03 m2</b>							
No Asbestos							
<b>B00I - R0032 - Deputy Principal - 14.75 m2</b>							
No Asbestos							
<b>B00I - R0033 - Interview - 12.1 m2</b>							
No Asbestos							
<b>B00I - R0034 - Movement - 12.47 m2</b>							
No Asbestos							
<b>B00I - R0035 - Sick Bay - 9.74 m2</b>							
No Asbestos							
<b>B00I - R0036 - Staff Kitchen - 3.67 m2</b>							
No Asbestos							
<b>B00I - R0037 - Clerical Office/Workroom - 21.25 m2</b>							
No Asbestos							
<b>B00I - R0038 - Clerical Office - 29.21 m2</b>							
No Asbestos							
<b>B00I - R0039 - Entry Vestibule - 17.85 m2</b>							
No Asbestos							
<b>B00I - R0040 - Communal Space - 31.36 m2</b>							
No Asbestos							
<b>B00I - R0041 - Communal Space - 83.03 m2</b>							
No Asbestos							
<b>B00I - R0042 - Raised Platform - 27.97 m2</b>							
No Asbestos							
<b>B00I - R0043 - Uniform Shop - 12.44 m2</b>							
No Asbestos							
<b>B00I - R0044 - External Movement - 96.71 m2</b>							
No Asbestos							
<b>B00J - Staff Facilities/Pupil Facilities - 1964 - Brick/Veneer</b>							
<b>Exterior</b>							
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Ceiling Voids	No Asbestos Found							
Underfloor Voids	Packing		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>Interior</b>								
<b>B00J - R0001 - Canteen Office/Store - 1.96 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00J - R0002 - Canteen Office/Store - 2.75 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00J - R0003 - Canteen - 18.67 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00J - R0004 - Movement - 13.23 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00J - R0005 - Movement - 21.72 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00J - R0006 - Staff Room - 105.45 m2</b>								
No Asbestos								
<b>B00J - R0007 - Staff Room Annexe - 9.25 m2</b>								
No Asbestos								
<b>B00K - Building Services - 1970 - Brick/Block</b>								
<b>Exterior</b>								
Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Material - Packing	Packing							
<b>Interior</b>								
<b>B00K - R0001 - Garden Store - 7.56 m2</b>								
No Asbestos								
<b>B00L - General Learning - 1964 - Brick/Veneer</b>								
<b>Exterior</b>								
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Slab on Ground	No Asbestos Found							
Underfloor Voids	Non Accessible Area							
Ceiling Voids	Requires Inspection							

Interior							
<b>B00L - R0001 - Home Base - 57.63 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00L - R0002 - Movement - 1.52 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00L - R0003 - Movement - 5.28 m2</b>							
No Asbestos							
<b>B00L - R0004 - Personal Effects Storage - 9.24 m2</b>							
No Asbestos							
<b>B00L - R0005 - Personal Effects Storage - 9.2 m2</b>							
No Asbestos							
<b>B00L - R0006 - Home Base - 57.86 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00M - Administration - 1970 - Brick/Veneer</b>							
Exterior							
Gable Ends	Flat AC Sheeting	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Packing		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Lagging						
Interior							
<b>B00M - R0001 - Interview - 15.95 m2</b>							
No Asbestos							
<b>B00M - R0002 - Staff Toilet - 2.82 m2</b>							
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0003 - General Storeroom - .38 m2</b>							
No Asbestos							
<b>B00M - R0004 - Movement - 2.84 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0005 - Movement - 16.83 m2</b>							
No Asbestos							
<b>B00M - R0006 - External Movement - 1.4 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0007 - Entry Vestibule - 20.62 m2</b>							
No Asbestos							
<b>B00M - R0008 - Movement - 4.87 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

<b>B00M - R0009 - Principal - 14.47 m2</b>							
No Asbestos							
<b>B00M - R0010 - Staff Toilet - 1.54 m2</b>							
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00M - R0011 - Movement - 2.08 m2</b>							
No Asbestos							
<b>B00M - R0012 - General Storeroom - 2.99 m2</b>							
No Asbestos							
<b>B00M - R0013 - Main Switch Board - 1.64 m2</b>							
No Asbestos							
<b>B00M - R0014 - Clerical Office - 31.01 m2</b>							
No Asbestos							
<b>B00N - Pupil Facilities - 2008 - Metal Shed</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00N - R0001 - Sports Store - 16.59 m2</b>							
No Asbestos							
<b>B00O - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00O - R0001 - Communal Space - 146.85 m2</b>							
No Asbestos							
<b>B00O - R0002 - Raised Platform - 60.44 m2</b>							
No Asbestos							
<b>B00O - R0003 - Movement - 6.7 m2</b>							
No Asbestos							
<b>B00O - R0004 - Movement - 11.76 m2</b>							
No Asbestos							
<b>B00O - R0005 - Ramp - 11.74 m2</b>							
No Asbestos							
<b>B00O - R0006 - Hall Chair Store - 9.53 m2</b>							
No Asbestos							
<b>B00O - R0007 - Communal/Performance Store - 9.53 m2</b>							
No Asbestos							
<b>B00O - R0008 - P.E. Store - 13.05 m2</b>							
No Asbestos							
<b>B00O - R0009 - Toilet - Lobby - 2.29 m2</b>							
No Asbestos							
<b>B00O - R0010 - Toilets - Girls - 7.31 m2</b>							
No Asbestos							
<b>B00O - R0011 - Sound Cupboard - 1.98 m2</b>							
No Asbestos							
<b>B00O - R0012 - Toilet - Lobby - 3.11 m2</b>							

No Asbestos	
<b>B000 - R0013 - Toilets - Boys - 5.8 m2</b>	
No Asbestos	
<b>B000 - R0014 - Cleaning Distributed Store - 5.19 m2</b>	
No Asbestos	
<b>B000 - R0015 - Disabled Shower/Toilet - 6.87 m2</b>	
No Asbestos	
<b>B000 - R0016 - Main Switch Board - 3.33 m2</b>	
No Asbestos	
<b>B000 - R0017 - Covered Outdoor Learning Area - 150.6 m2</b>	
No Asbestos	
<b>B000 - R0018 - External Movement - 2.25 m2</b>	
No Asbestos	

## Demountables

### OS 602 11030 - Learning Unit - Standard With P.A.A. - Placement Date : 03-DEC-2014

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 12665 - Learning Unit - Standard With P.A.A. - Placement Date : 04-JAN-2010

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 602 13518 - Learning Unit - Standard With P.A.A. - Placement Date : 10-NOV-2015

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 621 19391 - Learning Unit Single - PWD - Placement Date : 15-OCT-2019

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found