

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kareela Public School (4488)
Region:	Sydney AMU
State Electorate:	Miranda
Local Government Area:	Sutherland

Last Reviewed By:	Greencap 28-SEP-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning/Pupil Facilities - 1976 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Ceiling Structures/Linings	Flat AC Sheeting	20	Between B00A & B00E	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00A - R0001 - External Movement - 52.44 m2							
Ceiling Structures/Linings	Flat AC Sheeting	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0002 - Toilets - Girls - 8.94 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0003 - Practical Activities - 1hb - 14.94 m2							
No Asbestos							
B00A - R0004 - Toilets - Boys/Girls - 3.26 m2							
No Asbestos							
B00A - R0005 - Home Base - 71.93 m2							
No Asbestos							
B00A - R0006 - Home Base - 73.19 m2							
No Asbestos							
B00A - R0007 - Practical Activities - 1hb - 14.06 m2							
No Asbestos							
B00A - R0008 - Toilets - Boys/Girls - 3.24 m2							
No Asbestos							
B00A - R0009 - Toilets - Boys - 8.72 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0010 - External Movement - 1.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0011 - Distribution Board - .68 m2							
Note: No inspection of live electrical installation							
Electrical - Backing Board	Resinous Board	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0012 - General Assistant/Bulk Store - 6.75 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R0013 - Cleaning Distributed Store - 1.95 m2							
No Asbestos							
B00A - R0014 - General Storeroom - 5.47 m2							
No Asbestos							
B00A - R0015 - General Storeroom - 11.59 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R0016 - External Movement - 71.67 m2							
Wall Linings Internal	Flat AC Sheeting	2m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	72m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0017 - External Movement - 33.55 m2							
No Asbestos							
B00B - Library/Pupil Facilities - 1989 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Ceiling Structures/Linings	Flat AC Sheeting	15	Between B00B and B0E	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	15	Between B00B and B00C	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00B - R0001 - External Movement - 48.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0003 - Toilets - Girls - 9.04 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Toilets - Boys - 9.04 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0006 - Distribution Board - 48 m2							
Note: No inspection of live electrical installation							
Electrical - Backing Board	Resinous Board	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - External Movement - 41.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0012 - External Movement - 226.15 m2							
No Asbestos							
B00B - R0013 - Movement - 9.57 m2							
No Asbestos							
B00B - R0014 - Library Office/Workroom - 18.01 m2							
No Asbestos							
B00B - R0015 - K.L.A. Store - 9.91 m2							
No Asbestos							
B00B - R0016 - Reading Area - 198.39 m2							
No Asbestos							
B00C - General Learning/Pupil Facilities - 1976 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						

Ceiling Structures/Linings	Flat AC Sheeting	15	Between B00B and B00C	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00C - R0001 - External Movement - 66.66 m2							
Ceiling Structures/Linings	Flat AC Sheeting	67m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	West, upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0002 - General Storeroom - 12.86 m2							
No Asbestos							
B00C - R0003 - Special Programs Room - 11.94 m2							
No Asbestos							
B00C - R0004 - Distribution Board - .53 m2							
Note: No inspection of live electrical installation							
Electrical - Backing Board	Resinous Board	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0005 - Toilets - Girls - 8.72 m2							
No Asbestos							
B00C - R0006 - External Movement - 40.78 m2							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	West, upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0007 - Practical Activities - 1hb - 15.57 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00C - R0008 - Home Base - 52.45 m2							
No Asbestos							
B00C - R0009 - Home Base - 52.45 m2							
No Asbestos							
B00C - R0010 - Practical Activities - 1hb - 15.65 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00C - R0011 - Toilets - Boys - 8.91 m2							
No Asbestos							
B00D - Communal Facilities/Pupil Facilities - 1980 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area						
Gable Verge Lining	Flat AC Sheeting	40m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Interior							
B00D - M0001 - General Storeroom - 23.76 m2							
Wall Linings Internal	Flat AC Sheeting	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - M0002 - General Storeroom - 23.78 m2							

Wall Linings Internal	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0001 - External Movement - 29.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0002 - Cleaning Distributed Store - 6.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00D - R0003 - Canteen Office/Store - 5.33 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles						
B00D - R0004 - Canteen Office/Store - 6.58 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00D - R0005 - Staff Toilet - 1.71 m2							
No Asbestos							
B00D - R0006 - Canteen - 26.26 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00D - R0007 - Distribution Board - 1.04 m2							
Note: No inspection of live electrical installation							
Electrical - Backing Board	Resinous Board	2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00D - R0008 - Movement - 6.71 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00D - R0009 - Toilets - Boys - 9.2 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0010 - Movement - .81 m2							
No Asbestos							
B00D - R0011 - Hall Chair Store - 4.94 m2							
No Asbestos							
B00D - R0012 - Communal Space - 149.43 m2							
No Asbestos							
B00D - R0013 - Hall Chair Store - 4.94 m2							
No Asbestos							
B00D - R0014 - Raised Platform - 61.85 m2							

Floor Coverings Res/Textile	Vinyl Sheet							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B00D - R0015 - Movement - .81 m2								
No Asbestos								
B00D - R0016 - Toilets - Girls - 9.26 m2								
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00D - R0017 - Movement - 6.68 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B00D - R0018 - Sports Store - 11.52 m2								
No Asbestos								
B00D - R0019 - Movement - 9.32 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B00D - R0020 - Cleaning Distributed Store - 10.2 m2								
No Asbestos								
B00D - R0032 - External Movement - 57.47 m2								
No Asbestos								
B00E - Administration/Staff Facilities - 1962 - Brick/Block								
Exterior								
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Underfloor Voids	Non Accessible Area							
Ceiling Voids - Raked Ceiling	Non Accessible Area							
Ceiling Voids	No Asbestos Found							
Ceiling Structures/Linings	Flat AC Sheeting	15	Between B00E and B00B	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	20	Between B00A and B00E	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Interior								
B00E - R0001 - External Movement - 67.21 m2								
Ceiling Structures/Linings	Flat AC Sheeting	68m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00E - R0002 - Staff Room - 73.87 m2								
Floor Coverings Res/Textile	Vinyl Tiles							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B00E - R0003 - Staff Toilet - 4.8 m2								
No Asbestos								
B00E - R0004 - Cleaning Distributed Store - 1.08 m2								
No Asbestos								
B00E - R0005 - Staff Toilet - 4.81 m2								
No Asbestos								
B00E - R0006 - Sick Bay - 14.81 m2								
No Asbestos								
B00E - R0007 - Staff Room Annexe - 10.28 m2								
No Asbestos								

B00E - R0008 - External Movement - 39.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0009 - General Storeroom - 25.31 m2							
No Asbestos							
B00E - R0010 - Security Store - 12.52 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Furniture / Fixtures - Safe / Vault	Encapsulated Asbestos material within unit	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00E - R0011 - Staff Room Annexe - 10.32 m2							
No Asbestos							
B00E - R0012 - Movement - 8.5 m2							
No Asbestos							
B00E - R0013 - External Movement - 17.09 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0014 - Main Switch Board - 6.34 m2							
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00E - R0015 - Deputy Principal - 15.86 m2							
No Asbestos							
B00E - R0016 - Principal - 21.59 m2							
No Asbestos							
B00E - R0017 - Entry Vestibule - 10.44 m2							
No Asbestos							
B00E - R0018 - Movement - 46.15 m2							
No Asbestos							
B00E - R0019 - Clerical Office - 11.33 m2							
No Asbestos							
B00E - R0020 - Duplicating Workroom - 23.28 m2							
No Asbestos							
B00E - R0022 - Staff Toilet - 3.31 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00E - R0023 - General Storeroom - 12.61 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00E - R0024 - Interview - 11.37 m2							
No Asbestos							
B00F - General Learning/Pupil Facilities - 1982 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	20m2	North and South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B00F - R0001 - External Movement - 102.02 m2							

Ceiling Structures/Linings	Flat AC Sheeting	103m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0002 - General Storeroom - 2.89 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00F - R0003 - Personal Effects Storage - 4.63 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00F - R0004 - Home Base - 61.41 m2							
No Asbestos							
B00F - R0005 - Home Base Store - 5.68 m2							
No Asbestos							
B00F - R0006 - Withdrawal Space - 1hb - 12.1 m2							
No Asbestos							
B00F - R0007 - Practical Activities - 1hb - 49.22 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00F - R0008 - Home Base - 61.16 m2							
No Asbestos							
B00F - R0009 - Home Base Store - 5.64 m2							
No Asbestos							
B00F - R0010 - Withdrawal Space - 1hb - 16.86 m2							
No Asbestos							
B00F - R0011 - Distribution Board - .73 m2							
						Note: No inspection of live electrical installation	
Electrical - Backing Board	Resinous Board	3	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0012 - Home Base - 59.88 m2							
No Asbestos							
B00F - R0013 - Home Base Store - 5.66 m2							
No Asbestos							
B00F - R0014 - Withdrawal Space - 1hb - 12.06 m2							
No Asbestos							
B00F - R0015 - Practical Activities - 1hb - 48.8 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Plant / Equipment - Kiln	Encapsulated Asbestos material within unit	1	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00F - R0016 - Home Base - 61.42 m2							
No Asbestos							
B00F - R0017 - Home Base Store - 5.66 m2							
No Asbestos							
B00F - R0018 - Personal Effects Storage - 4.65 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00F - R0019 - P.E Store - 2.91 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00F - R0020 - Special Programs Room - 34.78 m2							
No Asbestos							
B00F - R0021 - Cleaning Distributed Store - 5.44 m2							
No Asbestos							
B00F - R0022 - Toilets - Girls - 10.71 m2							
No Asbestos							

B00F - R0023 - Toilets - Boys - 14.65 m2							
No Asbestos							
B00F - R0024 - Staff Toilet - 3.76 m2							
No Asbestos							
B00G - General Learning - 2010 - Brick/Veneer							
Exterior							
Underfloor Voids	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00G - R0001 - External Movement - 45.07 m2							
No Asbestos							
B00G - R0002 - Home Base Store - 5.81 m2							
No Asbestos							
B00G - R0003 - Home Base - 59.1 m2							
No Asbestos							
B00G - R0004 - Withdrawal Space - 1hb - 8.49 m2							
No Asbestos							
B00G - R0005 - Special Programs Room - Type 2 - 90.07 m2							
No Asbestos							
B00G - R0006 - Special Programs Store - 12.36 m2							
No Asbestos							
B00G - R0007 - Practical Activities/Movement - 1hb - 18.29 m2							
No Asbestos							
B00H - General Learning/Pupil Facilities - 1976 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Gable Verge Lining	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00H - R0001 - External Movement - 85.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	86m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Security Store - 10.28 m2							
No Asbestos							
B00H - R0003 - Cleaning Distributed Store - 2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0004 - Special Programs Room - 41.38 m2							
No Asbestos							
B00H - R0005 - Home Base Store - 2.9 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0006 - Personal Effects Storage - 4.76 m2							
Floor Coverings Res/Textile	Vinyl Sheet						

B00H - R0007 - Home Base - 61.38 m2							
No Asbestos							
B00H - R0008 - Home Base Store - 5.63 m2							
No Asbestos							
B00H - R0009 - Withdrawal Space - 1hb - 12.05 m2							
No Asbestos							
B00H - R0010 - Practical Activities - 1hb - 49.58 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0011 - Home Base - 60.63 m2							
No Asbestos							
B00H - R0012 - Home Base Store - 5.59 m2							
No Asbestos							
B00H - R0013 - Withdrawal Space - 1hb - 17.16 m2							
No Asbestos							
B00H - R0014 - Distribution Board - .57 m2							Note: No inspection of live electrical installation
Electrical - Backing Board	Resinous Board	3	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0015 - Home Base - 60.3 m2							
No Asbestos							
B00H - R0016 - Home Base Store - 5.59 m2							
No Asbestos							
B00H - R0017 - Withdrawal Space - 1hb - 11.95 m2							
No Asbestos							
B00H - R0018 - Practical Activities - 1hb - 49.43 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Plant / Equipment - Kiln	Encapsulated Asbestos material within unit	1	Northeast	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00H - R0019 - Home Base Store - 5.59 m2							
No Asbestos							
B00H - R0020 - Home Base - 60.8 m2							
No Asbestos							
B00H - R0021 - Personal Effects Storage - 4.74 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0022 - Home Base Store - 2.92 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0023 - Home Base Store - 8.88 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00H - R0024 - Home Base - 61.48 m2							
No Asbestos							
B00H - R0025 - Home Base Store - 5.63 m2							
No Asbestos							
B00H - R0026 - Withdrawal Space - 1hb - 11.99 m2							
No Asbestos							
B00H - R0027 - Practical Activities - 1hb - 49 m2							
Floor Coverings Res/Textile	Vinyl Sheet						

B00H - R0028 - Home Base Store - 5.59 m2							
No Asbestos							
B00H - R0029 - Home Base - 61.52 m2							
No Asbestos							
B00H - R0030 - Personal Effects Storage - 4.16 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0031 - Home Base Store - 3.34 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B00H - R0032 - External Movement - 30.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0033 - Toilets - Girls - 10.63 m2							
No Asbestos							
B00H - R0034 - Toilets - Boys - 14.82 m2							
No Asbestos							
B00H - R0035 - Staff Toilet - 3.78 m2							
No Asbestos							

Demountables

OS 602 12437 - Learning Unit - Standard With P.A.A. - Placement Date : 29-JUN-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 606 19195 - Learning Unit - Standard With P.A.A A/C - Placement Date : 15-JUN-2018

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found