


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kearns Public School (4593)
Region:	South Western Sydney AMU
State Electorate:	Macquarie Fields
Local Government Area:	Campbelltown

Last Reviewed By:	Greencap 30-NOV-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning/Administration - 1992 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00A - R0001 - Personal Effects Storage - 5.34 m2							
No Asbestos							
B00A - R0002 - Practical Activities - 1hb - 12.9 m2							
No Asbestos							
B00A - R0003 - Home Base - 59.53 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Withdrawal Space - 1hb - 5.45 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0005 - Home Base Store - 5.42 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Personal Effects Storage - 5.34 m2							
No Asbestos							
B00A - R0007 - Practical Activities - 1hb - 14.76 m2							
No Asbestos							
B00A - R0008 - Home Base - 59.54 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Movement - 23.79 m2							
No Asbestos							
B00A - R0010 - Cleaning Distributed Store - 2.4 m2							
No Asbestos							
B00A - R0011 - Distribution Board - 1.18 m2							
No Asbestos							Note: No inspection of live electrical installation
B00A - R0012 - Home Base Store - 3.71 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Home Base Store - 3.7 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0014 - Withdrawal Space - 1hb - 11.08 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0015 - Home Base - 59.54 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0016 - Practical Activities - 1hb - 14.76 m2							
No Asbestos							
B00A - R0017 - Personal Effects Storage - 5.35 m2							
No Asbestos							
B00A - R0018 - Movement - 23.79 m2							
No Asbestos							
B00A - R0019 - Staff Room - 45.96 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0020 - Staff Room Annexe - 20.3 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0021 - Movement - 12.53 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0022 - Cleaning Distributed Store - 2.61 m2							
No Asbestos							
B00A - R0023 - Distribution Board - .5 m2							
No Asbestos							Note: No inspection of live electrical installation

No Asbestos		
B00A - R0024 - Staff Toilet - 5.94 m2		
No Asbestos		
B00A - R0025 - Staff Toilet - 5.94 m2		
No Asbestos		
B00A - R0026 - Staff Toilet - 5.94 m2		
No Asbestos		
B00A - R0027 - Security Store - 18.36 m2		
No Asbestos		
B00A - R0028 - Movement - 2.46 m2		
No Asbestos		
B00A - R0029 - Staff Toilet - 1.94 m2		
No Asbestos		
B00A - R0030 - Staff Shower/Change - 2.97 m2		
No Asbestos		
B00A - R0031 - Sick Bay - 9.67 m2		
No Asbestos		
B00A - R0032 - Duplicating Workroom - 19.5 m2		
No Asbestos		
B00A - R0033 - Clerical Office - 18.07 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0034 - Interview - 11.8 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0035 - Staff Room Annexe - 11.84 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0036 - Principal - 17.94 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0037 - Staff Room Annexe - 8.99 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0038 - Movement - 27.93 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0039 - Entry Vestibule - 12.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00A - R0040 - Movement - 8.77 m2		
No Asbestos		
B00A - R0041 - Movement - .67 m2		
No Asbestos		
B00A - R0042 - Movement - .43 m2		
No Asbestos		
B00B - Library - 1992 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00B - R0002 - Library Office/Workroom - 20.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0003 - K.L.A. Store - 9.24 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0004 - Drinking Facilities - 28.95 m2		
No Asbestos		
B00B - R0005 - Distribution Board - 1.04 m2		
		Note: No inspection of live electrical installation

No Asbestos		
B00B - R0007 - Reading Area - 168.54 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0008 - Movement - 42.26 m2		
No Asbestos		
B00C - General Learning - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00C - R0001 - Withdrawal Space - 1hb - 5.39 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0002 - Home Base - 59.54 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0003 - Home Base Store - 5.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0004 - Practical Activities - 1hb - 13.17 m2		
No Asbestos		
B00C - R0005 - Personal Effects Storage - 5.34 m2		
No Asbestos		
B00C - R0006 - Personal Effects Storage - 5.34 m2		
No Asbestos		
B00C - R0007 - Practical Activities - 1hb - 13.17 m2		
No Asbestos		
B00C - R0008 - Home Base Store - 5.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0009 - Home Base - 59.54 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0010 - Withdrawal Space - 1hb - 5.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0011 - Movement - 23.75 m2		
No Asbestos		
B00C - R0012 - Toilets - Girls - 20.56 m2		
No Asbestos		
B00C - R0013 - Cleaning Distributed Store - 4.29 m2		
No Asbestos		
B00C - R0014 - Distribution Board - .42 m2		
No Asbestos		Note: No inspection of live electrical installation
B00C - R0015 - Toilets - Boys - 20.14 m2		
No Asbestos		
B00C - R0016 - Movement - 11.05 m2		
No Asbestos		
B00D - Library/Pupil Facilities - 1992 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00D - R0001 - Garden Store - 12.96 m2		
No Asbestos		
B00D - R0002 - General Storeroom - 4.61 m2		
No Asbestos		

B00D - R0003 - General Assistant/Bulk Store - 15.94 m2		
No Asbestos		
B00D - R0004 - Canteen Office/Store - 6.61 m2		
No Asbestos		
B00D - R0005 - Canteen - 13.69 m2		
No Asbestos		
B00D - R0006 - Communal/Performance Store - 6.72 m2		
No Asbestos		
B00D - R0007 - Cleaning Supplies - 8.82 m2		
No Asbestos		
B00D - R0008 - Main Switch Board - 5.11 m2		
No Asbestos		
B00D - R0009 - Security Store - 1.9 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0010 - Bulk Store - 33.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0011 - Movement - 1.82 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0012 - Movement - 1.82 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0013 - General Storeroom - 6.33 m2		
No Asbestos		
B00D - R0014 - Plant - 2.73 m2		
No Asbestos		
B00D - R0015 - Disabled Toilet - 4.8 m2		
No Asbestos		
B00D - R0016 - Staff Shower/Change - 2.42 m2		
No Asbestos		
B00D - R0017 - Distribution Board - .37 m2		Note: No inspection of live electrical installation
No Asbestos		
B00D - R0018 - Drinking Facilities - 137.69 m2		
No Asbestos		
B00D - R0021 - Movement - 52.01 m2		
No Asbestos		
B00D - R0022 - Movement - 52.01 m2		
No Asbestos		
B00D - R0023 - General Storeroom - .86 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0024 - General Storeroom - .86 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - Communal Facilities - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00E - R0001 - Communal Space - 145.31 m2		
No Asbestos		
B00E - R0002 - Raised Platform - 60.3 m2		
No Asbestos		
B00E - R0003 - Hall Chair Store - 9.27 m2		
No Asbestos		

B00E - R0004 - Communal/Performance Store - 9.25 m2	
No Asbestos	
B00E - R0005 - P.E Store - 13.05 m2	
No Asbestos	
B00E - R0006 - Toilet - Lobby - 2.38 m2	
No Asbestos	
B00E - R0007 - Toilets - Girls - 7.38 m2	
No Asbestos	
B00E - R0008 - Sound Cupboard - 2.06 m2	
No Asbestos	
B00E - R0009 - Toilet - Lobby - 3.39 m2	
No Asbestos	
B00E - R0010 - Toilets - Boys - 5.78 m2	
No Asbestos	
B00E - R0011 - Cleaning Distributed Store - 3.53 m2	
No Asbestos	
B00E - R0012 - General Storeroom - 1.61 m2	
No Asbestos	
B00E - R0013 - Main Switch Board - 3.17 m2	
No Asbestos	
B00E - R0014 - Access Shower/Toilet - 6.9 m2	
No Asbestos	
B00E - R0015 - Movement - 12.81 m2	
No Asbestos	
B00E - R0016 - Movement - 7.8 m2	
No Asbestos	
B00E - R0017 - Ramp - 10.93 m2	
No Asbestos	
B00E - R0018 - Covered Outdoor Learning Area - 148.78 m2	
No Asbestos	

Demountables

OS 602 10700 - Learning Unit - Standard With P.A.A. - Placement Date : 12-SEP-2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11393 - Learning Unit - Standard With P.A.A. - Placement Date : 05-FEB-1997

Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Learning space/withdrawal/entry

Ceiling Structures/Linings	Flat AC Sheeting	70m2	Assumed Asbestos
----------------------------	------------------	------	------------------

R2- Home Base Store

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Assumed Asbestos

OS 602 12417 - Learning Unit - Standard With P.A.A. - Placement Date : 05-MAR-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 13655 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 19-JUN-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found