


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kellyville Ridge Public School (4639)
Region:	Western Sydney AMU
State Electorate:	Riverstone
Local Government Area:	Blacktown

Last Reviewed By:	Greencap 23-MAY-2008
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Staff Facilities - 2004 - Brick/Veneer							
Exterior							
No Asbestos							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 84.7 m2							
No Asbestos							
B00A - R0002 - Staff Room Annexe - 25.76 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0003 - Staff Room - 51.62 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0004 - Staff Kitchen - 6.92 m2							
No Asbestos							
B00A - R0005 - Deputy Principal - 12.47 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0006 - Deputy Principal - 12.6 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0007 - Security Store - 13.91 m2							
No Asbestos							
B00A - R0008 - Principal - 17.14 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0009 - Clerical Office/Workroom - 57.75 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0010 - Movement - 8.1 m2							
No Asbestos							
B00A - R0011 - Entry Vestibule - 16.59 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0012 - Interview - 13.29 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Sick Bay - 9.09 m2							
No Asbestos							
B00A - R0014 - Access Shower/Toilet - 6.09 m2							
No Asbestos							
B00A - R0015 - Interview - 17.27 m2							
No Asbestos							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0016 - Staff Toilet - 4.58 m2							
No Asbestos							
B00A - R0017 - Staff Toilet - 5.09 m2							
No Asbestos							
B00A - R0018 - Staff Toilet - 5.06 m2							

No Asbestos		
B00A - R0019 - Distribution Board - 1.35 m2		Note: No inspection of live electrical installation
No Asbestos		
B00A - R0020 - Cleaning Distributed Store - 2.82 m2		
No Asbestos		
B00A - R0021 - Movement - 42.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
No Asbestos		
B00B - Communal Facilities/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00B - R0002 - Sports Store - 17.21 m2		
No Asbestos		
B00B - R0003 - Movement - 8.46 m2		
No Asbestos		
B00B - R0004 - Raised Platform - 57.37 m2		
No Asbestos		
B00B - R0005 - Movement - 27.69 m2		
No Asbestos		
B00B - R0006 - Main Switch Board - 4.58 m2		
No Asbestos		
B00B - R0007 - Communal/Performance Store - 10.22 m2		
No Asbestos		
B00B - R0008 - General Assistant/Bulk Store - 14.1 m2		
No Asbestos		
B00B - R0009 - General Assistant/Bulk Store - 9.46 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - Community Clinic - 19.36 m2		
No Asbestos		
B00B - R0011 - Toilets - Boys - 11.06 m2		
No Asbestos		
B00B - R0012 - Access Shower/Toilet - 5.81 m2		
No Asbestos		
B00B - R0013 - Staff Kitchen - 2.36 m2		
No Asbestos		
B00B - R0014 - Canteen - 44.23 m2		
No Asbestos		
B00B - R0015 - Canteen Office/Store - 10.72 m2		
No Asbestos		
B00B - R0016 - Toilets - Girls - 9.84 m2		
No Asbestos		
B00B - R0017 - Communications Cupboard - 2.06 m2		
No Asbestos		
B00B - R0018 - Garden Store - 12.71 m2		
No Asbestos		
B00B - R0019 - Cleaning Supplies - 7.18 m2		
No Asbestos		

B00B - R0020 - P.E Store - 17.61 m2		
No Asbestos		
B00B - R0021 - Hall Chair Store - 11.34 m2		
No Asbestos		
B00B - R0022 - Communal Space - 196.87 m2		
No Asbestos		
B00B - R0023 - External Movement - 598.98 m2		
No Asbestos		
B00D - Library - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0002 - Staff Toilet - 3.61 m2		
No Asbestos		
B00D - R0003 - Special Programs Store - 5.69 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0004 - Special Programs Room - 31.85 m2		
Floor Coverings Res/Textile	No Asbestos Found	
No Asbestos		
B00D - R0005 - K.L.A. Store - 19.78 m2		
No Asbestos		
B00D - R0006 - Cleaning Distributed Store - 5.06 m2		
No Asbestos		
B00D - R0007 - Reading Area - 229.02 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0008 - Communications Room - 7.81 m2		
No Asbestos		
B00D - R0009 - Library Office/Workroom - 26.75 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0010 - Distribution Board - .56 m2		
No Asbestos		
B00D - R0011 - Seminar/Study - 15.79 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0012 - Special Programs Room - 15.8 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0013 - Special Programs Store - 5.96 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0014 - Special Programs Room - Type 1 - 32.2 m2		
No Asbestos		
B00D - R0015 - Special Programs Store - 5.78 m2		
No Asbestos		
B00D - R0016 - General Storeroom - 5.87 m2		
No Asbestos		

Note: No inspection of live electrical installation

B00D - R0017 - External Movement - 128.25 m2		
No Asbestos		
B00E - General Learning/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00E - R0001 - Movement - 114.3 m2		
No Asbestos		
B00E - R0002 - Toilets - Boys - 24.43 m2		
No Asbestos		
B00E - R0003 - General Storeroom - 5.97 m2		
No Asbestos		
B00E - R0004 - Toilets - Girls - 27.79 m2		
No Asbestos		
B00E - R0005 - Practical Activities - 1hb - 19.31 m2		
No Asbestos		
B00E - R0006 - Home Base Store - 6.15 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0007 - Home Base - 60.66 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0008 - Withdrawal Space - 2hb - 11.79 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0009 - Home Base - 60.6 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0010 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0011 - Practical Activities - 1hb - 18.99 m2		
No Asbestos		
B00E - R0012 - Distribution Board - .7 m2		
No Asbestos		
		Note: No inspection of live electrical installation
B00E - R0013 - Practical Activities - 1hb - 18.72 m2		
No Asbestos		
B00E - R0014 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0015 - Home Base - 60.61 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0016 - Withdrawal Space - 2hb - 11.86 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - Home Base - 60.65 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	

B00E - R0018 - Home Base Store - 6.09 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0019 - Practical Activities - 1hb - 19.23 m2		
No Asbestos		
B00F - General Learning/Pupil Facilities - 2004 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
No Asbestos		
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - Movement - 72.67 m2		
No Asbestos		
B00F - R0002 - Toilets - Boys - 24.33 m2		
No Asbestos		
B00F - R0003 - Cleaning Distributed Store - 6.39 m2		
No Asbestos		
B00F - R0004 - Toilets - Girls - 27.93 m2		
No Asbestos		
B00F - R0005 - Practical Activities - 1hb - 19.24 m2		
No Asbestos		
B00F - R0006 - Home Base Store - 6.09 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0007 - Home Base - 60.6 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0008 - Withdrawal Space - 2hb - 11.78 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0009 - Home Base - 60.57 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0010 - Home Base Store - 6.1 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0011 - Practical Activities - 1hb - 18.8 m2		
No Asbestos		
B00F - R0012 - Distribution Board - .7 m2		
No Asbestos		
B00F - R0013 - Laundry - Type 2 - 7.32 m2		
No Asbestos		
B00F - R0014 - Access Shower/Toilet - Type 2 - 19.97 m2		
No Asbestos		
B00F - R0015 - Home Base - 60.71 m2		
No Asbestos		
B00F - R0016 - Home Base Store - 6.18 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0017 - Practical Activities - 1hb - 19.19 m2		
No Asbestos		

Note: No inspection of live electrical installation

B00F - R0018 - Withdrawal Space - 2hb - 11.75 m2		
No Asbestos		
B00F - R0019 - Home Base - 60.64 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0020 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0021 - Practical Activities - 1hb - 19.34 m2		
No Asbestos		
B00F - R0022 - Movement - 46.31 m2		
No Asbestos		
B00G - General Learning - 2004 - Brick/Veneer		
Exterior		
No Asbestos		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Interior		
B00G - R0001 - Movement - 131.79 m2		
No Asbestos		
B00G - R0002 - Practical Activities - 1hb - 19.2 m2		
No Asbestos		
B00G - R0003 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0004 - Home Base - 60.55 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0005 - Withdrawal Space - 2hb - 11.75 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0006 - Home Base - 60.85 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0007 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0008 - Practical Activities - 1hb - 18.81 m2		
No Asbestos		
B00G - R0009 - Distribution Board - .7 m2		
No Asbestos		
B00G - R0010 - Practical Activities - 1hb - 18.78 m2		
No Asbestos		
B00G - R0011 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0012 - Home Base - 60.53 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0013 - Withdrawal Space - 2hb - 11.78 m2		
No Asbestos		

Note: No inspection of live electrical installation

Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0014 - Home Base - 60.56 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0015 - Home Base Store - 6.12 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0016 - Practical Activities - 1hb - 18.8 m2		
No Asbestos		
B00G- R0017 - Distribution Board - .7 m2		Note: No inspection of live electrical installation
No Asbestos		
B00G- R0018 - Practical Activities - 1hb - 18.78 m2		
No Asbestos		
B00G- R0019 - Home Base Store - 6.09 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0020 - Home Base - 60.57 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0021 - Withdrawal Space - 2hb - 11.83 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0022 - Home Base - 60.22 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0023 - Home Base Store - 6.15 m2		
No Asbestos		
Floor Coverings Res/Textile	No Asbestos Found	
B00G- R0024 - Practical Activities - 1hb - 19.18 m2		
No Asbestos		
B00H - Other - Non-Govt Pre-School - 2010 - Brick/Veneer		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00H - R0001 - No Access - 662.03 m2		
No Asbestos		

Demountables

OS 602 10218 - Learning Unit - Standard With P.A.A. - Placement Date : 05-NOV-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 10809 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 05-JAN-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 11281 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 28-NOV-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11428 - Learning Unit - Standard With P.A.A. - Placement Date : 26-NOV-2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11531 - Learning Unit - Standard With P.A.A. - Placement Date : 09-DEC-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11710 - Learning Unit - Standard With P.A.A. - Placement Date : 11-JAN-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 12286 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 28-NOV-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 12295 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 08-JAN-2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12516 - Learning Unit - Standard With P.A.A. - Placement Date : 03-JUL-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12636 - Learning Unit - Standard With P.A.A. - Placement Date : 23-JAN-2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12708 - Learning Unit - Standard With P.A.A. - Placement Date : 11-JAN-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 12879 - Learning Unit - Standard With P.A.A. - Placement Date : 09-DEC-2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 13502 - Learning Unit - Standard With P.A.A. - Placement Date : 12-JAN-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 603 13744 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 05-NOV-2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 840 15038 - Girls Toilet - Placement Date : 23-JAN-2010

No Asbestos Found

OS 602 15709 - Learning Unit - Standard With P.A.A. - Placement Date : 11-JAN-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.
No Asbestos Found
OS 603 16091 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 18-JUL-2007
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.
No Asbestos Found
OS 603 17452 - Learning Unit - Standard With P.A.A. A/C - Placement Date : 05-JAN-2007
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.
No Asbestos Found