

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Kurrambee School (5621)</b>
<b>Region:</b>	<b>Western Sydney AMU</b>
<b>State Electorate:</b>	<b>Londonderry</b>
<b>Local Government Area:</b>	<b>Penrith</b>

Last Reviewed By:	WSP 28-MAY-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	<b>No</b>
No previous investigations have been recorded against the school. However, asbestos containing materials may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	

# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration/Staff Facilities - 2007 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Compressed AC Sheet						
<b>Interior</b>							
<b>B00A - R0002 - Entry Vestibule - 13.57 m2</b>							
No Asbestos							
<b>B00A - R0003 - Interview - 12.82 m2</b>							
No Asbestos							
<b>B00A - R0004 - Principal - 12.82 m2</b>							
No Asbestos							
<b>B00A - R0005 - Movement - 21.03 m2</b>							
No Asbestos							
<b>B00A - R0006 - Clerical Office - 17.47 m2</b>							
No Asbestos							
<b>B00A - R0008 - Sick Bay - 6.63 m2</b>							
No Asbestos							
<b>B00A - R0009 - Disabled Shower/Toilet - 5.08 m2</b>							
No Asbestos							
<b>B00A - R0010 - Security Store - 14.28 m2</b>							
No Asbestos							
<b>B00A - R0013 - Staff Room Annexe - 13.81 m2</b>							
No Asbestos							
<b>B00A - R0014 - Cleaning Distributed Store - 1.86 m2</b>							
No Asbestos							
<b>B00A - R0015 - Staff Toilet - 4.39 m2</b>							
No Asbestos							
<b>B00A - R0017 - Staff Room - 62.27 m2</b>							
No Asbestos							
<b>B00A - R0018 - Staff Room Annexe - 25.16 m2</b>							
No Asbestos							
<b>B00A - R0019 - Staff Toilet - 4.11 m2</b>							
No Asbestos							
<b>B00A - R0020 - Access Shower/Toilet - 7.68 m2</b>							
No Asbestos							
<b>B00A - R0021 - General Storeroom - .37 m2</b>							
No Asbestos							
<b>B00A - R0022 - General Storeroom - .37 m2</b>							
No Asbestos							
<b>B00A - R0023 - Reading Area - 99.28 m2</b>							
No Asbestos							
<b>B00A - R0024 - Communications Room - 9.41 m2</b>							
No Asbestos							
<b>B00A - R0025 - K.L.A. Store - 23.75 m2</b>							
No Asbestos							

<b>B00A - R0026 - Library Office/Workroom - 12.23 m2</b>							
No Asbestos							
<b>B00A - R0027 - External Movement - 87.6 m2</b>							
No Asbestos							
<b>B00A - R0028 - Staff Room Annexe - 22.95 m2</b>							
No Asbestos							
<b>B00B - General Learning/Pupil Facilities - 2007 - Brick/Block</b>							
<b>Exterior</b>							
Wall Linings Internal - Infill	Compressed AC Sheet	50	North, South, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Compressed AC Sheet						
<b>Interior</b>							
<b>B00B - R0001 - External Movement - 34.5 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00B - R0003 - General Storeroom - 7.63 m2</b>							
No Asbestos							
<b>B00B - R0004 - Toilets - Boys/Girls - 3.96 m2</b>							
No Asbestos							
<b>B00B - R0005 - Toilets - Boys/Girls - 3.94 m2</b>							
No Asbestos							
<b>B00B - R0007 - General Storeroom - 7.68 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00B - R0008 - Home Base Store - S - 27.7 m2</b>							
No Asbestos							
<b>B00B - R0009 - Practical Activities - S - 1hb - 30.61 m2</b>							
No Asbestos							
<b>B00B - R0010 - Home Base - S - 28.05 m2</b>							
No Asbestos							
<b>B00B - R0011 - Practical Activities - S - 1hb - 30.33 m2</b>							
No Asbestos							
<b>B00C - Special Purpose (Craft Art Science Tas Etc) - 2007 - Brick/Veneer</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Compressed AC Sheet						
<b>Interior</b>							
<b>B00C - R0001 - External Movement - 35.81 m2</b>							
No Asbestos							
<b>B00C - R0003 - General Storeroom - 9.59 m2</b>							
No Asbestos							
<b>B00C - R0004 - Disabled Shower/Toilet - 5.54 m2</b>							

No Asbestos							
<b>B00C - R0005 - Staff Toilet - 5.11 m2</b>							
No Asbestos							
<b>B00C - R0006 - General Storeroom - 6.21 m2</b>							
No Asbestos							
<b>B00C - R0008 - Home Base - S - 28.58 m2</b>							
No Asbestos							
<b>B00C - R0009 - Practical Activities - S - 1hb - 31.81 m2</b>							
No Asbestos							
<b>B00C - R0010 - Home Base - S - 22.47 m2</b>							
No Asbestos							
<b>B00C - R0011 - Practical Activities - S - 1hb - 34.31 m2</b>							
No Asbestos							
<b>B00D - General Learning - 2011 - Fibre Cement Clad</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Wall Cladding	Compressed AC Sheet						
<b>Interior</b>							
<b>B00D - R0001 - External Movement - 21.11 m2</b>							
No Asbestos							
<b>B00D - R0003 - Staff Kitchen - 3.79 m2</b>							
No Asbestos							
<b>B00D - R0004 - General Storeroom - 6.23 m2</b>							
No Asbestos							
<b>B00D - R0005 - Home Base - S - 31.5 m2</b>							
No Asbestos							
<b>B00D - R0006 - Home Base - S - 28.06 m2</b>							
No Asbestos							
<b>B00E - General Learning - 2013 - Brick/Veneer</b>							
<b>Exterior</b>							
Wall Linings Internal - Infill	Compressed AC Sheet	35	North, South, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00E - R0001 - Practical Activities - 22.56 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0002 - Home Base - 58.62 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0003 - Cleaning Distributed Store - 6.26 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0004 - Home Base Store - 6.43 m2</b>							
No Asbestos							

<b>B00E - R0005 - Withdrawal Space - 1hb - 9.74 m2</b>							
No Asbestos							
<b>B00E - R0006 - Breakout Area - 17.89 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal	Flat AC Sheeting	25m2	North, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0007 - Disabled Toilet - 7.31 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0008 - Other - 14.14 m2</b>							
No Asbestos							
<b>B00E - R0009 - Access Shower/Toilet - 8.31 m2</b>							
No Asbestos							
<b>B00E - R0010 - Practical Activities - 22.61 m2</b>							
No Asbestos							
<b>B00E - R0011 - Home Base - 58.85 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0012 - Access Shower/Toilet - 6.98 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0013 - Home Base Store - 5.59 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0014 - Withdrawal Space - 1hb - 9.71 m2</b>							
No Asbestos							
<b>B00E - R0015 - Breakout Area - 17.92 m2</b>							
No Asbestos							
<b>B00E - R0016 - Laundry - Type 3 - 6.23 m2</b>							
No Asbestos							
<b>B00E - R0017 - Home Base Store - 6.33 m2</b>							
No Asbestos							
<b>B00E - R0018 - Withdrawal Space - 1hb - 9.68 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00E - R0019 - Breakout Area - 17.9 m2</b>							
No Asbestos							
<b>B00E - R0020 - Practical Activities - 22.42 m2</b>							
No Asbestos							
<b>B00E - R0021 - Home Base - 58.55 m2</b>							
No Asbestos							
<b>B00E - R0022 - Disabled Toilet - 6.9 m2</b>							
No Asbestos							
<b>B00E - R0023 - Other - 14.14 m2</b>							
No Asbestos							
<b>B00E - R0024 - Access Shower/Toilet - 8.31 m2</b>							
No Asbestos							
<b>B00E - R0025 - Practical Activities - 22.56 m2</b>							
No Asbestos							
<b>B00E - R0026 - Home Base - 58.92 m2</b>							
No Asbestos							
<b>B00E - R0027 - Home Base Store - 6.28 m2</b>							
No Asbestos							

<b>B00E - R0028 - Withdrawal Space - 1hb - 9.77 m2</b>		
No Asbestos		
<b>B00E - R0029 - Breakout Area - 18.08 m2</b>		
No Asbestos		
<b>B00E - R0030 - Plant - 6.14 m2</b>		
No Asbestos		
<b>B00E - R0031 - Distribution Board - .78 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0032 - Distribution Board - .77 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0033 - External Movement - 51.96 m2</b>		
No Asbestos		
<b>B00E - R0034 - External Movement - 90.66 m2</b>		
No Asbestos		
<b>B00F - General Learning - 2013 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0001 - Practical Activities - 22.58 m2</b>		
No Asbestos		
<b>B00F - R0002 - Home Base - 58.77 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0003 - Cleaning Distributed Store - 6.2 m2</b>		
No Asbestos		
<b>B00F - R0004 - Home Base Store - 6.46 m2</b>		
No Asbestos		
<b>B00F - R0005 - Withdrawal Space - 1hb - 9.74 m2</b>		
No Asbestos		
<b>B00F - R0006 - Breakout Area - 17.93 m2</b>		
No Asbestos		
<b>B00F - R0007 - Disabled Toilet - 7.03 m2</b>		
No Asbestos		
<b>B00F - R0008 - Other - 14.51 m2</b>		
No Asbestos		
<b>B00F - R0009 - Access Shower/Toilet - 8.37 m2</b>		
No Asbestos		
<b>B00F - R0010 - Practical Activities - 22.55 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0011 - Home Base - 58.62 m2</b>		
No Asbestos		
<b>B00F - R0012 - Access Shower/Toilet - 7.01 m2</b>		
No Asbestos		
<b>B00F - R0013 - Home Base Store - 5.59 m2</b>		
No Asbestos		
<b>B00F - R0014 - Withdrawal Space - 1hb - 9.74 m2</b>		
No Asbestos		
<b>B00F - R0015 - Breakout Area - 17.85 m2</b>		

No Asbestos		
<b>B00F - R0016 - Laundry - Type 3 - 6.29 m2</b>		
No Asbestos		
<b>B00F - R0017 - Home Base Store - 6.33 m2</b>		
No Asbestos		
<b>B00F - R0018 - Withdrawal Space - 1hb - 9.64 m2</b>		
No Asbestos		
<b>B00F - R0019 - Breakout Area - 17.78 m2</b>		
No Asbestos		
<b>B00F - R0020 - Practical Activities - 22.57 m2</b>		
No Asbestos		
<b>B00F - R0021 - Home Base - 58.39 m2</b>		
No Asbestos		
<b>B00F - R0022 - Disabled Toilet - 6.98 m2</b>		
No Asbestos		
<b>B00F - R0023 - Other - 14.18 m2</b>		
No Asbestos		
<b>B00F - R0024 - Access Shower/Toilet - 8.34 m2</b>		
No Asbestos		
<b>B00F - R0025 - Practical Activities - 22.64 m2</b>		
No Asbestos		
<b>B00F - R0026 - Home Base - 58.62 m2</b>		
No Asbestos		
<b>B00F - R0027 - Home Base Store - 6.23 m2</b>		
No Asbestos		
<b>B00F - R0028 - Withdrawal Space - 1hb - 9.74 m2</b>		
No Asbestos		
<b>B00F - R0029 - Breakout Area - 17.91 m2</b>		
No Asbestos		
<b>B00F - R0030 - Plant - 6 m2</b>		
No Asbestos		
<b>B00F - R0031 - Distribution Board - .77 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0032 - Distribution Board - .79 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0033 - External Movement - 149.12 m2</b>		
No Asbestos		
<b>B00G - General Learning - 2013 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00G - R0001 - Practical Activities - 22.71 m2</b>		
No Asbestos		
<b>B00G - R0002 - Home Base - 58.46 m2</b>		
No Asbestos		
<b>B00G - R0003 - Cleaning Distributed Store - 6.26 m2</b>		
No Asbestos		
<b>B00G - R0004 - Home Base Store - 6.45 m2</b>		
No Asbestos		



<b>B00G - R0005 - Withdrawal Space - 1hb - 9.8 m2</b>	
No Asbestos	
<b>B00G - R0006 - Breakout Area - 17.89 m2</b>	
No Asbestos	
<b>B00G - R0007 - Disabled Toilet - 7.05 m2</b>	
No Asbestos	
<b>B00G - R0008 - Other - 14.4 m2</b>	
No Asbestos	
<b>B00G - R0009 - Access Shower/Toilet - 8.31 m2</b>	
No Asbestos	
<b>B00G - R0010 - Practical Activities - 22.76 m2</b>	
No Asbestos	
<b>B00G - R0011 - Home Base - 58.68 m2</b>	
No Asbestos	
<b>B00G - R0012 - Access Shower/Toilet - 7.05 m2</b>	
No Asbestos	
<b>B00G - R0013 - Home Base Store - 5.57 m2</b>	
No Asbestos	
<b>B00G - R0014 - Withdrawal Space - 1hb - 9.77 m2</b>	
No Asbestos	
<b>B00G - R0015 - Breakout Area - 17.92 m2</b>	
No Asbestos	
<b>B00G - R0016 - Laundry - Type 3 - 6.22 m2</b>	
No Asbestos	
<b>B00G - R0017 - Home Base Store - 6.36 m2</b>	
No Asbestos	
<b>B00G - R0018 - Withdrawal Space - 1hb - 9.71 m2</b>	
No Asbestos	
<b>B00G - R0019 - Breakout Area - 17.85 m2</b>	
No Asbestos	
<b>B00G - R0020 - Practical Activities - 22.71 m2</b>	
No Asbestos	
<b>B00G - R0021 - Home Base - 58.54 m2</b>	
No Asbestos	
<b>B00G - R0022 - Disabled Toilet - 6.9 m2</b>	
No Asbestos	
<b>B00G - R0023 - Other - 14.1 m2</b>	
No Asbestos	
<b>B00G - R0024 - Access Shower/Toilet - 8.31 m2</b>	
No Asbestos	
<b>B00G - R0025 - Practical Activities - 22.84 m2</b>	
No Asbestos	
<b>B00G - R0026 - Home Base - 58.53 m2</b>	
No Asbestos	
<b>B00G - R0027 - Home Base Store - 6.23 m2</b>	
No Asbestos	
<b>B00G - R0028 - Withdrawal Space - 1hb - 9.74 m2</b>	
No Asbestos	
<b>B00G - R0029 - Breakout Area - 17.86 m2</b>	
No Asbestos	
<b>B00G - R0030 - Plant - 5.92 m2</b>	

No Asbestos		
<b>B00G - R0031 - Distribution Board - .79 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R0032 - Distribution Board - .77 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R0033 - External Movement - 143.82 m2</b>		
No Asbestos		
<b>B00H - Communal Facilities/Building Services - 2013 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0001 - Covered Outdoor Learning Area - 69.75 m2</b>		
No Asbestos		
<b>B00H - R0002 - Communal Space - 118.64 m2</b>		
No Asbestos		
<b>B00H - R0003 - Kitchen - Pre - 29.33 m2</b>		
No Asbestos		
<b>B00H - R0004 - Special Programs Room - 29.51 m2</b>		
No Asbestos		
<b>B00H - R0005 - Special Programs Store - 6.09 m2</b>		
No Asbestos		
<b>B00H - R0006 - P.E Store - 13.27 m2</b>		
No Asbestos		
<b>B00H - R0007 - Chair Storeroom - 8.8 m2</b>		
No Asbestos		
<b>B00H - R0008 - Main Switch Board - 10.81 m2</b>		
No Asbestos		
<b>B00H - R0009 - General Assistant/Bulk Store - 13.77 m2</b>		
No Asbestos		
<b>B00H - R0010 - Sports Store - 11.96 m2</b>		
No Asbestos		
<b>B00H - R0011 - Garden Store - 12.08 m2</b>		
No Asbestos		
<b>B00H - R0012 - Access Shower/Toilet - 6.45 m2</b>		
No Asbestos		
<b>B00H - R0013 - Disabled Toilet - 5.41 m2</b>		
No Asbestos		
<b>B00H - R0014 - Cleaning Distributed Store - 6.79 m2</b>		
No Asbestos		
<b>B00H - R0017 - Covered Outdoor Learning Area - 41.35 m2</b>		
No Asbestos		
<b>B00H - R0018 - Distribution Board - .78 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R0019 - External Movement - 58.63 m2</b>		
No Asbestos		
<b>B00H - R0020 - External Movement - 23.46 m2</b>		
No Asbestos		
<b>B00H - R0021 - External Movement - 21.44 m2</b>		
No Asbestos		

## B00I - Pupil Facilities/Special Purpose - 2013 - Brick/Veneer

### Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

### Interior

#### B00I - R0001 - Movement - 7.73 m2

No Asbestos

#### B00I - R0002 - Hydrotherapy - 15.98 m2

No Asbestos

#### B00I - R0003 - Movement - 95.84 m2

No Asbestos

#### B00I - R0004 - Hydrotherapy - Pool - 64.58 m2

No Asbestos

#### B00I - R0005 - Sports Store - 11.7 m2

No Asbestos

#### B00I - R0006 - Shower/Change - 21.23 m2

No Asbestos

#### B00I - R0007 - Disabled Toilet - 5.94 m2

No Asbestos

#### B00I - R0008 - Access Shower/Toilet - 7 m2

No Asbestos

#### B00I - R0009 - Other - 11.31 m2

No Asbestos

#### B00I - R0010 - General Storeroom - 6.96 m2

No Asbestos

#### B00I - R0011 - Plant - 19.04 m2

No Asbestos

#### B00I - R0012 - Distribution Board - .72 m2

Note: No inspection of live electrical installation

No Asbestos

#### B00I - R0013 - Plant - 25.21 m2

No Asbestos

#### B00I - R0014 - External Movement - 62.92 m2

No Asbestos

## B00J - Staff Facilities - 2013 - Timber

### Exterior

Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

### Interior

#### B00J - R0001 - Residential Staff Kitchen - 19.59 m2

No Asbestos

#### B00J - R0002 - Movement - .83 m2

No Asbestos

#### B00J - R0003 - Residential Bedroom - 9.89 m2

No Asbestos

#### B00J - R0004 - Teacher Bathroom - 4.92 m2

No Asbestos

#### B00J - R0005 - Teacher Bedroom - 10.25 m2

No Asbestos	
<b>B00J - R0006 - Teacher Bedroom - 9.24 m2</b>	
No Asbestos	
<b>B00J - R0007 - Movement - 9.59 m2</b>	
No Asbestos	
<b>B00J - R0008 - Teacher Bedroom - 10.02 m2</b>	
No Asbestos	
<b>B00J - R0009 - Teacher Bedroom - 9.9 m2</b>	
No Asbestos	
<b>B00J - R0010 - Movement - 3.85 m2</b>	
No Asbestos	
<b>B00J - R0011 - Teacher Bathroom - 3.35 m2</b>	
No Asbestos	
<b>B00J - R0012 - Residential Laundry - 6.32 m2</b>	
No Asbestos	
<b>B00J - R0013 - External Movement - 21.32 m2</b>	
No Asbestos	

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020