

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kandos High School (8318)
Region:	North Western NSW AMU
State Electorate:	Bathurst
Local Government Area:	Mid-Western

Last Reviewed By:	Greencap 17-APR-2015
Last Revised By:	OHMS Hygiene 23-JUL-2020

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	

Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B005 - Storage - 2010 - Metal Shed							
Exterior							
No Asbestos							
Interior							
B005 - R0001 - Garden Store Room - 40.33 m2							
No Asbestos							
B00A - Various - 1969 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	120m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found						
Interior							
B00A - M0001 - Staff - Toilet - 6.61 m2							
No Asbestos							
B00A - M0002 - Darkroom Space - 6.65 m2							
No Asbestos							
B00A - M0003 - Movement - 6.19 m2							
No Asbestos							
B00A - M0004 - Movement - 6.21 m2							
No Asbestos							
B00A - M0005 - Stairs - 2.57 m2							
No Asbestos							
B00A - M0006 - Stairs - 1.29 m2							
No Asbestos							
B00A - M0007 - Stairs - 2.45 m2							
No Asbestos							
B00A - M0008 - Stairs - 2.45 m2							
No Asbestos							
B00A - M1001 - Staff - Toilet - 6.61 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - M1002 - Cleaning Store - Distributed - 6.54 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - M1003 - Movement - 6.19 m2							
No Asbestos							
B00A - M1004 - Movement - 6.21 m2							
No Asbestos							
B00A - M1005 - Stairs - 2.54 m2							
No Asbestos							
B00A - M1006 - Stairs - 2.54 m2							
No Asbestos							
B00A - M1007 - Stairs - 2.54 m2							
No Asbestos							
B00A - M1008 - Stairs - 2.54 m2							
No Asbestos							
B00A - R0001 - Laboratory L.S. - 93.39 m2							
Furniture / Fixtures	Flat AC Sheeting						
B00A - R0002 - Apparatus Store - 12.68 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0003 - Chemical Store - 12.65 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0004 - Interview/Office - Type 1 - 26.27 m2							
Window	Compressed AC Sheet	2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0006 - Apparatus Store - 7.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Window	Compressed AC Sheet	2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0007 - Distribution Board Cupboard - .9 m2						Note: No inspection of live electrical installation	
Electrical - Backing Board	Resinous Board	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R0008 - Staff Study - 25.03 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Window	Compressed AC Sheet	2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0009 - Laboratory L.S. - 93.89 m2							
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Window	Compressed AC Sheet	5	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R0010 - Preparation - 29.08 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0011 - Resources Space - 9.44 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Window	Compressed AC Sheet	2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R0012 - Laboratory L.S. - 94.08 m2							
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
Window	Compressed AC Sheet	5	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Furniture / Fixtures	Compressed AC Sheet	3	East	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0013 - General Storeroom - 13.37 m2							
No Asbestos							

B00A - R0017 - Plant - 10.53 m2							
No Asbestos							
B00A - R0018 - External Movement - 8.95 m2							
No Asbestos							
B00A - R0019 - Plant - 8.9 m2							
No Asbestos							
B00A - R0020 - Stairs - 5.88 m2							
No Asbestos							
B00A - R0021 - Stairs - 2.57 m2							
No Asbestos							
B00A - R0022 - Stairs - 2.45 m2							
No Asbestos							
B00A - R0023 - Movement - 156.76 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Window	Compressed AC Sheet	50	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1001 - General Learning Space - 53.63 m2							
Window	Compressed AC Sheet	3	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R1002 - General Storeroom - 12.46 m2							
Window	Compressed AC Sheet	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R1003 - General Learning Space - 52.67 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Window	Compressed AC Sheet	20	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1004 - Staff Study - 26.66 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Window	Compressed AC Sheet	10	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1005 - Distribution Board Cupboard - .59 m2						Note: No inspection of live electrical installation	
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R1006 - General Storeroom - 9.01 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R1007 - Special Learning Space - 52.82 m2							

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
Wnindow	Compressed AC Sheet	53	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B00A - R1008 - Commonroom - 52.61 m2								
Wnindow	Compressed AC Sheet	3	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
B00A - R1009 - Music Learning Space - 66.11 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
Wnindow	Compressed AC Sheet	20	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R1010 - Music Store - 6.14 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00A - R1011 - Music Store - 6.09 m2								
Wnindow	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00A - R1012 - General Learning Space - 53.78 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
Wnindow	Compressed AC Sheet	20	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R1013 - Movement - 144.51 m2								
Wnindow	Compressed AC Sheet							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B00A - R1014 - Stairs - 19.62 m2								
No Asbestos								
B00A - R1015 - Stairs - 2.54 m2								
No Asbestos								
B00A - R1016 - Stairs - 2.54 m2								
No Asbestos								
B00A - R1017 - Stairs - 2.54 m2								
No Asbestos								
B00A - R1018 - Stairs - 2.54 m2								
No Asbestos								
B00A - R2001 - General Learning Space - 53.63 m2								

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Wnindow	Compressed AC Sheet	20	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R2002 - General Storeroom - 6.13 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2003 - General Storeroom - 6.12 m2							
Wnindow	Compressed AC Sheet	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2004 - General Learning Space - 52.76 m2							
Wnindow	Compressed AC Sheet	10	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2005 - Staff Study - 26.51 m2							
Wnindow	Compressed AC Sheet	2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2006 - Distribution Board Cupboard - .65 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R2007 - Cleaning Store - Distributed - 2.6 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R2008 - General Storeroom - 7.49 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Wnindow	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R2009 - Stage - 24.54 m2							
Wnindow	Compressed AC Sheet	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00A - R2010 - General Learning Space - 52.76 m2							
Window	Compressed AC Sheet	10	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2011 - General Learning Space - 52.76 m2							
Window	Compressed AC Sheet	10	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2012 - Resources Store - 6.09 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R2013 - Art Learning Space - 86.05 m2							
Window	Compressed AC Sheet	20	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00A - R2014 - Resources Store - 6.61 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R2015 - Resources Store - 6.61 m2							
Window	Compressed AC Sheet	5	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00A - R2016 - Movement - 145.14 m2							
Window	Compressed AC Sheet	50	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (120 - 250 m2) - (X15)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B00A - R2017 - Stairs - 19.62 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Window	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R2018 - Stairs - 11.07 m2							
No Asbestos							
B00A - R2019 - Stairs - 11.07 m2							

No Asbestos							
B00A - R9001 - Main Switchroom - 8.85 m2							
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R9002 - Plant - 15.6 m2							
Plant / Equipment	Insulation Material						
Electrical - Backing Board	Resinous Board	1	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - Administration/General Learning - 1929 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0002 - General Learning Space - 47.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0004 - Toilets-Disabled - 9.98 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0007 - Staff - Toilet - 3.74 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0010 - Cleaning Supplies Store - 7.61 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0012 - Staff Study - 18.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0013 - Clinic - Boys - 16.14 m2							
No Asbestos							
B00C - R0017 - General Storeroom - 3.66 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0018 - Uniform Shop - 4.77 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R0019 - Interview/Meeting - 19.92 m2							
Non Accessible							
B00C - R0020 - Distribution Board Cupboard - .34 m2							
Non Accessible							
B00C - R0021 - Public Reception - 15.37 m2							
Non Accessible							

B00C - R0022 - Administration - Clerical - 31.41 m2							
Non Accessible							
B00C - R0023 - Student Reception - 21.92 m2							
Non Accessible							
B00C - R0024 - Principal Office - 25.25 m2							
Non Accessible							
B00C - R0025 - Plant - 2.88 m2							
Non Accessible							
B00C - R0026 - Printing/Photocopying - 18.18 m2							
Non Accessible							
B00C - R0027 - Office/Store - 8.06 m2							
Non Accessible							
B00C - R0028 - Deputy Principal Office - 18.17 m2							
Non Accessible							
B00C - R0029 - Entry - 2.12 m2							
Non Accessible							
B00C - R0030 - Movement - 66.16 m2							
Non Accessible							
B00C - R1001 - Toilets-Girls - 2.71 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1002 - Resources Space - 18.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1003 - General Learning Space - 49.71 m2							
Ceiling Structures/Linings	Flat AC Sheeting	50m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R1004 - General Learning Space - 49.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	50m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R1005 - General Learning Space - 50.96 m2							
Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R1006 - Staff Study - 7.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						

Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R1007 - General Storeroom - 11.03 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R1008 - Movement - 16.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Floor Coverings Res/Textile	Vinyl Sheet - Adhesive						
B00C - R1009 - Stairs - 12.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R9001 - Chair Store - 3.84 m2							
No Asbestos							
B00E - Pupil Facilities/Physical Education - 1969 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Cladding	Compressed AC Sheet	12m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00E - R0002 - Sport Equipment Store - 11.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0003 - Student Canteen - 40.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Furniture / Fixtures	Vinyl Lining						
Furniture / Fixtures	Vinyl Tiles - Adhesive						
B00E - R0004 - General Storeroom - 4.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0005 - Staff Change - 1.62 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0006 - Staff - Toilet - 3.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0007 - Sport Equipment Store - 23.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0008 - Shower/Change - 4.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0009 - Plant - 4.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0010 - Toilets-Girls - 46 m2							
Ceiling Structures/Linings	Flat AC Sheeting	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0011 - Shower/Change - 18.29 m2							
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0012 - Cleaning Supplies Store - 6.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0013 - Toilets-Boys - 27.01 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0014 - External Movement - 1.11 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0015 - General Storeroom - 17.86 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0016 - Sport Equipment Store - 8.03 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0017 - Sport Equipment Store - 19.52 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0018 - Sport Equipment Store - 19.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0019 - General Storeroom - 21.89 m2							
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0020 - Covered Area - 80.55 m2							
Ceiling Structures/Linings	Flat AC Sheeting	81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0021 - Covered Area - 179.53 m2							
No Asbestos							
B00E - R0022 - External Movement - 20.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0023 - Adjoining School - 18.4 m2							
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0024 - Adjoining School - 2.53 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0025 - Adjoining School - 1.83 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0026 - Adjoining School - 21.59 m2							

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubides)	Compressed AC Sheet	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0027 - Adjoining School - 1.38 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - Technological & Applied Studies - 1955 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	50m2	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00F - R0007 - Movement - 3.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0008 - Staff Study - 10.5 m2							
No Asbestos							
B00F - R0009 - Staff - Toilet - 5.42 m2							
No Asbestos							
B00F - R0010 - Commonroom - 6.99 m2							
No Asbestos							
B00F - R0015 - Wood Technology Bay - 138.15 m2							
No Asbestos							
B00F - R0016 - External Movement - 8.79 m2							
No Asbestos							
B00F - R0017 - Materials Store - 6.13 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0018 - Metal Technology L.S. - 151.04 m2							
Ceiling Structures/Linings	Flat AC Sheeting	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0019 - Materials Store - 21.74 m2							
Ceiling Structures/Linings	Flat AC Sheeting	22m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0020 - Welding Area - 34.09 m2							
No Asbestos							
B00F - R9001 - General Storeroom - 134.4 m2							
No Asbestos							
B00F - R9002 - Dust Extraction Space - 6.14 m2							
No Asbestos							
B00J - Technological & Applied Studies - 1994 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00J - R0001 - Distribution Board Cupboard - 1.08 m2							
No Asbestos							
B00J - R0002 - External Movement - 5.48 m2							
No Asbestos							
B00J - R0003 - Computer Learning Space - 76.32 m2							
No Asbestos							

B00J - R0004 - General Storeroom - 15.75 m2							
No Asbestos							
B00J - R0005 - Cleaning Store - Distributed - 3.22 m2							
No Asbestos							
B00J - R0006 - Materials Technology L.S. - 76.49 m2							
No Asbestos							
B00J - R0011 - Staff Study - 20.32 m2							
No Asbestos							
B00J - R0012 - Staff - Toilet - 6.29 m2							
No Asbestos							
B00J - R0013 - Seminar - 15.31 m2							
No Asbestos							
B00J - R0014 - Movement - 36.86 m2							
No Asbestos							
B00J - R0015 - External Movement - 2.11 m2							
No Asbestos							
B00J - R0016 - Laundry - 2.28 m2							
No Asbestos							
B00J - R0017 - Food Technology L.S. - 82.61 m2							
No Asbestos							
B00J - R0018 - Preparation - Materials - 28.88 m2							
No Asbestos							
B00J - R0019 - Pantry - 6.59 m2							
No Asbestos							
B00J - R0020 - Preparation - Materials - 17.76 m2							
No Asbestos							
B00J - R0021 - Food/Research Space - 13.51 m2							
No Asbestos							
B00K - Building Services - 2003 - Timber Shed							
Exterior							
Eaves Linings	Flat AC Sheeting	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Cladding	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical - Backing Board	Resinous Board	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids - Raked Ceiling	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00K - R0001 - General Storeroom - 25.5 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	North, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00L - Library - 2008 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00L - R0001 - Main Entry - 21.57 m2							
No Asbestos							
B00L - R0002 - Staff - Toilet - 5.18 m2							
No Asbestos							

B00L - R0003 - Toilets-Disabled - 5.86 m2		
No Asbestos		
B00L - R0004 - Careers Advisers Office - 12.02 m2		
No Asbestos		
B00L - R0005 - System Administrators Office - 12.93 m2		
No Asbestos		
B00L - R0006 - Communication Space - 9.85 m2		
No Asbestos		
B00L - R0007 - Store - 5.79 m2		
No Asbestos		
B00L - R0008 - Main Area - 146.16 m2		
No Asbestos		
B00L - R0009 - Store - 5.18 m2		
No Asbestos		
B00L - R0010 - Library Administration - 53.09 m2		
No Asbestos		
B00L - R0011 - Seminar - Type 1 - 15.5 m2		
No Asbestos		
B00L - R0012 - Seminar - 12.88 m2		
No Asbestos		
B00L - R0013 - Seminar - 12.88 m2		
No Asbestos		
B00L - R0014 - External Movement - 54.4 m2		
No Asbestos		
B00L - R0015 - Distribution Board Cupboard - .47 m2		Note: No inspection of live electrical installation
No Asbestos		
B00L - R0016 - Seminar - Type 1 - 15.5 m2		
No Asbestos		
B00M - Multi Purpose Facilities/Performing Arts - 2008 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00M - R0001 - Gymnasium - 487.11 m2		
No Asbestos		
B00M - R0002 - Apparatus Store - 24.98 m2		
No Asbestos		
B00M - R0003 - Stage - 66.41 m2		
No Asbestos		
B00M - R0004 - Movement - 10.51 m2		
No Asbestos		
B00M - R0005 - Chair Store - 23.74 m2		
No Asbestos		
B00M - R0007 - Toilet - Lobby - 3.64 m2		
No Asbestos		
B00M - R0008 - Toilets-Boys - 20.11 m2		
No Asbestos		
B00M - R0009 - Change - 20.78 m2		
No Asbestos		
B00M - R0010 - Toilet - Lobby - 3.64 m2		

No Asbestos		
B00M - R0011 - Toilets-Girls - 25.22 m2		
No Asbestos		
B00M - R0012 - Change - 20.74 m2		
No Asbestos		
B00M - R0013 - Control Room - 9.75 m2		
No Asbestos		
B00M - R0014 - Toilets-Disabled - 5.63 m2		
No Asbestos		
B00M - R0015 - Distribution Board Cupboard - 1.39 m2		
		Note: No inspection of live electrical installation
No Asbestos		
B00M - R0016 - External Movement - 20.95 m2		
No Asbestos		
B00M - R0017 - External Movement - 74.14 m2		
No Asbestos		
B00M - R0018 - Shower - 6.91 m2		
No Asbestos		
B00M - R0019 - Cleaning Supplies Store - 2.59 m2		
No Asbestos		
B00M - R0020 - Shower - 7.47 m2		
No Asbestos		
B00M - R0021 - Ramp - 11.18 m2		
No Asbestos		
B00N - Other - 2008 - Metal Shed		
Exterior		
Ceiling Voids	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	
Interior		
B00N - R0001 - Garden Store Room - 33.67 m2		
No Asbestos		
B00O - Agricultural Science - 1955 - Steel		
Exterior		
Underfloor Voids	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00O - R0001 - General Storeroom - 19.73 m2		
No Asbestos		
B00O - R0002 - Plant Growing Space - 16.48 m2		
No Asbestos		
B00O - R0003 - General Storeroom - 13.37 m2		
No Asbestos		
B00O - R0004 - Toilets-Unisex - 6.34 m2		
No Asbestos		
B00O - R0005 - Machine Storage - 30.38 m2		
No Asbestos		
B00O - R0006 - General Learning Space - 44.44 m2		
No Asbestos		
B00P - Science - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	No Asbestos Found	

Underfloor Voids - Slab on Ground	No Asbestos Found						
Interior							
B00P - R0001 - Science Laboratory - 21.09 m2							
No Asbestos							
B00P - R0002 - Staff Study - 21.09 m2							
No Asbestos							
B00P - R0003 - Chemical Store - 12.13 m2							
No Asbestos							
B00P - R0004 - Preparation - 36.45 m2							
No Asbestos							
B00P - R0005 - Distribution Board Cupboard - .63 m2							
No Asbestos							Note: No inspection of live electrical installation
B00P - R0006 - Apparatus Storage - 13.71 m2							
No Asbestos							
B00P - R0007 - Laboratory L.S. - 60.06 m2							
No Asbestos							
B00P - R0008 - Laboratory L.S. - 60.06 m2							
No Asbestos							
B00P - R0009 - Outdoor Learning Space - Type 4 - 41.45 m2							
No Asbestos							
B00P - R0010 - External Movement - 44.19 m2							
No Asbestos							
B00Q - Residential Facilities - 1970 - Brick/Veneer							
Exterior							
Non Accessible							
Interior							
B00Q - R0001 - Residence - Garage - 21.31 m2							
Non Accessible							
B00Q - R0002 - Residence - Dining - 6.9 m2							
Non Accessible							
B00Q - R0003 - Residence - Kitchen - 12.03 m2							
Non Accessible							
B00Q - R0004 - Residence - Laundry - 3.16 m2							
Non Accessible							
B00Q - R0005 - Residence - Bedroom - 8.08 m2							
Non Accessible							
B00Q - R0006 - Residence - Toilet - 1.37 m2							
Non Accessible							
B00Q - R0007 - Residence - Movement - 8.86 m2							
Non Accessible							
B00Q - R0008 - Residence - Living - 19.78 m2							
Non Accessible							
B00Q - R0009 - Residence - Movement - 1.13 m2							
Non Accessible							
B00Q - R0010 - Residence - Bedroom - 10.52 m2							
Non Accessible							
B00Q - R0011 - Residence - Other - .92 m2							
Non Accessible							
B00Q - R0012 - Residence - Other - .87 m2							
Non Accessible							
B00Q - R0013 - Residence - Bathroom - 4.54 m2							

Non Accessible							
B00Q - R0014 - Residence - Bathroom - 2.31 m2							
Non Accessible							
B00Q - R0015 - Residence - Bedroom - 13.43 m2							
Non Accessible							
B00R - Residential Facilities - 1884 - Sandstone							
Exterior							
Non Accessible							
Interior							
B00R - R0001 - Residence - Movement - 25.74 m2							
Non Accessible							
B00R - R0002 - Residence - Lounge - 20.35 m2							
Non Accessible							
B00R - R0003 - Residence - Bedroom - 14.52 m2							
Non Accessible							
B00R - R0004 - Residence - Living - 22.61 m2							
Non Accessible							
B00R - R0005 - Residence - Bedroom - 16.22 m2							
Non Accessible							
B00R - R0006 - Residence - Bedroom - 13.84 m2							
Non Accessible							
B00R - R0007 - Residence - Movement - 4.98 m2							
Non Accessible							
B00R - R0008 - Residence - Kitchen - 13.03 m2							
Non Accessible							
B00R - R0009 - Residence - Dining - 21.19 m2							
Non Accessible							
B00R - R0010 - Residence - Bathroom - 4.04 m2							
Non Accessible							
B00R - R0011 - Residence - Toilet - 2.31 m2							
Non Accessible							
B00R - R0012 - Residence - Laundry - 8.57 m2							
Non Accessible							
B00S - Storage - 2010 - Metal Shed							
Exterior							
Non Accessible							
Interior							
B00S - R0001 - General Storeroom - 18.2 m2							
Non Accessible							
B0R1 - Residential Facilities - 1970 - Fibre Clad Shed							
Exterior							
Non Accessible							
Interior							
B0R1 - R0001 - Residence - Garage - 21.62 m2							
Non Accessible							

Demountables

OS 621 10435 - Single Learning Unit - H/Cap - Placement Date : 03-NOV-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 601 10882 - Learning Unit - Standard/Withdrawal - Placement Date : 14-JAN-2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 844 13850 - Country Toilet - Reltc - Boys/Girls - Placement Date : 30-JUN-1995

Exterior

Eaves Linings	Flat AC Sheeting	2.88m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

Interior

R1- Staff Toilet

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Assumed Asbestos

R2- Staff Toilet

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Assumed Asbestos