


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Kellyville High School (8477)
Region:	Western Sydney AMU
State Electorate:	Castle Hill
Local Government Area:	The Hills

Last Reviewed By:	Greencap 18-DEC-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Multi Purpose Facilities - 2003 - Brick/Veneer							
Exterior							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00A - R0001 - Distribution Board Cupboard - .73 m2				Note: No inspection of live electrical installation			
No Asbestos							
B00A - R0002 - Office/Store - 14.19 m2							
No Asbestos							
B00A - R0003 - Vending Machines - 1.7 m2							
No Asbestos							
B00A - R0004 - Student Canteen - 54.2 m2							
No Asbestos							
B00A - R0005 - Gymnasium - 477.14 m2							
No Asbestos							
B00A - R0006 - Cleaning Store - Distributed - 2.5 m2							
No Asbestos							
B00A - R0007 - Main Switchroom - 5.81 m2							
No Asbestos							
B00A - R0008 - Gymnasium - 118.82 m2							
No Asbestos							
B00A - R0009 - Movement - 635.88 m2							
No Asbestos							
B00A - R0010 - First Aid - 12.72 m2							
No Asbestos							
B00A - R0011 - Sport Equipment Store - 24.73 m2							
No Asbestos							
B00A - R0012 - Control Room - 10 m2							
Floor Coverings Res/Textile	No Asbestos Found						
B00A - R0013 - Chair Store - 32.54 m2							
No Asbestos							
B00A - R0014 - Large Equipment Store - 25.2 m2							
No Asbestos							
B00A - R0015 - Bulk Store - 13.65 m2							
No Asbestos							
B00A - R0016 - Cleaning Supplies Store - 7 m2							
No Asbestos							
B00A - R0017 - Movement Studio - 158.85 m2							
No Asbestos							
B00A - R0018 - Access Staff Shower/Toilet - 5.11 m2							
No Asbestos							
B00A - R0019 - Staff Shower - 11.04 m2							
No Asbestos							
B00A - R0020 - Movement Studio Store - 34.1 m2							
No Asbestos							
B00A - R0021 - Toilets-Boys - 34.13 m2							
No Asbestos							
B00A - R0022 - Toilets-Girls - 45.11 m2							
No Asbestos							
B00A - R0023 - Change - 61.67 m2							

No Asbestos		
B00A - R0024 - Movement - 34.89 m2		
No Asbestos		
B00A - R0025 - Distribution Board Cupboard - .5 m2		Note: No inspection of live electrical installation
No Asbestos		
B00A - R0026 - Change - 61.67 m2		
No Asbestos		
B00A - R0027 - Movement - 20.96 m2		
No Asbestos		
B00A - R0028 - Stage - 56.72 m2		
No Asbestos		
B00A - R0029 - Movement - 29.77 m2		
No Asbestos		
B00A - R9001 - Outdoor Equipment Store - 19.3 m2		
No Asbestos		
B00A - R9002 - Garden Store Room - 15.75 m2		
No Asbestos		
B00B - Administration/General Learning - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00B - R0001 - General Learning Space - Type 3 - 58.79 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0002 - General Learning Space - Type 3 - 58.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0003 - Chemical Store - 12.27 m2		
No Asbestos		
B00B - R0004 - Cleaning Store - Distributed - 4.3 m2		
No Asbestos		
B00B - R0005 - Apparatus Storage - 14.5 m2		
No Asbestos		
B00B - R0006 - Apparatus Storage - 24.72 m2		
No Asbestos		
B00B - R0007 - Distribution Board Cupboard - .61 m2		Note: No inspection of live electrical installation
No Asbestos		
B00B - R0008 - General Learning Space - Type 3 - 57.49 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0009 - General Learning Space - Type 3 - 58.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0010 - General Learning Space - Type 3 - 58.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0011 - General Learning Space - Type 3 - 57.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0012 - Science Laboratory - 97.94 m2		
No Asbestos		
B00B - R0013 - Science Laboratory - 97.52 m2		
No Asbestos		
B00B - R0014 - Preparation - Science - 49.28 m2		
No Asbestos		
B00B - R0015 - Science Laboratory - 97.94 m2		

No Asbestos		
B00B - R0016 - Seminar - Type 2 - 20.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R0017 - Seminar - 16.28 m2		
No Asbestos		
B00B - R0018 - Movement - 176.15 m2		
No Asbestos		
B00B - R0019 - Stairs - 7.39 m2		
No Asbestos		
B00B - R0020 - Distribution Board Cupboard - .59 m2		Note: No inspection of live electrical installation
No Asbestos		
B00B - R0021 - Movement - 68.9 m2		
No Asbestos		
B00B - R1002 - Distribution Board Cupboard - .8 m2		Note: No inspection of live electrical installation
No Asbestos		
B00B - R1003 - Cleaning Store - Distributed - 3.55 m2		
No Asbestos		
B00B - R1019 - General Learning Space - Type 1 - 58.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1020 - Movement - 160.5 m2		
No Asbestos		
B00B - R1023 - General Learning Space - Type 6 - 58.88 m2		
No Asbestos		
B00B - R1024 - General Learning Space - Type 7 - 58.79 m2		
No Asbestos		
B00B - R1025 - Seminar - Type 2 - 20.35 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1026 - Laundry - 9.59 m2		
No Asbestos		
B00B - R1027 - General Learning Space - Type 1 - 58.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1028 - General Learning Space - Type 1 - 59.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1029 - Distribution Board Cupboard - .71 m2		Note: No inspection of live electrical installation
No Asbestos		
B00B - R1030 - Performance Store - 18.81 m2		
No Asbestos		
B00B - R1031 - Practice/Seminar - 22.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1032 - Performance Workshop - 115.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00B - R1033 - Materials Store - Type 1 - 8.21 m2		
No Asbestos		
B00B - R1034 - Pantry - 5.39 m2		
No Asbestos		
B00B - R1035 - Preparation - Materials - 19.1 m2		
No Asbestos		
B00B - R1040 - Toilets-Girls - 19.12 m2		
No Asbestos		
B00B - R1041 - Toilets-Boys - 17.01 m2		
No Asbestos		
B00B - R1042 - Stairs - 7.04 m2		

No Asbestos	
B00B - R1043 - Food Technology L.S. - 93.81 m2	
No Asbestos	
B00B - R1044 - Food Technology L.S. - 93.34 m2	
No Asbestos	
B00B - R1045 - Food/Research Space - 13.5 m2	
No Asbestos	
B00B - R1046 - Pantry - 20.93 m2	
No Asbestos	
B00B - R1047 - Pantry - 3.42 m2	
No Asbestos	
B00C - Administration/General Learning - 2003 - Brick/Veneer	
Exterior	
Underfloor Voids - Slab on Ground	Non Accessible Area
Ceiling Voids	No Asbestos Found
Interior	
B00C - R0001 - Interview/Office - Type 1 - 14.75 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0002 - Deputy Principal Office - 16.08 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0003 - Administration - Executive - 23.37 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0004 - Principal Office - 20.39 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0005 - Security Store - 13.39 m2	
No Asbestos	
B00C - R0006 - Staff - Toilet - 5.06 m2	
No Asbestos	
B00C - R0007 - Staff - Toilet - 5.06 m2	
No Asbestos	
B00C - R0008 - Visitors Office - 13.35 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0009 - Movement - 16.57 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0010 - Interview/Meeting - 12.97 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0011 - Cleaning Store - Distributed - 2.72 m2	
No Asbestos	
B00C - R0012 - Public Reception - 34.11 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0013 - Tea Room - 4.92 m2	
No Asbestos	
B00C - R0014 - Administration - Clerical - 64.93 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0015 - Interview/Office - Type 2 - 13.36 m2	
Floor Coverings Res/Textile	No Asbestos Found
B00C - R0016 - Clinic - Boys - 13.28 m2	
No Asbestos	
B00C - R0017 - Access Staff Shower/Toilet - 5.1 m2	
No Asbestos	
B00C - R0018 - Student Reception - 54.26 m2	

Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0019 - Clinic - Girls - 12.28 m2		
No Asbestos		
B00C - R0020 - Distribution Board Cupboard - 1.08 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R0021 - Interview/Office - Type 1 - 13.1 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0022 - Movement - 7.56 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0023 - Interview/Meeting - 12.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R0024 - Movement - 360.61 m2		
No Asbestos		
B00C - R0025 - Stairs - 7.47 m2		
No Asbestos		
B00C - R0026 - Stairs - 7.97 m2		
No Asbestos		
B00C - R1025 - General Learning Space - Type 1 - 55.65 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1026 - General Learning Space - Type 1 - 56.53 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1027 - Seminar - Type 1 - 24.57 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1028 - General Learning Space - Type 1 - 56.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1029 - General Learning Space - Type 1 - 56.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1030 - General Learning Space - Type 2 - 68.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1032 - General Learning Space - Type 1 - 57.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1035 - Movement - 124.32 m2		
No Asbestos		
B00C - R1036 - Distribution Board Cupboard - .75 m2		Note: No inspection of live electrical installation
No Asbestos		
B00C - R1037 - Stairs - 7.53 m2		
No Asbestos		
B00C - R1038 - Stairs - 7.53 m2		
No Asbestos		
B00C - R1039 - Movement - 38.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1040 - General Storeroom - 5.23 m2		
No Asbestos		
B00C - R1041 - General Storeroom - 24.28 m2		
No Asbestos		
B00C - R1042 - Movement - 88.55 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00C - R1043 - Movement - 19.34 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - General Learning - 2003 - Brick/Veneer		
Exterior		

Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00D - R0001 - General Learning Space - Type 1 - 58.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0002 - Practical Activity Area - 12.81 m2		
No Asbestos		
B00D - R0003 - General Learning Space - Type 2 - 64.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0004 - Movement - 4.75 m2		
No Asbestos		
B00D - R0005 - General Learning Space - Type 1 - 59.3 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0006 - General Learning Space - Type 1 - 59.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0007 - Seminar - Type 1 - 24.46 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0008 - General Learning Space - Type 1 - 59.16 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0009 - General Learning Space - Type 1 - 60.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0010 - Store - 24.9 m2		
No Asbestos		
B00D - R0011 - Cleaning Store - Distributed - 3 m2		
No Asbestos		
B00D - R0012 - Store - .62 m2		
No Asbestos		
B00D - R0013 - Distribution Board Cupboard - .61 m2		
No Asbestos		Note: No inspection of live electrical installation
B00D - R0014 - Shared Learning Space - 140.43 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R0015 - Movement - 10.33 m2		
No Asbestos		
B00D - R0016 - Stairs - 9.26 m2		
No Asbestos		
B00D - R1004 - Distribution Board Cupboard - .61 m2		
No Asbestos		Note: No inspection of live electrical installation
B00D - R1009 - Practical Activity Area - 12.51 m2		
No Asbestos		
B00D - R1010 - Movement - 10.33 m2		
No Asbestos		
B00D - R1011 - Stairs - 19.86 m2		
No Asbestos		
B00D - R1012 - Shared Learning Space - 139.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1013 - General Learning Space - Type 1 - 58.79 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1014 - Movement - 4.78 m2		
No Asbestos		
B00D - R1015 - General Learning Space - Type 2 - 64.21 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1016 - General Learning Space - Type 1 - 59.22 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1017 - General Learning Space - Type 1 - 59.47 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1018 - Seminar - Type 1 - 24.42 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1019 - General Learning Space - Type 1 - 59.16 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1020 - General Learning Space - Type 1 - 60.29 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00D - R1021 - Store - 24.77 m2		
No Asbestos		
B00D - R1022 - Cleaning Store - Distributed - 3.04 m2		
No Asbestos		
B00D - R1023 - Store - .58 m2		
No Asbestos		
B00E - General Learning/Library - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00E - R0001 - General Learning Space - Type 2 - 64.2 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0002 - Shared Learning Space - 202.13 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0003 - Special Learning Space - 59.6 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0004 - Staff Study - 21.17 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0005 - Toilets-Disabled - 26.63 m2		
No Asbestos		
B00E - R0006 - Toilets-Disabled - 26.63 m2		
No Asbestos		
B00E - R0007 - Toilets-Boys - 43.33 m2		
No Asbestos		
B00E - R0008 - Student Laundry - Type 2 - 7.56 m2		
No Asbestos		
B00E - R0009 - Distribution Board Cupboard - .64 m2		
No Asbestos		Note: No inspection of live electrical installation
B00E - R0010 - Toilets-Girls - 63.41 m2		
No Asbestos		
B00E - R0011 - G.L.S. Store - 20.31 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0012 - Special Learning Space - 60.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0013 - Special Learning Space - 60.03 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0014 - Seminar - Type 1 - 25.22 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0015 - General Learning Space - Type 1 - 60.11 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0016 - General Learning Space - Type 1 - 60.19 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00E - R0017 - G.L.S. Store - 24.35 m2		
No Asbestos		
B00E - R0018 - Cleaning Store - Distributed - 3 m2		
No Asbestos		
B00E - R0019 - Distribution Board Cupboard - .64 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R0020 - Movement - 55.8 m2		
No Asbestos		
B00E - R0021 - Stairs - 7.54 m2		
No Asbestos		
B00E - R0022 - Movement - 13.47 m2		
No Asbestos		
B00E - R0023 - Movement - 209.05 m2		
No Asbestos		
B00E - R1017 - Distribution Board Cupboard - .52 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R1018 - Distribution Board Cupboard - .41 m2		Note: No inspection of live electrical installation
No Asbestos		
B00E - R1019 - Movement - 21.8 m2		
No Asbestos		
B00E - R1020 - Stairs - 16.57 m2		
No Asbestos		
B00E - R1021 - Seminar - Type 3 - 12.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1022 - Seminar - Type 3 - 12.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1023 - Seminar - Type 3 - 12.91 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1024 - Careers Advisers Office - 12.15 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1025 - Main Area - 425.52 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1026 - Computer Learning Space - 63.09 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1027 - Movement - 46.97 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1028 - Computer Store - 11.48 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1029 - Staff - Toilet - 5.99 m2		
No Asbestos		
B00E - R1030 - Toilets-Disabled - 4.84 m2		
No Asbestos		
B00E - R1031 - General Learning Space - 57.01 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1032 - Movement - 108.32 m2		
No Asbestos		
B00E - R1033 - General Learning Space - 57.92 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1034 - General Learning Space - 63.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1035 - Communication Space - 10.72 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1036 - System Administrators Office - 13.26 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00E - R1037 - Library Administration - 77.79 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - Staff Facilities/General Learning - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00F - R0001 - General Learning Space - Type 1 - 58.78 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0002 - Shared Learning Space - 157.12 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0003 - General Learning Space - Type 2 - 64.05 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0004 - Movement - 296.78 m2		
No Asbestos		
B00F - R0005 - General Learning Space - Type 1 - 59.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0006 - General Learning Space - Type 1 - 59.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0007 - Seminar - Type 1 - 38.71 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0008 - General Learning Space - Type 1 - 58.36 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0009 - General Learning Space - Type 1 - 59.45 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R0010 - G.L.S. Store - 40.79 m2		
No Asbestos		
B00F - R0011 - Cleaning Store - Distributed - 2.94 m2		
No Asbestos		
B00F - R0012 - Distribution Board Cupboard - 1.37 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0013 - Distribution Board Cupboard - .77 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R0014 - Practical Activity Area - 14.28 m2		
No Asbestos		
B00F - R0015 - Stairs - 6.71 m2		
No Asbestos		
B00F - R1010 - Movement - 106.22 m2		
No Asbestos		
B00F - R1011 - Movement - 88.58 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1012 - Movement - 13.76 m2		
No Asbestos		
B00F - R1013 - Stairs - 6.71 m2		
No Asbestos		
B00F - R1014 - Interview/Meeting - 12.38 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1015 - Interview/Meeting - 12.38 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1016 - Preparation/Printing - 34.71 m2		
No Asbestos		
B00F - R1017 - Distribution Board Cupboard - .81 m2		Note: No inspection of live electrical installation
No Asbestos		
B00F - R1018 - Access Staff Shower/Toilet - 5.06 m2		
No Asbestos		
B00F - R1019 - Cleaning Store - Distributed - 4.63 m2		
No Asbestos		
B00F - R1020 - Staff - Toilet - 4.63 m2		
No Asbestos		
B00F - R1021 - Staff - Toilet - 4.63 m2		
No Asbestos		
B00F - R1022 - Staff - Toilet - 4.63 m2		
No Asbestos		
B00F - R1023 - Staff - Toilet - 4.63 m2		
No Asbestos		
B00F - R1024 - Interview/Meeting - 12.68 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1025 - Interview/Meeting - 12.76 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1026 - Staff Study - 200.4 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1027 - Staff Lounge - 106.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00F - R1028 - Staff Study - 200.02 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - Performing Arts/Technological & Applied Studies - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00G - R0001 - Distribution Board Cupboard - .95 m2		Note: No inspection of live electrical installation
No Asbestos		
B00G - R0002 - Dust Extraction Space - 7.71 m2		
No Asbestos		
B00G - R0003 - Project Store - Type 1 - 21.97 m2		
No Asbestos		
B00G - R0004 - Materials Workshop - Type 3 - 121.82 m2		
No Asbestos		
B00G - R0005 - Seminar - Type 1 - 19.98 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0006 - Fitness Store - 19.85 m2		
No Asbestos		
B00G - R0007 - Fitness Laboratory - 100.99 m2		
No Asbestos		
B00G - R0008 - Change - 24.06 m2		
No Asbestos		
B00G - R0009 - Change - 21.86 m2		
No Asbestos		
B00G - R0010 - General Learning Space - Type 1 - 59.71 m2		

Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0011 - General Learning Space - Type 1 - 60.04 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0012 - Visual Arts Store - 20.28 m2		
Floor Coverings Res/Textile	No Asbestos Found	
B00G - R0013 - General Learning Space - Type 9 - 59.55 m2		
No Asbestos		
B00G - R0014 - General Learning Space - Type 5 - 59.69 m2		
No Asbestos		
B00G - R0015 - Distribution Board Cupboard - .56 m2		Note: No inspection of live electrical installation
No Asbestos		
B00G - R0016 - Movement - 273.37 m2		
No Asbestos		
B00H - Technological & Applied Studies - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00H - R0001 - Distribution Board Cupboard - .89 m2		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0002 - Dust Extraction Space - 7.52 m2		
No Asbestos		
B00H - R0003 - Project Store - Type 1 - 7.51 m2		
No Asbestos		
B00H - R0004 - Materials Workshop - Type 2 - 108.24 m2		
No Asbestos		
B00H - R0005 - Materials Store - Type 2 - 36.77 m2		
No Asbestos		
B00H - R0006 - Visual Arts Workshop - 100.16 m2		
No Asbestos		
B00H - R0007 - Cleaning Store - Distributed - 3.03 m2		
No Asbestos		
B00H - R0008 - Distribution Board Cupboard - 1.94 m2		Note: No inspection of live electrical installation
No Asbestos		
B00H - R0009 - Dark Room - 28.78 m2		
No Asbestos		
B00H - R0010 - General Learning Space - Type 5 - 60.3 m2		
No Asbestos		
B00H - R0011 - General Learning Space - Type 4 - 60.44 m2		
No Asbestos		
B00H - R0012 - Visual Arts Store - 18.96 m2		
No Asbestos		
B00H - R0013 - Project Store - Type 1 - 46.7 m2		
No Asbestos		
B00H - R0014 - General Learning Space - Type 9 - 60.78 m2		
No Asbestos		
B00H - R0015 - General Learning Space - Type 8 - 60.64 m2		
No Asbestos		
B00H - R0016 - Outdoor Workshop - 87.73 m2		
No Asbestos		
B00H - R0017 - L.P.G Store - .91 m2		

No Asbestos		
B00H - R0018 - Welding/Hot Metals Area - 12.23 m2		
No Asbestos		
B00H - R0019 - Pottery Store - 9.71 m2		
No Asbestos		
B00H - R0020 - Kiln Space - 8.87 m2		
No Asbestos		
B00H - R0021 - Welding/Hot Metals Area - 11.39 m2		
No Asbestos		
B00H - R0022 - Movement - 192.99 m2		
No Asbestos		
B00I - Mechanical Services - 2003 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
Interior		
B00I - R0001 - Movement - 3.85 m2		
No Asbestos		
B00I - R0002 - Lift - 2.1 m2		
No Asbestos		
B00I - R0003 - Plant - 4.2 m2		
No Asbestos		
B00I - R0004 - Movement - 19.76 m2		
No Asbestos		
B00I - R0005 - Stairs - 8.66 m2		
No Asbestos		
B00I - R1001 - Lift - 2.1 m2		
No Asbestos		
B00I - R1002 - Movement - 3.85 m2		
No Asbestos		
B00I - R1003 - Movement - 19.15 m2		
No Asbestos		
B00I - R1004 - Stairs - 8.66 m2		
No Asbestos		

Demountables

NS 200 11651 - Art Learning Space/Workshop/Bulk Store - Placement Date : 12-FEB-2007

No Asbestos Found

NS 110 13825 - Learning Unit - Single Secondary/Secure - Placement Date : 07-FEB-2007

No Asbestos Found

NS 110 14379 - Learning Unit - Single Secondary/Secure - Placement Date : 07-FEB-2007

No Asbestos Found