

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Keira High School (8541)</b>
<b>Region:</b>	<b>Southern NSW AMU</b>
<b>State Electorate:</b>	<b>Keira</b>
<b>Local Government Area:</b>	<b>Wollongong</b>

<b>Last Reviewed By:</b>	<b>Greencap 26-AUG-2014</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

8541 - Keira High School  
Site Plan (13205)



1:3,248

Printed: 21-Mar-2020

# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Physical Education - 1985 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00A - M0001 - Sport Equipment Store - 38.08 m2</b>							
No Asbestos							
<b>B00A - M0002 - Stairs - 2.28 m2</b>							
No Asbestos							
<b>B00A - R0001 - Shower/Change - 66.57 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00A - R0002 - Shower/Change - 71.28 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00A - R0003 - Gymnasium - 287.9 m2</b>							
No Asbestos							
<b>B00A - R0004 - Sport Equipment Store - 16.07 m2</b>							
No Asbestos							
<b>B00A - R0005 - Staff - Toilet - 3.11 m2</b>							
No Asbestos							
<b>B00A - R0006 - Sport Equipment Store - 35.13 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	18m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0007 - Plant Space - 6.43 m2</b>							
Plant / Equipment - Flue	Fibre Cement Pipe	2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0008 - Stairs - .36 m2</b>							
No Asbestos							
<b>B00A - R0009 - Main Switchroom - 2.35 m2</b>							
No Asbestos							
<b>B00B - Administration/General Learning - 1969 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
External Wall Structure - Awnings	Flat AC Sheeting						
External Roof Structure	Resinous Membrane	160	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00B - R0001 - Duplicating Workroom - 26.88 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	26.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0002 - Administration - Clerical - 38.62 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	38.62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	38.62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0003 - Movement - 11.93 m2</b>							
No Asbestos							
<b>B00B - R0004 - Clinic - Boys - 13.57 m2</b>							
No Asbestos							
<b>B00B - R0005 - Clinic-Toilets - 2.25 m2</b>							
No Asbestos							
<b>B00B - R0006 - Clinic - Girls - 13.49 m2</b>							
No Asbestos							
<b>B00B - R0007 - Clinic-Toilets - 2.25 m2</b>							
No Asbestos							
<b>B00B - R0009 - Administration - Clerical - 10.83 m2</b>							
No Asbestos							
<b>B00B - R0010 - Principal Office - 22.36 m2</b>							
No Asbestos							
<b>B00B - R0011 - Leading Teacher - 12.12 m2</b>							
Floor Coverings Res/Textile	Vinyl Sheet						
<b>B00B - R0012 - Security Store - 6.15 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	6.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0013 - Staff Study - 14.3 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	14.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0014 - Staff - Toilet - 7.52 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0015 - Security Store - .89 m2</b>							
No Asbestos							
<b>B00B - R0016 - Security Store - 2.89 m2</b>							
No Asbestos							
<b>B00B - R0018 - Deputy Principal Office - 29.4 m2</b>							
No Asbestos							
<b>B00B - R0019 - Staff - Toilet - 7.3 m2</b>							
No Asbestos							
<b>B00B - R0020 - Security Store - 16.16 m2</b>							
No Asbestos							
<b>B00B - R0022 - Commonroom - 52.97 m2</b>							
No Asbestos							
<b>B00B - R0023 - Cleaning Store - Distributed - 1.08 m2</b>							
No Asbestos							
<b>B00B - R0024 - Deputy Principal Office - 21.41 m2</b>							
No Asbestos							
<b>B00B - R0025 - Movement - 16.9 m2</b>							
No Asbestos							
<b>B00B - R0026 - General Learning Space - 53.23 m2</b>							
No Asbestos							
<b>B00B - R0027 - General Learning Space - 53.07 m2</b>							
No Asbestos							
<b>B00B - R0028 - General Learning Space - 53.07 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0029 - General Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	56.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0030 - Staff Study - 7.84 m2</b>							
No Asbestos							
<b>B00B - R0031 - Main Switchroom - 7.6 m2</b>							
Electrical - Mounting Board	Resinous Board	3	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0032 - General Learning Space - 52.33 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0033 - Laboratory L.S. - 89.93 m2</b>							
No Asbestos							
<b>B00B - R0034 - Preparation - Science - 15.87 m2</b>							
No Asbestos							
<b>B00B - R0035 - Chemical Store - 10.73 m2</b>							
No Asbestos							
<b>B00B - R0036 - Cleaning Store - Distributed - .7 m2</b>							
No Asbestos							
<b>B00B - R0038 - Special Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0040 - General Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0041 - Cleaning Store - Distributed - .88 m2</b>							
No Asbestos							
<b>B00B - R0042 - Movement - 29.42 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0044 - Movement - 4.12 m2</b>							
No Asbestos							
<b>B00B - R0045 - Public Entry - 48.36 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	4.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0046 - Movement - 52.6 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	52.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0047 - Stairs - 7.3 m2</b>							
No Asbestos							
<b>B00B - R0048 - External Movement - 4.05 m2</b>							
No Asbestos							
<b>B00B - R0049 - Stairs - 6.52 m2</b>							
No Asbestos							
<b>B00B - R0050 - Toilets-Disabled - 6.05 m2</b>							
No Asbestos							
<b>B00B - R0051 - Withdrawal - S - 9.7 m2</b>							
No Asbestos							
<b>B00B - R0052 - Toilets-Disabled - 12.92 m2</b>							
No Asbestos							
<b>B00B - R0053 - Staff Study - 24.15 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive	24.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	24.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0054 - Movement - 14.19 m2</b>							
No Asbestos							
<b>B00B - R0055 - Movement - 267.32 m2</b>							
Electrical - Mounting Board	Resinous Board	0.2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R0056 - General Storeroom - 9.77 m2</b>							
No Asbestos							
<b>B00B - R0057 - External Movement - 14.39 m2</b>							
No Asbestos							
<b>B00B - R0058 - Covered Vehicle Area/Porte Cochere - 90.1 m2</b>							
No Asbestos							
<b>B00B - R0059 - External Movement - 16.28 m2</b>							
No Asbestos							
<b>B00B - R1001 - General Storeroom - 3.84 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R1002 - Staff - Toilet - 2.53 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R1003 - Staff Study - 38.64 m2</b>							
No Asbestos							
<b>B00B - R1004 - Staff - Toilet - 7.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R1006 - General Storeroom - 15.74 m2</b>							

No Asbestos							
<b>B00B - R1007 - General Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1008 - General Learning Space - 53.07 m2</b>							
No Asbestos							
<b>B00B - R1009 - General Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1010 - General Learning Space - 53.07 m2</b>							
No Asbestos							
<b>B00B - R1011 - General Learning Space - 53.07 m2</b>							
No Asbestos							
<b>B00B - R1012 - Computer Learning Space - 53.07 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	53.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1013 - General Storeroom - 15.87 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R1014 - Staff - Toilet - 15.41 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00B - R1015 - General Storeroom - 14.23 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	14.23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R1016 - Staff - Toilet - 16.17 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00B - R1017 - Preparation/Printing - 19.75 m2</b>							
No Asbestos							
<b>B00B - R1018 - Commonroom - 146.29 m2</b>							
No Asbestos							
<b>B00B - R1019 - General Learning Space - 52.91 m2</b>							
No Asbestos							
<b>B00B - R1020 - Preparation - 15.51 m2</b>							
No Asbestos							
<b>B00B - R1021 - Laboratory L.S. - 89.6 m2</b>							
No Asbestos							
<b>B00B - R1022 - Apparatus Store - 10.47 m2</b>							
No Asbestos							
<b>B00B - R1023 - Cleaning Store - Distributed - .75 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1024 - Cleaning Store - Distributed - .88 m2</b>							
No Asbestos							

<b>B00B - R1025 - Movement - 8.71 m2</b>							
No Asbestos							
<b>B00B - R1026 - Cleaning Distributed Store - 1.12 m2</b>							
No Asbestos							
<b>B00B - R1027 - Stairs - 3.44 m2</b>							
No Asbestos							
<b>B00B - R1028 - Movement - 251.72 m2</b>							
No Asbestos							
<b>B00B - R1029 - Stairs - 3.44 m2</b>							
No Asbestos							
<b>B00B - R1030 - External Movement - 1.23 m2</b>							
No Asbestos							
<b>B00C - Science/General Learning - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids	No Asbestos Found						
Ceiling Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00C - R0001 - Movement - 80.04 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
Window	Compressed AC Sheet	20	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0002 - General Storeroom - 19.49 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19.49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00C - R0003 - Laboratory L.S. - 85.75 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )						
Window	Compressed AC Sheet	12	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0004 - Preparation - 20.1 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles						
Plant / Equipment - Fume Cupboard	Flat AC Sheeting	1	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Plant / Equipment - Flue	Fibre Cement Pipe	2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00C - R0005 - Growing/Breeding - 4.8 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00C - R0006 - Distribution Board Cupboard - .33 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00C - R0007 - External Movement - 6.34 m2</b>							



No Asbestos							
<b>B00C - R0008 - External Movement - 7.35 m2</b>							
No Asbestos							
<b>B00C - R0009 - External Movement - 2.78 m2</b>							
No Asbestos							
<b>B00C - R0010 - Stairs - 4.98 m2</b>							
No Asbestos							
<b>B00C - R0011 - Stairs - 5.04 m2</b>							
No Asbestos							
<b>B00C - R0012 - External Movement - 4.43 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1001 - Apparatus Store - 9.27 m2</b>							
No Asbestos							
<b>B00C - R1002 - Staff - Toilet - 6.75 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
<b>B00C - R1003 - Cleaning Store - Distributed - 9.62 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
<b>B00C - R1004 - General Learning Space - 52.56 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Wn dow	Compressed AC Sheet	8	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1005 - General Learning Space - 52.24 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Wn dow	Compressed AC Sheet	8	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1006 - Cleaning Store - Distributed - .27 m2</b>							
No Asbestos							
<b>B00C - R1008 - Stairs - 12.21 m2</b>							
Wn dow	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1009 - Stairs - 14.23 m2</b>							
Wn dow	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1010 - External Movement - 2.39 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00C - R1011 - Movement - 62.41 m2</b>							
Furniture / Fixtures	Compressed AC Sheet	63	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wn dow	Compressed AC Sheet	20	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	63m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

<b>B00C - R2001 - Staff Study - 25.55 m2</b>							
Window	Compressed AC Sheet	4	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2002 - Special Learning Space - 52.49 m2</b>							
Window	Compressed AC Sheet	53	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2003 - General Learning Space - 52.17 m2</b>							
Window	Compressed AC Sheet	8	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2004 - Distribution Board Cupboard - .27 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00C - R2005 - General Storeroom - 5.98 m2</b>							
Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	5.98m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2006 - Movement - 51.1 m2</b>							
Window	Compressed AC Sheet	20	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2007 - Stairs - 16.06 m2</b>							
Window	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R2008 - Stairs - 15.9 m2</b>							
Window	Compressed AC Sheet	5	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - Pupil Facilities - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Cleaning Store - Distributed - 13.71 m2</b>							
No Asbestos							
<b>B00D - R0002 - Garden Store Room - 21.79 m2</b>							
No Asbestos							
<b>B00D - R0003 - Sport Equipment Store - 30.52 m2</b>							
No Asbestos							
<b>B00D - R0004 - General Assistants - 18.18 m2</b>							
No Asbestos							
<b>B00D - R0005 - Distribution Board Cupboard - .83 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00D - R0006 - Shower/Change - 65.57 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00D - R0007 - Shower/Change - 100.01 m2</b>							
No Asbestos							
<b>B00D - R0008 - Cleaning Store - Distributed - 2.99 m2</b>							

No Asbestos							
<b>B00D - R0009 - Cleaning Store - Distributed - 5.53 m2</b>							
No Asbestos							
<b>B00D - R0010 - Staff - Toilet - 3.04 m2</b>							
No Asbestos							
<b>B00D - R0011 - External Movement - 19.73 m2</b>							
No Asbestos							
<b>B00D - R0012 - External Movement - 49.92 m2</b>							
No Asbestos							
<b>B00E - Technological &amp; Applied Studies/Art - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting						
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00E - R0001 - Materials Technology L.S. - 134.19 m2</b>							
Wall Linings Internal	Flat AC Sheeting	25m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R0002 - Materials Technology L.S. - 111.38 m2</b>							
Wall Linings Internal	Flat AC Sheeting	25m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R0003 - Seminar/Technology Space - 21.86 m2</b>							
Wall Linings Internal	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)
<b>B00E - R0004 - Materials Store - 16.21 m2</b>							
No Asbestos							
<b>B00E - R0005 - Materials Store - 7.72 m2</b>							
No Asbestos							
<b>B00E - R0006 - Materials Technology L.S. - 103.52 m2</b>							
No Asbestos							
<b>B00E - R0007 - Materials Store - 12.17 m2</b>							
No Asbestos							
<b>B00E - R0008 - Materials Store - 7.75 m2</b>							
No Asbestos							
<b>B00E - R0009 - Cleaning Store - Distributed - 3.42 m2</b>							
No Asbestos							
<b>B00E - R0010 - Materials Store - 27.86 m2</b>							
No Asbestos							
<b>B00E - R0011 - Design L.S. - 74.72 m2</b>							
No Asbestos							
<b>B00E - R0012 - Movement - 4.56 m2</b>							
No Asbestos							
<b>B00E - R0014 - Staff Study - 35.52 m2</b>							
No Asbestos							
<b>B00E - R0015 - Staff - Toilet - 5.74 m2</b>							
No Asbestos							
<b>B00E - R0016 - Staff - Toilet - 5.7 m2</b>							
No Asbestos							
<b>B00E - R0017 - Design L.S. - 80 m2</b>							
No Asbestos							

<b>B00E - R0018 - Materials Technology L.S. - 103.52 m2</b>								
No Asbestos								
<b>B00E - R0019 - Materials Store - 16.18 m2</b>								
No Asbestos								
<b>B00E - R0020 - Materials Store - 7.81 m2</b>								
No Asbestos								
<b>B00E - R0021 - Movement - 143.23 m2</b>								
No Asbestos								
<b>B00E - R0023 - Art Learning Space - 60.06 m2</b>								
No Asbestos								
<b>B00E - R0024 - Resources Store - 13.46 m2</b>								
No Asbestos								
<b>B00E - R0026 - Darkroom Space - 54.52 m2</b>								
No Asbestos								
<b>B00E - R0027 - Art Learning Space - 81.62 m2</b>								
No Asbestos								
<b>B00E - R0028 - Staff Study - 16.16 m2</b>								
No Asbestos								
<b>B00E - R0031 - Resources Store - 17.44 m2</b>								
No Asbestos								
<b>B00E - R0032 - Distribution Board Cupboard - 1.53 m2</b>								
						<b>Note: No inspection of live electrical installation</b>		
Electrical - Mounting Board	Resinous Board	0.4	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00E - R0033 - Computer Learning Space - 50.64 m2</b>								
No Asbestos								
<b>B00E - R0034 - Movement - 5.54 m2</b>								
No Asbestos								
<b>B00E - R0035 - Movement - 41.27 m2</b>								
No Asbestos								
<b>B00E - R0036 - Movement - 8.24 m2</b>								
No Asbestos								
<b>B00E - R0037 - Art Learning Space - 76.85 m2</b>								
No Asbestos								
<b>B00E - R0038 - External Movement - 4.81 m2</b>								
No Asbestos								
<b>B00E - R0039 - External Movement - 4.78 m2</b>								
No Asbestos								
<b>B00G - Science/Music - 1952 - Concrete Framed</b>								
<b>Exterior</b>								
Wall Cladding	Flat AC Sheeting							
External Wall Structure - Awnings	Flat AC Sheeting							
Underfloor Voids	Flat AC Sheeting	50	South	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found							
<b>Interior</b>								
<b>B00G - R0001 - Cleaning Store - Distributed - 5.51 m2</b>								
No Asbestos								
<b>B00G - R0002 - General Storeroom - 6.46 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )							

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0003 - Cleaning Store - Distributed - 6.51 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0004 - Movement - 22.1 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0005 - General Learning Space - 53.57 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R0006 - General Learning Space - 53.87 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R0007 - General Learning Space - 52.99 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R0008 - General Learning Space - 53.72 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R0009 - Stage - 26.2 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R0010 - Performing Arts Changeroom - 7.95 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0011 - Performing Arts Changeroom - 7.95 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0012 - Distribution Board Cupboard - .65 m2</b>							
						<b>Note: No inspection of live electrical installation</b>	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R0014 - Careers Advisers Office - 29.65 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R0015 - Cleaning Store - Distributed - 4.86 m2</b>							
No Asbestos							
<b>B00G- R0017 - Movement - 319.9 m2</b>							
No Asbestos							
<b>B00G- R0018 - Student Canteen - 43.64 m2</b>							
Ceiling Structures/Linings	Non Accessible Area	m2					
Wall Linings Internal	Flat AC Sheeting	15m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles							
<b>B00G- R0019 - General Storeroom - 4.81 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R0020 - Staff - Toilet - 3.11 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R0021 - Disabled Toilet - 9.86 m2</b>								
No Asbestos								
<b>B00G- R0023 - Distribution Board Cupboard - 1.15 m2</b>						<b>Note: No inspection of live electrical installation</b>		
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Electrical - Mounting Board	Resinous Board							
<b>B00G- R0024 - Apparatus Store - 28.97 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	28.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
<b>B00G- R0025 - Laboratory L.S. - 87.14 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
Furniture / Fixtures	Flat AC Sheeting	2	East	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R0026 - Preparation - 29.34 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
<b>B00G- R0027 - Growing/Breeding - 9.57 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
<b>B00G- R0028 - Laboratory L.S. - 87.41 m2</b>								
Ceiling Structures/Linings	Non Accessible Area	m2						
Furniture / Fixtures	Flat AC Sheeting	2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R0029 - General Storeroom - 5.5 m2</b>								
No Asbestos								
<b>B00G- R0030 - External Movement - 71.52 m2</b>								
No Asbestos								
<b>B00G- R0031 - Stairs - 5.24 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R0032 - Interview - 7.07 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R0033 - Movement - 27.88 m2</b>								

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00G- R0034 - Stairs - 4.5 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R0035 - General Storeroom - 4.65 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	4.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R0036 - Stairs - 9.59 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R0037 - Stairs - 4.93 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R0038 - External Movement - 2.13 m2</b>								
No Asbestos								
<b>B00G- R0040 - Lift - 2.25 m2</b>								
Ceiling Structures/Linings	Flat AC Sheeting							
<b>B00G- R0041 - Movement - 119.29 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
Floor Coverings Res/Textile	Vinyl Tiles	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1001 - Movement - 16.8 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1002 - Cleaning Store - Distributed - 3.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R1003 - Communication Space - 17.79 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	47.9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1005 - Study Space - 12.99 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1006 - Study Space - 12.99 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1007 - General Learning Space - 66.88 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
<b>B00G- R1008 - Study Space - 12.96 m2</b>								

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1009 - Study Space - 12.99 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1010 - Staff Study - 56.96 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
<b>B00G- R1011 - Distribution Board Cupboard - .66 m2</b>						<b>Note: No inspection of live electrical installation</b>		
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1013 - Staff Study - 27.67 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00G- R1014 - General Learning Space - 54.31 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
<b>B00G- R1015 - General Storeroom - 24.05 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting							
<b>B00G- R1016 - General Learning Space - 55.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting							
<b>B00G- R1017 - Computer Learning Space - 81.1 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )							
Floor Coverings Res/Textile	Vinyl Tiles	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1018 - Computer Learning Space - 53.94 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1019 - Staff Study - 29.08 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1020 - Staff - Toilet - 9.86 m2</b>								



Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Partition Walls (Cubides)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1021 - Distribution Board Cupboard - 1.15 m2</b>				<b>Note: No inspection of live electrical installation</b>				
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1022 - Apparatus Store - 24.27 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1023 - Laboratory L.S. - 87.21 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )							
Furniture / Fixtures	Compressed AC Sheet	2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1026 - Laboratory L.S. - 87.73 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )							
Furniture / Fixtures	Compressed AC Sheet	2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1027 - External Movement - 75.94 m2</b>								
Wall Linings Internal - Infill	Flat AC Sheeting							
<b>B00G- R1028 - Stairs - 16.73 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							
<b>B00G- R1029 - General Learning Space - 53.43 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
<b>B00G- R1030 - General Storeroom - 6.28 m2</b>								
Floor Coverings Res/Textile	Vinyl Tiles	6.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
<b>B00G- R1031 - General Storeroom - 6.31 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	6.31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1032 - Movement - 7.18 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R1033 - Stairs - 15.52 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )							

<b>B00G- R1035 - Stairs - 16.46 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R1036 - Staff Study - 38.95 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R1037 - Stairs - 16.99 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R1038 - Lift - 2.25 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00G- R1039 - Movement - 213.72 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 120 - 250 m2) - ( X15 )						
Floor Coverings Res/Textile	Vinyl Tiles	213.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2001 - Movement - 16.87 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R2002 - External Movement - 73.94 m2</b>							
No Asbestos							
<b>B00G- R2003 - Cleaning Store - Distributed - 3.87 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	3.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2004 - Senior Study - 17.6 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2005 - General Learning Space - 53.36 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R2006 - General Learning Space - 53.58 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2007 - General Learning Space - 53.58 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2008 - General Storeroom - 12.99 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2009 - General Storeroom - 6.37 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2010 - General Storeroom - 6.33 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2011 - General Learning Space - 57.85 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Floor Coverings Res/Textile	Vinyl Tiles	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2013 - Distribution Board Cupboard - .59 m2</b>				<b>Note: No inspection of live electrical installation</b>			
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2014 - Practice/Seminar - 53.95 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R2015 - Secure Storeroom - 12.8 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2016 - Resources - 26.49 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R2017 - Practice/Seminar - 26.57 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R2018 - General Learning Space - 64.97 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
<b>B00G- R2019 - Practice/Seminar - 28.64 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G- R2020 - Computer Learning Space - 53.5 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )						
Floor Coverings Res/Textile	Vinyl Tiles	53.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2021 - Staff Study - 26.79 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00G- R2022 - Staff - Toilet - 9.74 m2</b>							
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G- R2023 - Movement - 76.52 m2</b>							

Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 70 - 120 m2) - ( X8 )							
Floor Coverings Res/Textile	Vinyl Tiles	77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2025 - Distribution Board Cupboard - 1.15 m2</b>								<b>Note: No inspection of live electrical installation</b>
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2026 - General Learning Space - 51.43 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2027 - General Storeroom - 6.33 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2028 - General Storeroom - 6.37 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2029 - General Learning Space - 53.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2030 - General Learning Space - 53.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2031 - General Storeroom - 5.13 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2032 - General Learning Space - 53.87 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 40 - 70 m2) - ( X5 )							
Floor Coverings Res/Textile	Vinyl Tiles	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2033 - Cleaning Store - Distributed - 2.48 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
<b>B00G- R2034 - General Storeroom - 5.13 m2</b>								
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )							

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R2035 - Stairs - 16.73 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G - R2036 - Movement - 7.19 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( < 10 m2) - ( X2 )						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R2037 - Staff Study - 27.46 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - R2038 - Stairs - 14.9 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G - R2039 - Stairs - 15.74 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 10 - 40 m2) - ( X3 )						
<b>B00G - R2040 - Stairs - 16.44 m2</b>							
No Asbestos							
<b>B00G - R2041 - Lift - 2.25 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00G - R2042 - Movement - 135.38 m2</b>							
Ceiling Structures/Linings	Vermiculite - Composite Sample - ( 120 - 250 m2) - ( X15 )						
Floor Coverings Res/Textile	Vinyl Tiles	135.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - Library/Technological &amp; Applied Studies - 1969 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	150m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
External Wall Structure - Awnings	Flat AC Sheeting	20	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00H - R0003 - Toilets-Girls - 14 m2</b>							
No Asbestos							
<b>B00H - R0004 - Distribution Board Cupboard - 2.07 m2</b>							
No Asbestos							
<b>B00H - R0005 - Food Technology L.S. - 102.93 m2</b>							
No Asbestos							
<b>B00H - R0006 - Preparation - Materials - 18.43 m2</b>							
No Asbestos							
<b>B00H - R0007 - Laundry - 11.94 m2</b>							
No Asbestos							
<b>B00H - R0008 - Food Technology L.S. - 103.08 m2</b>							

No Asbestos		
<b>B00H - R0009 - Design L.S. - 65.85 m2</b>		
No Asbestos		
<b>B00H - R0011 - General Learning Space - 67.35 m2</b>		
No Asbestos		
<b>B00H - R0012 - External Movement - 9.24 m2</b>		
No Asbestos		
<b>B00H - R0014 - Staff Kitchen - 5.46 m2</b>		
No Asbestos		
<b>B00H - R0015 - Staff Study - 17.52 m2</b>		
No Asbestos		
<b>B00H - R0016 - External Movement - 23.48 m2</b>		
No Asbestos		
<b>B00H - R0017 - Movement - 81.3 m2</b>		
No Asbestos		
<b>B00H - R0018 - Food Technology L.S. - 41.2 m2</b>		
No Asbestos		
<b>B00H - R0019 - Materials Store - 18.79 m2</b>		
No Asbestos		
<b>B00H - R1001 - Toilets-Boys - 17.27 m2</b>		
No Asbestos		
<b>B00H - R1002 - Movement - 13.74 m2</b>		
No Asbestos		
<b>B00H - R1003 - Distribution Board Cupboard - 1.47 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R1004 - Toilets-Girls - 17.27 m2</b>		
No Asbestos		
<b>B00H - R1005 - Main Area - 444.79 m2</b>		
No Asbestos		
<b>B00H - R1006 - Workroom - 42.44 m2</b>		
No Asbestos		
<b>B00H - R1007 - Audio Visual Workroom - 43.5 m2</b>		
No Asbestos		
<b>B00H - R1008 - Librarian - 13.72 m2</b>		
No Asbestos		
<b>B00H - R1009 - Seminar - 14.4 m2</b>		
No Asbestos		
<b>B00H - R1010 - Seminar - 14.7 m2</b>		
No Asbestos		
<b>B00H - R1011 - Seminar - 14.44 m2</b>		
No Asbestos		
<b>B00H - R1012 - External Movement - 2.01 m2</b>		
No Asbestos		
<b>B00H - R1014 - External Movement - 22 m2</b>		
No Asbestos		
<b>B00I - Building Services - 2007 - Steel</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00I - R0001 - General Storeroom - 97.5 m2</b>		
No Asbestos		

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020