


# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Kincumber High School (8585)</b>
<b>Region:</b>	<b>Hunter/Central Coast AMU</b>
<b>State Electorate:</b>	<b>Terrigal</b>
<b>Local Government Area:</b>	<b>Central Coast</b>

<b>Last Reviewed By:</b>	<b>WSP 29-JUN-2017</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Administration - 1989 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Ancillary Staff - 22.12 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0002 - Staff - Toilet - 3.37 m2</b>							
No Asbestos							
<b>B00A - R0003 - Deputy Principal Office - 13.19 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0004 - Principal Office - 19.8 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0005 - Administration - Executive - 12.71 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0006 - Leading Teacher - 12.61 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0007 - Clinic - Girls - 13.89 m2</b>							
No Asbestos							
<b>B00A - R0008 - Toilets-Girls - 2.29 m2</b>							
No Asbestos							
<b>B00A - R0009 - Toilets-Boys - 2.31 m2</b>							
No Asbestos							
<b>B00A - R0010 - Clinic - Boys - 14.05 m2</b>							
No Asbestos							
<b>B00A - R0011 - Deputy Principal Office - 16.14 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0012 - Administration - Clerical - 35.12 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0013 - Secure Storeroom - 18.48 m2</b>							
No Asbestos							
<b>B00A - R0015 - Cleaning Store - Distributed - 3.03 m2</b>							
No Asbestos							
<b>B00A - R0018 - Distribution Board Cupboard - .73 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00A - R0019 - Student Canteen - 54.85 m2</b>							
No Asbestos							
<b>B00A - R0020 - Office/Store - 12.35 m2</b>							
No Asbestos							
<b>B00A - R0021 - Toilets-Disabled - 5.04 m2</b>							
No Asbestos							
<b>B00A - R0023 - General Assistants - 13.19 m2</b>							
No Asbestos							
<b>B00A - R0026 - Printing/Photocopying - 26.18 m2</b>							
No Asbestos							
<b>B00A - R0027 - Movement - 87.29 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0028 - External Movement - 340.23 m2</b>							
No Asbestos							
<b>B00A - R0029 - External Movement - 23.58 m2</b>							

No Asbestos		
<b>B00B - Technological &amp; Applied Studies - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - M0001 - General Storeroom - 42.04 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - M0002 - Stairs - 3.53 m2</b>		
No Asbestos		
<b>B00B - R0001 - Metal Technology L.S. - 84.28 m2</b>		
No Asbestos		
<b>B00B - R0002 - Welding Area - 8.35 m2</b>		
No Asbestos		
<b>B00B - R0003 - Resources Store - 16.26 m2</b>		
No Asbestos		
<b>B00B - R0004 - Movement - 10.81 m2</b>		
No Asbestos		
<b>B00B - R0005 - Resources Store - 32.63 m2</b>		
No Asbestos		
<b>B00B - R0006 - Wood Technology L.S. - 92.82 m2</b>		
No Asbestos		
<b>B00B - R0007 - Dust Extraction Space - 9.59 m2</b>		
No Asbestos		
<b>B00B - R0008 - Wood Technology L.S. - 92.74 m2</b>		
No Asbestos		
<b>B00B - R0009 - Wood Technology Bay - 34.43 m2</b>		
No Asbestos		
<b>B00B - R0010 - Staff Study - 27.94 m2</b>		
No Asbestos		
<b>B00B - R0011 - Design L.S. - 56.76 m2</b>		
No Asbestos		
<b>B00B - R0012 - Design L.S. - 56.68 m2</b>		
No Asbestos		
<b>B00B - R0013 - Resources Store - 28.09 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0014 - L.P.G Store - 1.62 m2</b>		
No Asbestos		
<b>B00B - R0015 - Wood Technology Bay - 87.33 m2</b>		
No Asbestos		
<b>B00B - R0016 - Resources Store - 2.86 m2</b>		
No Asbestos		
<b>B00B - R0019 - Cleaning Store - Distributed - 3.63 m2</b>		
No Asbestos		
<b>B00B - R0020 - Distribution Board Cupboard - 5.07 m2</b>		
No Asbestos		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00B - R0021 - Metal Technology Bay - 35.73 m2</b>		
No Asbestos		
<b>B00B - R0024 - Cleaning Supplies Store - 13.34 m2</b>		
No Asbestos		
<b>B00B - R0025 - General Storeroom - 7.26 m2</b>		

No Asbestos	
<b>B00B - R0026 - Toilets-Boys - 11.28 m2</b>	
No Asbestos	
<b>B00B - R0027 - Toilets-Girls - 11.77 m2</b>	
No Asbestos	
<b>B00B - R0028 - Staff - Toilet - 5.36 m2</b>	
No Asbestos	
<b>B00B - R0029 - Metal Technology L.S. - 91.64 m2</b>	
No Asbestos	
<b>B00B - R0030 - Movement - 117.24 m2</b>	
No Asbestos	
<b>B00B - R0031 - Stairs - 2.1 m2</b>	
No Asbestos	
<b>B00B - R0032 - External Movement - 153.58 m2</b>	
No Asbestos	
<b>B00C - Art - 1989 - Brick/Block</b>	
<b>Exterior</b>	
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found
<b>Interior</b>	
<b>B00C - R0001 - Art Learning Space - 60.95 m2</b>	
No Asbestos	
<b>B00C - R0002 - Resources Store - 19.05 m2</b>	
No Asbestos	
<b>B00C - R0003 - Cleaning Store - Distributed - 3.63 m2</b>	
No Asbestos	
<b>B00C - R0004 - Study Space - 18.92 m2</b>	
Floor Coverings Res/Textile	No Asbestos Found
<b>B00C - R0005 - Resources Store - 6.92 m2</b>	
No Asbestos	
<b>B00C - R0006 - Staff Study - 23.22 m2</b>	
Floor Coverings Res/Textile	No Asbestos Found
<b>B00C - R0007 - Distribution Board Cupboard - 1.26 m2</b>	
<b>Note: No inspection of live electrical installation</b>	
No Asbestos	
<b>B00C - R0008 - Art Learning Space - 60.87 m2</b>	
No Asbestos	
<b>B00C - R0010 - Kiln Space - 11.28 m2</b>	
No Asbestos	
<b>B00C - R0012 - Art Learning Space - 61.02 m2</b>	
No Asbestos	
<b>B00C - R0013 - Outdoor Learning Area - 25.88 m2</b>	
No Asbestos	
<b>B00C - R0014 - Movement - 93.12 m2</b>	
No Asbestos	
<b>B00C - R0015 - External Movement - 61.42 m2</b>	
No Asbestos	
<b>B00C - R0016 - Pottery Store - 18.51 m2</b>	
No Asbestos	
<b>B00C - R0017 - Workshop - 30.08 m2</b>	
No Asbestos	
<b>B00D - Technological &amp; Applied Studies - 1989 - Brick/Block</b>	

<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00D - R0001 - Food Technology L.S. - 100.38 m2</b>		
No Asbestos		
<b>B00D - R0002 - Computer Learning Space - 75.36 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0003 - Resources Store - 18.16 m2</b>		
No Asbestos		
<b>B00D - R0004 - Cleaning Store - Distributed - 3.11 m2</b>		
No Asbestos		
<b>B00D - R0005 - Design/Technology L.S. - 75.46 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0006 - Interview/Office - Type 1 - 22.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0007 - Distribution Board Cupboard - .95 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0008 - Laundry - 6.5 m2</b>		
No Asbestos		
<b>B00D - R0009 - Staff Study - 24.23 m2</b>		
No Asbestos		
<b>B00D - R0010 - Food Technology L.S. - 100.41 m2</b>		
No Asbestos		
<b>B00D - R0011 - Pantry - 11.98 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0012 - Preparation - Materials - 20.95 m2</b>		
No Asbestos		
<b>B00D - R0013 - Movement - 111.78 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0014 - External Movement - 1.93 m2</b>		
No Asbestos		
<b>B00D - R0015 - External Movement - 3.86 m2</b>		
No Asbestos		
<b>B00D - R0016 - External Movement - 76.78 m2</b>		
No Asbestos		
<b>B00E - Science Learning - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00E - R0001 - Laboratory L.S. - 93.65 m2</b>		
No Asbestos		
<b>B00E - R0002 - Resources Store - 11.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0003 - Laboratory L.S. - 91.19 m2</b>		
No Asbestos		
<b>B00E - R0004 - Laboratory L.S. - 91.08 m2</b>		
No Asbestos		
<b>B00E - R0005 - Staff Study - 36.89 m2</b>		

Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0006 - Distribution Board Cupboard - .96 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0007 - Laboratory L.S. - 93.43 m2</b>		
No Asbestos		
<b>B00E - R0008 - Laboratory L.S. - 93.31 m2</b>		
No Asbestos		
<b>B00E - R0009 - Movement - 25.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0010 - Preparation - Science - 79.11 m2</b>		
No Asbestos		
<b>B00E - R0011 - Apparatus Storage - 40.97 m2</b>		
No Asbestos		
<b>B00E - R0012 - Cleaning Store - Distributed - 3.05 m2</b>		
No Asbestos		
<b>B00E - R0013 - Chemical Store - 11.93 m2</b>		
No Asbestos		
<b>B00E - R0015 - External Movement - 212.85 m2</b>		
No Asbestos		
<b>B00F - General Learning/Library/Support Unit - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0004 - Seminar/Study - 13.28 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0005 - Audio Visual Workroom - 25.96 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0006 - Library Administration - 37.01 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0007 - Librarian - 11.47 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0008 - Distribution Board Cupboard - 2.88 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0009 - Toilets-Girls - 18.81 m2</b>		
No Asbestos		
<b>B00F - R0010 - Staff - Toilet - 6.21 m2</b>		
No Asbestos		
<b>B00F - R0013 - General Learning Space - 47.96 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0014 - General Learning Space - 47.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0015 - General Learning Space - 47.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0016 - General Learning Space - 48.13 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0017 - General Learning Space - 47.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0018 - General Learning Space - 47.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0019 - Cleaning Store - Distributed - 3.14 m2</b>		

No Asbestos		
<b>B00F - R0020 - General Learning Space - 46.75 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0021 - Staff Study - 52.14 m2</b>		
No Asbestos		
<b>B00F - R0022 - Staff - Toilet - 6.02 m2</b>		
No Asbestos		
<b>B00F - R0023 - Distribution Board Cupboard - .78 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0024 - Study Space - 25.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0025 - General Learning Space - 48.11 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0026 - General Learning Space - 48.13 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0027 - Resources Store - 17.75 m2</b>		
No Asbestos		
<b>B00F - R0028 - Leading Teacher - 13.15 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0030 - System Administrators Office - 14.92 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0031 - Photographic Studio - 13.17 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0032 - Staff Study - 39.02 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0033 - Computer Learning Space - 61.22 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0034 - Computer Store - 8.69 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0035 - Computer Store - 8.68 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0036 - Resources Store - 17.78 m2</b>		
No Asbestos		
<b>B00F - R0037 - Senior Seminar - 13.04 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0038 - Senior Seminar - 12.98 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0039 - Senior Study - 60.43 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0043 - Distribution Board Cupboard - .73 m2</b>		
		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0044 - Staff - Toilet - 5.98 m2</b>		
No Asbestos		
<b>B00F - R0045 - Special Learning Space - 49.64 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0046 - Special Learning Space - 49.55 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0047 - Cleaning Store - Distributed - 3.31 m2</b>		
No Asbestos		
<b>B00F - R0048 - Special Learning Space - 48.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0049 - Special Learning Space - 47.89 m2</b>		



Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0050 - General Learning Space - 48.05 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0051 - General Learning Space - 48.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0052 - General Learning Space - 48.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0053 - General Learning Space - 47.89 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0054 - General Learning Space - 52.06 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0055 - General Learning Space - 52.21 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0056 - Toilets-Boys - 18.64 m2</b>		
No Asbestos		
<b>B00F - R0057 - Toilets-Girls - 18.38 m2</b>		
No Asbestos		
<b>B00F - R0058 - Distribution Board Cupboard - 3.28 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0059 - Toilets-Disabled - 4.6 m2</b>		
No Asbestos		
<b>B00F - R0060 - Tiered Learning Area - 67.33 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0061 - Performing Arts Store - 6.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0062 - Interview/Office - Type 1 - 12.76 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0063 - Interview/Office - Type 1 - 14.99 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0071 - Plant - 20.27 m2</b>		
No Asbestos		
<b>B00F - R0072 - External Movement - 13.09 m2</b>		
No Asbestos		
<b>B00F - R0073 - External Movement - 18.73 m2</b>		
No Asbestos		
<b>B00F - R0074 - External Movement - 18.4 m2</b>		
No Asbestos		
<b>B00F - R0075 - External Movement - 63.38 m2</b>		
No Asbestos		
<b>B00F - R0076 - External Movement - 4.65 m2</b>		
No Asbestos		
<b>B00F - R0077 - External Movement - 22.48 m2</b>		
No Asbestos		
<b>B00F - R0078 - External Movement - 4.92 m2</b>		
No Asbestos		
<b>B00F - R0079 - Outdoor Learning Area - 22.42 m2</b>		
No Asbestos		
<b>B00F - R0081 - External Movement - 14.83 m2</b>		
No Asbestos		
<b>B00F - R0082 - Main Entry - 12.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	

<b>B00F - R0083 - Main Area - 348.44 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0084 - Seminar - 27.64 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0085 - Commonroom - 80.48 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0086 - Tea Room - 9.16 m2</b>		
No Asbestos		
<b>B00F - R0087 - Resources Store - 8.86 m2</b>		
No Asbestos		
<b>B00F - R0088 - Darkroom Space - 1.67 m2</b>		
No Asbestos		
<b>B00F - R0089 - Dark Room - 14.75 m2</b>		
No Asbestos		
<b>B00F - R0090 - General Storeroom - 1.31 m2</b>		
No Asbestos		
<b>B00F - R0091 - System Administrators Office - 23.5 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0094 - External Movement - 28.64 m2</b>		
No Asbestos		
<b>B00F - R0097 - Stairs - 16.48 m2</b>		
No Asbestos		
<b>B00F - R0098 - General Storeroom - 5.65 m2</b>		
Require Inspection		
<b>B00F - R0099 - General Learning Space - 45.36 m2</b>		
Require Inspection		
<b>B00F - R0100 - Toilets-Disabled - 21.33 m2</b>		
Require Inspection		
<b>B00F - R0101 - General Learning Space - 47.6 m2</b>		
Require Inspection		
<b>B00F - R0102 - Staff Study - 32.64 m2</b>		
Require Inspection		
<b>B00F - R0103 - Staff Study - 32.82 m2</b>		
Require Inspection		
<b>B00F - R0104 - Student Kitchen - 17.33 m2</b>		
Require Inspection		
<b>B00F - R0105 - Movement - 935.5 m2</b>		
Require Inspection		
<b>B00F - R0106 - Staff Study - 63.46 m2</b>		
Require Inspection		
<b>B00F - R0107 - General Learning Space - 47.48 m2</b>		
Require Inspection		
<b>B00F - R0108 - General Learning Space - 47.21 m2</b>		
Require Inspection		
<b>B00F - R0109 - Communication Space - 19.29 m2</b>		
Require Inspection		
<b>B00G - Music - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		

<b>B00G - R0001 - Cleaning Store - Distributed - 2.97 m2</b>		
No Asbestos		
<b>B00G - R0002 - Practice/Seminar - 26.33 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0003 - Distribution Board Cupboard - .69 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00G - R0004 - Music Learning Space - 61.03 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0005 - Practice/Seminar - 25.96 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0006 - Music Learning Space - 77.98 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0007 - Music Store - 17.68 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0008 - Staff Study - 15.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0010 - External Movement - 3.2 m2</b>		
No Asbestos		
<b>B00G - R0011 - Toilets-Boys - 14.57 m2</b>		
No Asbestos		
<b>B00G - R0012 - Movement - 26.34 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00G - R0013 - Handwashing Facilities - 2.62 m2</b>		
No Asbestos		
<b>B00H - Multi Purpose Facilities - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00H - R0003 - Cleaning Store - Distributed - 2.89 m2</b>		
No Asbestos		
<b>B00H - R0005 - Control Room - 1.68 m2</b>		
No Asbestos		
<b>B00H - R0006 - Sport Equipment Store - 38.81 m2</b>		
No Asbestos		
<b>B00H - R0007 - Staff Study - 16.14 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00H - R0008 - General Storeroom - 7.62 m2</b>		
No Asbestos		
<b>B00H - R0010 - Plant - 1.06 m2</b>		
No Asbestos		
<b>B00H - R0011 - General Storeroom - 13.91 m2</b>		
No Asbestos		
<b>B00H - R0012 - General Storeroom - 14.04 m2</b>		
No Asbestos		
<b>B00H - R0014 - Plant - 1.01 m2</b>		
No Asbestos		
<b>B00H - R0015 - Movement - 55.21 m2</b>		
No Asbestos		
<b>B00H - R0016 - Movement - 21.47 m2</b>		
No Asbestos		

<b>B00H - R0018 - Multi-Purpose Space - 491.86 m2</b>		
No Asbestos		
<b>B00H - R0019 - Distribution Board Cupboard - .82 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00H - R0020 - Main Switchroom - 10.4 m2</b>		
No Asbestos		
<b>B00H - R0021 - External Movement - 48.1 m2</b>		
No Asbestos		
<b>B00H - R0022 - Staff Study - 21.99 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00H - R0023 - Garden Store Room - 15.24 m2</b>		
No Asbestos		
<b>B00H - R0025 - External Movement - 2.75 m2</b>		
No Asbestos		
<b>B00H - R0026 - External Movement - 8.82 m2</b>		
No Asbestos		
<b>B00H - R0027 - External Movement - 2.72 m2</b>		
No Asbestos		
<b>B00H - R0029 - Toilet - Lobby - 3.29 m2</b>		
No Asbestos		
<b>B00H - R0030 - Toilets-Boys - 14.16 m2</b>		
No Asbestos		
<b>B00H - R0031 - Toilet - Lobby - 7.08 m2</b>		
No Asbestos		
<b>B00H - R0032 - Toilets-Girls - 18.82 m2</b>		
No Asbestos		
<b>B00H - R0033 - Toilet - Lobby - 2.79 m2</b>		
No Asbestos		
<b>B00H - R0034 - Chair Store - 27.4 m2</b>		
No Asbestos		
<b>B00H - R0035 - Other-Community Use - 5.5 m2</b>		
No Asbestos		
<b>B00H - R0036 - Plant - .92 m2</b>		
No Asbestos		
<b>B00H - R0037 - Change - 60.57 m2</b>		
No Asbestos		
<b>B00H - R0038 - Change - 60.72 m2</b>		
No Asbestos		
<b>B00H - R0039 - Plant - .76 m2</b>		
No Asbestos		
<b>B00H - R0040 - Stage - 115.91 m2</b>		
No Asbestos		
<b>B00H - R0041 - External Movement - 59.61 m2</b>		
No Asbestos		
<b>B00H - R0042 - External Movement - 95.28 m2</b>		
No Asbestos		
<b>B00I - Agricultural Science - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		

<b>B00I - R0001 - Animal Space - 24.05 m2</b>		
No Asbestos		
<b>B00I - R0002 - General Storeroom - 6.1 m2</b>		
No Asbestos		
<b>B00I - R0003 - General Learning Space - 40.23 m2</b>		
No Asbestos		
<b>B00I - R0004 - Machine Storage - 35.69 m2</b>		
No Asbestos		
<b>B00I - R0005 - General Storeroom - 10.9 m2</b>		
No Asbestos		
<b>B00I - R0006 - Movement - 5.71 m2</b>		
No Asbestos		
<b>B00I - R0008 - Shower - 1.94 m2</b>		
No Asbestos		
<b>B00I - R0009 - External Movement - 26.51 m2</b>		
No Asbestos		
<b>B00I - R0010 - Toilet - Lobby - 2.99 m2</b>		
No Asbestos		
<b>B00I - R0011 - Staff - Toilet - 1.91 m2</b>		
No Asbestos		
<b>B00I - R0012 - Bulk Store - 32.8 m2</b>		
Require Inspection		
<b>B00J - Building Services - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00J - R0001 - Plant - 1.64 m2</b>		
No Asbestos		
<b>B00K - Agricultural Science - 2010 - Metal Shed</b>		
<b>Exterior</b>		
Require Inspection		
<b>Interior</b>		
<b>B00K - R0001 - Animal Space - 34.24 m2</b>		
Require Inspection		
<b>B00L - Storage - 2015 - Metal Shed</b>		
<b>Exterior</b>		
Require Inspection		
<b>Interior</b>		
<b>B00L - R0001 - Bulk Store - 42.74 m2</b>		
Require Inspection		
<b>B0II - Agricultural Science - 2010 - Greenhouse</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B0II - R0001 - Growing/Breeding - 36.62 m2</b>		
No Asbestos		

## Demountables

### OS 601 11322 - Learning Unit - Standard/Withdrawal - Placement Date : 09-FEB-1998

#### Exterior

Eaves Linings	Flat AC Sheeting	11.52m2	Assumed Asbestos
Landing	Compressed AC Sheet	1.2m2	Assumed Asbestos
Step Treads	Compressed AC Sheet	1.08m2	Assumed Asbestos

#### Interior

##### R1- Entry

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Assumed Asbestos

##### R2- General Learning Space

End Wall Panel	Flat AC Sheeting	18m2	Assumed Asbestos
Ceiling Structures/Linings	Flat AC Sheeting	55m2	Assumed Asbestos

##### R3- Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Assumed Asbestos
----------------------------	------------------	------	------------------

### NS 200 13178 - Art Learning Space/Workshop/Bulk Store - Placement Date : 30-JUN-1995

No Asbestos Found

### NS 220 13191 - Science Learning/Preparation Space - Placement Date : 30-JUN-1995

No Asbestos Found

### OS 601 14297 - Learning Unit - Standard/Withdrawal - Placement Date : 17-SEP-2018

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### NS 120 15108 - Learning Unit - Single Primary H/Cap PAA - Placement Date : 03-OCT-2007

No Asbestos Found

### OS 522 18178 - Staff Study - Placement Date : 19-FEB-2007

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 601 19455 - Learning Unit - Standard/Withdrawal - Placement Date : 07-FEB-2019

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

### OS 601 19460 - Learning Unit - Standard/Withdrawal - Placement Date : 07-FEB-2019

**Note:** This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found