


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lismore Public School (1780)
Region:	North Coast AMU
State Electorate:	Lismore
Local Government Area:	Lismore

Last Reviewed By:	WSP 31-OCT-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - General Learning - 1942 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Movement - 1.49 m2							
No Asbestos							
B00A - R0002 - Home Base - 47.03 m2							
No Asbestos							
B00A - R0003 - Home Base - 47.01 m2							
No Asbestos							
B00A - R0004 - Home Base - 46.96 m2							
No Asbestos							
B00A - R0005 - Staff Room Annexe - 16.55 m2							
No Asbestos							
B00A - R0006 - Staff Toilet - 4.46 m2							
No Asbestos							
B00A - R0007 - General Storeroom - 4.32 m2							
No Asbestos							
B00A - R0008 - Movement - 1.27 m2							
No Asbestos							
B00A - R0009 - Practical Activities - 1hb - 72.09 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0010 - Staff Room Annexe - 16.39 m2							
No Asbestos							
B00A - R0011 - Cleaning Distributed Store - 4.92 m2							
No Asbestos							
B00A - R0012 - Movement - 5.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0013 - Movement - 2.02 m2							
No Asbestos							
B00A - R0014 - Movement - 3.12 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0015 - Stairs - 6.55 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R0016 - Movement - 10.99 m2							
No Asbestos							
B00A - R1001 - Home Base - 47.64 m2							
No Asbestos							
B00A - R1002 - Home Base - 47.99 m2							
No Asbestos							
B00A - R1003 - Home Base - 47.93 m2							
No Asbestos							
B00A - R1004 - Staff Room Annexe - 18.75 m2							
No Asbestos							
B00A - R1005 - General Storeroom - 5.01 m2							

No Asbestos							
B00A - R1006 - Practical Activities - 1hb - 4.54 m2							
No Asbestos							
B00A - R1007 - Practical Activities - 1hb - 65.64 m2							
No Asbestos							
B00A - R1008 - Movement - 16.93 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1009 - Movement - 4.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00A - R1010 - Stairs - 10.79 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - General Learning - 1942 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00B - R0001 - Movement - 1.47 m2							
No Asbestos							
B00B - R0002 - Special Programs Room - 16.15 m2							
No Asbestos							
B00B - R0003 - Movement - 29.12 m2							
No Asbestos							
B00B - R0004 - Main Switch Board - 3.65 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Electrical - Mounting Board	Flat AC Sheeting	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Staff Toilet - 4.97 m2							
No Asbestos							
B00B - R0006 - Staff Room Annexe - 16.73 m2							
No Asbestos							
B00B - R0007 - General Storeroom - 5.08 m2							
No Asbestos							
B00B - R0008 - Practical Activities - 1hb - 34.57 m2							
No Asbestos							
B00B - R0009 - Home Base - 46.37 m2							
No Asbestos							
B00B - R0010 - Home Base - 46.85 m2							
No Asbestos							
B00B - R0011 - Home Base - 46.83 m2							
No Asbestos							
B00B - R0012 - Movement - 12.8 m2							
No Asbestos							
B00B - R0013 - Movement - 3.14 m2							
No Asbestos							
B00B - R0014 - Movement - 2.03 m2							
No Asbestos							
B00B - R0015 - Movement - 4.42 m2							
No Asbestos							

B00B - R0016 - Stairs - 6.85 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R0017 - Stairs - 17.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1001 - Movement - 4.59 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1002 - Practical Activities - 1hb - 66.56 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1003 - General Storeroom - 3.98 m2							
No Asbestos							
B00B - R1004 - Staff Toilet - 5.52 m2							
No Asbestos							
B00B - R1005 - Interview - 18.57 m2							
No Asbestos							
B00B - R1006 - Home Base - 47.84 m2							
No Asbestos							
B00B - R1007 - Home Base - 47.92 m2							
No Asbestos							
B00B - R1008 - Home Base - 47.96 m2							
No Asbestos							
B00B - R1009 - Movement - 4.65 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1010 - General Storeroom - 6.27 m2							
No Asbestos							
B00B - R1011 - Movement - 17.04 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1012 - Stairs - 11.44 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R1013 - Stairs - 14.42 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00B - R9001 - Cleaning Supplies - 7.33 m2							
No Asbestos							
B00B - R9002 - Movement - 3.21 m2							
No Asbestos							
B00B - R9003 - Stairs - 4.64 m2							
No Asbestos							
B00C - General Learning - 1942 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	16m2	North, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - Clerical Office/Workroom - 13.02 m2							
No Asbestos							
B00C - R0002 - Toilets - Boys/Girls - 2.79 m2							

No Asbestos		
B00C - R0003 - General Storeroom - 1.44 m2		
No Asbestos		
B00C - R0005 - Duplicating Workroom - 19.54 m2		
No Asbestos		
B00C - R0006 - General Storeroom - 1.17 m2		
No Asbestos		
B00C - R0007 - General Storeroom - .64 m2		
No Asbestos		
B00C - R0008 - Movement - 8.46 m2		
Floor Coverings Res/Textile	Vinyl Tiles	
B00C - R0009 - Practical Activities - 1hb - 63.93 m2		
No Asbestos		
B00C - R0010 - Home Base - 46.89 m2		
No Asbestos		
B00C - R0011 - Home Base - 46.91 m2		
No Asbestos		
B00C - R0012 - Home Base - 46.86 m2		
No Asbestos		
B00C - R0014 - Movement - 14.74 m2		
No Asbestos		
B00C - R0015 - Home Base - 46.9 m2		
No Asbestos		
B00C - R0019 - Movement - 7.49 m2		
No Asbestos		
B00C - R0023 - Movement - 2.24 m2		
No Asbestos		
B00C - R0024 - Movement - 2.34 m2		
No Asbestos		
B00C - R0025 - Movement - 2.15 m2		
No Asbestos		
B00C - R0026 - Staff Toilet - 1.94 m2		
No Asbestos		
B00C - R0027 - Toilet - Lobby - 2.8 m2		
No Asbestos		
B00C - R0028 - Withdrawal Space - 1hb - 24.01 m2		
No Asbestos		
B00C - R0029 - Interview - 10 m2		
No Asbestos		
B00C - R0030 - Interview - 11.23 m2		
No Asbestos		
B00C - R0031 - Movement - 4.61 m2		
No Asbestos		
B00C - R0032 - General Storeroom - 12.45 m2		
No Asbestos		
B00C - R0033 - Home Base - 38 m2		
No Asbestos		
B00C - R0034 - Practical Activities/Movement - 1hb - 23.49 m2		
No Asbestos		
B00C - R0035 - Toilets - Boys/Girls - Pre - 3.29 m2		
No Asbestos		

B00C - R0036 - Access Shower/Toilet - 8.27 m2							
No Asbestos							
B00C - R9001 - General Storeroom - 16.66 m2							
No Asbestos							
B00D - General Learning - 1942 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00D - R0001 - Staff Toilet - 5.57 m2							
No Asbestos							
B00D - R0002 - General Storeroom - 2.1 m2							
No Asbestos							
B00D - R0003 - General Storeroom - 19.75 m2							
No Asbestos							
B00D - R0004 - Movement - 63.29 m2							
No Asbestos							
B00D - R0005 - Toilets - Boys/Girls - 3.12 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0006 - Practical Activities - 1hb - 16.23 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0007 - Home Base - 84.79 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0008 - Home Base - 85.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0009 - Practical Activities - 1hb - 16.52 m2							
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0010 - Toilets - Boys/Girls - 3.05 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0011 - Cleaning Supplies - 6.74 m2							
No Asbestos							
B00D - R0012 - General Storeroom - 20.02 m2							
No Asbestos							
B00D - R0013 - General Storeroom - 1.03 m2							
No Asbestos							
B00D - R0014 - Stairs - 1.52 m2							
No Asbestos							
B00D - R0015 - Stairs - 1.49 m2							
No Asbestos							
B00D - R1001 - Movement - 90.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1002 - Home Base - 51.88 m2							

No Asbestos							
B00D - R1003 - Home Base Store - 6.83 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1004 - Practical Activities - 1hb - 21.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1005 - Home Base - 53.16 m2							
No Asbestos							
B00D - R1006 - Home Base - 53.55 m2							
No Asbestos							
B00D - R1007 - Practical Activities - 1hb - 21.2 m2							
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1008 - Staff Toilet - 5.74 m2							
No Asbestos							
B00D - R1009 - Cleaning Distributed Store - 2.08 m2							
No Asbestos							
B00D - R1010 - Distribution Board - 1.02 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1011 - Withdrawal Space - 1hb - 7.02 m2							
No Asbestos							
B00D - R1012 - Stairs - 6.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R1013 - Stairs - 6.61 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - Communal Facilities - 1942 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00E - R0001 - Movement - 170.76 m2							
No Asbestos							
B00E - R0002 - Disabled Toilet - 4.33 m2							
No Asbestos							
B00E - R0003 - Communal Space - 192.57 m2							
No Asbestos							
B00E - R0004 - Toilets - Boys - 16.87 m2							
No Asbestos							
B00E - R0005 - Toilets - Girls - 37.87 m2							
No Asbestos							
B00E - R0006 - Staff Toilet - 2.03 m2							
No Asbestos							
B00E - R0007 - Cleaning Supplies - 7.12 m2							
No Asbestos							
B00E - R0008 - Cleaning Distributed Store - 2.79 m2							
No Asbestos							
B00E - R0009 - Movement - 1.65 m2							
No Asbestos							
B00E - R0010 - Sports Store - 20.73 m2							

No Asbestos							
B00E - R0011 - Plant - .67 m2							
No Asbestos							
B00E - R0012 - Out Of School Hours Care Centre - 16.7 m2							
No Asbestos							
B00E - R0013 - Kiln Room - 6.89 m2							
No Asbestos							
B00E - R0014 - Hall Chair Store - 9.44 m2							
No Asbestos							
B00E - R0015 - Raised Platform - 52.02 m2							
No Asbestos							
B00E - R0016 - Plant - .9 m2							
No Asbestos							
B00E - R0017 - Movement - 1.88 m2							
No Asbestos							
B00E - R0018 - Sports Store - 2.5 m2							
No Asbestos							
B00E - R0019 - Canteen - 41.32 m2							
No Asbestos							
B00E - R0020 - Canteen Office/Store - 4.57 m2							
No Asbestos							
B00E - R0021 - Canteen Office/Store - 5.39 m2							
No Asbestos							
B00E - R0022 - Distribution Board - .75 m2							
No Asbestos							
B00G - Support Unit - 1942 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	36m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Gable Verge Lining	Flat AC Sheeting	10m2	East & West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior							
B00G - R0001 - Home Base - P - 48.42 m2							
No Asbestos							
B00G - R0002 - Home Base Store - P - 1.96 m2							
No Asbestos							
B00G - R0004 - Movement - 53.84 m2							
Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Mastic						
B00G - R0005 - Home Base - P - 43.71 m2							
No Asbestos							
B00G - R0007 - Home Base Store - P - 6.28 m2							
No Asbestos							
B00G - R0008 - Distribution Board - 1.07 m2							
No Asbestos							
B00G - R0011 - Cleaning Distributed Store - 3.7 m2							
No Asbestos							

B00G - R0012 - Home Base Store - P - 3.72 m2							
No Asbestos							
B00G - R0014 - Covered Vehicle Area/Porte Cochere - 78 m2							
No Asbestos							
B00G - R0016 - Access Shower/Toilet - 6.64 m2							
No Asbestos							
B00G - R0019 - Practical Activities - 1hb - 10.69 m2							
No Asbestos							
B00G - R0020 - Movement - 4.21 m2							
No Asbestos							
B00G - R0021 - Toilets - Boys/Girls - 1.71 m2							
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0022 - Toilet - Lobby - 1.78 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0023 - Toilet - Lobby - 1.79 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0024 - Toilets - Boys/Girls - 1.7 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0025 - Home Base/Practical Activities - 43.92 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00G - R0026 - Movement - 12.98 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00G - R0027 - Movement - 5.44 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00H - Administration/Library - 1974 - Brick/Block							
Exterior							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Interior							
B00H - R0001 - Duplicating Workroom - 18.88 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0002 - Movement - 29.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0003 - Staff Toilet - 5.94 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0005 - Deputy Principal - 12.31 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0006 - Clerical Office - 12.96 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0007 - Entry Vestibule - 13.43 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0008 - Movement - 156.12 m2							
No Asbestos							
B00H - R0009 - Clerical Office - 13 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0010 - Sick Bay - 5.94 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0011 - Distribution Board - 5.59 m2							
Note: No inspection of live electrical installation							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0012 - Staff Toilet - 3.39 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0013 - Principal - 16.51 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0014 - General Storeroom - 3.81 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00H - R0015 - Cleaning Distributed Store - 3.62 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00H - R0016 - General Storeroom - 6 m2							
Ceiling Structures/Linings	Non Accessible Area	m2					
B00H - R0017 - Staff Room - 99.09 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (70 - 120 m2) - (X8)						
B00H - R0018 - Staff Room - 32.6 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0020 - Cleaning Distributed Store - .81 m2							
Ceiling Structures/Linings	No Asbestos Found						
B00H - R0022 - Staff Room Annexe - 19.14 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (10 - 40 m2) - (X3)						
B00H - R0023 - Stairs - 8.75 m2							
No Asbestos							
B00H - R0024 - Toilet - Lobby - 4.09 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0025 - Staff Toilet - 2.27 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0026 - Toilet - Lobby - 3.62 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0027 - Staff Toilet - 1.4 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
B00H - R0028 - Toilet - Lobby - 3.53 m2							

Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00H - R0029 - Staff Toilet - 2.3 m2								
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)							
B00H - R1001 - Movement - 22.92 m2								
No Asbestos								
B00H - R1002 - Reading Area - 269.75 m2								
No Asbestos								
B00H - R1003 - Library Office/Workroom - 6.43 m2								
No Asbestos								
B00H - R1004 - Library Office/Workroom - 18.43 m2								
No Asbestos								
B00H - R1006 - Cleaning Distributed Store - .97 m2								
No Asbestos								
B00H - R1008 - Seminar/Study - 12.13 m2								
No Asbestos								
B00H - R1009 - Communications Room - 12.89 m2								
No Asbestos								
B00H - R1010 - Movement - 31.45 m2								
No Asbestos								
B00H - R1011 - Distribution Board - .97 m2								
Note: No inspection of live electrical installation								
No Asbestos								
B00H - R1012 - Stairs - 4.12 m2								
No Asbestos								
B00H - R1013 - Toilet - Lobby - 3.65 m2								
No Asbestos								
B00H - R1014 - Staff Toilet - 1.41 m2								
No Asbestos								
B00H - R1015 - Toilet - Lobby - 3.48 m2								
No Asbestos								
B00H - R1016 - Staff Toilet - 2.32 m2								
No Asbestos								
B00J - Pupil Facilities - 1942 - Brick/Block								
Exterior								
Ceiling Voids - Flat Roof	No Asbestos Found							
Underfloor Voids - Slab on Ground	No Asbestos Found							
Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Interior								
B00J - R0001 - Toilets - Girls - 25.2 m2								
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00J - R0002 - Staff Toilet - 1.62 m2								
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00K - Pupil Facilities - 2011 - Brick/Veneer								
Exterior								
Underfloor Voids - Slab on Ground	No Asbestos Found							
Ceiling Voids	No Asbestos Found							

Interior		
B00K - R0001 - Garden Store - 20.53 m2		
No Asbestos		
B00K - R0002 - General Assistant/Bulk Store - 25.39 m2		
No Asbestos		
B00K - R0003 - Sports Store - 20.53 m2		
No Asbestos		
B00K - R0004 - Toilets - Girls - 22.83 m2		
No Asbestos		
B00K - R0005 - Toilets - Boys - 16.37 m2		
No Asbestos		
B00K - R0006 - Access Shower/Toilet/Change - 5.8 m2		
No Asbestos		
B00L - Pupil Facilities - 2011 - Brick/Veneer		
Exterior		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	
Interior		
B00L - R0001 - Garden Store - 20.53 m2		
No Asbestos		
B00L - R0002 - General Assistant/Bulk Store - 25.39 m2		
No Asbestos		
B00L - R0003 - Sports Store - 20.53 m2		
No Asbestos		
B00L - R0004 - Toilets - Girls - 22.83 m2		
No Asbestos		
B00L - R0005 - Toilets - Boys - 16.37 m2		
No Asbestos		
B00L - R0006 - Access Shower/Toilet/Change - 5.8 m2		
No Asbestos		

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020