


# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lake Munmorah Public School (2362)
Region:	Hunter/Central Coast AMU
State Electorate:	Swansea
Local Government Area:	Central Coast

Last Reviewed By:	AECOM 28-JUN-2016
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Communal Facilities/Pupil Facilities - 1994 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Movement - 15.1 m2</b>							
No Asbestos							
<b>B00A - R0002 - Cleaning Supplies - 12.63 m2</b>							
No Asbestos							
<b>B00A - R0003 - Special Programs Room - 16.61 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0004 - Movement - 25.62 m2</b>							
No Asbestos							
<b>B00A - R0005 - Canteen Office/Store - 10.74 m2</b>							
No Asbestos							
<b>B00A - R0006 - Canteen - 44.12 m2</b>							
No Asbestos							
<b>B00A - R0007 - External Movement - 278.02 m2</b>							
No Asbestos							
<b>B00A - R0008 - Sports Store - 16 m2</b>							
No Asbestos							
<b>B00A - R0009 - Communal Space - 228.76 m2</b>							
No Asbestos							
<b>B00A - R0010 - Plant - .58 m2</b>							
No Asbestos							
<b>B00A - R0011 - Distribution Board - .57 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00A - R0012 - Toilets - Girls - 8.94 m2</b>							
No Asbestos							
<b>B00A - R0013 - Communal Space - 36.44 m2</b>							
No Asbestos							
<b>B00A - R0014 - Shower/Change - 2.18 m2</b>							
No Asbestos							
<b>B00A - R0015 - Toilets - Boys - 6.58 m2</b>							
No Asbestos							
<b>B00A - R0016 - Hall Chair Store - 11.49 m2</b>							
No Asbestos							
<b>B00A - R0017 - P.E Store - 16.83 m2</b>							
No Asbestos							
<b>B00A - R0018 - Plant - .55 m2</b>							
No Asbestos							
<b>B00A - R0019 - Cleaning Distributed Store - 2.95 m2</b>							
No Asbestos							
<b>B00A - R0020 - Disabled Toilet - 5.56 m2</b>							
No Asbestos							
<b>B00A - R0021 - Cleaning Supplies - 12.6 m2</b>							
No Asbestos							
<b>B00A - R0022 - General Assistant/Bulk Store - 12.59 m2</b>							
No Asbestos							

## B00B - Administration - 1994 - Brick/Veneer

### Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	

### Interior

#### B00B - R0001 - Clerical Office - 17.74 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0002 - Entry Vestibule - 13.14 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0003 - Duplicating Workroom - 32.66 m2

No Asbestos

#### B00B - R0004 - Principal - 16.78 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0005 - General Storeroom - 18.4 m2

No Asbestos

#### B00B - R0006 - Cleaning Distributed Store - 3.02 m2

No Asbestos

#### B00B - R0007 - Staff Toilet - 2.51 m2

No Asbestos

#### B00B - R0008 - Staff Toilet - 2.51 m2

No Asbestos

#### B00B - R0009 - Staff Toilet - 2.5 m2

No Asbestos

#### B00B - R0010 - Main Switch Board - .69 m2

No Asbestos

#### B00B - R0011 - Staff Room Annexe - 25.34 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0012 - Staff Room - 58.93 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0013 - Movement - 32.12 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0014 - Deputy Principal - 13.13 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0015 - Deputy Principal - 13.17 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0016 - Interview - 11.96 m2

Floor Coverings Res/Textile	No Asbestos Found	
-----------------------------	-------------------	--

#### B00B - R0017 - Sick Bay - Shower/Toilet - 4.15 m2

No Asbestos

#### B00B - R0018 - Sick Bay - Shower/Toilet - 2.83 m2

No Asbestos

#### B00B - R0019 - Sick Bay - 8.64 m2

No Asbestos

#### B00B - R0020 - External Movement - 79.06 m2

No Asbestos

## B00C - General Learning/Pupil Facilities - 1994 - Brick/Veneer

### Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	

### Interior

<b>B00C - R0001 - External Movement - 87.58 m2</b>		
No Asbestos		
<b>B00C - R0002 - Toilets - Girls - 17.05 m2</b>		
No Asbestos		
<b>B00C - R0003 - Kiln Room - 6.7 m2</b>		
No Asbestos		
<b>B00C - R0004 - Toilets - Boys - 14.38 m2</b>		
No Asbestos		
<b>B00C - R0005 - Distribution Board - .3 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00C - R0006 - Withdrawal Space - 1hb - 5.8 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0007 - Home Base Store - 5.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0008 - Home Base - 51.08 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0009 - Practical Activities - 1hb - 27.99 m2</b>		
No Asbestos		
<b>B00C - R0010 - Practical Activities - 1hb - 27.89 m2</b>		
No Asbestos		
<b>B00C - R0011 - Home Base - 51 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0012 - Home Base Store - 5.92 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00C - R0013 - Withdrawal Space - 1hb - 5.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - General Learning - 1994 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00D - R0001 - Distribution Board - .29 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0002 - External Movement - 103.91 m2</b>		
No Asbestos		
<b>B00D - R0003 - Practical Activities - 1hb - 27.58 m2</b>		
No Asbestos		
<b>B00D - R0004 - Home Base Store - 5.95 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0005 - Withdrawal Space - 1hb - 5.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0006 - Home Base - 50.95 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0007 - Home Base - 50.94 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0008 - Withdrawal Space - 1hb - 5.82 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0009 - Home Base Store - 5.9 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0010 - Practical Activities - 1hb - 27.97 m2</b>		

No Asbestos		
<b>B00D - R0011 - Practical Activities - 1hb - 28 m2</b>		
No Asbestos		
<b>B00D - R0012 - Home Base Store - 5.86 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0013 - Withdrawal Space - 1hb - 5.88 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0014 - Home Base - 50.94 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0015 - Home Base - 51.3 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0016 - Withdrawal Space - 1hb - 5.88 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0017 - Home Base Store - 5.86 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0018 - Practical Activities - 1hb - 27.51 m2</b>		
No Asbestos		
<b>B00D - R0019 - Distribution Board - .29 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - General Learning/Tiered Learning - 1994 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00E - R0001 - External Movement - 148.87 m2</b>		
No Asbestos		
<b>B00E - R0002 - Special Programs Room - 40.18 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0003 - Cleaning Distributed Store - 2.45 m2</b>		
No Asbestos		
<b>B00E - R0004 - Special Programs Store - 2.59 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0005 - Plant - 3.82 m2</b>		
No Asbestos		
<b>B00E - R0006 - Withdrawal Space - 1hb - 5.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0007 - Home Base Store - 5.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0008 - Home Base - 51.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0009 - Practical Activities - 1hb - 27.33 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0010 - Distribution Board - .29 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00E - R0011 - Practical Activities - 1hb - 28.07 m2</b>		
No Asbestos		
<b>B00E - R0012 - Home Base - 51.16 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0013 - Withdrawal Space - 1hb - 5.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	

<b>B00E - R0014 - Home Base Store - 5.87 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0015 - Withdrawal Space - 1hb - 5.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0016 - Home Base Store - 5.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0017 - Home Base - 51.09 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0018 - Practical Activities - 1hb - 27.96 m2</b>		
No Asbestos		
<b>B00E - R0019 - Practical Activities - 1hb - 27.45 m2</b>		
No Asbestos		
<b>B00E - R0020 - Home Base - 50.94 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0021 - Home Base Store - 5.85 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0022 - Withdrawal Space - 1hb - 5.89 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0023 - Distribution Board - .28 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - General Learning/Pupil Facilities - 1994 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0001 - External Movement - 137.02 m2</b>		
No Asbestos		
<b>B00F - R0002 - Toilets - Boys - 23.18 m2</b>		
No Asbestos		
<b>B00F - R0003 - Disabled Toilet - 5.83 m2</b>		
No Asbestos		
<b>B00F - R0004 - Toilets - Girls - 29.66 m2</b>		
No Asbestos		
<b>B00F - R0005 - Distribution Board - .28 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00F - R0006 - Practical Activities - 1hb - 27.63 m2</b>		
No Asbestos		
<b>B00F - R0007 - Home Base Store - 5.82 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0008 - Withdrawal Space - 1hb - 5.82 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0009 - Home Base - 50.94 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0010 - Home Base - 50.8 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0011 - Withdrawal Space - 1hb - 5.89 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0012 - Home Base Store - 5.89 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00F - R0013 - Practical Activities - 1hb - 28.01 m2</b>		
No Asbestos		

<b>B00F - R0014 - Practical Activities - 1hb - 27.97 m2</b>							
No Asbestos							
<b>B00F - R0015 - Home Base Store - 5.87 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0016 - Withdrawal Space - 1hb - 5.89 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0017 - Home Base - 51.03 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0018 - Home Base - 50.87 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0019 - Withdrawal Space - 1hb - 5.88 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0020 - Home Base Store - 5.87 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00F - R0021 - Practical Activities - 1hb - 27.37 m2</b>							
No Asbestos							
<b>B00F - R0022 - Distribution Board - .3 m2</b>							
							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00G - Library - 1994 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00G - R0002 - Library Office/Workroom - 26.89 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00G - R0003 - Communications Room - 12.61 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00G - R0004 - Distribution Board - .31 m2</b>							
							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00G - R0005 - Resource/Toy Space - 24.83 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00G - R0006 - Reading Area - 200.15 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00H - General Learning/Support Unit - 1922 - Timber</b>							
<b>Exterior</b>							
Underfloor Voids	Compressed AC Sheet						
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
External Wall Structure - Awnings	Flat AC Sheeting	16	Over North and South Entrance	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00H - R0001 - Staff Kitchen - 16.62 m2</b>							
No Asbestos							
<b>B00H - R0002 - Home Base - 74.05 m2</b>							
No Asbestos							
<b>B00H - R0003 - Home Base - 56.68 m2</b>							
No Asbestos							
<b>B00H - R0004 - Toilet - E - 13.02 m2</b>							



No Asbestos		
<b>B00H - R0005 - Personal Effects - E - 4.88 m2</b>		
No Asbestos		
<b>B00H - R0006 - Home Base Store - E - 8.6 m2</b>		
No Asbestos		
<b>B00H - R0007 - Home Base Store - E - 6.59 m2</b>		
No Asbestos		
<b>B00H - R0008 - Movement - 7.73 m2</b>		
No Asbestos		
<b>B00J - Pupil Facilities - 2005 - Timber</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00J - R0001 - General Assistant/Bulk Store - 4.03 m2</b>		
No Asbestos		
<b>B00L - General Learning/Building Services - 2010 - Brick/Veneer</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00L - R0001 - Distribution Board - .53 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00L - R0002 - General Assistant/Bulk Store - 15.85 m2</b>		
No Asbestos		
<b>B00L - R0003 - Sports Store - 12.6 m2</b>		
No Asbestos		
<b>B00L - R0004 - Practical Activities - 1hb - 16.52 m2</b>		
No Asbestos		
<b>B00L - R0005 - Personal Effects Storage - 3.67 m2</b>		
No Asbestos		
<b>B00L - R0006 - Home Base - 58.57 m2</b>		
No Asbestos		
<b>B00L - R0007 - Home Base Store - 5.94 m2</b>		
No Asbestos		
<b>B00L - R0008 - Withdrawal Space - 1hb - 9.23 m2</b>		
No Asbestos		
<b>B00L - R0009 - Practical Activities - 1hb - 14.03 m2</b>		
No Asbestos		
<b>B00L - R0010 - Personal Effects Storage - 3.71 m2</b>		
No Asbestos		
<b>B00L - R0011 - Home Base - 61.19 m2</b>		
No Asbestos		
<b>B00L - R0012 - Home Base Store - 6.2 m2</b>		
No Asbestos		
<b>B00L - R0013 - Withdrawal Space - 2hb - 11.68 m2</b>		
No Asbestos		
<b>B00L - R0014 - Practical Activities - 1hb - 13.94 m2</b>		
No Asbestos		

<b>B00L - R0015 - Personal Effects Storage - 4.79 m2</b>	
No Asbestos	
<b>B00L - R0016 - Home Base - 60.7 m2</b>	
No Asbestos	
<b>B00L - R0017 - Home Base Store - 6.24 m2</b>	
No Asbestos	
<b>B00L - R0018 - Garden Store - 12.03 m2</b>	
No Asbestos	
<b>B00L - R0019 - General Storeroom - 14.4 m2</b>	
No Asbestos	
<b>B00L - R0020 - General Storeroom - 14.47 m2</b>	
No Asbestos	
<b>B00L - R0021 - External Movement - 89.19 m2</b>	
No Asbestos	
<b>B00L - R0022 - External Stairs - 1.37 m2</b>	
No Asbestos	
<b>B00L - R0023 - External Stairs - 1.31 m2</b>	
No Asbestos	
<b>B00L - R1001 - Practical Activities - 1hb - 14.3 m2</b>	
No Asbestos	
<b>B00L - R1002 - Personal Effects Storage - 4.76 m2</b>	
No Asbestos	
<b>B00L - R1003 - Home Base - 60.53 m2</b>	
No Asbestos	
<b>B00L - R1004 - Home Base Store - 6.18 m2</b>	
No Asbestos	
<b>B00L - R1005 - Withdrawal Space - 2hb - 11.68 m2</b>	
No Asbestos	
<b>B00L - R1006 - Practical Activities - 1hb - 14.12 m2</b>	
No Asbestos	
<b>B00L - R1007 - Personal Effects Storage - 3.94 m2</b>	
No Asbestos	
<b>B00L - R1008 - Home Base - 60.83 m2</b>	
No Asbestos	
<b>B00L - R1009 - Home Base Store - 6.24 m2</b>	
No Asbestos	
<b>B00L - R1010 - Distribution Board - .41 m2</b>	
No Asbestos	<b>Note: No inspection of live electrical installation</b>
<b>B00L - R1011 - Practical Activities - 1hb - 17.63 m2</b>	
No Asbestos	
<b>B00L - R1012 - Personal Effects Storage - 3.38 m2</b>	
No Asbestos	
<b>B00L - R1013 - Home Base Store - 5.94 m2</b>	
No Asbestos	
<b>B00L - R1014 - Withdrawal Space - 1hb - 9.23 m2</b>	
No Asbestos	
<b>B00L - R1015 - Home Base - 57.8 m2</b>	
No Asbestos	
<b>B00L - R1016 - External Movement - 61.83 m2</b>	
No Asbestos	
<b>B00L - R1017 - External Stairs - 23.33 m2</b>	
No Asbestos	

<b>B00L - R1018 - External Stairs - 23.18 m2</b>	
No Asbestos	
<b>B00M - Storage - 2019 - Metal Shed</b>	
<b>Exterior</b>	
Require Inspection	
<b>Interior</b>	
<b>B00M - R0001 - Sports Store - 47.96 m2</b>	
Require Inspection	

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020