

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lambton Public School (2366)
Region:	Hunter/Central Coast AMU
State Electorate:	Wallsend
Local Government Area:	Newcastle

Last Reviewed By:	WSP 30-JUN-2017
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	

2366 - Lambton Public School
Site Plan (12748)



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration/Staff Facilities - 1966 - Brick/Block							
Exterior							
Wall Linings Internal - Infill	Flat AC Sheeting	52	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00A - R0001 - Clerical Office - 18.56 m2							
No Asbestos							
B00A - R0002 - Movement - 17.47 m2							
No Asbestos							
B00A - R0003 - Sick Bay - 13.55 m2							
No Asbestos							
B00A - R0004 - Deputy Principal - 13.63 m2							
No Asbestos							
B00A - R0005 - General Storeroom - 6.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0006 - Cleaning Distributed Store - 4.26 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0007 - Movement - 2.03 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0008 - Staff Toilet - 5.64 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0009 - Movement - 3.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0010 - Distribution Board - 3.51 m2							
						Note: No inspection of live electrical installation	
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Electrical - Mounting Board	Resinous Board	1	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00A - R0011 - Clerical Office - 13.75 m2							
No Asbestos							
B00A - R0012 - Duplicating Workroom - 13.68 m2							
No Asbestos							
B00A - R0013 - Movement - 3.85 m2							
No Asbestos							
B00A - R0014 - Entry Vestibule - 12.58 m2							
No Asbestos							
B00A - R0015 - Movement - 11.17 m2							
No Asbestos							
B00A - R0016 - Principal - 20.45 m2							
No Asbestos							
B00A - R0017 - Staff Toilet - 4.35 m2							

Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0018 - Staff Toilet - 5.74 m2							
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0019 - Movement - 2.63 m2							
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0020 - Staff Room - 64.8 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0021 - Access Shower/Toilet - 8.48 m2							
No Asbestos							
B00A - R9001 - Movement - 2.26 m2							
No Asbestos							
B00A - R9002 - General Assistant/Bulk Store - 15.86 m2							
No Asbestos							
B00A - R9003 - Garden Store - 17.49 m2							
No Asbestos							
B00B - General Learning/Pupil Facilities - 1890 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B00B - R0001 - Movement - 39.24 m2							
No Asbestos							
B00B - R0002 - Home Base - 60.31 m2							
No Asbestos							
B00B - R0003 - Home Base - 60.1 m2							
No Asbestos							
B00B - R0004 - Home Base - 64.63 m2							
No Asbestos							
B00B - R0005 - Movement - 21.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6.2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0006 - Toilets - Girls - 14.45 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0007 - Toilets - Boys - 14.33 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Movement - 18.64 m2							
No Asbestos							
B00B - R0009 - General Storeroom - 11.32 m2							
No Asbestos							
B00B - R0010 - Withdrawal Space - 2hb - 37.48 m2							
No Asbestos							

B00B - R0011 - General Storeroom - 11.37 m2							
No Asbestos							
B00C - General Learning/Communal Facilities - 1876 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - General Storeroom - 9.89 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
B00C - R0002 - Home Base - 48.27 m2							
No Asbestos							
B00C - R0003 - Movement - 21.88 m2							
No Asbestos							
B00C - R0004 - Home Base - 48.34 m2							
No Asbestos							
B00C - R0005 - Home Base - 55.45 m2							
Furniture / Fixtures - Blackboard	Flat AC Sheeting	14	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00C - R0008 - General Storeroom - 1.78 m2							
No Asbestos							
B00C - R0009 - General Storeroom - 8.81 m2							
No Asbestos							
B00C - R0010 - Movement - 21.01 m2							
No Asbestos							
B00C - R0011 - General Storeroom - 5.89 m2							
No Asbestos							
B00C - R0012 - Movement - 3.8 m2							
No Asbestos							
B00C - R0013 - Home Base - 71.39 m2							
Require Inspection							
B00C - R0014 - Home Base - 65.72 m2							
Require Inspection							
B00C - R9001 - General Storeroom - 34.33 m2							
No Asbestos							
B00D - Administration - 1950 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00D - R0001 - General Storeroom - 1.74 m2							
Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R0002 - General Storeroom - 25.63 m2							

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - Pupil Facilities - 1966 - Brick/Block							
Exterior							
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	8m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Interior							
B00E - R0001 - Staff Toilet - 3.01 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting						
B00E - R0002 - Toilets - Girls - 34.38 m2							
Partition Walls (Cubicles)	No Asbestos Found						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0004 - Toilets - Boys - 27.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0005 - External Movement - 41.57 m2							
No Asbestos							
B00F - General Learning/Pupil Facilities - 1958 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00F - R0001 - Movement - 52.04 m2							
No Asbestos							
B00F - R0002 - Personal Effects Storage - 9.8 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0003 - Home Base Store - 4.43 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0004 - Home Base - 57.95 m2							
No Asbestos							
B00F - R0005 - Home Base - 58.1 m2							
No Asbestos							
B00F - R0006 - Home Base Store - 4.4 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0007 - Personal Effects Storage - 9.82 m2							
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0008 - Toilets - Girls - 26.62 m2							

Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00F - R0009 - Toilets - Boys - 26.65 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - General Learning/Special Purpose Learning - 1912 - Timber							
Exterior							
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area						
Interior							
B00G - R0001 - Movement - 26.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Home Base - 50.95 m2							
No Asbestos							
B00G - R0003 - Home Base - 50.74 m2							
No Asbestos							
B00G - R0004 - Craft Store - 6.63 m2							
No Asbestos							
B00H - General Learning - 1912 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B00H - R0001 - General Storeroom - 6.25 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0002 - Home Base - 52.31 m2							
Ceiling Structures/Linings	Flat AC Sheeting	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0003 - Home Base - 52.24 m2							
Ceiling Structures/Linings	Flat AC Sheeting	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0005 - General Storeroom - 4.58 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00H - R0006 - Practical Activities - 2hb - 13.7 m2							

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00H - R0007 - Practical Activities - 1hb - 9.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting						
B00H - R0008 - External Movement - 33.57 m2							
No Asbestos							
B00I - Library - 1982 - Brick/Veneer							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Interior							
B00I - R0001 - Movement - 140.41 m2							
No Asbestos							
B00I - R0002 - Toilets - Boys - 6.89 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0003 - Distribution Board - 1.95 m2						Note: No inspection of live electrical installation	
Wall Linings Internal	Flat AC Sheeting	4m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0004 - Toilets - Girls - 6.52 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - R0005 - Library Office/Workroom - 24.69 m2							
No Asbestos							
B00I - R0006 - K.L.A Store - 12.98 m2							
No Asbestos							
B00I - R0007 - Reading Area - 158.11 m2							
No Asbestos							
B00I - R0008 - Special Programs Room - 44.02 m2							
No Asbestos							
B00I - R0009 - Plant - 1.76 m2							
No Asbestos							
B00I - R0010 - Special Programs Store - 4.95 m2							
No Asbestos							
B00J - Communal Facilities - 1966 - Timber							
Exterior							
Wall Cladding	Flat AC Sheeting						
Underfloor Voids - Slab on Ground	Non Accessible Area						
Ceiling Voids	No Asbestos Found						
Interior							
B00J - R0001 - Sports Store - 11.78 m2							
No Asbestos							
B00J - R0002 - Covered Outdoor Learning Area - 78.33 m2							
No Asbestos							
B00K - Pupil Facilities - 1966 - Brick/Block							
Exterior							

Ceiling Voids	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
Eaves Linings	Flat AC Sheeting	
Gable Verge Lining	Flat AC Sheeting	
Interior		
B00K - R0002 - Canteen Office/Store - 3.17 m2		
No Asbestos		
B00K - R0003 - Canteen Office/Store - 3.11 m2		
No Asbestos		
B00K - R0005 - General Storeroom - 39.13 m2		
Require Inspection		
B00L - Communal Facilities/Pupil Facilities - 2010 - Brick/Veneer		
Exterior		
Ceiling Voids	Non Accessible Area	
Underfloor Voids - Slab on Ground	Non Accessible Area	
Interior		
B00L - R0001 - Covered Outdoor Learning Area - 190.62 m2		
No Asbestos		
B00L - R0003 - Access Shower/Toilet - 6.9 m2		
No Asbestos		
B00L - R0004 - Main Switch Board - 3.37 m2		
No Asbestos		
B00L - R0005 - Communal Space - 200.36 m2		
No Asbestos		
B00L - R0006 - Cleaning Distributed Store - 3.57 m2		
No Asbestos		
B00L - R0007 - General Storeroom - 1.59 m2		
No Asbestos		
B00L - R0008 - Toilet - Lobby - 3.5 m2		
No Asbestos		
B00L - R0009 - Toilets - Boys - 5.77 m2		
No Asbestos		
B00L - R0010 - Sound Cupboard - 2.05 m2		
No Asbestos		
B00L - R0011 - Toilet - Lobby - 2.51 m2		
No Asbestos		
B00L - R0012 - Toilets - Girls - 7.41 m2		
No Asbestos		
B00L - R0013 - P.E. Store - 16.37 m2		
No Asbestos		
B00L - R0014 - Communal/Performance Store - 10.9 m2		
No Asbestos		
B00L - R0015 - Hall Chair Store - 11.19 m2		
No Asbestos		
B00L - R0016 - Movement - 17.39 m2		
No Asbestos		
B00L - R0017 - Raised Platform - 59 m2		
No Asbestos		
B00L - R0018 - Ramp - 12.62 m2		

No Asbestos	
B00L - R0019 - Movement - 5.96 m2	
No Asbestos	
B00L - R0020 - External Movement - 71.76 m2	
No Asbestos	
B00L - R0021 - Canteen - 38.71 m2	
No Asbestos	
B00L - R0022 - Canteen Office/Store - 8.79 m2	
No Asbestos	

Demountables

OS 602 10243 - Learning Unit - Standard With P.A.A. - Placement Date : 10-FEB-2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found

OS 602 11080 - Learning Unit - Standard With P.A.A. - Placement Date : 12-JAN-2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found