


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lane Cove Public School (2368)
Region:	Northern Sydney AMU
State Electorate:	Lane Cove
Local Government Area:	Lane Cove

Last Reviewed By:	Greencap 24-JUN-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B001 - General Learning - 1920 - Brick/Block							
Exterior							
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B001 - R0001 - General Storeroom - 4.78 m2							
No Asbestos							
B001 - R0004 - Movement - 4.58 m2							
No Asbestos							
B001 - R0005 - General Storeroom - 8.19 m2							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B001 - R0006 - Toilets - Boys/Girls - 3.84 m2							
No Asbestos							
B001 - R0007 - Movement - 14.02 m2							
No Asbestos							
B001 - R0008 - Practical Activities - 1hb - 12.17 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12.17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0009 - Home Base - 47.38 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0010 - Home Base - 66.29 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	66.29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0011 - Movement - 2.33 m2							
No Asbestos							
B001 - R0012 - Withdrawal Space - 2hb - 13.75 m2							
No Asbestos							
B001 - R0013 - Home Base Store - 4.31 m2							
No Asbestos							
B001 - R0014 - Home Base - 66.29 m2							
Wall Linings Internal	Vinyl Tiles	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	66.29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0015 - Home Base - 47.38 m2							

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0016 - Practical Activities - 1hb - 11.35 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	11.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B001 - R0017 - Staff Toilet - 4.39 m2							
No Asbestos							
B001 - R0018 - Home Base Store - 7.74 m2							
No Asbestos							
B001 - R0019 - Movement - 5.45 m2							
No Asbestos							
B001 - R0020 - Personal Effects Storage - 12.37 m2							
No Asbestos							
B001 - R0021 - Cleaning Distributed Store - 3.19 m2							
No Asbestos							
B001 - R0022 - Plant - 25.04 m2							
No Asbestos							
B001 - R0023 - Movement - 2.72 m2							
No Asbestos							
B001 - R0024 - Movement - 12.11 m2							
No Asbestos							
B001 - R0025 - Stairs - 10.31 m2							
No Asbestos							
B001 - R0026 - Stairs - 11.42 m2							
No Asbestos							
B001 - R1001 - Personal Effects Storage - 8.6 m2							
Floor Coverings Res/Textile	Vinyl Tiles						
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B001 - R1002 - General Storeroom - 5.12 m2							
No Asbestos							
B001 - R1003 - Toilets - Boys/Girls - 3.45 m2							
No Asbestos							
B001 - R1004 - Movement - 16.5 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B001 - R1005 - Home Base - 48.67 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
B001 - R1006 - Home Base - 67.95 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B001 - R1007 - Home Base - 67.94 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B001 - R1008 - Withdrawal Space - 1hb - 21.78 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B001 - R1009 - Home Base - 48.67 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B001 - R1010 - Movement - 9.36 m2								
No Asbestos								
B001 - R1011 - Plant - 8.88 m2								
No Asbestos								
B001 - R1012 - Plant - 4.53 m2								
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B001 - R1013 - Personal Effects Storage - 12.62 m2								
No Asbestos								
B001 - R1014 - Movement - 5.08 m2								
No Asbestos								
B001 - R1015 - Stairs - 10.04 m2								
No Asbestos								
B001 - R1016 - Stairs - 11.72 m2								
No Asbestos								
B001 - R9001 - General Storeroom - 4.4 m2								
No Asbestos								
B002 - General Learning - 1935 - Brick/Block								
Exterior								
Ceiling Voids	Non Accessible Area							
Underfloor Voids	Non Accessible Area							
Interior								
B002 - R0002 - Staff Toilet - 2.32 m2								
No Asbestos								
B002 - R0003 - Handwashing Facilities - 2.3 m2								
No Asbestos								
B002 - R0005 - Kiln Room - 1.8 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R0006 - Special Programs Room - 74.94 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R0007 - Movement - 2.72 m2								
No Asbestos								
B002 - R0008 - Special Programs Room - 12.8 m2								
No Asbestos								
B002 - R0009 - Cleaning Distributed Store - 2.21 m2								

Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R0010 - General Storeroom - 12.33 m2								
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B002 - R0011 - Staff Toilet - 4.83 m2								
No Asbestos								
B002 - R0012 - Movement - 3.14 m2								
No Asbestos								
B002 - R0013 - Personal Effects Storage - 22.15 m2								
Electrical - Backing Board	Resinous Board	1	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
B002 - R0014 - Movement - 3.46 m2								
No Asbestos								
B002 - R0015 - Staff Room Annexe - 17.41 m2								
No Asbestos								
B002 - R0016 - Home Base - 47.31 m2								
No Asbestos								
B002 - R0017 - Movement - 17.82 m2								
No Asbestos								
B002 - R0018 - Home Base - 47.31 m2								
No Asbestos								
B002 - R0019 - Movement - 16.04 m2								
No Asbestos								
B002 - R0020 - Home Base - 47.31 m2								
No Asbestos								
B002 - R0021 - Movement - 14.22 m2								
No Asbestos								
B002 - R0022 - Withdrawal Space - 1hb - 19.24 m2								
No Asbestos								
B002 - R0023 - Stairs - 8.28 m2								
No Asbestos								
B002 - R0024 - Stairs - 3.96 m2								
No Asbestos								
B002 - R0025 - Garden Store - 11.65 m2								
No Asbestos								
B002 - R0026 - Stairs - 19.9 m2								
No Asbestos								
B002 - R1001 - Toilets - Boys/Girls - 3.53 m2								
No Asbestos								
B002 - R1002 - Home Base Store - 5.62 m2								
No Asbestos								
B002 - R1003 - Movement - 7.97 m2								
No Asbestos								
B002 - R1004 - Practical Activities - 1hb - 17.12 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R1005 - Home Base - 49.24 m2								
No Asbestos								
B002 - R1006 - Practical Activities - 1hb - 14.77 m2								

Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R1007 - Home Base - 49.42 m2								
No Asbestos								
B002 - R1008 - Practical Activities - 1hb - 13.35 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B002 - R1009 - Home Base - 49.42 m2								
No Asbestos								
B002 - R1010 - General Storeroom - 4.03 m2								
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B002 - R1011 - Movement - 7.9 m2								
No Asbestos								
B002 - R1012 - Movement - 21.94 m2								
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B002 - R1013 - Stairs - 17.58 m2								
No Asbestos								
B002 - R1014 - Stairs - 11.98 m2								
No Asbestos								
B003 - General Learning - 1983 - Brick/Block								
Exterior								
Eaves Linings	Flat AC Sheeting	60m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Ends	Flat AC Sheeting	10m2	North and South elevations	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
Underfloor Voids	No Asbestos Found							
Ceiling Voids	Non Accessible Area							
Interior								
B003 - R0001 - Home Base - 57.88 m2								
No Asbestos								
B003 - R0002 - Home Base Store - 4.9 m2								
No Asbestos								
B003 - R0003 - Personal Effects Storage - 7.52 m2								
No Asbestos								
B003 - R0004 - Movement - 6.21 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0005 - Movement - 1.57 m2								
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)	
B003 - R0006 - Home Base Store - 4.9 m2								
No Asbestos								
B003 - R0007 - Home Base - 57.88 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0008 - Special Programs Room - 32.34 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0009 - Cleaning Distributed Store - 1.7 m2								
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B003 - R0010 - Home Base Store - 10.18 m2								
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive							
B003 - R0011 - Movement - 15.8 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
Electrical - Backing Board	Resinous Board	1	West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos	
B003 - R0012 - Staff Toilet - 3.19 m2								
No Asbestos								
B003 - R0013 - Movement - 1.68 m2								
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R0014 - Staff Toilet - 3.22 m2								
No Asbestos								
B003 - R0015 - Home Base - 57.88 m2								
No Asbestos								
B003 - R0017 - Personal Effects Storage - 7.53 m2								
No Asbestos								
B003 - R0018 - Movement - 6.21 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0019 - Movement - 1.57 m2								
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R0021 - Home Base - 57.88 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0025 - Movement - 1.5 m2								
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R0026 - Practical Activities - 2hb - 9.66 m2								
Floor Coverings Res/Textile	Vinyl Sheet							
B003 - R0027 - Uniform Shop - 27.03 m2								
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)							
B003 - R9001 - Toilets - Boys - 15.04 m2								
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R9002 - Sports Store - 27.29 m2								
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R9003 - Garden Store - 11.44 m2								
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R9004 - Cleaning Supplies - 7.56 m2								
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R9005 - General Assistant/Bulk Store - 7.14 m2								
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (brown asbestos)	
B003 - R9006 - Garden Store - 13.99 m2								

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R9007 - P.E. Store - 13.98 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R9008 - Garden Store - 14.19 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R9009 - Cleaning Distributed Store - 3.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B004 - General Learning - 1935 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B004 - R0001 - Handwashing Facilities - 12.62 m2							
No Asbestos							
B004 - R0002 - General Storeroom - 2.07 m2							
No Asbestos							
B004 - R0003 - Movement - 5.24 m2							
No Asbestos							
B004 - R0004 - General Storeroom - 14.08 m2							
No Asbestos							
B004 - R0005 - Craft Store - 2.84 m2							
No Asbestos							
B004 - R0007 - Movement - 5.4 m2							
No Asbestos							
B004 - R0008 - Cleaning Distributed Store - 2.13 m2							
No Asbestos							
B004 - R0009 - Movement - 4.37 m2							
No Asbestos							
B004 - R0010 - Staff Toilet - 3.56 m2							
No Asbestos							
B004 - R0011 - Staff Toilet - 3.55 m2							
No Asbestos							
B004 - R0012 - Home Base - 67.98 m2							
No Asbestos							
B004 - R0013 - Home Base - 47.89 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	8	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B004 - R0014 - Home Base - 47.89 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	10	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B004 - R0015 - Home Base - 48.35 m2							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B004 - R0016 - Movement - 3.34 m2							
No Asbestos							
B004 - R0017 - Movement - 55.94 m2							

Electrical - Mounting Board	Resinous Membrane	1	South end west wall	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B004 - R0018 - Stairs - 7.21 m2							
No Asbestos							
B004 - R0019 - Stairs - 7.37 m2							
No Asbestos							
B004 - R1001 - Staff Toilet - 4.48 m2							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B004 - R1002 - Personal Effects Storage - 7.93 m2							
No Asbestos							
B004 - R1003 - Staff Room Annexe - 20.51 m2							
No Asbestos							
B004 - R1004 - General Storeroom - 8.44 m2							
No Asbestos							
B004 - R1005 - Movement - 8.66 m2							
No Asbestos							
B004 - R1006 - Practical Activities - 1hb - 6.05 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B004 - R1007 - Home Base - 49.64 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B004 - R1008 - Home Base - 48.91 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	8	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B004 - R1009 - Home Base - 48.91 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	6	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
B004 - R1010 - Home Base - 48.91 m2							
Furniture / Fixtures - Blackboard	Compressed AC Sheet	10	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B004 - R1011 - Movement - 73.79 m2							
Floor Coverings Res/Textile	Vinyl Sheet						
B004 - R1012 - Stairs - 10.61 m2							
No Asbestos							
B004 - R1013 - Stairs - 10.82 m2							
No Asbestos							

B005 - General Learning - 1923 - Brick/Block

Exterior

Ceiling Voids	No Asbestos Found						
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	40m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos

Interior

B005 - R0001 - Home Base - 55.03 m2

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						

B005 - R0002 - Home Base Store - 7.91 m2

Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B005 - R0003 - Personal Effects Storage - 7.91 m2

Floor Coverings Res/Textile	Vinyl Sheet						
-----------------------------	-------------	--	--	--	--	--	--

B005 - R0004 - General Storeroom - 9.57 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0005 - Practical Activities - 1hb - 27.01 m2

Wall Linings Internal	Flat AC Sheeting	3m2	near switch board	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Sheet						

B005 - R0006 - Toilets - Boys/Girls - 3.37 m2

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
-----------------------	------------------	-----	--------------	--------------------	---------	--------------------	---

B005 - R0007 - Movement - 1.16 m2

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

B005 - R0008 - Home Base - 84.36 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0009 - Home Base - 56.34 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0010 - General Storeroom - 6.05 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0011 - Personal Effects Storage - 3.2 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0012 - Movement - 2.67 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

B005 - R0013 - Movement - 1.25 m2

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

B005 - R9001 - Home Base - 55.18 m2

Ceiling Structures/Linings	Vermiculite - Composite Sample - (40 - 70 m2) - (X5)						
----------------------------	---	--	--	--	--	--	--

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	55.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B005 - R9002 - Home Base Store - 4.66 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B005 - R9003 - Personal Effects Storage - 6.97 m2							
Ceiling Structures/Linings	Vermiculite - Composite Sample - (< 10 m2) - (X2)						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						
B005 - R9004 - Movement - 1.26 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B006 - General Learning - 1891 - Brick/Block							
Exterior							
Ceiling Voids	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Eaves Linings	Flat AC Sheeting	10m2	East & west	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Interior							
B006 - R0001 - Movement - 35.8 m2							
No Asbestos							
B006 - R0002 - Home Base - 46.71 m2							
No Asbestos							
B006 - R0003 - Practical Activities - 1hb - 45.54 m2							
No Asbestos							
B008 - Pupil Facilities - 1935 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B008 - R0003 - Handwashing Facilities - 13.45 m2							
No Asbestos							
B008 - R0004 - Cleaning Supplies - 12.01 m2							
No Asbestos							
B008 - R0005 - Handwashing Facilities - 13.44 m2							
No Asbestos							
B008 - R0008 - Toilets - Boys - 25.33 m2							
No Asbestos							
B008 - R0009 - Toilets - Girls - 42.92 m2							
No Asbestos							
B008 - R0010 - External Movement - 24.99 m2							
No Asbestos							
B008 - R0011 - External Movement - 17.25 m2							
No Asbestos							

B00A - Administration/General Learning - 1935 - Brick/Block

Exterior

Eaves Linings	Flat AC Sheeting	50m2	Upper and lower eaves	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids - Raked Ceiling	Non Accessible Area						

Interior

B00A - R0001 - Movement - 15.57 m2

No Asbestos

B00A - R0002 - Deputy Principal - 13.3 m2

No Asbestos

B00A - R0003 - Principal - 21.17 m2

No Asbestos

B00A - R0004 - Deputy Principal - 12.07 m2

No Asbestos

B00A - R0005 - Staff Toilet - 5.38 m2

Partition Walls (Cubides)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
---------------------------	---------------------	-----	--------------------	--------------------	---------	--------------------	-----------------------------

B00A - R0006 - Distribution Board - 1.04 m2

Note: No inspection of live electrical installation

Electrical - Backing Board	Resinous Board	1	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
----------------------------	----------------	---	---------	--------------------	---------	--------------------	------------------

B00A - R0007 - Staff Toilet - 5.38 m2

Partition Walls (Cubides)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00A - R0008 - Staff Room Annexe - 11.59 m2

Floor Coverings Res/Textile	Vinyl Sheet						
-----------------------------	-------------	--	--	--	--	--	--

B00A - R0009 - Staff Room - 70.69 m2

No Asbestos

B00A - R0010 - Cleaning Distributed Store - 1.36 m2

No Asbestos

B00A - R0011 - Security Store - 21.76 m2

No Asbestos

B00A - R0012 - Duplicating Workroom - 32 m2

Floor Coverings Res/Textile	Vinyl Sheet						
-----------------------------	-------------	--	--	--	--	--	--

B00A - R0013 - Security Store - 32.73 m2

Floor Coverings Res/Textile	Vinyl Tiles	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles - Adhesive						

B00A - R0014 - Sick Bay - 13.94 m2

No Asbestos

B00A - R0015 - Clerical Office - 15.2 m2

No Asbestos

B00A - R0016 - Entry Vestibule - 52.45 m2

No Asbestos

B00A - R0017 - Movement - 25.9 m2

No Asbestos

B00A - R0018 - Movement - 23.39 m2							
No Asbestos							
B00A - R0019 - General Storeroom - 4.25 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	4m2	Adobe shutter door	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0020 - Movement - 3.36 m2							
No Asbestos							
B00A - R0021 - Movement - 40.72 m2							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0022 - Movement - 9.67 m2							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
External Roof Structure - Packing	Flat AC Sheeting	5	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0023 - Stairs - 10.97 m2							
No Asbestos							
B00A - R1001 - Communications Room - 13.57 m2							
No Asbestos							
B00A - R1002 - Library Office/Workroom - 8.98 m2							
No Asbestos							
B00A - R1003 - Library Office/Workroom - 21.44 m2							
No Asbestos							
B00A - R1004 - Seminar/Study - 11.97 m2							
No Asbestos							
B00A - R1005 - Seminar/Study - 15.26 m2							
No Asbestos							
B00A - R1006 - Movement - 8.68 m2							
No Asbestos							
B00A - R1007 - Cleaning Distributed Store - .37 m2							
No Asbestos							
B00A - R1008 - Toilets - Girls - 4.07 m2							
No Asbestos							
B00A - R1009 - Movement - .94 m2							
No Asbestos							
B00A - R1010 - Distribution Board - .68 m2						Note: No inspection of live electrical installation	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
B00A - R1011 - Toilets - Boys - 4.67 m2							
Ceiling Structures/Linings	Flat AC Sheeting	0.5m2	Loft hatch	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1012 - Reading Area - 261.36 m2							
No Asbestos							
B00A - R1013 - Movement - 45.55 m2							
No Asbestos							
B00A - R1014 - Movement - 49.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R1015 - Stairs - 14.79 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - Communal Facilities - 1935 - Brick/Block							
Exterior							

Gable Ends	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area						
Underfloor Voids	Non Accessible Area						
Interior							
B00B - R0001 - Movement - 194.7 m2							
Ceiling Structures/Linings	Flat AC Sheeting	200m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0002 - Canteen - 41.51 m2							
No Asbestos							
B00B - R0003 - Canteen Office/Store - 4.73 m2							
No Asbestos							
B00B - R0004 - Staff Toilet - 3.5 m2							
No Asbestos							
B00B - R0005 - Canteen Office/Store - 4.84 m2							
No Asbestos							
B00B - R0006 - Distribution Board - .97 m2							
Note: No inspection of live electrical installation							
Electrical - Backing Board	Resinous Board	1	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
B00B - R0007 - Hall Chair Store - 11.28 m2							
Floor Coverings Res/Textile	Compressed AC Sheet	1m2	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0008 - Plant - 3.56 m2							
No Asbestos							
B00B - R0009 - Raised Platform - 71.25 m2							
No Asbestos							
B00B - R0010 - Music Store - 6.94 m2							
No Asbestos							
B00B - R0011 - P.E Store - 11.25 m2							
No Asbestos							
B00B - R0012 - Communal Space - 256.73 m2							
No Asbestos							
B00B - R0013 - Toilets - Girls - 9.74 m2							
Partition Walls (Cubides)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0014 - Cleaning Distributed Store - 1.42 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
B00B - R0015 - Toilets - Boys - 9.74 m2							
Partition Walls (Cubides)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - General Learning - 2011 - Brick/Veneer							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00C - R0001 - Home Base - 59.24 m2							
No Asbestos							
B00C - R0002 - Home Base - 61.03 m2							
No Asbestos							
B00C - R0003 - Home Base - 60.86 m2							
No Asbestos							
B00C - R0004 - Practical Activities - 1hb - 20.76 m2							

No Asbestos	
B00C - R0005 - Withdrawal Space - 1hb - 5.13 m2	
No Asbestos	
B00C - R0006 - Home Base Store - 9.06 m2	
No Asbestos	
B00C - R0007 - Practical Activities - 1hb - 19.93 m2	
No Asbestos	
B00C - R0008 - Home Base Store - 5.45 m2	
No Asbestos	
B00C - R0009 - Withdrawal Space - 2hb - 11.6 m2	
No Asbestos	
B00C - R0010 - Practical Activities - 1hb - 19.21 m2	
No Asbestos	
B00C - R0011 - Home Base Store - 5.51 m2	
No Asbestos	
B00C - R0012 - General Storeroom - 5.66 m2	
No Asbestos	
B00C - R0013 - General Storeroom - 4.6 m2	
No Asbestos	
B00C - R0014 - External Movement - 73.6 m2	
No Asbestos	
B00C - R0015 - External Stairs - 12.51 m2	
No Asbestos	
B00C - R0016 - External Stairs - 13.81 m2	
No Asbestos	
B00C - R1001 - Home Base - 59.14 m2	
No Asbestos	
B00C - R1002 - Home Base - 61.06 m2	
No Asbestos	
B00C - R1003 - Home Base - 60.68 m2	
No Asbestos	
B00C - R1004 - Practical Activities - 1hb - 20.31 m2	
No Asbestos	
B00C - R1005 - Withdrawal Space - 1hb - 9.04 m2	
No Asbestos	
B00C - R1006 - Home Base Store - 5.08 m2	
No Asbestos	
B00C - R1007 - Practical Activities - 1hb - 18.78 m2	
No Asbestos	
B00C - R1008 - Home Base Store - 5.52 m2	
No Asbestos	
B00C - R1009 - Withdrawal Space - 2hb - 11.56 m2	
No Asbestos	
B00C - R1010 - Practical Activities - 1hb - 18.91 m2	
No Asbestos	
B00C - R1011 - Home Base Store - 5.47 m2	
No Asbestos	
B00C - R1012 - External Movement - 69.99 m2	
No Asbestos	
B00C - R1013 - External Stairs - 19.13 m2	
No Asbestos	
B00C - R1014 - External Stairs - 20.34 m2	

No Asbestos	
B00C - R9001 - General Storeroom - 121.13 m2	
No Asbestos	

Demountables

OS 801 17382 - FSU - Placement Date : 14-FEB-2020

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found