

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>La Perouse Public School (2373)</b>
<b>Region:</b>	<b>Sydney AMU</b>
<b>State Electorate:</b>	<b>Maroubra</b>
<b>Local Government Area:</b>	<b>Randwick</b>

<b>Last Reviewed By:</b>	<b>WSP 01-NOV-2016</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>Yes</b>
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

2373 - La Perouse Public School  
Site Plan (13084)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

### Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

### Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

### Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

#### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Library/Administration - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	100m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	AC Fragments/Debris	1	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Requires Inspection						
<b>Interior</b>							
<b>B00A - R0001 - Outdoor Learning Area - 20.62 m2</b>							
No Asbestos							
<b>B00A - R0002 - Disabled Toilet - 7.16 m2</b>							
Wall Linings Internal	Vinyl Sheet						
Underfloor Voids	No Asbestos Found						
<b>B00A - R0003 - Practical Activities - 1hb - 10 m2</b>							
No Asbestos							
<b>B00A - R0004 - Home Base - 64.23 m2</b>							
No Asbestos							
<b>B00A - R0005 - Movement - 174.47 m2</b>							
No Asbestos							
<b>B00A - R0006 - External Movement - 1.78 m2</b>							
No Asbestos							
<b>B00A - R0007 - Clerical Office - 12.29 m2</b>							
No Asbestos							
<b>B00A - R0008 - Principal - 20.22 m2</b>							
No Asbestos							
<b>B00A - R0009 - Staff Toilet - 4.41 m2</b>							
No Asbestos							
<b>B00A - R0010 - Security Store - 11.83 m2</b>							
No Asbestos							
<b>B00A - R0011 - Other-Community Use - 51.43 m2</b>							
No Asbestos							
<b>B00A - R0012 - Home Base - 51.43 m2</b>							
No Asbestos							
<b>B00A - R0013 - Home Base - 57.53 m2</b>							
No Asbestos							
<b>B00A - R0014 - Home Base - 45.3 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	46m2	North facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0015 - Outdoor Learning Area - 56.74 m2</b>							
No Asbestos							
<b>B00A - R0016 - Movement - 6.58 m2</b>							
No Asbestos							
<b>B00A - R0017 - Toilets - Girls - 29.35 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00A - R0018 - Toilets - Boys - 30.87 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00A - R0019 - Cleaning Distributed Store - 4.15 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0020 - Cleaning Distributed Store - .41 m2</b>							
No Asbestos							
<b>B00A - R0021 - External Movement - 1.14 m2</b>							
No Asbestos							
<b>B00A - R0022 - External Movement - 1.14 m2</b>							
No Asbestos							
<b>B00A - R0023 - External Movement - 2.5 m2</b>							
No Asbestos							
<b>B00A - R0024 - P.E Store - 7.37 m2</b>							
No Asbestos							
<b>B00A - R0025 - Movement - 25.06 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R0026 - Home Base - 61.58 m2</b>							
No Asbestos							
<b>B00A - R0027 - Practical Activities - 1hb - 4.49 m2</b>							
No Asbestos							
<b>B00A - R0028 - Home Base Store - 8.64 m2</b>							
No Asbestos							
<b>B00A - R0029 - Home Base Store - 8.59 m2</b>							
No Asbestos							
<b>B00A - R0030 - Home Base - 65.25 m2</b>							
No Asbestos							
<b>B00A - R0031 - Practical Activities - 1hb - 4.95 m2</b>							
No Asbestos							
<b>B00A - R0032 - Withdrawal Space - 1hb - 8.61 m2</b>							
No Asbestos							
<b>B00A - R0033 - Movement - 2.79 m2</b>							
No Asbestos							
<b>B00A - R0034 - External Movement - 3.43 m2</b>							
No Asbestos							
<b>B00A - R0035 - External Movement - 12.46 m2</b>							
No Asbestos							
<b>B00A - R0036 - Stairs - 8.1 m2</b>							
No Asbestos							
<b>B00A - R0037 - Stairs - 7.95 m2</b>							
No Asbestos							
<b>B00A - R1001 - Practical Activities - 1hb - 13.81 m2</b>							
No Asbestos							
<b>B00A - R1002 - Home Base - 64.43 m2</b>							
No Asbestos							
<b>B00A - R1003 - Movement - 146.1 m2</b>							
No Asbestos							
<b>B00A - R1004 - General Storeroom - 4.03 m2</b>							
No Asbestos							
<b>B00A - R1005 - Craft Store - 15.69 m2</b>							

No Asbestos		
<b>B00A - R1006 - Interview - 19.54 m2</b>		
No Asbestos		
<b>B00A - R1007 - Staff Toilet - 4.46 m2</b>		
No Asbestos		
<b>B00A - R1008 - Security Store - 11.8 m2</b>		
Ceiling Structures/Linings - Access Hatch	Flat AC Sheeting	
<b>B00A - R1009 - Reading Area - 104.53 m2</b>		
No Asbestos		
<b>B00A - R1010 - Library Office/Workroom - 51.51 m2</b>		
No Asbestos		
<b>B00A - R1011 - Home Base - 51.51 m2</b>		
No Asbestos		
<b>B00A - R1012 - General Storeroom - 4.16 m2</b>		
No Asbestos		
<b>B00A - R1013 - Movement - 28.36 m2</b>		
No Asbestos		
<b>B00A - R1014 - General Storeroom - 18.45 m2</b>		
No Asbestos		
<b>B00A - R1015 - Home Base - 62.71 m2</b>		
No Asbestos		
<b>B00A - R1016 - Practical Activities - 1hb - 3.45 m2</b>		
No Asbestos		
<b>B00A - R1017 - Music Store - 8.69 m2</b>		
No Asbestos		
<b>B00A - R1018 - Cleaning Distributed Store - 1.89 m2</b>		
No Asbestos		
<b>B00A - R1019 - Personal Effects Storage - 4.34 m2</b>		
No Asbestos		
<b>B00A - R1020 - Home Base Store - 8.59 m2</b>		
No Asbestos		
<b>B00A - R1021 - Home Base - 65.44 m2</b>		
No Asbestos		
<b>B00A - R1022 - Practical Activities - 1hb - 4.08 m2</b>		
No Asbestos		
<b>B00A - R1023 - Stairs - 13.55 m2</b>		
No Asbestos		
<b>B00A - R1024 - Stairs - 13.5 m2</b>		
No Asbestos		
<b>B00B - Pupil Facilities - 1952 - Brick/Block</b>		
<b>Exterior</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
Ceiling Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - R0001 - External Movement - 41.93 m2</b>		
Wall Linings Internal	Flat AC Sheeting	
<b>B00B - R0002 - Canteen - 31.59 m2</b>		
No Asbestos		

<b>B00B - R0003 - Canteen Office/Store - 9.75 m2</b>							
No Asbestos							
<b>B00B - R0004 - General Storeroom - 1.27 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00C - General Learning - 1956 - Brick/Veneer</b>							
<b>Exterior</b>							
Underfloor Voids	Flat AC Sheeting	10	North	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos)
Underfloor Voids	Compressed AC Sheet						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	15m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00C - R0001 - Home Base Store - 6.82 m2</b>							
No Asbestos							
<b>B00C - R0002 - Home Base - 113.17 m2</b>							
Wall Linings Internal	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00C - R0003 - Personal Effects Storage - 3.55 m2</b>							
No Asbestos							
<b>B00C - R0004 - Movement - 3.44 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0005 - External Movement - 4.79 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00C - R0006 - Home Base Store - 9.85 m2</b>							
No Asbestos							
<b>B00C - R0007 - Personal Effects Storage - 4.94 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00C - R0008 - Movement - 5.36 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00C - R0009 - External Movement - 5.93 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00C - R0010 - Practical Activities - 1hb - 7.27 m2</b>							
No Asbestos							
<b>B00C - R0011 - Home Base - 49.8 m2</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00C - R9001 - General Storeroom - 9.84 m2</b>							
No Asbestos							
<b>B00C - R9002 - General Storeroom - 18.11 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00C - R9003 - General Storeroom - 41.5 m2</b>							

No Asbestos							
<b>B00D - Communal Facilities - 1965 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - External Movement - 4.9 m2</b>							
No Asbestos							
<b>B00D - R0002 - Toilets - Girls - 1.89 m2</b>							
No Asbestos							
<b>B00D - R0003 - Movement - 3.45 m2</b>							
No Asbestos							
<b>B00D - R0004 - Shower/Change - 9.4 m2</b>							
No Asbestos							
<b>B00D - R0005 - Raised Platform - 45.17 m2</b>							
No Asbestos							
<b>B00D - R0006 - Shower/Change - 9.34 m2</b>							
No Asbestos							
<b>B00D - R0007 - Toilets - Boys - 1.9 m2</b>							
No Asbestos							
<b>B00D - R0008 - Movement - 3.45 m2</b>							
No Asbestos							
<b>B00D - R0009 - Communal Space - 232.4 m2</b>							
No Asbestos							
<b>B00D - R0010 - External Movement - 12.29 m2</b>							
No Asbestos							
<b>B00D - R0011 - External Movement - 4.9 m2</b>							
No Asbestos							
<b>B00D - R9001 - Staff Kitchen - 8.9 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces, Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces, Lower portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R9002 - Cleaning Distributed Store - 1.68 m2</b>							
No Asbestos							
<b>B00E - Other-Community Use - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	Non Accessible Area						
<b>Interior</b>							
<b>B00E - R0001 - Other-Community Use - 19.86 m2</b>							
No Asbestos							
<b>B00E - R0002 - Other-Community Use - .68 m2</b>							
No Asbestos							
<b>B00E - R0003 - Other-Community Use - 13.13 m2</b>							
No Asbestos							
<b>B00E - R0004 - Other-Community Use - 3.5 m2</b>							
No Asbestos							
<b>B00E - R0005 - Other-Community Use - 2.85 m2</b>							
No Asbestos							
<b>B00E - R0006 - Other-Community Use - 2.97 m2</b>							

Plant / Equipment - Incinerator	Encapsulated Asbestos material within unit	1	West facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)	Assumed Asbestos
<b>B00E - R0007 - Other-Community Use - 8.3 m2</b>							
No Asbestos							
<b>B00E - R0008 - Other-Community Use - 9.78 m2</b>							
No Asbestos							
<b>B00E - R0009 - Other-Community Use - 5.21 m2</b>							
No Asbestos							
<b>B00E - R0010 - Other-Community Use - .54 m2</b>							
No Asbestos							
<b>B00E - R0011 - Other-Community Use - 65.41 m2</b>							
No Asbestos							
<b>B00F - Building Services/Other-Community Use - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Wall Cladding	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	15m2	North & South	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	15m2	North facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting	15m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00F - R0001 - Other-Community Use - 2.56 m2</b>							
No Asbestos							
<b>B00F - R0002 - Other-Community Use - 43.22 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0003 - Other-Community Use - 4.82 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
<b>B00F - R0004 - Other-Community Use - 18.26 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0005 - Other-Community Use - 20.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0006 - Other-Community Use - 8.93 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0007 - Other-Community Use - 66.07 m2</b>							
Non Accessible							
<b>B00F - R0008 - Other-Community Use - 3.24 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0009 - Other-Community Use - 4.61 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00F - R0010 - External Movement - 45.13 m2</b>							



No Asbestos							
<b>B00G - Pupil Facilities - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	AC Fragments/Debris	3	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00G - R0001 - Toilets - Boys - 23.94 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00H - Pupil Facilities - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	5m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	AC Fragments/Debris	2	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00H - R0001 - Toilets - Girls - 28.67 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
<b>B00J - Pupil Facilities - 1952 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids - Flat Roof	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	5m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>Interior</b>							
<b>B00J - R0001 - Drinking Facilities - 10.4 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0002 - Drinking Facilities - 9.22 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020