

Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Lavington Public School (2378)
Region:	Southern NSW AMU
State Electorate:	Albury
Local Government Area:	Albury

Last Reviewed By:	AECOM 10-OCT-2014
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	No
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - o Any wall cavity
 - o Sub floor area, particularly formwork for slabs in/on ground,
 - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1968 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	30	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	5	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
External Roof Structure	Fibre Cement Pipe	2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	No Asbestos Found						
Underfloor Voids	AC Fragments/Debris		Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00A - R0002 - Staff Toilet - 4.35 m2							
No Asbestos							
B00A - R0003 - Staff Toilet - 4.39 m2							
No Asbestos							
B00A - R0004 - Distribution Board - .32 m2							
No Asbestos							
B00A - R0005 - Principal - 17.35 m2							
No Asbestos							
B00A - R0006 - Sick Bay - 8.39 m2							
Wall Linings Internal	Flat AC Sheeting						
B00A - R0007 - Staff Room Annexe - 11.63 m2							
No Asbestos							
B00A - R0008 - Cleaning Supplies - 1.22 m2							
No Asbestos							
B00A - R0009 - General Storeroom - 11.75 m2							
No Asbestos							
B00A - R0010 - Staff Room - 51.08 m2							
No Asbestos							
B00A - R0011 - Staff Kitchen - 11.87 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0012 - Movement - 16.91 m2							
No Asbestos							
B00A - R0013 - Staff Room Annexe - 12.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Cover to ceiling access hatch	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0014 - Duplicating Workroom - 29.95 m2							
No Asbestos							
B00A - R0015 - Clerical Office - 14.06 m2							
No Asbestos							
B00A - R0016 - Entry Vestibule - 18.04 m2							
No Asbestos							
B00A - R0017 - External Movement - 40.21 m2							
No Asbestos							
B00A - R0018 - Ramp - 14.54 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	

Wall Linings Internal	Flat AC Sheeting	1m2	Upper portion, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
Wall Linings Internal - Infill	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	
B00A - R0019 - External Movement - 37.61 m2							
Wall Linings Internal - Infill	Flat AC Sheeting	2m2	South & West	Good Condition (1)	Low (1)	Low Priority (2-3)	
Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
Wall Linings Internal	Flat AC Sheeting	2m2	Upper portion, South & West	Good Condition (1)	Low (1)	Low Priority (2-3)	
B00B - General Learning - 1957 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	5	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	25	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
External Roof Structure	Fibre Cement Pipe	4	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids - Slab on Ground							
Ceiling Voids	No Asbestos Found						
Interior							
B00B - R0001 - General Storeroom - 7.68 m2							
No Asbestos							
B00B - R0002 - Movement - 82.56 m2							
Ceiling Structures/Linings	Flat AC Sheeting	85m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0004 - Toilets - Girls - 49.15 m2							
Partition Walls (Cubicles)	Compressed AC Sheet						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0005 - Cleaning Supplies - 6.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0006 - Toilets - Boys - 54.96 m2							
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet						
B00B - R0007 - Home Base - 62.66 m2							
No Asbestos							
B00B - R0008 - Home Base - 64.65 m2							
No Asbestos							
B00B - R0009 - Kiln Room - 7.63 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00B - R0010 - Sports Store - 7.63 m2							
No Asbestos							
B00B - R0011 - Practical Activities - 1hb - 7.91 m2							
No Asbestos							
B00B - R0012 - Practical Activities - 1hb - 7.95 m2							
No Asbestos							

B00B - R0013 - Special Programs Room - 83.61 m2							
No Asbestos							
B00D - General Learning - 1965 - Brick/Veneer							
Exterior							
Gable Verge Lining	Flat AC Sheeting	24m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	10	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Flat AC Sheeting	1	Collar of manhole above ceiling access hatch	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00D - R0001 - Movement - 18.03 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00D - R0002 - Home Base - 64.89 m2							
No Asbestos							
B00D - R0003 - Movement - 9.03 m2							
No Asbestos							
B00E - General Learning - 1964 - Brick/Block							
Exterior							
Wall Linings Internal - Infill	Flat AC Sheeting	25	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
External Roof Structure	Fibre Cement Pipe	4	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Flat AC Sheeting	1	Collar of manhole above ceiling access hatch	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	34m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	15	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00E - R0001 - Home Base Store - 5.61 m2							
No Asbestos							
B00E - R0002 - Home Base - 57.23 m2							
No Asbestos							
B00E - R0003 - Home Base - 57.17 m2							
No Asbestos							
B00E - R0004 - Home Base Store - 5.72 m2							
No Asbestos							
B00E - R0005 - Personal Effects Storage - 8.23 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Cover to ceiling access hatch	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0007 - General Storeroom - 3.74 m2							
No Asbestos							
B00E - R0008 - General Storeroom - 3.49 m2							
No Asbestos							
B00E - R0009 - Withdrawal Space - 1hb - 22.51 m2							

No Asbestos							
B00E - R0010 - Personal Effects Storage - 8.27 m2							
No Asbestos							
B00E - R0011 - Clerical Office - 16.92 m2							
Ceiling Structures/Linings	Flat AC Sheeting	16.93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0012 - General Storeroom - 5.3 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0013 - External Movement - 47.77 m2							
Ceiling Structures/Linings	Flat AC Sheeting	47.76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Window	Mastic						
B00F - Communal Facilities - 1962 - Brick/Block							
Exterior							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Interior							
B00F - R0001 - Cleaning Supplies - .91 m2							
No Asbestos							
B00F - R0002 - Plant - .8 m2							
No Asbestos							
B00F - R0003 - Shower/Change - 2.15 m2							
No Asbestos							
B00F - R0004 - Toilets - Girls - 10.9 m2							
No Asbestos							
B00F - R0005 - Hall Chair Store - 2.59 m2							
No Asbestos							
B00F - R0006 - Movement - 78.49 m2							
No Asbestos							
B00F - R0007 - Communal Space - 134.55 m2							
No Asbestos							
B00F - R0008 - Canteen - 26.36 m2							
No Asbestos							
B00F - R0009 - Canteen Office/Store - 9.19 m2							
No Asbestos							
B00F - R0010 - P.E. Store - 13.03 m2							
No Asbestos							
B00F - R0011 - P.E. Store - 10.76 m2							
No Asbestos							
B00F - R0012 - Movement - 24.64 m2							
No Asbestos							
B00F - R0013 - Toilets - Boys - 10.81 m2							
No Asbestos							
B00F - R0014 - Hall Chair Store - 2.59 m2							
No Asbestos							
B00F - R0015 - Raised Platform - 53.53 m2							
No Asbestos							
B00F - R0016 - Movement - 6.29 m2							
No Asbestos							
B00F - R0017 - Shower/Change - 2.63 m2							

No Asbestos							
B00F - R0018 - Distribution Board - 1.62 m2							Note: No inspection of live electrical installation
No Asbestos							
B00F - R0019 - Movement - 17.48 m2							
No Asbestos							
B00F - R0020 - Movement - 6.47 m2							
No Asbestos							
B00F - R0021 - Disabled Toilet - 3.31 m2							
No Asbestos							
B00G - General Learning - 1968 - Brick/Block							
Exterior							
Gable Verge Lining	Flat AC Sheeting	36m2	North facing, south facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	25	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Wall Linings Internal - Infill	Flat AC Sheeting	25	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
External Roof Structure	Fibre Cement Pipe	2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Ceiling Voids	Flat AC Sheeting	1	Collar of manhole above ceiling access hatch in GR0008.	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area						
Interior							
B00G - R0001 - Movement - 48.45 m2							
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Toilets - Boys/Girls - 3.42 m2							
No Asbestos							
B00G - R0003 - Toilets - Boys/Girls - 3.36 m2							
No Asbestos							
B00G - R0004 - Withdrawal Space - 1hb - 20.1 m2							
No Asbestos							
B00G - R0005 - Home Base - 57.41 m2							
No Asbestos							
B00G - R0006 - Home Base Store - 4.17 m2							
No Asbestos							
B00G - R0007 - Home Base Store - 4.2 m2							
No Asbestos							
B00G - R0008 - Withdrawal Space - 1hb - 19.35 m2							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Cover to ceiling access hatch	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0009 - Home Base - 57.47 m2							
No Asbestos							
B00G - R0013 - Garden Store - 13.6 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00G - R0014 - Toilets-Unisex - 13.62 m2							
Requires Inspection							
B00H - General Learning - 1968 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting						

External Roof Structure	Fibre Cement Pipe	5	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Assumed Asbestos
Underfloor Voids	Non Accessible Area						
Ceiling Voids	Non Accessible Area						
Interior							
B00H - R0001 - Home Base - 57.8 m2							
No Asbestos							
B00H - R0002 - General Storeroom - 3.37 m2							
No Asbestos							
B00H - R0003 - General Storeroom - 18.6 m2							
No Asbestos							
B00H - R0004 - Withdrawal Space - 1hb - 24.66 m2							
No Asbestos							
B00H - R0005 - Cleaning Supplies - 3.13 m2							
No Asbestos							
B00H - R0006 - Home Base - 57.63 m2							
No Asbestos							
B00H - R0007 - Home Base - 57.73 m2							
No Asbestos							
B00H - R0008 - General Storeroom - 5.56 m2							
No Asbestos							
B00H - R0009 - Movement - 3.05 m2							
No Asbestos							
B00H - R0010 - Interview - 12.91 m2							
No Asbestos							
B00H - R0011 - Home Base - 66.75 m2							
No Asbestos							
B00H - R0012 - Home Base - 53.85 m2							
No Asbestos							
B00H - R0013 - Movement - 104.76 m2							
Ceiling Structures/Linings	Flat AC Sheeting	105m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00I - General Learning - 1968 - Brick/Block							
Exterior							
Wall Linings Internal - Infill	Flat AC Sheeting	25	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	5	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting						
Gable Verge Lining	Flat AC Sheeting	20m2	North facing, south facing	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	Flat AC Sheeting	1	Collar of manhole in ceiling above IR0011.	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Underfloor Voids							
Interior							
B00I - R0001 - Toilets - Boys - 22.08 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00I - R0002 - Toilets - Girls - 20.51 m2							
Ceiling Structures/Linings	Flat AC Sheeting						
B00I - R0003 - Cleaning Supplies - 2.84 m2							

Ceiling Structures/Linings	Flat AC Sheeting							
B00I - R0004 - Movement - 91.03 m2								
Ceiling Structures/Linings	Flat AC Sheeting	92m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00I - R0006 - Home Base - 65.95 m2								
No Asbestos								
B00I - R0007 - Home Base - 93.87 m2								
No Asbestos								
B00I - R0008 - Toilets - Boys/Girls - 3.31 m2								
No Asbestos								
B00I - R0009 - Practical Activities - 1hb - 8.22 m2								
No Asbestos								
B00I - R0010 - Practical Activities - 1hb - 6.3 m2								
No Asbestos								
B00I - R0011 - Special Programs Room - 56.23 m2								
Ceiling Structures/Linings	Flat AC Sheeting	56.26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting							
B00I - R0012 - Craft Store - 8.03 m2								
Wall Linings Internal	Flat AC Sheeting							
Ceiling Structures/Linings	Flat AC Sheeting	8.04m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
B00I - R0013 - Sports Store - 8.03 m2								
Ceiling Structures/Linings	Flat AC Sheeting	8.04m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting							
B00J - Building Services - 1989 - Metal Shed								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00J - R0001 - Garden Store - 26.2 m2								
No Asbestos								
B00L - Library - 2005 - Brick/Veneer								
Exterior								
Ceiling Voids	No Asbestos Found							
Underfloor Voids	No Asbestos Found							
Interior								
B00L - R0001 - Reading Area - 169.76 m2								
Floor Coverings Res/Textile	No Asbestos Found							
B00L - R0002 - Cleaning Distributed Store - 3.62 m2								
No Asbestos								
B00L - R0003 - Distribution Board Cupboard - .55 m2								
No Asbestos								
B00L - R0004 - K.L.A. Store - 17.09 m2								
No Asbestos								
B00L - R0005 - Communications Room - 7.96 m2								
No Asbestos								

B00L - R0006 - Library Office/Workroom - 22.81 m2						
Floor Coverings Res/Textile	No Asbestos Found					
B00L - R0007 - Movement - 89.87 m2						
No Asbestos						
B00L - R0008 - Plant - 10.17 m2						
No Asbestos						
B00M - General Learning - 2010 - Brick/Veneer						
Exterior						
Underfloor Voids - Slab on Ground						
Ceiling Voids	Non Accessible Area					
Interior						
B00M - R0001 - Home Base - 59.98 m2						
No Asbestos						
B00M - R0002 - Home Base Store - 5.83 m2						
No Asbestos						
B00M - R0003 - Practical Activities - 19.11 m2						
No Asbestos						
B00M - R0004 - Withdrawal Space - 2hb - 11.56 m2						
No Asbestos						
B00M - R0005 - Home Base - 60.2 m2						
No Asbestos						
B00M - R0006 - Practical Activities - 19.05 m2						
No Asbestos						
B00M - R0007 - Home Base Store - 5.83 m2						
No Asbestos						
B00M - R0008 - Practical Activities - 19.05 m2						
No Asbestos						
B00M - R0009 - Home Base Store - 5.83 m2						
No Asbestos						
B00M - R0010 - Home Base - 60.2 m2						
No Asbestos						
B00M - R0011 - Withdrawal Space - 2hb - 11.56 m2						
No Asbestos						
B00M - R0012 - Practical Activities - 19.05 m2						
No Asbestos						
B00M - R0013 - Home Base - 60.2 m2						
No Asbestos						
B00M - R0014 - Home Base Store - 5.83 m2						
No Asbestos						
B00M - R0015 - Security Store - 15.08 m2						
No Asbestos						
B00M - R0016 - Security Store - 12.23 m2						
No Asbestos						
B00M - R0017 - General Storeroom - 12.42 m2						
No Asbestos						
B00M - R0018 - External Movement - 97.94 m2						
No Asbestos						
B00M - R0019 - Distribution Board - .62 m2						
No Asbestos						Note: No inspection of live electrical installation

B00N - Building Services - 2009 - Metal Shed

Exterior

Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground							

Interior

B00N - R0001 - Garden Store - 23.37 m2

No Asbestos	
-------------	--

Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020