

# Asbestos Register

(Hazardous Materials and Risk Assessment)

<b>School:</b>	<b>Lismore South Public School (2409)</b>
<b>Region:</b>	<b>North Coast AMU</b>
<b>State Electorate:</b>	<b>Lismore</b>
<b>Local Government Area:</b>	<b>Lismore</b>

<b>Last Reviewed By:</b>	<b>WSP 31-OCT-2016</b>
<b>Last Revised By:</b>	

<b>Historical Fibro In Grounds Investigations/Events</b>	<b>No</b>
<p>No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.</p>	



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>

<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - Communal Facilities/Library - 1978 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	30m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00A - R0001 - Movement - 1.33 m2</b>							
No Asbestos							
<b>B00A - R0002 - Communal Space - 155.02 m2</b>							
No Asbestos							
<b>B00A - R0003 - Movement - 17.43 m2</b>							
No Asbestos							
<b>B00A - R0004 - Music Store - 6.07 m2</b>							
No Asbestos							
<b>B00A - R0005 - Garden Store - 9.75 m2</b>							
No Asbestos							
<b>B00A - R0006 - Shower/Change - 11.64 m2</b>							
No Asbestos							
<b>B00A - R0007 - Movement - 18.57 m2</b>							
No Asbestos							
<b>B00A - R0008 - Raised Platform - 51.91 m2</b>							
No Asbestos							
<b>B00A - R0009 - P.E Store - 15.1 m2</b>							
No Asbestos							
<b>B00A - R0010 - Movement - 20.84 m2</b>							
No Asbestos							
<b>B00A - R0011 - Shower/Change - 11.54 m2</b>							
No Asbestos							
<b>B00A - R0012 - Cleaning Supplies - 10.42 m2</b>							
No Asbestos							
<b>B00A - R0013 - Hall Chair Store - 6.05 m2</b>							
No Asbestos							
<b>B00A - R0014 - Movement - 17.43 m2</b>							
No Asbestos							
<b>B00A - R0015 - Movement - 7.14 m2</b>							
No Asbestos							
<b>B00A - R0016 - Stairs - 6 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R1001 - Movement - 1.79 m2</b>							
No Asbestos							
<b>B00A - R1002 - Reading Area - 194.23 m2</b>							
No Asbestos							
<b>B00A - R1003 - Seminar/Study - 9.4 m2</b>							
No Asbestos							
<b>B00A - R1004 - Seminar/Study - 9.75 m2</b>							

No Asbestos							
<b>B00A - R1005 - Library Office/Workroom - 14.12 m2</b>							
No Asbestos							
<b>B00A - R1006 - Library Office/Workroom - 8.2 m2</b>							
No Asbestos							
<b>B00A - R1007 - Communications Room - 10.97 m2</b>							
No Asbestos							
<b>B00A - R1008 - Toilets - Boys - 3.35 m2</b>							
No Asbestos							
<b>B00A - R1009 - Toilets - Girls - 3.37 m2</b>							
No Asbestos							
<b>B00A - R1010 - Cleaning Distributed Store - 1.66 m2</b>							
No Asbestos							
<b>B00A - R1011 - Movement - 40.73 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00A - R1012 - Staff Room - 47.74 m2</b>							
No Asbestos							
<b>B00A - R1013 - Distribution Board - 2.06 m2</b>							
<b>Note: No inspection of live electrical installation</b>							
No Asbestos							
<b>B00A - R1014 - Stairs - 8.29 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - Administration/Pupil Facilities - 1978 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00B - R0001 - Toilets - Boys - 21.79 m2</b>							
No Asbestos							
<b>B00B - R0002 - Movement - 14.6 m2</b>							
No Asbestos							
<b>B00B - R0003 - Toilets - Girls - 21.69 m2</b>							
No Asbestos							
<b>B00B - R0004 - Movement - 120.07 m2</b>							
No Asbestos							
<b>B00B - R1001 - General Storeroom - 14.88 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1002 - Movement - .95 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1003 - Movement - 42.39 m2</b>							
No Asbestos							
<b>B00B - R1004 - Staff Toilet - 6.41 m2</b>							
No Asbestos							
<b>B00B - R1005 - Staff Toilet - 6.41 m2</b>							

No Asbestos							
<b>B00B - R1006 - Sick Bay - 8.03 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1007 - Duplicating Workroom - 12.03 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1008 - Clerical Office - 11.74 m2</b>							
No Asbestos							
<b>B00B - R1009 - Deputy Principal - 16.03 m2</b>							
No Asbestos							
<b>B00B - R1010 - Movement - .97 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00B - R1011 - Principal - 21.01 m2</b>							
No Asbestos							
<b>B00B - R1012 - Deputy Principal - 12.85 m2</b>							
No Asbestos							
<b>B00B - R1013 - Interview - 12.35 m2</b>							
No Asbestos							
<b>B00B - R1014 - General Storeroom - 12.03 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - General Learning - 1977 - Timber</b>							
<b>Exterior</b>							
Ceiling Voids	Requires Inspection						
Underfloor Voids - Slab on Ground	No Asbestos Found						
<b>Interior</b>							
<b>B00C - R0003 - Craft Store - 27.18 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R0004 - Other - 112.89 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00C - R1001 - Sports Store - 11.16 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	14m2	North, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1002 - Home Base - 71.21 m2</b>							
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1003 - Practical Activities - 1hb - 12.66 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1004 - Toilets - Boys/Girls - 2.89 m2</b>							
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

<b>B00C - R1006 - General Storeroom - 16.96 m2</b>							
Wall Linings Internal	Flat AC Sheeting	28m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00C - R1007 - Movement - 12.56 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00C - R1008 - Other - 10.64 m2</b>							
No Asbestos							
<b>B00D - General Learning - 1978 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00D - R0001 - Movement - 280.35 m2</b>							
No Asbestos							
<b>B00D - R0002 - Stairs - 9.7 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00D - R1001 - Movement - 66.77 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00D - R1002 - Distribution Board - .8 m2</b>							
							<b>Note: No inspection of live electrical installation</b>
No Asbestos							
<b>B00D - R1003 - Practical Activities - 1hb - 17.84 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R1004 - Home Base - 50.94 m2</b>							
No Asbestos							
<b>B00D - R1005 - Home Base - 50.94 m2</b>							
No Asbestos							
<b>B00D - R1006 - Practical Activities - 1hb - 18.96 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R1007 - Practical Activities - 1hb - 18.96 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00D - R1008 - Home Base - 50.39 m2</b>							
No Asbestos							
<b>B00D - R1009 - Stairs - 5.29 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00E - General Learning/Pupil Facilities - 1978 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							

<b>B00E - R0001 - Movement - 142.16 m2</b>							
No Asbestos							
<b>B00E - R0002 - Canteen - 30.18 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0003 - Canteen Office/Store - 4.61 m2</b>							
No Asbestos							
<b>B00E - R0004 - Canteen Office/Store - 3.08 m2</b>							
No Asbestos							
<b>B00E - R0005 - Staff Toilet - 3.16 m2</b>							
No Asbestos							
<b>B00E - R0006 - Stairs - 6.33 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R0007 - Kiln Room - 6.43 m2</b>							
Wall Linings Internal	Flat AC Sheeting						
<b>B00E - R1001 - Movement - 42.74 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R1002 - Home Base - 50.78 m2</b>							
No Asbestos							
<b>B00E - R1003 - Practical Activities - 1hb - 18.96 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R1004 - Practical Activities - 1hb - 19.03 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00E - R1005 - Home Base - 50.7 m2</b>							
No Asbestos							
<b>B00E - R1006 - Stairs - 10.71 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - General Learning - 1978 - Brick/Block</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00F - R0001 - Distribution Board - 3.55 m2</b>						<b>Note: No inspection of live electrical installation</b>	
Electrical - Backing Board	Resinous Board	1	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0002 - Movement - 512.78 m2</b>							
No Asbestos							
<b>B00F - R0003 - Stairs - 11.8 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0004 - Stairs - 11.76 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1001 - Movement - 125.46 m2</b>							

Ceiling Structures/Linings	Flat AC Sheeting	125m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1002 - Home Base - 51.24 m2</b>							
No Asbestos							
<b>B00F - R1003 - Practical Activities - 1hb - 18.98 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1004 - Home Base - 50.39 m2</b>							
No Asbestos							
<b>B00F - R1005 - Practical Activities - 1hb - 18.96 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1006 - Practical Activities - 1hb - 19.06 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1007 - Home Base - 52.1 m2</b>							
No Asbestos							
<b>B00F - R1008 - Home Base - 49.3 m2</b>							
No Asbestos							
<b>B00F - R1009 - Practical Activities - 1hb - 19.11 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1010 - General Storeroom - 24.66 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1011 - Distribution Board - 2.6 m2</b>						<b>Note: No inspection of live electrical installation</b>	
No Asbestos							
<b>B00F - R1012 - Home Base - 50.3 m2</b>							
No Asbestos							
<b>B00F - R1013 - Practical Activities - 1hb - 19.06 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1014 - Stairs - 5.41 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R1015 - Stairs - 5.38 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - Pupil Facilities - 1955 - Timber</b>							
<b>Exterior</b>							
Underfloor Voids - Slab on Ground	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00G - R0005 - External Movement - 27.42 m2</b>							
No Asbestos							
<b>B00G - R0006 - Toilets - Girls - 10.48 m2</b>							
No Asbestos							
<b>B00G - R0007 - Disabled Shower/Toilet - 9.23 m2</b>							
No Asbestos							
<b>B00G - R0008 - Toilets - Boys - 11.46 m2</b>							
No Asbestos							



## B00H - General Learning - 1977 - Timber

### Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						
Gable Ends	Corrugated AC Sheeting	12m2	East & West	Mnimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)

### Interior

#### B00H - R0001 - Movement - 113.95 m2

Ceiling Structures/Linings	Flat AC Sheeting						
----------------------------	------------------	--	--	--	--	--	--

#### B00H - R1001 - Toilets - Boys/Girls - 5.1 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00H - R1002 - Personal Effects Storage - 12.84 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00H - R1003 - Home Base - 66.37 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00H - R1004 - Practical Activities - 1hb - 15.06 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00H - R1005 - Withdrawal Space - 1hb - 11.11 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

## B00I - Building Services - 1978 - Brick/Block

### Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						

### Interior

#### B00I - R0001 - Movement - 8.24 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00I - R0002 - Stairs - 11.83 m2

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	------	------------	--------------------	---------	--------------------	-----------------------------

#### B00I - R1001 - Movement - 7.39 m2

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	-----------------------------

#### B00I - R1002 - Stairs - 5.43 m2

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------	-----------------------------

## B00J - Pre-School Facilities - 2004 - Brick/Veneer

### Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found						
Ceiling Voids	No Asbestos Found						

### Interior

#### B00J - R0001 - Movement - 2.23 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00J - R0002 - Entry Vestibule - 13.89 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00J - R0003 - Security Store - 8.59 m2

No Asbestos							
-------------	--	--	--	--	--	--	--

#### B00J - R0004 - General Storeroom - Pre - 12.39 m2

No Asbestos		
<b>B00J - R0005 - Home Base - Pre - 68.95 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00J - R0006 - Practical Activities - Pre - 46.29 m2</b>		
No Asbestos		
<b>B00J - R0007 - Toilets - Boys/Girls - Pre - 12.8 m2</b>		
No Asbestos		
<b>B00J - R0008 - Laundry - Pre - 4.54 m2</b>		
No Asbestos		
<b>B00J - R0009 - Access Shower/Toilet - Type 2 - 5.55 m2</b>		
No Asbestos		
<b>B00J - R0010 - Cleaning Distributed Store - 3.54 m2</b>		
No Asbestos		
<b>B00J - R0011 - Kitchen - Pre - 12.9 m2</b>		
No Asbestos		
<b>B00J - R0012 - Clerical Office - Pre - 12.42 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00J - R0013 - Clerical Office - Pre - 8.65 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00J - R0014 - General Storeroom - Pre - 20.54 m2</b>		
No Asbestos		
<b>B00J - R0015 - External Movement - 69.34 m2</b>		
No Asbestos		
<b>B00K - Communal Facilities/Pupil Facilities - 2011 - Brick/Veneer</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00K - R0001 - Sports Store - 47.57 m2</b>		
No Asbestos		
<b>B00K - R0002 - External Movement - 23.02 m2</b>		
No Asbestos		
<b>B00K - R0003 - Ramp - 65.93 m2</b>		
No Asbestos		
<b>B00K - R0004 - External Stairs - 12.62 m2</b>		
No Asbestos		
<b>B00K - R1001 - Toilets - Girls - 22.42 m2</b>		
No Asbestos		
<b>B00K - R1002 - Toilets - Boys - 16.36 m2</b>		
No Asbestos		
<b>B00K - R1003 - Access Shower/Toilet/Change - 6.08 m2</b>		
No Asbestos		
<b>B00K - R1004 - External Movement - 15.54 m2</b>		
No Asbestos		
<b>B00K - R1005 - Ramp - 71.86 m2</b>		
No Asbestos		
<b>B00K - R1006 - External Stairs - 12.91 m2</b>		

No Asbestos	
-------------	--

## Demountables

There are no Demountable(s) Located at this school as per the AMS records as of 09-Sep-2020