

# Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Llandilo Public School (2413)
Region:	Western Sydney AMU
State Electorate:	Londonderry
Local Government Area:	Penrith

Last Reviewed By:	WSP 14-MAY-2015
Last Revised By:	

Historical Fibro In Grounds Investigations/Events	Yes
Please refer to the latest site specific Asbestos Management Plans available from the Department's website (Refer to Note 2).	

2413 - Llandilo Public School  
Site Plan (10466)



# Preface to Asbestos Register

## Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
4. Successive inspections have reduced any inconclusive records such as 'assumed asbestos' in difficult to access areas, by undertaking additional sampling with lifting devices.
5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
  - o Where the ground floor is slab on ground, no inspection is made beneath the slab.
  - o Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
  - o Any wall cavity
  - o Sub floor area, particularly formwork for slabs in/on ground,
  - o Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.  
Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

## Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

## Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

## Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were 'composite tested' in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

## Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/working-with-us/schools-asbestos-register.html>  
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

## Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

### 3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
<b>B00A - General Learning/Building Services - 1989 - Brick/Block</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00A - R0001 - Withdrawal Space - 1hb - 7.16 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0002 - Home Base Store - 6.45 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0003 - Cleaning Distributed Store - 2.17 m2</b>							
No Asbestos							
<b>B00A - R0004 - Practical Activities - 1hb - 21.06 m2</b>							
No Asbestos							
<b>B00A - R0005 - Home Base - 60.21 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0006 - Home Base - 60.36 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0007 - Practical Activities - 1hb - 21.13 m2</b>							
No Asbestos							
<b>B00A - R0008 - Home Base Store - 5.62 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0009 - Home Base Store - 5.62 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0010 - Withdrawal Space - 1hb - 10.5 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0011 - Home Base - 60.14 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0012 - Practical Activities - 1hb - 21.08 m2</b>							
No Asbestos							
<b>B00A - R0013 - Practical Activities - 1hb - 21.11 m2</b>							
No Asbestos							
<b>B00A - R0014 - Home Base - 60.21 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0015 - Withdrawal Space - 1hb - 7.31 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0016 - Home Base Store - 7.57 m2</b>							
Floor Coverings Res/Textile	No Asbestos Found						
<b>B00A - R0017 - Distribution Board - 1.48 m2</b>							
No Asbestos							<b>Note: No inspection of live electrical installation</b>
<b>B00A - R0018 - Personal Effects Storage - 4.1 m2</b>							
No Asbestos							
<b>B00A - R0019 - Personal Effects Storage - 6.33 m2</b>							

No Asbestos		
<b>B00A - R0020 - Personal Effects Storage - 4.04 m2</b>		
No Asbestos		
<b>B00A - R0021 - Movement - 89.85 m2</b>		
No Asbestos		
<b>B00A - R0022 - Movement - 20.8 m2</b>		
No Asbestos		
<b>B00B - General Learning/Library - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00B - R0001 - Practical Activities - 1hb - 21.02 m2</b>		
No Asbestos		
<b>B00B - R0002 - Home Base - 60.35 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0003 - Withdrawal Space - 1hb - 9.91 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0004 - Home Base Store - 6.07 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0005 - Home Base Store - 6.07 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0006 - Practical Activities - 1hb - 21 m2</b>		
No Asbestos		
<b>B00B - R0007 - Home Base - 60.35 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0008 - Kiln Room - 5.83 m2</b>		
No Asbestos		
<b>B00B - R0009 - Main Switch Board - 3.85 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00B - R0010 - Reading Area - 162.04 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0011 - Library Office/Workroom - 23.58 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0012 - Library Office/Workroom - 13.05 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0013 - Special Programs Room - 32.77 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0014 - Special Programs Store - 2.1 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00B - R0015 - Plant - 5.55 m2</b>		
No Asbestos		
<b>B00B - R0016 - Movement - 148.36 m2</b>		
No Asbestos		

**B00B - R0017 - Personal Effects Storage - 6.58 m2**

No Asbestos

**B00C - Pupil Facilities - 1982 - Brick/Block****Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00C - R0001 - Canteen - 38.34 m2**

No Asbestos

**B00C - R0002 - Canteen Office/Store - 3.81 m2**

No Asbestos

**B00C - R0003 - Canteen Office/Store - 1.99 m2**

No Asbestos

**B00C - R0004 - Staff Toilet - 2.81 m2**

No Asbestos

**B00C - R0005 - Canteen Office/Store - 2.81 m2**

No Asbestos

**B00C - R0006 - Movement - 26.72 m2**

No Asbestos

**B00C - R0007 - Movement - 55.59 m2**

No Asbestos

**B00D - Administration - 1983 - Brick/Block****Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00D - R0001 - Staff Room Annexe - 22.17 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0002 - Staff Room - 42.78 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0003 - Staff Toilet - 4.4 m2**

No Asbestos

**B00D - R0004 - Movement - 27.09 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0005 - Security Store - 17.58 m2**

No Asbestos

**B00D - R0006 - Principal - 18.53 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0007 - Clerical Office - 17.07 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0008 - Entry Vestibule - 16.85 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0009 - Interview - 12.73 m2**Floor Coverings  
Res/Textile No Asbestos Found**B00D - R0010 - Duplicating Workroom - 20.83 m2**

No Asbestos

<b>B00D - R0011 - Deputy Principal - 12.39 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0012 - Sick Bay - 9.16 m2</b>		
No Asbestos		
<b>B00D - R0013 - Staff Shower/Change - 6.65 m2</b>		
No Asbestos		
<b>B00D - R0014 - Deputy Principal - 13 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00D - R0015 - Cleaning Distributed Store - 1.42 m2</b>		
No Asbestos		
<b>B00D - R0016 - Distribution Board - .48 m2</b>		<b>Note: No inspection of live electrical installation</b>
No Asbestos		
<b>B00D - R0017 - Staff Toilet - 3.5 m2</b>		
No Asbestos		
<b>B00D - R0018 - Movement - 68.06 m2</b>		
No Asbestos		
<b>B00D - R0019 - Movement - 8.15 m2</b>		
No Asbestos		
<b>B00E - Communal Facilities/Administration - 1989 - Brick/Block</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00E - R0001 - Movement - 6.98 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0002 - Shower/Change - 2.46 m2</b>		
No Asbestos		
<b>B00E - R0003 - Communal/Performance Store - 2.31 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0004 - Communal Space - 144.14 m2</b>		
No Asbestos		
<b>B00E - R0005 - Disabled Toilet - 4.63 m2</b>		
No Asbestos		
<b>B00E - R0006 - Staff Toilet - 2.07 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0007 - Community Clinic - 5.86 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0008 - Community Clinic - 21.2 m2</b>		
Floor Coverings Res/Textile	No Asbestos Found	
<b>B00E - R0009 - Plant - .45 m2</b>		
No Asbestos		
<b>B00E - R0010 - Hall Chair Store - 8.4 m2</b>		
No Asbestos		
<b>B00E - R0011 - P.E. Store - 12.43 m2</b>		
No Asbestos		
<b>B00E - R0012 - General Assistant/Bulk Store - 16.41 m2</b>		
No Asbestos		

<b>B00E - R0013 - Cleaning Supplies - 5.43 m2</b>		
No Asbestos		
<b>B00E - R0014 - Staff Room Annexe - 10.4 m2</b>		
No Asbestos		
<b>B00E - R0015 - Distribution Board - 2.06 m2</b>		<b>Note: No inspection of live electrical installation</b>
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0016 - Movement - 22.81 m2</b>		
No Asbestos		
<b>B00E - R0017 - Movement - 10.64 m2</b>		
No Asbestos		
<b>B00E - R0018 - Cleaning Distributed Store - 2.29 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0019 - Shower/Change - 2.52 m2</b>		
No Asbestos		
<b>B00E - R0020 - Movement - 6.92 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0021 - Garden Store - 7.49 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0022 - Toilets - Boys - 11.45 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0023 - Movement - 1.33 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0024 - Sports Store - 13.91 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0025 - Toilets - Girls - 11.77 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0026 - Movement - 1.33 m2</b>		
Ceiling Structures/Linings	Flat AC Sheeting	
<b>B00E - R0027 - Raised Platform - 45.74 m2</b>		
No Asbestos		
<b>B00E - R0028 - Movement - 40.63 m2</b>		
No Asbestos		
<b>B00E - R0029 - Movement - 25.53 m2</b>		
No Asbestos		
<b>B00E - R0030 - Movement - 46.83 m2</b>		
No Asbestos		
<b>B00E - R0031 - Ramp - 19.66 m2</b>		
No Asbestos		
<b>B00F - Museum - 1913 - Timber</b>		
<b>Exterior</b>		
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
<b>Interior</b>		
<b>B00F - R0001 - Museum - 14.03 m2</b>		
No Asbestos		

<b>B00F - R0002 - Museum - 22.34 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00F - R0003 - Museum - 7.92 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00G - General Learning/Staff Facilities - 1959 - Timber</b>							
<b>Exterior</b>							
Wall Cladding	Flat AC Sheeting						
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00G - R0001 - Personal Effects Storage - 15.25 m2</b>							
Wall Linings Internal	Flat AC Sheeting	8m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00G - R0002 - Home Base - 53.66 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00G - R0003 - Home Base Store - 10.86 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
<b>B00G - R0004 - Staff Room Annexe - 11.06 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
<b>B00G - R0005 - General Storeroom - 6.93 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
Wall Linings Internal	Flat AC Sheeting	24m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - General Learning/Pupil Facilities - 1964 - Brick/Block</b>							
<b>Exterior</b>							
Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00H - R0001 - Practical Activities - 1hb - 9.28 m2</b>							
No Asbestos							
<b>B00H - R0002 - Home Base - 62.85 m2</b>							
No Asbestos							
<b>B00H - R0003 - Movement - 4.12 m2</b>							
No Asbestos							
<b>B00H - R0004 - Personal Effects Storage - 3.2 m2</b>							
No Asbestos							
<b>B00H - R0005 - Toilets - Boys - 16.53 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)



<b>B00H - R0006 - Toilets - Girls - 16.58 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00H - R0007 - Movement - 21.32 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting						
<b>B00J - General Learning/Pupil Facilities - 1972 - Brick/Block</b>							
<b>Exterior</b>							
Wall Linings Internal - Infill	Flat AC Sheeting	9	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	East & West	Minimal Damage (2)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>Interior</b>							
<b>B00J - R0001 - Cleaning Distributed Store - 4.62 m2</b>							
No Asbestos							
<b>B00J - R0002 - Cleaning Distributed Store - .76 m2</b>							
No Asbestos							
<b>B00J - R0003 - Staff Toilet - 2.7 m2</b>							
No Asbestos							
<b>B00J - R0004 - Toilets - Boys - 18.85 m2</b>							
No Asbestos							
<b>B00J - R0005 - Movement - 74.39 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0006 - Movement - 2.84 m2</b>							
No Asbestos							
<b>B00J - R0007 - General Storeroom - 6.93 m2</b>							
No Asbestos							
<b>B00J - R0008 - Movement - .5 m2</b>							
No Asbestos							
<b>B00J - R0009 - Toilets - Girls - 19.46 m2</b>							
No Asbestos							
<b>B00J - R0010 - Staff Toilet - 2.16 m2</b>							
No Asbestos							
<b>B00J - R0011 - Main Switch Board - 3.45 m2</b>							
No Asbestos							
<b>B00J - R0012 - Practical Activities - 1hb - 16.13 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0013 - Toilets - Boys/Girls - 4.34 m2</b>							
No Asbestos							
<b>B00J - R0014 - Home Base - 83.21 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0015 - Home Base - 52.89 m2</b>							
Floor Coverings Res/Textile	Vinyl Tiles	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0016 - Practical Activities - 1hb - 20.99 m2</b>							

Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0017 - Movement - 40.2 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Wall Linings Internal - Infill	Flat AC Sheeting	9m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00J - R0018 - Movement - 53.42 m2</b>							
No Asbestos							
<b>B00J - R0019 - Stairs - 2.73 m2</b>							
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
<b>B00K - General Learning/Support Unit (M P S) - 2010 - Brick/Veneer</b>							
<b>Exterior</b>							
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						
<b>Interior</b>							
<b>B00K - R0001 - External Movement - 80.57 m2</b>							
No Asbestos							
<b>B00K - R0002 - Practical Activities - 1hb - 18.73 m2</b>							
No Asbestos							
<b>B00K - R0003 - Home Base Store - 6.22 m2</b>							
No Asbestos							
<b>B00K - R0004 - Home Base - 59.82 m2</b>							
No Asbestos							
<b>B00K - R0005 - Withdrawal Space - 2hb - 11.34 m2</b>							
No Asbestos							
<b>B00K - R0006 - Home Base - 59.82 m2</b>							
No Asbestos							
<b>B00K - R0007 - Home Base Store - 6.22 m2</b>							
No Asbestos							
<b>B00K - R0008 - Practical Activities - 1hb - 18.73 m2</b>							
No Asbestos							
<b>B00K - R0009 - Special Programs Room - 33.33 m2</b>							
No Asbestos							
<b>B00K - R0010 - Special Programs Store - 6.3 m2</b>							
No Asbestos							

**Demountables**

**OS 602 10202 - Learning Unit - Standard With P.A.A. - Placement Date : 08-OCT-2014**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 602 13118 - Learning Unit - Standard With P.A.A. - Placement Date : 29-JAN-2016**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found

**OS 606 19203 - Learning Unit - Standard With P.A.A A/C - Placement Date : 23-FEB-2018**

**Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.**

No Asbestos Found